

OPEN MEETING ITEM







BOB STUMP

ARIZONA CORPORATION COMMISSION

DATE:

MARCH 16, 2010

DOCKET NO .:

E-01345A-07-0663 AND T-01846B-07-0663

Arizona Corporation Commission DOCKETED

MAR 1 6 2010

DOCKETED BY

TO ALL PARTIES:

Enclosed please find the recommendation of Administrative Law Judge Sarah N. Harpring. The recommendation has been filed in the form of an Opinion and Order on:

> ARIZONA PUBLIC SERVICE COMPANY and VERIZON CALIFORNIA, INC. (UNDERGROUND CONVERSION SERVICE AREA)

Pursuant to A.A.C. R14-3-110(B), you may file exceptions to the recommendation of the Administrative Law Judge by filing an original and thirteen (13) copies of the exceptions with the Commission's Docket Control at the address listed below by 4:00 p.m. on or before:

MARCH 25, 2010

The enclosed is NOT an order of the Commission, but a recommendation of the Administrative Law Judge to the Commissioners. Consideration of this matter has tentatively been scheduled for the Commission's Open Meeting to be held on:

MARCH 31, 2010 AND APRIL 1, 2010

For more information, you may contact Docket Control at (602) 542-3477 or the Hearing Division at (602) 542-4250. For information about the Open Meeting, contact the Executive Director's Office at (602) 542-3931.

EXECUTIVE DIRECTOR

1200 WEST WASHINGTON STREET; PHOENIX, ARIZONA 85007-2927 / 400 WEST CONGRESS STREET; TUCSON, ARIZONA 85701-1347 www.azcc.gov

1	BEFORE THE ARIZONA CORPORATION COMMISSION				
2	<u>COMMISSIONERS</u>				
3	KRISTIN K. MAYES - Chairman		•		
4	I AOL NE WIMAN				
5	SANDRA D. KENNEDY BOB STUMP				
6		,	DOCKETNO F 012454 07 0662		
7	IN THE MATTER OF ARIZONA PUBLIC SERVICE COMPANY AND VERIZON	C	DOCKET NO. E-01345A-07-0663		
8	CALIFORNIA, INC.'S JOINT PETITION ESTABLISHMENT OF AN UNDERGRO		DOCKET NO. T-01846B-07-0663		
9	CONVERSION SERVICE AREA.		DECISION NO.		
10			OPINION AND ORDER		
11	DATE OF HEARING:	January 18, 2008; July 21 and 22, 2009			
12	PLACE OF HEARING:	Phoenix, Arizona			
13	ADMINISTRATIVE LAW JUDGE:	Sarah N. Harpring			
14	APPEARANCES:	Mr. Robert J. Metli, SNELL & WILMER, L.L.P., on behalf of Arizona Public Service Company;			
15 16		nel T. Hallam, LEWIS AND ROCA, L.L.P., of Verizon California, Inc.;			
17		on Loftis, property owner, pro se;			
18	Mr. Timothy J. Sabo, ROSHKA DEWULF & PA on behalf of Hillcrest Bay, Inc.;				
19		Mr. John Sears, property owner, pro se;			
20		Ms. Jane Sears, property owner, pro se;			
21		Mr. Robert Nielson, property owner, pro se;			
22		Mr. Ron Nelson, property owner, pro se;			
23		Ms. Sylvia Nelson, property owner, pro se;			
24		Ms. Robyn Stein, property owner, pro se;			
25		Ms. Grace Babcock, property owner, pro se;			
26		Mr. Tom L	orch, property owner, pro se;		
27		Ms. Teddie	e Lorch, property owner, pro se;		
28		Mr. Philip	Garcia, property owner, pro se;		

2

3

4

5

6

7

8

9

10

11

12 13

14

15

16

17

18

19

BY THE COMMISSION:

20 21

22 23 24

25

26 27

28

Mr. Terence Bitrich, property owner, pro se;

Ms. Carole Jones, property owner, pro se;

Ms. Joy Muzic, property owner, pro se;

Ms. Lynne Muzic, property owner, pro se;

Mr. Nando Haase, property owner, pro se;

Mr. Johnny Dodson, property owner, pro se;

Ms. Billie Dodson, property owner, pro se;

Mr. Wayne Dunham, property owner, pro se;

Ms. Janet Calvin, property owner, pro se;

Mr. Steve Benton, property owner, pro se;

Ms. Harlayne Bond, property owner, pro se;

Mr. William Bond, property owner, pro se;

Ms. Judy Wilson-Kawagoye, property owner, pro se;

Ms. Marjorie Ward, property owner, pro se; and

Ms. Robin Mitchell, Staff Attorney, Legal Division, on behalf of the Utilities Division of the Arizona Corporation Commission.

This case involves a joint petition to establish an underground conversion service area ("UCSA") in a development known as Hillcrest Bay Mobile Manor ("Hillcrest Bay"). The joint petition was filed with the Arizona Corporation Commission ("Commission") by the Arizona Public Service Company ("APS") and Verizon California Inc. ("Verizon") under Arizona Revised Statutes ("A.R.S.") § 40-343(B). A Recommended Opinion and Order ("ROO") for this case, which recommended denial of the joint petition based on a lack of economic feasibility for the affected property owners, was considered by the Commission at its Open Meeting in July 2008. Rather than voting on the ROO, the Commission directed that the record be kept open to allow submission of specific additional information concerning economic feasibility. Hillcrest Bay, Inc. ("HBI"), the homeowners' association for Hillcrest Bay and a property owner, filed additional information in

support of the joint petition in May 2009. An additional evidentiary hearing was held in July 2009.

Having considered the entire record herein and being fully advised in the premises, the Commission finds, concludes, and orders that:

FINDINGS OF FACT

Statutory Process for Establishment of an UCSA

- 1. An UCSA is an area in which existing overhead electric and communication facilities are to be placed underground. (A.R.S. § 40-341.) The statutes in A.R.S. Title 40, Chapter 2, Article 6.1 ("UCSA statutes") provide a process by which the owners of the real property within a proposed UCSA ("owners") can cause the public service corporations providing electric and communications service to the area through overhead facilities ("PSCs") to petition the Commission for establishment of an UCSA. An UCSA must be a reasonably sized, reasonably compact area of contiguous real property. (A.R.S. §§ 40-342(A); 40-346(A).)
- 2. The UCSA process is commenced by a petition filed with the PSCs by at least 60 percent of the owners, who own at least 60 percent of the real property within the proposed UCSA on a square footage basis, for a study of the costs related to the establishment of the area as an UCSA ("first petition"). (A.R.S. § 40-342(A).) The first petition must set forth the necessity for the proposed UCSA; that the establishment of the UCSA would promote the public convenience, necessity, or welfare and would benefit the property to be included therein; and the name and address of the owner of each parcel or lot within the proposed UCSA as reflected on the records of the county assessor. (A.R.S. § 40-342(B).) Each copy of the first petition must be verified by one of the petitioning owners and must be accompanied by a plat or sketch indicating the boundaries of the proposed UCSA and the size in square feet of each parcel or lot within the proposed UCSA. (A.R.S. § 40-342(C).)
- 3. Each PSC that receives a first petition must make a study of the costs of converting its facilities in the area to underground service and make available to the owners, within 120 days after receiving the first petition, a joint report of the cost study ("joint report"). (A.R.S. § 40-342(D).) The joint report must set forth the estimated cost to be assessed to each lot or parcel of real property

located within the proposed UCSA for converting the facilities in public places¹ ("public costs") and the estimated cost to be assessed to each lot or parcel for converting the facilities located within the boundaries of the lot or parcel receiving service ("service costs"). (*Id.*) The costs of preparing the joint report must be borne by the PSCs unless the Commission orders the establishment of the UCSA, in which case the costs are included in the underground conversion costs. (*Id.*) The PSCs must mail a summary of the costs to be assessed against each lot or parcel within the proposed UCSA to each owner at the address set forth in the first petition. (A.R.S. § 40-342(F).)

- 4. Within 90 days after the joint report is made available to the owners, at least 60 percent of the owners, who own at least 60 percent of the real property in the proposed UCSA, excluding public places, may petition the PSCs for establishment of an UCSA in the same area described in the first petition ("second petition"). (A.R.S. § 40-343(A).)
- 5. The PSCs that receive a second petition must file with the Commission, within 60 days after receiving the second petition, a petition for establishment of an UCSA ("joint petition"). (A.R.S. § 40-343(B).) The PSCs must also, upon filing the joint petition, record in the office of the county recorder of the county where the proposed UCSA is located, a notice of proposed lien as to each lot or parcel in the proposed UCSA for the estimated costs to be assessed against each lot or parcel by each PSC for placing underground the facilities of the PSC should the Commission order establishment of the UCSA. (A.R.S. § 40-343(D).)
- 6. Upon receipt of a joint petition, the Commission must set a date for a hearing on the petition, which date must be between 30 and 60 days after receipt of the petition. (A.R.S. § 40-344(A).) No fewer than 30 days before the date set for hearing, the Commission must mail notice announcing the hearing and describing the boundaries of the proposed UCSA to each owner and to those governmental agencies having rights in public places within the proposed UCSA. (A.R.S. § 40-344(C).) In addition, notice announcing the hearing, describing the boundaries of the proposed UCSA, and stating that the estimated underground conversion costs for each lot or parcel are available at the office of each PSC must be posted in at least three public places within the proposed

[&]quot;'Public place' includes streets, alleys, roadways, sidewalks, rights of way, easements and similar properties as to which a city, town, county, the state, the public service corporation or the public agency may have a right." (A.R.S. § 40-341(9).)

1 UCSA for at least 30 days before the date of the hearing and published once, at least 20 days before 2 3 4

5 6

8 9

7

10 11

12

13 14

15

17

16

18 19

20 21

22

23

24

25

28

the date of the hearing, in a newspaper published in the county and of general circulation with the proposed UCSA. (A.R.S. § 40-344(B).) The costs of the posting, publication, and mailing provided for in A.R.S. § 40-344 are to be assessed by the Commission on a pro rata basis to each PSC. (A.R.S. § 40-344(I).) 7. Any owner wishing to withdraw his or her signature from the second petition or to

- object to the establishment of the UCSA or to the underground conversion costs for his or her lot or parcel as contained in the joint report must file an objection with the Commission at least 10 days before the hearing date. (A.R.S. § 40-344(A).) In determining protests, withdrawals of signatures, and objections, the Commission "shall be guided" by the provisions in A.R.S. § 40-345. (A.R.S. § 40-345.) Among other things, A.R.S. § 40-345 states: "Each paper containing signatures shall have attached thereto an affidavit of an owner of real estate within the proposed underground conversion service area, stating that each signature was affixed in his presence and is the signer's genuine signature."² (A.R.S. § 40-345(1) (emphasis added.)
- At the hearing, all interested owners may appear and be heard on the matter. (A.R.S. § 8. 40-344(A).) The PSCs involved and all owners are deemed to be parties to the proceedings for the purposes of applications for rehearing or appeals under A.R.S. §§ 40-253 or 40-254. (A.R.S. § 40-344(C).)
- 9. A.R.S. § 40-346(A) explains the Commission's duties regarding the hearing to be held and the findings to be made by the Commission as follows:

The corporation commission . . . shall hold a hearing, upon notice as provided in this article, to establish the fact that the requirements for the establishment of an [UCSA] have been satisfied, and that owners of no more than forty per cent of the real property within the [UCSA], or no more than forty per cent of the owners of real property, have not objected to the formation of the [UCSA], and if the commission . . . so determines, and if the commission . . . further

26 27

address validity.

HBI asserts that this requires any objection or withdrawal of signature to be accompanied by an affidavit from a witnessing owner. We find that this statutory provision only requires an affidavit to accompany protests, withdrawals of signature, or objections that are signed by multiple persons, as is apparent from the plural "signatures" along with the reference to "each signature." This interpretation, as opposed to that proposed by HBI, gives effect to the actual language of this statutory provision. We also note that A.R.S. § 40-345(1) does not state that an objection or withdrawal that is not accompanied by an affidavit is not valid, although a number of the other subsections in A.R.S. § 40-345 specifically

determines after considering all objections, that the cost of conversion as reflected in the joint report prepared pursuant to § 40-342 is economically and technically feasible for the public service corporations . . . involved and the property owners affected and that the [UCSA] is a reasonably compact area of reasonable size, the commission . . . shall then issue an order establishing the area as an [UCSA].³

- 10. If the Commission concludes at hearing that territory not included in the petition should be included within the UCSA, the Commission must provide the owners of the additional territory notice as provided in connection with the original hearing and must hold another hearing on the question of including the additional territory. (A.R.S. § 40-346(B).) If the Commission determines that any territory described in the joint petition will not be benefited by establishment of the UCSA or that conversion is not economically or technically feasible for any territory described in the joint petition, the Commission must eliminate the territory from the proposed UCSA. (*Id.*)
- 11. The Commission must not establish an UCSA unless the local government has already approved the establishment by resolution. (A.R.S. § 40-344(J).) For an unincorporated area, the local government approval needed is a resolution of the county board of supervisors. (*See id.*; A.R.S. § 40-341(4).)
- 12. A Commission order establishing an UCSA must direct the PSCs owning overhead electric or communications facilities within the UCSA to convert the facilities to underground in accordance with standard underground practices, set forth the underground conversion costs to be charged to each lot or parcel, and authorize each PSC to charge those underground conversion costs to each lot or parcel. (A.R.S. §§ 40-346(D), (F); A.R.S. § 40-347(A).) The underground conversion costs may not exceed the estimated costs included in the joint report, but must be sufficient to repay each PSC for:
- a. The remaining undepreciated original costs of the existing overhead facilities to be removed, determined according to the uniform system of accounts applicable to the PSC;
- b. The actual costs of removing the overhead facilities, less the salvage value of the facilities removed;
 - c. The contribution in aid of construction that the PSC would require under its

^{28 (}A.R.S. § 40-346(A).)

rules and regulations applicable to UCSAs;

- d. If not paid in full as provided in A.R.S. § 40-348, the actual cost of converting to underground electric service facilities from the public place to the point of delivery on the lot or parcel or of converting to underground communications service facilities from the public place to the connection point within the house or structure, less any credit that may be given an owner under an existing PSC line extension policy;⁴ and
- e. If property belonging to the U.S., the state, a county, a city, a school district, or any other political subdivision or institution of the state or county is included in the UCSA, and the governmental entity does not voluntarily assume the costs, the underground conversion cost applicable to such property, which shall be charged pro rata against the rest of the property within the UCSA. (A.R.S. § 40-347(A).)
- 13. The public costs must be apportioned among the owners on the basis of relative size of each parcel. (A.R.S. § 40-347(B).)
- 14. The underground conversion costs may be paid in cash by the owners within 60 days after the date the overhead facilities are removed from public places or may be paid by a uniform plan applicable to all owners not paying within 60 days, in equal periodic installments over a reasonable period of time, not to exceed 15 years, together with interest at a rate not to exceed 8 percent per annum. (A.R.S. § 40-347(B).) The Commission must establish both the period of repayment and the interest rate. (*Id.*) The UCSA statutes allow for the PSCs and all of the owners to agree upon an alternate arrangement for reimbursing the PSCs for the cost of conversion, either as to payment or security. (A.R.S. § 40-347(D).
- 15. If funds from another source, public or private, become available to pay all or any part of the underground conversion costs, the funds must be applied on a pro rata basis to reduce the underground conversion costs charged against each lot or parcel. (A.R.S. § 40-347(C).)
 - 16. The service facilities within the boundaries of each lot or parcel within the UCSA

APS testified that its line extension policy is consistent with the UCSA statutes. (See Tr. I at 105-06.) Verizon testified that it did not have a line extension policy that would provide a credit. (See Tr. I at 141-42.)

DECISION NO.

These are "service costs." A.R.S. § 40-348(B) provides that if a property owner does not reimburse a PSC in cash for the service costs within 30 days after completion of the conversion work incident thereto, or reach another agreement with the PSC for payment in some other manner, the service costs shall be included in the underground conversion cost.

must be placed underground at the same time as or after the underground system in private easements and public places is placed underground. (A.R.S. § 40-348(A).) Upon an owner's request, at the owner's expense, and either directly or through a contractor, the electric PSC must underground its facilities on the lot or parcel up to the point of delivery, and the communications PSC must underground its facilities on the lot or parcel up to the connection point within the house or structure. (Id.) If an owner does not fully reimburse the PSCs in cash for these service costs within 30 days after the conversion, or reach another agreement allowing for payment in some other manner, the costs must be included in the underground conversion costs for the lot or parcel. (A.R.S. § 40-348(B).)

- 17. The owner of each lot or parcel, either directly or through a contractor, must have the overhead electric facilities from the point of delivery to the service entrance placed underground. (A.R.S. § 40-348(A).)
- 18. Upon completion of the underground system in public places, the Commission must mail a notice to each owner advising of the owner's responsibility to have the service facilities within the boundaries of the owner's lot or parcel undergrounded as provided in A.R.S. § 40-348(A) and stating that unless the owner complies with A.R.S. § 40-348(A) within 30 days thereafter, all buildings, structures, and improvements located on the owner's lot or parcel will be subject to disconnection from the electric or communications facilities providing it service. (A.R.S. § 40-348(C).) If an owner fails to comply within the time allotted, each PSC must disconnect and remove all overhead facilities providing service to any building, structure, or improvement located on the lot or parcel, after first leaving written notice of the proposed disconnection, at least 30 days before disconnection, at the principal building, structure, or improvement located upon the lot or parcel. (Id.) After the underground system in private easements and public places has been energized, discontinuing service to any lots or parcels whose owners have not furnished a permit or easement for conversion work to be done, the PSC must remove its overhead facilities that have been replaced by

A PSC is prohibited from commencing the conversion work on an owner's lot or parcel, other than in a private easement or public place, until the owner has furnished a permit or easement expressly authorizing the PSC and its workers to enter upon the lot or parcel for the conversion work and agreeing to have the costs of the conversion work included in the underground conversion service costs if the owner does not pay them in full within 30 days after completion of the work. (A.R.S. § 40-349(A).)

underground facilities. (A.R.S. § 40-349(B).)

- 19. Upon completing conversion, each PSC must determine its total conversion costs and prepare and file a verified statement of the costs with the Commission. (A.R.S. § 40-350(A).) If the actual public costs are less than the estimated public costs from the joint report, the underground conversion costs to be paid by each owner must be reduced proportionately. (*Id.*) If the actual service costs are less than the estimated service costs from the joint report for any lot or parcel, then the underground conversion costs assessed to the owner of the lot or parcel must be reduced. (*Id.*) A PSC cannot receive reimbursement of actual costs that exceed estimated costs. (*See id.*; A.R.S. § 40-347(B).) The Commission must mail each owner a statement of the underground conversion costs, including any revisions, along with a statement specifying the date payments are to commence. (A.R.S. § 40-350(A).) An owner may submit to the Commission a written objection as to any revisions and shall receive a hearing on any such objection, but must make payments as scheduled during the pendency of any objection or appeal. (*Id.*)
- 20. The costs to be paid by each owner to each PSC are to be a separate lien on the owner's lot or parcel in favor of the PSC, effective as of the date the notice of proposed lien was filed, after the PSC perfects the lien by recording a notice of lien within 90 days after the overhead system is removed in public places. (A.R.S. § 40-350(B).) The lien can include only the underground conversion costs determined under A.R.S. § 40-347 plus any service costs included pursuant to A.R.S. § 40-348. (*Id.*)
- 21. If an owner defaults on payment of a periodic installment of the underground conversion costs, a PSC may (1) elect to make the unpaid balance due and payable immediately, after providing and recording written notice; (2) discontinue service to the meter or account until the delinquent amount has been paid, after providing written notice; and (3) institute an action in superior court to foreclose its lien against the lot or parcel. (A.R.S. § 40-350(D) and (F).) A property cannot be sold to satisfy a lien granted under the UCSA statutes unless there has been a judgment of

In response to questioning from Commissioner Mayes, APS witness Donald Wilson testified that he believed APS would be willing to consult with Staff before APS initiates a disconnect on a customer for failure to pay installments. (Tr. I at 78.) Staff also testified that Staff, specifically the Consumer Services Section and the Utilities Division's Director's Office, would be willing to engage in such consultations. (Tr. I at 194.)

foreclosure and order of sale. (A.R.S. § 40-351.)

Background

- 22. Hillcrest Bay is located in an unincorporated area of La Paz County, (Tr. I⁷ at 91,) approximately 17 miles north of Parker, Arizona, on a hillside directly across Highway 95 from and overlooking Lake Havasu, (Ex. I S-4; LFE I A-18). Hillcrest Bay is surrounded on the south and east by the Buckskin Mountains. (Tr. I at 82.) The streets within Hillcrest Bay are terraced so that for parcels between streets, the rear parcel is terraced higher than the front parcel, while parcels on either side of a street are at approximately the same elevation. (Ex. I S-4.) No other developments are immediately adjacent to Hillcrest Bay. (*Id.*)
- 23. Hillcrest Bay is described by some owners as a place of exceptional natural beauty that is marred by the presence of numerous utility poles and overhead lines. (See, e.g., Tr. II at 45-47, 50.)
- 24. Hillcrest Bay currently receives electric service from APS and communications service from Verizon through overhead facilities. Most of the parcels located on the west, north, and east perimeters of Hillcrest Bay have overhead facilities in a front-lot street location. (LFE I A-12.) The majority of the parcels, located on the streets that run approximately east to west within the perimeter of Hillcrest Bay, have overhead facilities in a rear-lot location between homes that essentially back up to each other. (*Id.*) The electric facilities and communications facilities were installed between 1972 and approximately 1979. (Tr. I at 97-98, 140.) Hillcrest Bay currently contains 70 utility poles, mostly made of wood. (*See* LFE I A-12.)
- 25. Although the Commission's General Order U-48 effective at the time generally required that new facilities be installed underground, on June 30, 1972, in Decision No. 42189, the Commission granted Max A. Dunlap and Arizona Western Land & Development Co. an exception to the underground policy expressed in General Order U-48, as amended, thereby authorizing APS to

Official notice is taken of this Decision.

References to the Transcript from the initial hearing in this matter are indicated by "Tr. I." References to the Transcripts from the second hearing in this matter are indicated by "Tr. II." Likewise, references to Exhibits and Latefiled Exhibits ("LFEs") from the first hearing and second hearing are indicated by "Ex. I" or "LFE I" or "Ex. II" or "LFE II" before the specific identifier, as applicable.

There are exceptions, where owners have had their utility lines installed underground. (See Tr. II at 278.) These owners may still incur costs from conduit to reach that service if the UCSA is approved. (Id.)

1

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

proceed to install the overhead facilities necessary to serve within Hillcrest Bay. In the Decision, the Commission stated that "it would be unfeasible from an engineering, operational or economic standpoint to require the construction of underground electrical and telephone facilities within said area."10

- The installation of overhead utilities in Hillcrest Bay has been an area of concern for 26. the residents of Hillcrest Bay since at least the late 1970s. (Tr. I at 92.) In light of this concern, APS's Parker Area Manager, Donald Wilson, has tried to keep HBI apprised of all of the APS work to be done in Hillcrest Bay and of the reason for it. (Tr. I at 92.)
- In approximately 2004, HBI approached Mr. Wilson about underground conversion 27. within Hillcrest Bay, with the intent to use an improvement district process. (Tr. I at 92.) APS collected a design deposit from HBI, which was the original basis for preparing the underground cost estimate. (Tr. I at 92-93.) At the same time, APS prepared a cost estimate for the overhead system. (Tr. I at 93.)
- In March 2005, APS determined that, as need and opportunity arose, APS would 28. replace the rear-lot overhead facilities with front-lot overhead facilities because of difficult access to the rear-lot facilities; the increasing age of the facilities; concern about being able to maintain and upgrade the facilities in the future; and a recent change in APS policy for meters to be at the front corner of the property, 11 which makes it more difficult to serve properties from the rear. (Tr. I at 51-52: Tr. II at 364-65.) APS created a detailed map showing how a new overhead system would likely be built ("overhead plan"). (See LFE I A-12.) Per the overhead plan, APS would replace 42 existing poles with 42 steel poles that would provide front-lot service. (See id.) After looking at the cost estimates for the overhead plan and for underground conversion, APS determined that underground conversion would be slightly less expensive to APS, with the customer providing the trenching, conduit, and backfill. (Tr. I at 52.)
 - On April 1, 2005, APS wrote a letter to HBI indicating that HBI and APS had been 29.

This provision is included in an APS electric service requirements manual specification. (Tr. II at 365.)

DECISION NO.

Like General Order U-48, the Commission's current rules require underground installation for extensions of single phase electric lines necessary to furnish permanent electric service to new residential buildings or mobile homes within a subdivision in which facilities for electric service have not yet been constructed, except where underground installation is not feasible from an engineering, operational, or economic standpoint. (A.A.C. R14-2-207(E)(1).)

1 dis 2 um 3 co 4 res 5 tha 6 gro 7 tha 8 ea 9 fur 10 do 11 HI 12 to

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

discussing the process and costs to replace the existing overhead facilities in Hillcrest Bay with an underground system; that HBI had advanced funds to cover the estimated costs to prepare detailed construction drawings and cost estimates for the APS portion of the work; that HBI would be responsible for providing trenching, conduit, backfill, transformer pad sites, and surface restoration; that APS would provide, and HBI would be responsible for installation of, the transformer pads and ground rods at each transformer site; and that HBI and/or individual owners would be responsible for the conduit from the transformer to the front-lot meter locations and the meter pedestals or panels for each individual home as well as reconnecting the home to the new meter panel. (Ex. I A-2.) APS further stated in the letter that APS would not require a contribution from HBI for the work to be done and that, after the underground facilities were installed and energized, the amounts advanced by HBI for preparation of design drawings and estimates would be refunded, and HBI would be eligible to receive a conduit reimbursement of \$23,472.80. (Id.) Mr. Wilson testified that this letter was not created in the context of establishment of an UCSA. (Tr. I at 56.)

- 30. In 2005, Verizon procured special funding specific to the 2006 year, and an agreement was in place for HBI to do trenching and placement of conduit and for Verizon to absorb the costs of transferring its facilities from overhead to underground. (Tr. I at 133.) Once the process went beyond 2006, that special funding was no longer available, as it was not carried over as a budget item to the 2007 year. (Tr. I at 134, 136.)
- 31. According to Mr. Wilson, the improvement district process "fell apart" because HBI had used the statute for a transmission improvement district rather than a distribution improvement district. (Tr. I at 93.) Mr. Wilson stated that that is when it was determined to pursue the statutory process for establishment of an UCSA. (Tr. I at 93.)
- 32. John Sears, Chairman of HBI's Underground Conversion Project and an owner, testified that the underground utility district was formed after HBI had a hearing before the county supervisors. (Tr. I at 153.) Mr. Sears testified that HBI had relied on cooperation from both APS and Verizon at that time, but that in approximately July 2006, Verizon e-mailed APS that it would no longer participate in the underground district and that if APS abandoned the lines, Verizon was entitled to use the poles and would leave their lines on the poles. (*Id.*) According to Mr. Sears, that

DECIGIONA

is what ended the first effort to convert to underground service. (*Id.*) Mr. Sears testified that the plan to use the current statutory process to establish an UCSA was suggested by then-La Paz County Supervisor Cliff Edey, at a meeting held at the APS office that included HBI's Board, Mr. Wilson, and some owners, as a method that would compel both PSCs to participate. (Tr. I at 154.)

Categories of Costs for the UCSA

- 33. There are three categories of costs that would result from establishment of the UCSA and for which owners are responsible to pay: (1) public costs, (2) service costs, and (3) private costs.
- Public costs are the costs attributable to converting the facilities in public places¹² and are assessed on each parcel based upon its square footage. (See A.R.S. §§ 40-342(D), 40-347(B).)

 The estimated public costs are included in the PSCs' joint report.
- 35. The service costs for electric service are the actual costs of converting facilities from the public place to the point of delivery on a parcel. (See A.R.S. § 40-347(A)(4).) The service costs for telecommunications service are the actual costs of converting facilities from the public place to the connection point within the house or structure on a parcel. (See id.) The estimated services costs are included in the PSCs' joint report.
- 36. Private costs are the actual costs of converting electric facilities beyond the point of delivery on a parcel to the service entrance for a structure on the parcel. (See A.R.S. § 40-348.) Private costs are the sole responsibility of the owner, cannot be financed with the PSCs, and are not included within the PSCs' joint report. (See id; A.R.S. §§ 40-347, 40-342(F).)

The UCSA and Commission Process

The UCSA process was initiated by HBI in 2006 and has been pursued ever since by HBI and Mr. Sears, who provides his services as Chairman of HBI's Underground Conversion Project on a purely unpaid and volunteer basis. (See, e.g., Tr. I at 151.) Most of the signatures for the first petition were gathered at the annual HBI homeowners meeting, although those owners who did not attend had petition forms sent to them. (Tr. I at 155.) One of the things that induced owners to sign the first petition was that it would enable HBI to receive a refund of the \$28,000 that HBI had

12 See note 1.

advanced to APS for engineering drawings. 13 (Tr. I at 155.)

- On November 21, 2006, APS received the first petition, requesting that APS and Verizon make a study of the costs related to the establishment of the "Hillcrest Bay Underground Conversion Service Area," for which the following legal description was provided: "Hillcrest Bay Mobile Manor, a Subdivision of SE1/4 SE1/4 Section 14, T11N, R18W G&SRB&M, excluding Tract C & Lot #1, (that are located across the highway), La Paz County, Arizona." (Ex. I A-1.) The first petition included signatures from the owners for 152 of 240 parcels in Hillcrest Bay. (See id.) The owners signing the first petition comprised 63.33 percent of owners, who owned 61.47 percent of the total square footage of Hillcrest Bay. A copy of the map accompanying the first petition is attached hereto and incorporated herein as Exhibit A. A table showing the square footage of each parcel and the signatures obtained for the first petition is attached hereto and incorporated herein as Exhibit B.
- 39. APS presented the first petition to the La Paz County Assessor for verification that the signatures were correct for the parcels indicated. (Tr. I at 45.) After APS received the first petition back from the La Paz County Assessor, APS evaluated the first petition and determined that the signatures exceeded the 60-percent threshold for both owners and square footage. (Tr. I at 45-46.)
- 40. On March 21, 2007, 120 days after receiving the first petition, APS and Verizon mailed each owner other than La Paz County a letter including "estimated costs to be paid to APS and Verizon for conversion of overhead electric and communication facilities to underground facilities" for the owner's parcel and stating that copies of the joint report of the cost study were available for review at the APS Parker office and from Verizon by appointment. (Ex. I A-1.) For 86 of the parcels, the total cost estimate provided on the letter exceeded the sum of the individually listed costs on the letter. (*Id.*) Combined, the overstated estimates totaled approximately \$147,000. (*Id.*)
 - 41. Also on March 21, 2007, APS and Verizon mailed each owner other than La Paz

APS has refunded the \$28,000 design deposit to HBI. (Tr. 1 at 167.)

As will be discussed below, this legal description included 240 parcels, including Parcel 274.

There is no indication that the signatures on the first petition forms were witnessed or notarized. (Ex. I A-1.) Each is stamped "Verified by Hillcrest Bay Inc. Homeowners Assoc." and has an accompanying signature near the stamp. (Id.)

3

4

5

7

6

8

9 10

11

12

13

14

15

16

17 18

19 20

21

23

22

24 25

26

27

28

County a copy of the joint report of that date. (Ex. I A-1.) The joint report showed a total APS public cost of \$601,441.29, a total Verizon public cost of \$851,547.20, a total APS service cost of \$161,108.46, a total Verizon service cost of \$393,908.28, and a grand total of \$2,008,005.23.16

The cover letter to the joint report explained that a second petition needed to be 42. presented to the PSCs, who would then request the Commission to order work to proceed. (Ex. I A-1.) The letter also stated that after completion of the work, each property owner would be assessed a pro rata share of the actual public area costs plus the actual conversion cost of the services on the owner's individual property, not to exceed the amount shown in the joint report, and that these amounts, if unpaid within the specified time frames, would be secured by a lien on the property and financed by the PSCs for a period not to exceed 15 years, with interest not to exceed 8 percent, as specified by the Commission. (Id.) The letter also stated:

> Each property owner is responsible for the upgrades and/or changes on their property to accept underground utility services. For the electrical service this may include modification or replacement and/or relocation of the service entrance (meter loop) and new wiring into the home. For telephone this may include new wiring to the home from the existing or a relocated demarcation point.

(Id.) The letter did not provide any estimated cost figures for these upgrades/changes, which are private costs. 17 (See Tr. I at 50-51.)

- HBI sent the estimated private costs for each parcel to the owners in letters included in 43. the same envelope in which the petition forms for the second petition were sent. (Tr. I at 169.) The private costs for the entire proposed UCSA totaled \$902,527. (LFE I A-11.)
- On June 18, 2007, 89 days after the joint report was made available, HBI submitted to 44. APS a second petition. (Ex. I A-1.) HBI stated in its cover letter that the second petition included signatures for 153 lots, representing 64.2 percent of 238 parcels. (Id.) The "Hillcrest Bay Property

The electric facilities from meter panel to meter are generally considered to be customer equipment, and APS does not work on those facilities beyond the actual meter itself. (Tr. I at 53-54.)

The joint report also showed, on its first page, a total APS public cost of \$601,441.50 and a total Verizon public cost of \$851,547.17. For the 86 parcels that received overstated estimate totals in the letters sent to owners, the joint report also included the overstated estimate totals, although the total APS public conversion cost and the total APS service cost provided in the joint report did not include the overstated amounts. (Ex. I A-1.) The overstated amounts resulted from a hidden column in the APS spreadsheet for parcels that had APS lot conversion costs, to allow APS to perform some additional calculations behind the scenes; the hidden figures were inadvertently added into the grand total for each of the affected parcels. (Tr. I at 50.)

Owner List" included with the second petition lists 240 parcels, including Parcel 274, and includes a note stating that "Parcel 310-32-274 is owned by La Paz County which has declined to voluntarily participate in the Underground Service Conversion Area." (*Id.*) The signatures submitted with the second petition actually represented 152 of 240 parcels, or 63.33 percent of the owners, and 59.99 percent of the square footage of Hillcrest Bay. (*Id.*) Exhibit B, attached hereto, shows the parcels for which signatures were obtained in support of the second petition. The second petition submittal included the same legal description for the UCSA and the same map of the UCSA as had the first petition submittal.

- 45. APS submitted the second petition to the La Paz County Assessor's Office to verify that the signatures were valid for the indicated parcels and then proceeded with calculations on percentages. (Tr. I at 54-55.) APS concluded that the second petition met the 60-percent threshold for both owners and square footage. (Tr. I at 55.)
- 46. On November 26, 2007, 161 days after the second petition was received, ²⁰ APS and Verizon filed with the Commission a joint petition to establish an UCSA pursuant to A.R.S. § 40-343(B) for Hillcrest Bay, using the same legal description and same map of the proposed UCSA as had been used in the first and second petitions. (Ex. I A-1.) As described in the joint petition and shown in the accompanying map, which is attached hereto as Exhibit A, Hillcrest Bay includes La Paz County Parcels 310-32-002 through 310-32-274 ("Parcel 002 through Parcel 274"), plus "Tract B," which has been identified by number 91312703. ²¹
- 47. Also on or around November 26, 2007, APS and Verizon each recorded with the La Paz County Recorder's Office a Notice of Proposed Lien for the costs of conversion for each parcel

The signatures represented 802,765.35 SF of the total 1,337,983.42 SF of the proposed UCSA.

There is no indication that the signatures on the second petition forms were either witnessed or notarized. (Ex. I A-

This filing was made 101 days later than the 60-day deadline for filing under A.R.S. § 40-343(B). Prior Commission Decisions have established that the time requirements of A.R.S. §§ 40-342 and 40-343 are desirable but not mandatory in the absence of some tangible harm to other parties. (See Decision No. 57051 (August 22, 1990); Decision No. 55490 (March 19, 1987).) No testimony or other evidence has been presented to indicate that harm resulted from the PSCs' failure to file the joint petition with the Commission within 60 days after receiving the second petition.

Parcel 274 appears on the map as "Tract A." (See Exhibit A hereto.) A note on the joint cost report included with the joint petition states: "Parcel 91312703 is centrally assessed property, property record includes Tract B and Tract C. This spreadsheet includes only square footage for Tract B as Tract C was excluded from the Underground Conversion Service Area."

in the proposed UCSA other than Parcel 274. (Ex. I A-1; Tr. I at 55-56.)

- 48. On December 3, 2007, a telephonic procedural conference regarding the scheduling of the hearing in this matter was held. APS, Verizon, and the Commission's Utilities Division ("Staff") participated through counsel. During the procedural conference, it was determined that the hearing would be scheduled for January 18, 2008, at 9:30 a.m., at the Commission's offices in Phoenix.
- 49. On December 6, 2007, the Commission issued a Procedural Order scheduling the hearing in this matter for January 18, 2008, 53 days after receipt of the joint petition. Among other things, the Procedural Order also prescribed the form and language of the notice to be published and posted by the PSCs; required the PSCs to cause notice to be posted by December 19, 2007, for a period of at least 30 days; required the PSCs to cause notice to be published once, by December 29, 2007, in a newspaper published in La Paz County and of general circulation within the proposed UCSA; required objections or withdrawals of signature to be filed with the Commission by January 8, 2008; and required the PSCs to provide the Commission with an updated service list and to identify the governmental agencies having rights in public places within the proposed UCSA. The Commission's Hearing Division mailed copies of the Procedural Order to the owners identified in the joint petition, including La Paz County.
- 50. On December 11, 2007, APS and Verizon filed a joint response to the Procedural Order, identifying La Paz County as the only governmental agency with rights in public places within the proposed UCSA, providing names and addresses for service to La Paz County, and providing corrections to the service list.
- 51. On December 12, 2007, the Commission's Hearing Division sent the December 6, 2007, Procedural Order to the La Paz County Assessor and the La Paz County Attorney.
- 52. On December 18, 2007, APS and Verizon filed additional corrections to the service list.
- 53. On December 19, 2007, APS and Verizon filed corrections to the service list, based upon review of a more recent version of the La Paz County Assessor's records, and the Commission's Hearing Division re-sent the December 6, 2007, Procedural Order to the owners for whom corrected addresses had been provided.

54.

the following three locations in Hillcrest Bay: (1) on Parcel 002, on the south side of Bay Shore Drive, the entry street into the subdivision; (2) on Parcel 273, on the entry gate to Hillcrest Bay's refuse collection area; and (3) on Parcel 057, on the end of the community mailboxes, which are visible from the entry street. (LFE I A-14.) Notice was also posted in the public library at 1001 Navajo Avenue in Parker, Arizona. (*Id.*) The notices remained posted until February 1, 2008. (*Id.*)

On December 19, 2007, 30 days before the hearing date, public notices were posted at

- On December 27, 2007, APS and Verizon sent letters to all of the owners other than La Paz County providing them with notice of the Commission hearing date and location, the deadline and requirements for filing withdrawals and objections,²² and the estimated costs attributable to their individual parcels. (Ex. I A-5.) For the 86 parcels that had previously received overstated total cost estimates, the letters provided corrected cost estimates.²³ (*Id.*) For two of the 86 parcels (Parcels 183A and 184), the letters also provided reduced service cost estimates, and for another one, the letter corrected a very minor math error. (*Id.*; Ex. I A-4; Tr. I at 73.) The letters did not include the private cost estimates for each parcel. (*See* Ex. I A-5.)
- Also on December 27, 2007, a two-part telephonic procedural conference was held at the request of APS and Verizon. APS, Verizon, and Staff participated through counsel and stated during the first part of the procedural conference that the *Parker Pioneer* newspaper had failed to publish notice on December 26, 2007, as arranged, and would not be published again until after the notice publication deadline of December 29, 2007. APS and Verizon were instructed to obtain additional information and report back later that day. During the second part of the procedural conference, APS and Verizon reported that publication in the *Arizona Republic* could be arranged for December 29, 2007, and that there was not another newspaper generally circulated in La Paz County that could publish by that deadline. APS and Verizon were directed to have notice published in the *Arizona Republic* on December 29, 2007; to have notice published in the *Parker Pioneer* on January 2, 2008; and to file a joint document explaining the plan to resolve the publication problem and

The letters did not include a reference to A.R.S. § 40-345. (See Ex. I A-5.)

During its review, APS also identified six parcels for which APS had understated cost estimates, for a total understatement of \$4,790.71, but APS did not increase the affected owners' cost estimates to correct those errors, because of the statutory provision prohibiting the PSCs from charging costs in excess of their original estimates. (Ex. I A-4; Tr. I at 73, 77.)

whether the plan complied with the A.R.S. § 40-344(B) requirement for publication.

- 57. Public notice was published in the *Arizona Republic* on December 29, 2007, 20 days before the hearing, and in the *Parker Pioneer* on January 2, 2008, 16 days before the hearing.
- 58. On December 31, 2007, Erna L. Davis, the owner of Parcel 208, filed with the Commission a handwritten, signed, and dated letter requesting withdrawal of her name and her husband's name from the second petition, as her husband's death in August 2007 rendered her unable to afford the high expense of the underground cable. Ms. Davis's request to withdraw her signature reduced the number of owners supporting the UCSA from 152 to 151 (62.92 percent) and the square footage of those owners from 802,765.35 SF to 798,640.64 SF (59.69 percent).
- 59. On January 4, 2008, APS and Verizon made a joint filing stating that notice had been published in the *Arizona Republic* on December 29, 2007, and in the *Parker Pioneer* on January 2, 2008; that APS had mailed a letter, including the notice required to be published, to all of the owners on December 28, 2007; and that the December 29, 2007, publication in the *Arizona Republic* had met the notice requirement of A.R.S. § 40-344(B).
- 60. Also on January 4, 2008, APS and Verizon made a joint filing that included Affidavits of Publication; stated that APS and Verizon should each be assessed a 50% share of the costs of mailing under A.R.S. § 40-344(I); and included a copy of the agenda and a proposed resolution for the January 7, 2008, La Paz County Board of Supervisors meeting, at which the Board was to consider the proposed resolution approving establishment of an UCSA for utility facilities within Hillcrest Bay.
- 61. On January 7, 2008, the Board of Supervisors of La Paz County passed La Paz County Board of Supervisors Resolution No. 2008-01, approving the establishment of an underground conversion service area for utility facilities within Hillcrest Bay. APS and Verizon filed a copy of the Resolution on January 11, 2008.
- 62. On January 14, 2008, Staff filed a Staff Report recommending approval and recommending financing of the underground conversion costs for 15 years at the lower of the prime rate or the statutory maximum of 8 percent. Staff stated that it had toured Hillcrest Bay with APS and Verizon in December 2007 in preparation for creating the Staff Report.

- On January 18, 2008, a full evidentiary hearing was held before a duly authorized 63. 1 Administrative Law Judge of the Commission at the Commission's offices in Phoenix, Arizona. 2 Commissioner Kristin K. Mayes attended and participated in the examination of several witnesses. 3 APS, Verizon, and Staff appeared through counsel and presented evidence and testimony. Testimony 4 for APS was received from Donald Wilson. Testimony for Verizon was received from Bill Kearns, 5 District Manager for Verizon's Sunbelt District. Testimony for Staff was received from owner John 6 Sears and from Richard Boyles, Staff Engineer. In addition, testimony pro se was received from the 7 following seven owners: Carlson Loftis, Thomas Lorch, Robyn Stein, Teddie Lorch, Terence 8 Bitrich, Steven Benton, and Nando Haase. Mr. Loftis also requested to participate as a party and participated in the cross-examination of APS, Verizon, and Staff witnesses. HBI did not appear at the 10 first hearing. At the conclusion of the hearing, APS, Verizon, and Staff were directed to file a 11 number of LFEs as well as briefs regarding the standard for approval of an UCSA under A.R.S. § 40-12 Staff was also directed to include in its brief information regarding Hillcrest Water 13 Company's obligation to obtain approval for the debt that would be incurred if the UCSA were 14 approved and the impact that would have on this matter.24 The record was left open pending receipt 15 and consideration of the LFEs. 16
 - 64. On February 19, 2008, APS, Verizon, and Staff filed a joint closing brief regarding the standard for Commission approval of an UCSA; APS and Verizon filed their LFEs; and Staff filed a supplemental brief regarding Hillcrest Water Company.
 - 65. On February 20, 2008, Verizon filed a supplement to its LFEs.
 - 66. On February 22, 2008, a Procedural Order was issued requiring APS, Verizon, and

26

27

28

17

18

19

20

21

²³²⁴

The Hillcrest Water Company is a Class D water utility that received its Certificate of Convenience and Necessity in Decision No. 41064 (Dec. 23, 1970). The Hillcrest Water Company owns Tract B, which is included within the proposed UCSA. The joint report shows that the Hillcrest Water Company would be assessed \$6330.14 in public costs and \$0 in service costs if the UCSA were established. Staff testified that, to Staff's knowledge, Hillcrest Water Company had not yet applied to the Commission for approval to incur the debt that would be incurred from participating in the UCSA. (Tr. I at 190-91.) Staff testified that Hillcrest Water Company could incur the cost as a normal operating expense unless it is financed, in which case a financing application would be required. (Tr. I at 191.) Staff conducted an unaudited review of Hillcrest Water Company's finances based on its 2006 annual report and determined that the assessment would be treated as paid in capital if paid in full and that Hillcrest Water Company would be able to service the debt if it chose to finance the UCSA costs. Staff concluded that the Commission could (1) approve the encumbrance as part of the approval of the UCSA, or (2) if the Commission desires a more in-depth review of Hillcrest Water Company's financial position, order Hillcrest Water Company to file a financing application.

Staff each, jointly or severally, to file a brief analyzing the meaning of the language from A.R.S. § 40-346(A) regarding owners of no more than 40 percent of the real property within the UCSA, or no more than 40 percent of the owners of real property, having <u>not</u> objected to the formation of the UCSA, as that issue had not been addressed in the joint closing brief. In addition, APS and Verizon were directed to file a map showing all of the parcels within the UCSA, including Parcel 310-32-274, along with an explanation of the prior ownership of Parcel 310-32-274, and APS was directed to file responses to several questions.

- 67. On March 21, 2008, APS filed responses to the questions specified in the Procedural Order; APS and Verizon filed a joint supplemental closing brief; and Staff filed a brief.
- 68. On April 11, 2008, APS filed a Notice of Errata correcting provisions in the joint supplemental closing brief.
- 69. On May 16, 2008, a ROO was issued concluding that the cost of conversion was not economically feasible for the owners affected and that the joint petition should be denied.
- 70. On May 27, 2008, timely exceptions to the ROO were filed by owners Tom Lorch, Philip Garcia, and John Sears. Between June 11 and 26, 2008, late exceptions were filed by Arthur Wood, Brian Wood, Vern and Loretta Kraus, Filmore Anderson, Thomas and Cynthia McGregor, Bill Lambrose, and Terence Bitrich.
- 71. At the Open Meeting on July 1, 2008, the Commission discussed the ROO at length and ultimately determined that it should be pulled from the agenda without decision to allow the parties to file additional information in the docket going to the issue of the economic feasibility of the UCSA for the owners. The Commission directed the Hearing Division to issue a Procedural Order keeping the record in this matter open for 10 months to allow the parties to make the filings detailed in Hatch-Miller Proposed Amendment #1 and stating that the ROO would be placed back on an Open Meeting agenda after 10 months if the parties failed to make such filings.
- 72. On July 3, 2008, a Procedural Order was issued providing that the record in this matter was to remain open to allow for the creation of a more fully developed evidentiary record on the issue of economic feasibility for the owners; requiring APS and Verizon to work together with the owners to determine whether a mutually beneficial, economically feasible plan to underground the lines in

13

14

15 16

17 18

19

20

2122

23

24

2526

2728

Hillcrest Bay could be created; requiring the owners to cooperate with APS and Verizon and each other in furtherance of the effort to determine whether such a plan could be created; requiring the owners, to the extent possible, to work together to reach an agreement and make a single joint filing in the record or, if that proved impossible, requiring groups of owners supporting and opposing the UCSA to organize their efforts to the extent possible, to make joint filings on each side of the issue; allowing APS, Verizon, and owners to file, by May 1, 2009, documentation going to the issue of economic feasibility of the UCSA for the owners, with prescribed minimum requirements for any documentation filed by UCSA supporters; requiring the Hearing Division to determine the necessity for additional hearing if additional filings contemplated by the Procedural Order were made by May 1, 2009; and directing that the ROO would be considered by the Commission at a subsequent Open Meeting if the UCSA supporters failed to file the minimum documentation prescribed by May 1, 2009.

- 73. On April 1, 2009, a Notice of Appearance was filed by counsel for HBI.
- 74. On May 1, 2009, APS filed an Economic Feasibility Update for the UCSA.
- 75. Also on May 1, 2009, HBI filed Updated Documentation in Support of UCSA. The Updated Documentation included information regarding an HBI financial assistance program for low-income residents; updated cost estimates prepared by Tades, Inc. ("Tades"), one showing an overall reduction of \$51,093 and the other showing an overall reduction of \$665,124;²⁶ a letter

Regarding the additional documentation to be provided, the Procedural Order of July 3, 2008, stated:

IT IS FURTHER ORDERED that APS, Verizon, and Hillcrest Bay owners may file, no later than May 1, 2009, documentation going to the issue of the economic feasibility of the UCSA for the Hillcrest Bay owners. If the parties supporting the UCSA make such a filing, they shall ensure that it contains at least the following: (1) a document detailing the financial assistance to be provided to individual Hillcrest Bay owners, who shall be identified by name and parcel number; (2) amended cost estimates showing for each parcel the public costs, service costs, and private costs resulting from the UCSA; (3) any reliable evidence establishing that the UCSA will result in increased property values; (4) a new petition listing each parcel, indicating whether the owner/s of each parcel support or oppose the UCSA, and including the dated signature of an owner of each parcel; and (5) a list of the Hillcrest Bay owners of record generated by the La Paz County Recorder's Office within 30 days before the documentation is filed with the Commission. Such a filing may also include demographic and income information concerning the Hillcrest Bay property owners; documentation of property values; documentation of which parcels are undeveloped, developed but vacant, full-time residences, vacation residences, and rental properties; and other documentation relevant to the issue of economic feasibility.

Official notice is taken of the copies of these estimates that were filed by HBI with a Notice of Errata on May 8, 2009. The copies accompanying the Notice of Errata contain the same information as, but are much easier to read, than are the copies that were provided by HBI as part of Exhibit H-1.

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

written by Philip Garcia regarding the impact of the UCSA on property values; a tabulation of the results of a new petition of owners showing that 193 responses to the new petition had been received, with 127 of them in support and 66 opposed; an updated list of owners from the La Paz County Recorder's Office; information regarding histoplasmosis, psittacosis, and cryptococcosis from the website of the Centers for Disease Control and Prevention ("CDC"); and photographs showing utility poles completely enveloped by patio and deck surfaces and wires hanging over patios and decks. HBI did not submit the actual signed new petition response forms.

76. On May 8, 2009, HBI filed a Notice of Errata that included complete copies of the updated cost estimates previously filed.

77. On May 11, 2009, a Procedural Order was issued stating that although the Updated Documentation filed by HBI did not comply in all respects with the requirements of the Procedural Order of July 3, 2008, it did provide sufficient new information to make it appropriate to hold an additional hearing specifically related to the issues of economic feasibility, the current level of owner support for the UCSA, and the standard for Commission approval of the UCSA. The Procedural Order required APS, Verizon, HBI, and Staff to file pre-hearing briefs, and stated that any other owner desiring to do so could file a pre-hearing brief, analyzing (1) whether it is appropriate for the Commission to consider updated cost estimates in determining whether the cost of conversion is economically feasible, when A.R.S. § 40-346(A) specifically refers to economic feasibility based on the cost of conversion reflected in the joint report prepared pursuant to A.R.S. § 40-342; (2) whether it is appropriate for the Commission to consider withdrawals of signature and/or objections to the UCSA received later than January 8, 2008, in considering whether the standard for approval of the UCSA is met, when A.R.S. § 40-344(A) provides that an owner who desires to object or withdraw a signature supporting the UCSA shall file the objection/withdrawal no later than 10 days before the date set for hearing; (3) the current level of support for the UCSA among the owners, both as to number of parcels and as to square footage, and how it was determined; and (4) whether the Commission can and should approve the UCSA if the current level of support is less than 60 percent for either number of parcels or square footage. The Procedural Order required any owner desiring to participate as a party at hearing to file a notice to that effect; required APS and Verizon to publish

7

11

10

28

and post notice of the additional hearing; required HBI to submit the actual new petition responses for which the tabulation had been filed on May 1, 2009; scheduled a hearing for July 21, 2009; and established other procedural requirements and deadlines.

- On May 22, 2009, HBI filed copies of the signed new petition responses. 78.
- On June 24, 2009, APS and Verizon filed proof that notice had been published on May 79. 27, 2009, in Today's News-Herald, a newspaper published in Lake Havasu City, in Mohave County, and of general circulation within Hillcrest Bay; that notice had been posted on June 5, 2009, in three public locations within Hillcrest Bay; and that APS was monitoring the posted notices to ensure that they would remain posted through July 22, 2009.
- On July 6, 2009, APS and Verizon filed a joint brief, HBI filed a brief, and Staff filed 80. a brief in response to the Procedural Order of May 11, 2009.
- On July 21 and 22, 2009, a full evidentiary hearing was held before a duly authorized 81. Administrative Law Judge of the Commission at the Commission's offices in Phoenix, Arizona. APS, Verizon, Staff, and HBI appeared through counsel. The following 12 owners appeared pro se to support the UCSA: Jane Sears, John Sears, Robert Nielson, Ron Nelson, Sylvia Nelson, Robyn Stein, Grace Babcock, Tom Lorch, Teddie Lorch, Philip Garcia, Terence Bitrich, and Carole Jones. The following 12 owners appeared pro se to oppose the UCSA: Joy Muzic, Lynne Muzic, Nando Haase, Billie Dodson, Johnny Dodson, Wayne Dunham, Janet Calvin, Steve Benton, Harlayne Bond, Judith Wilson-Kawagoye, Marjorie Ward, and William Bond. HBI provided the testimony of Mr. Sears and of Chris Kellogg, Senior Vice President of Tades. APS provided the testimony of Mr. Wilson. Verizon provided the testimony of Mr. Kearns. Staff provided the testimony of Armando Fimbres, Staff Telecommunications Analyst. Testimony pro se was provided by owners Mr. Nielson, Ms. Stein, Ms. Babcock, Mr. Haase, Ms. Calvin, Ms. Ward, Mr. Garcia, Mr. Nelson, Mr. Lorch, Ms. Lorch, Ms. J. Muzic, Ms. L. Muzic, Ms. Dodson, Mr. Dodson, Mr. Dunham, Mr. Benton, and Ms. Bond. No owner provided comment without having entered an appearance as a party. During the hearing, official notice was taken of the National Bureau of Economic Research's December 2008 Declaration that the U.S. has been in recession since December 2007; of all owner comments filed in the docket since July 1, 2008; of Decision No. 42189 (June 30, 1972); of the new petitions filed by

HBI on May 22, 2009; of a June 10, 2009, letter written by Thomas L. Mumaw, Senior Attorney for Pinnacle West Capital Corporation, to Chairman Kristin Mayes regarding the unavailability of federal stimulus funding for the electrification of rural, underserved, or unserved areas; and of the existence of Docket No. T-01846B-09-0274 et al., in which was then pending an application for the transfer of Verizon's service area and customer base to Frontier Communications Corporation. In addition, it was announced that the entire evidentiary record in this docket, including that from the first hearing, would be considered in this matter. APS and HBI were directed to file LFEs, and APS, Verizon, Staff, and HBI were directed to file, and other owners were permitted to file, post-hearing briefs and reply briefs regarding (1) the standard for approval and whether it has been met, with a detailed analysis of how the conclusion was reached; (2) how the Commission should interpret the language in A.R.S. § 40-346(A) in light of the double negative therein, which had not been addressed by HBI in its pre-hearing brief; (3) how the Commission should analyze the validity of withdrawals of signature and objections; (4) whether dismissal of the joint petition is appropriate because of the current level of property owner support; and (5) whether, consistent with statutory authority, the service costs for the UCSA can be attributed on a square footage basis as Tades did in one of its updated cost estimates.

- 82. On July 29, 2009, APS filed its LFEs, and HBI filed most of its LFEs. HBI filed its remaining LFE on July 31, 2009.
 - 83. On August 26, 2009, APS, Verizon, Staff, and HBI filed their post-hearing briefs.
 - 84. On September 8 and 9, 2009, APS, Verizon, Staff, and HBI filed their reply briefs.

The Proposed UCSA Area

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

At the time of the joint petition, Hillcrest Bay consisted of 240 parcels with a combined size of 1,337,983.42 square feet.²⁷ Since the joint petition, through consolidation of Parcels 023 and 024 into 024A and Parcels 039 and 040 into 040A, the number of Parcels in Hillcrest Bay has been reduced to 238. (Ex. II H-1.) Of those 238 parcels, approximately 48 house full-time residents, approximately 33 to 37 are vacant lots, and the remaining parcels are used either regularly²⁸

This figure includes the square footage for Parcel 274, which is 40,734.68 square feet in size.

Approximately 102 parcels are used regularly on the weekends, and approximately 10 are used as winter homes. (See Ex. II H-11.)

or sporadically as second homes. (See Ex. II H-11; Ex. II H-8.)

- 86. Parcel 274 is owned by La Paz County due to the failure of its previous owner to pay back taxes. (LFE I A-15.) La Paz County's Interim County Administrator, Donna Hale, stated in a February 2008 letter that La Paz County does not intend to assume the costs relating to the conversion of Parcel 274, which Ms. Hale understood to be \$18,310.89. (*Id.*) Ms. Hale further stated in the letter that she has been told that Parcel 274 has no access and has not been saleable through the tax deed sale process. (*Id.*) Ms. Hale indicated that it would not be feasible to spend taxpayer dollars for improvements on a lot that already appears not to be saleable for back taxes. (*Id.*)
- APS and Verizon assert that Parcel 274 should not be included in the UCSA because it is owned by La Paz County, which will not assume the costs for its conversion; because conversion would not make it more saleable due to its topography and lack of accessibility; and because it will not be benefited by the conversion. APS and Verizon state that they treated Parcel 274 as a "public place," as defined in A.R.S. § 40-341, because it is akin to a right of way and is too steep for construction. Mr. Sears has asserted through a letter to the Commission that Parcel 274 should be excluded from the UCSA under A.R.S. § 40-346(B) as it will not be benefited by the conversion. Staff asserts that while the determination of the UCSA boundaries comes from the owners in the first petition, which is accompanied by a map showing the boundaries, the arguments that Parcel 274 should not be included in the UCSA are reasonable.
- 88. Mr. Wilson testified that there was a period of a couple weeks during which there was a "discrepancy on the actual percentages" on the second petitions due to the inclusion of Parcel 274 in the UCSA. (Tr. I at 95.) Mr. Wilson testified that Parcel 274 is part of the UCSA, although it is considered to be a public area and thus was excluded from the joint report. (Tr. I at 95-96.) According to APS, the public cost attributable to Parcel 274 is \$18,310.89, which does not include a service cost, because Parcel 274 does not have electrical service, and no provision was made for future underground service to it. (LFE I A-15.) In the joint report, APS and Verizon allocated this cost to the other parcels under A.R.S. § 40-347(A)(5). (See Tr. I at 96.)
- 89. The legal description for the proposed UCSA provided with the first petition, second petition, and joint petition includes Parcel 274. (See Ex. I A-1.) Parcel 274 was not expressly

excluded from the legal description, as were both Tract C and Lot #1. (See id.) The map of the proposed UCSA provided with the first petition, second petition, and joint petition also includes Parcel 274, although it is labeled as Tract A on the map. (Id.; Exhibit A hereto.) Mr. Wilson testified that the legal description and map included in the joint petition are accurate depictions of the legal description and map of the proposed UCSA. (Tr. I at 44-45.)

- 90. The Hillcrest Bay Property Owner List, dated March 20, 2007, included as an exhibit to the second petition, lists Parcel 274 and includes a note explaining that Parcel 274 is "owned by La Paz County which has declined to voluntarily participate in the Underground Service Conversion Area." (Ex. I A-1.) This is in contrast to the treatment of the expressly excluded properties: Lot # 1 is not listed, and a note explains that Tract C is excluded from the UCSA. (*Id.*)
- 91. On the joint report, APS and Verizon included a note stating that "Parcel 310-32-274 is owned by La Paz County who has declined to voluntarily participate, therefore this parcel has been deleted from this spreadsheet." (Ex. I A-1.) Mr. Wilson testified that Parcel 274 was excluded from the joint report so that its costs could be attributed to the other parcels based on square footage. (Tr. I at 96.) Regarding Tract C, which was expressly excluded, APS and Verizon included the following note: "Parcel 91312703 is centrally assessed property, property record includes Tract B and Tract C. This spreadsheet includes only square footage for Tract B as Tract C was excluded from the Underground Conversion Service Area." (Ex. I A-1.)
- 92. Mr. Wilson's testimony that Parcel 274 is part of the proposed UCSA is credible, as is Mr. Wilson's testimony that the square footage for Parcel 274 was excluded from the calculations in the joint report so that the costs attributed to its inclusion within the UCSA would be apportioned to the other parcels pro rata by square footage, as permitted under A.R.S. § 40-347(A)(5). We find that Parcel 274 is part of the proposed UCSA.

Benefits Expected To Be Obtained From The UCSA

93. All but one²⁹ of the first petition forms state:

The first petition form signed on October 26, 2006, by Linda Duran, owner of Parcel 263, instead states: "The necessity for the proposed [UCSA] is: due to unsafe poles, low wires, extremely hard access and increasing unreliability due to age and increased load." (See Ex. I A-1.) Mr. Wilson testified that this petition form language was from the original improvement district process that APS had no part in preparing or making comments on and should not have

9

12

10

11

14

13

15 16

17

18 19

20

21

22

23

24

2526

27

28

been included. (Tr. I at 94.) Mr. Wilson testified that he collaborated on the language for the first petition with La Paz County Supervisor Cliff Edey, Mr. Sears, and Verizon. (Tr. I at 93.)

The necessity for the proposed [UCSA] is: Existing overhead facilities intrude into terraced lot views of Lake Havasu and surrounding mountains reducing value of properties. APS anticipates replacement of some overhead facilities in a front lot location to facilitate future maintenance and upgrades. Underground conversion at this time will minimize future investment by the utilities and benefit the property owners by restoring unobstructed views and increased property values.

(Ex. I A-1.) All of the second petition forms include the rationale for the proposed UCSA quoted above. (See id.)

94 A number of owners have testified to their sincere beliefs that the UCSA would result in real benefits to Hillcrest Bay and its owners. At the first hearing, Mr. Loftis, Mr. Lorch, and Mr. Bitrich testified to their beliefs that aesthetics and property values will be increased by the UCSA. (Tr. I at 12, 14-15, 21.) Mr. Bitrich also testified that he believes the poles present a safety hazard that the UCSA would remedy. (Tr. I at 21-22.) At the second hearing, Mr. Nielson testified that the UCSA would provide a better, more beautiful, and safer environment. (Tr. II at 185.) Ms. Stein testified that quality of life will be improved by the UCSA because Hillcrest Bay is a rare community surrounded by natural wildlife on three sides. (Tr. II at 187.) Mr. Garcia testified that undergrounding the lines would remove a "blight on the neighborhood," (Tr. II at 226), which is a "gorgeous" property sitting on the side of a terraced hill, surrounded by a mesa, a wildlife sanctuary, and "a lake that extends for miles," (Tr. II at 241). Mr. Garcia testified that Hillcrest Bay is very desirable and could be a very desirable property for someone to develop, but that a lot of people do not want to own there because they think it looks "tacky," mostly because of the wires, but also because of unattended, rundown, and abandoned looking properties. (Tr. II at 241-42.) Mr. Nelson testified that Hillcrest Bay "has the potential to become the premier spot on Lake Havasu," but that the existing poles and lines harm property values, and additional poles and lines would harm those values further. (Tr. II at 450.)

95. The owners who support the UCSA have cited the following as reasons for their support: (1) APS's assistance with the financing of the UCSA, which is believed to be a one-time-only offer; (2) beautification of Hillcrest Bay; (3) preventing the parking difficulties that would occur

if power poles are moved to the streets; (4) belief that undergrounding of facilities is the norm: (5) cost-sharing with APS and Verizon; (6) increase in property values; (7) improved reliability of electric service: 30 (8) avoidance of escalating maintenance and repair costs of the existing poles in the future; (9) need to replace the aging poles for safety reasons, particularly because of a pole that broke and fell into the street in October 2007; (10) avoiding a mass of lines overhead that would result from having two sets of poles; (11) improved quality of life/ambiance; (12) enhanced safety from removing low-hanging lines;³¹ and (13) eliminating problems related to excessive bird droppings on properties. (Tr. I at 11-23, 176-78; Tr. II at 47.) HBI has also asserted that the cost discounts offered by Tades and the potential for diseases caused by exposure to excessive bird droppings are additional reasons to support the UCSA. (See Ex. II H-1.)

96. As of January 2008, there had been no complaints regarding APS's service or Verizon's service to Hillcrest Bay within the prior two years. (Tr. I at 192-93.) There is no evidence of service complaints since that time.

- 97. APS has made the following seven repairs in the Hillcrest Bay service area from January 2006 through July 2009: (1) on January 7, 2006, a repair to the fence fabric at Buckskin Substation; (2) on July 28, 2006, a repair for an oil leak on Buckskin Substation Transformer Tap Changer; (3) on October 9, 2006, replacement of a leaking 75 kVA OH Transformer; (4) on October 5, 2007, replacement of a broken pole and down guy; (5) on June 30, 2008, replacement of a pole, located at 782 Bay View Drive, that was identified as a potential hazard during pole butt inspections; (6) on July 3, 2008, replacement of a pole, at 2910 Manor View Drive, that was identified as a potential hazard during pole butt inspections; and (7) on November 11, 2008, removal of a pole down guy and anchor at a pole because they were unneeded. (LFE II A-2.)
- 98. APS conducts annual public safety reviews that check for leaning poles, broken down guys, and other things that might create a public safety hazard. (Tr. I at 79; Tr. II at 276.) At the

Robyn Stein testified that she has to reset any electric clocks in her home on a monthly basis, due to power failures. (Tr. I at 18.)

Nr. Sepre testified that Hillered Base has described that Hillered Base has described to the series of th

Mr. Sears testified that Hillcrest Bay has developed slowly over time and that additions such as awnings and decks have been made to existing homes, sometimes making the telephone lines and power lines within reach, such as with a stick or rod, and setting them at eye level. (Tr. I at 177.)

A power pole and line fell in October 2007, sending the pole and line into the street, because the down guy rotted or broke off, and the pole had a defect that caused it to snap and the down guy to cut loose. (Tr. I at 79-80.)

1 ti
2 (7)
3 H
4 in
5 ft
6 pp

time of the first hearing, the next such inspection for Hillcrest Bay was due in March or April 2008. (Tr. I at 79.) Mr. Wilson testified at the second hearing that two inspections had been completed in Hillcrest Bay in 2008 and that no public safety hazards had been identified. (Tr. II at 276-77.) One inspection focused on overhead clearance, and one on the condition of pole butts. (*Id.*) Mr. Wilson further testified that the 2009 inspection in Hillcrest Bay had already been completed, revealing no public safety issues. (Tr. II at 277, 339.)

8 | 1 | 9 | 6 | 10 | 11 | 11 | 12 | 1

13

7

99. Mr. Kellogg, who has been in the construction business for 23 years, testified that he believes there are code violations where 7200-volt lines are within reach if a person reaches far enough. (Tr. II at 128, 163-64.) He attributed this to the addition of structures that encroach the lines, such as where people have built patios and decks around power poles. (See Tr. II at 163-64.) He also opined that those added structures do not comply with local building codes. (Tr. II at 163.) He believes that these are safety issues and in violation of the National Electrical Safety Code. (Tr. II at 163-64.)

27

28

easements or rights of way. (Tr. II at 369.) An APS project has commenced to identify properties with such encroachments and had already identified approximately 46 such properties as of the second hearing. (Id.) APS has not determined what to do about the encroachments, but the next step is to resolve them. (Id.) According to Mr. Wilson, there are three possible resolutions for an encroachment: (1) the owner could obtain a permission-of-encroachment permit from APS, although APS does not generally grant these; (2) the owner could pay for removal of the encroaching structure; or (3) the owner could pay for the APS facilities to be moved. (Id.) If an owner were to choose the third option, the owner could also pay to have the lines reinstalled underground. (Tr. II at 369-70.) Mr. Wilson recalled one previous instance of encroachment in Hillcrest Bay, when a deck was built, resulting in inadequate clearance. (Tr. II at 370.) On that occasion, APS raised the primary line at APS expense, but Mr. Wilson believes that both the owner and HBI were notified at that time that future encroachments would be rectified at owner expense. (Id.)

101. Hillcrest Bay is served by Buckskin feeder #01 and has the following statistics related to electrical outages for the years 2002-2009 (through July 20, 2009):

1	Year	SAIFI ³³	CAIDI	SAIDI
2			(hours) ³⁴	(hours) ³⁵
_	2002	3.00	3.60	10.80
3	2003	0.96	0.13	0.13
	2004	0.00	0.00	0.00
4	2005	4.84	1.56	7.56
5	2006	9.31	1.85	17.25
	2007	2.17	1.12	2.43
6	2008	3.00	0.62	1.85
١	2009	11.00	0.87	9.54

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

(LFE II A-3.) APS's outage database shows that for the period of 2002 through 2007, 95 percent of customer interruptions and 95 percent of outage duration were caused by loss of the transmission source rather than by the distribution feeder. (Id.) The Buckskin substation that feeds Hillcrest Bay is served by a Western Area Power Authority ("WAPA") transmission line, running from Parker Dam to Bagdad, that had a significant number of outages, both planned and unplanned, in 2006; thus, the poor reliability for Hillcrest Bay that year had to do with transmission problems rather than the Hillcrest Bay facilities. (Tr. I at 101, 114.) In 2008 and 2009, 100 percent of customer interruptions and outage duration were caused by loss or planned interruption of the non-APS transmission sources. (LFE II A-3.) Prior to the first hearing in this matter, as a result of APS's request to have a circuit breaker installed to the east of Hillcrest Bay to isolate it and another subdivision from most of the outages that were occurring, WAPA performed a survey and determined that seven miles of that WAPA line need to be replaced. (Tr. I at 116.) APS and WAPA have begun Phase 1 of that project, which includes providing a second transmission circuit that will isolate Hillcrest Bay and should eliminate almost all transmission source outages. (LFE II A-3.) Work on the project was expected to resume in October 2009 and to be completed early in 2010.³⁶ (Id.) APS is also building from its Colorado substation, about three miles west of Hillcrest Bay, an underbuilt three-phase feeder to Hillcrest Bay, which will eliminate use of the Buckskin substation. (See Tr. I at 116; Tr. II at 366-67.) APS anticipates that these changes will result in a very significant improvement in reliability for

SAIFI means system average interrupt frequency index, the average number of outages greater than five minutes per customer. (Tr. I at 100.)

⁴ CAIDI means customer average interruption duration index.

³³ SAIDI means system average interruption duration index.

APS ceased work for a period because of a request from the U.S. Fish and Wildlife Service related to migratory bird issues. (Tr. II at 366.)

Hillcrest Bay. (See Tr. I at 117.)

2

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

as broadband over power lines, linked to the underground conversion that may be of benefit to endusers. (Ex. I A-9.) Rather, the benefit to end-users would be reflected in the reliability of a new system, whether overhead or underground. (*Id.*) Undergrounding will not substantially improve reliability in Hillcrest Bay. (*Id.*) Undergrounding would reduce the likelihood of wind damage to the facilities, (Tr. II at 383), although the APS repair records for 2006 through 2009 do not seem to support a conclusion that wind damage is a problem for the area, (LFE II A-2).

- 103. APS and Verizon have not completed a study regarding how much or to what degree the underground conversion would improve property values for the parcels in Hillcrest Bay. (Tr. I at 76.) Mr. Wilson testified that the only way to determine that would be through hiring an appraiser. (Tr. I at 76.) Mr. Wilson testified that he personally agrees that the property values would be increased by the underground conversion. (Tr. I at 76.)
- Mr. Garcia, an owner and retired appraiser with degrees in finance, who worked as a 104. business valuation appraiser for 25 years and held a California broker's license for 35 years, performed a preliminary analysis of the possible impact to home values from the UCSA, concluding that, in a normalized real estate market, undergrounding of the utility lines in Hillcrest Bay could increase property values for 80 percent of the properties in Hillcrest Bay by 5 percent to 15 percent. (Tr. II at 222-24; Ex. II H-1.) Mr. Garcia acknowledged, however, that the studies he reviewed estimated the highest increase at 7 percent. (Tr. II at 240.) Mr. Garcia testified that he is very confident in the mean of 5 percent to 7 percent. (Id.) He believes that Hillcrest Bay would see a greater increase in value because of the unique nature of the property, as very little property in La Paz County is privately owned. (Id.) Mr. Garcia also testified that the estimated increase is based on a normalized market, not the current market, which he described as the worst real estate market in 75 years. (Tr. II at 238.) Mr. Garcia added that homes that were selling for \$500,000 when the UCSA process started are now selling for \$150,000. (Tr. II at 236-37.) Mr. Garcia never did formal residential property appraisals in a professional capacity, although he has done work-ups for family members. (Tr. II at 244-45.) Mr. Garcia acknowledged that any appreciation in home value would

only be realized upon sale of the property. (Tr. II at 458.)

105. Verizon was running at a 43-percent fill in Hillcrest Bay, meaning that 43 percent of the facilities were currently in use, during the peak season at the time of the first hearing. (Tr. I at 138-39.) Verizon was running at a 34-percent fill in Hillcrest Bay as of the second hearing, as it had lost some customers since the first hearing. (Tr. II at 415.) There are currently sufficient Verizon lines available to bring on new customers or to add additional lines for existing customers as the need arises. (Tr. I at 139; Tr. II at 420-21.)

106. At the first hearing, Mr. Kearns testified that he was not aware of any unplanned communications service outages in Hillcrest Bay in the prior year. (Tr. I at 140.) At the second hearing, Mr. Kearns testified that he was not aware of any unplanned communication service outages in Hillcrest Bay in 2008 or in the first half of 2009. (Tr. II at 415.) Hillcrest Bay is not a problematic area for Verizon, and its communications facilities there only require routine maintenance, not repair. (Tr. I at 140.) Verizon facilities can last more than 60 years. (Tr. I at 141.)

107. Verizon believes that its facilities currently in place in Hillcrest Bay are sufficient to provision for service there and would not have pursued the underground conversion on its own initiative. (Tr. I at 143.) Verizon does not currently provide broadband service in Hillcrest Bay and does not intend to install any broadband service in Hillcrest Bay if the UCSA is approved, due to the cost of broadband. (Tr. II at 419.) If Verizon's lines are placed underground, that will not enhance or update the telecommunications service provided to Hillcrest Bay in any way. (Tr. II at 405.)

108. Since the second hearing, the Commission has approved a Verizon application to transfer its Certificate of Convenience and Necessity ("CC&N") and its local exchange business to a Frontier Communications Corporation subsidiary known as New Communications of the Southwest, Inc. ("NewILEC"), which was formed exclusively to take over Verizon's services and service area. (Decision No. 71486 (February 23, 2010).) There is no evidence to indicate what position NewILEC would take on the UCSA and whether it has plans for extending additional services, such as broadband, to Hillcrest Bay. As of the second hearing, before the Decision granting the CC&N

Official notice of this transfer docket was taken at the second hearing in this matter. (Tr. II at 414.)

7

12

18

26 27

28

transfer was issued, Mr. Kearns had not analyzed the impact of the CC&N transfer on the UCSA, but stated that Verizon would continue to maintain its facilities until the transfer occurs. (Tr. II at 401-02.)

- 109. Mr. Wilson testified that some properties within the proposed UCSA will not be benefited by establishment of the UCSA because they already have unobstructed views. (Tr. I at 112.)
- 110. Staff stated in the Staff Report that it is evident that some parcel owners may benefit more from a view perspective than other owners due to the terraced nature of Hillcrest and/or a parcel's location, such as along the perimeter. (Ex. I S-4.) Staff also stated, however, that to the extent the underground conversion may increase property values or provide increased reliability, the benefit would accrue, to some extent, to all owners of property within the UCSA. (1d.)
- 111. Mr. Wilson testified that it would not be technically feasible to exclude any parcels from the UCSA, should it be approved, because there would then be parallel overhead and underground facilities. (Tr. I at 112.) Staff also believes that it would not be practical to do a "piecemeal" underground conversion within the area because of the geography of Hillcrest Bay and its existing rear-lot overhead facilities. (Ex. I S-4.)

If The UCSA Is Approved

- If the UCSA is approved, APS would go back to bid for the trenching work, select a 112. contractor, and have the contractor proceed with the conversion as quickly as possible thereafter. (Tr. I at 53, 82; Tr. II at 384-88.) Verizon also intends to have the project re-bid and to hire an authorized vendor to do its portion of the work. (Tr. II at 410-11.) If there is any decrease in costs as a result of the rebidding process, the PSCs would pass the decrease on to the owners. (See A.R.S. § 40-350(A); Tr. I at 53.)
- 113. Based on the tight circumstances and the type of terrain, APS estimates that trenching and service restoration would take six to nine months to complete. (See Tr. I at 82; Tr. II at 384-88.) There should not be any power outages as a result of the conversion, other than when an individual parcel's conversion is completed, because the underground system would be built in parallel to the overhead, and pieces of the overhead system would be de-energized and removed as the services are

3

114.

115.

construction. (Tr. I at 132.)

4 5

6

7 8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

387.)

If the UCSA Is Not Approved

116. If the UCSA is not approved, APS currently intends to move the rear-lot distribution by overhead lines to a front-lot distribution by overhead lines. (Tr. I at 102-04; LFE I A-12.) This would result in the removal of APS's lines from 42 existing poles currently providing rear-lot distribution and the addition of 42 steel poles to provide front-lot distribution. (LFE I A-12.) Another 28 existing poles that currently provide front-lot distribution would either remain or be replaced with new poles in the same location. (Id.) This conversion to overhead front-lot service would occur gradually over time, possibly several or even 5, 10, 15, 20, or 30 years. (See Tr. I at 85, 87; Tr. II at 273-74.) APS is not planning a wholesale replacement of poles in Hillcrest Bay in the next 5 or even 10 years. (Tr. II at 275.) APS may replace poles in place or may implement part of its overhead plan, as need and opportunity arises. (Tr. II at 274.) Mr. Wilson testified that the overhead

converted. (Tr. I at 83.) The big inconvenience would be during the trenching, because of the

conversion is completed for the customers served off of the overhead line. (Tr. I at 88.) Mr. Wilson

testified that the time to complete this would depend on how quickly individual owners transfer

service on their properties from overhead to underground. (Tr. II at 388.) APS estimates that it

would take APS approximately another 30 days to compile and provide final cost data. (Tr. II at

Verizon's timeline for construction would follow along with APS's timeline for

The poles belong to APS, so APS would be responsible to remove them once

disruption in the streets, which are fairly narrow already. (Tr. I at 83.)

117. Verizon does not intend to move its lines or make any changes to its facilities if the UCSA is not approved, even though Verizon is aware that APS intends to move its lines to front-lot positions in that event. (Tr. I at 139-40.) As a result, if APS were to move its lines, APS would be unable to remove the rear-lot poles, which are currently shared with Verizon, although APS would cut them down to a lower height after its own lines were removed, as Verizon's lines are lower. (Tr. I at 103-04.)

35

plan is not set in stone, but is flexible as things change. (Tr. II at 312.)

5

10

11

14

20

21

22

23

24

25

28

Moving the rear-lot distribution by overhead lines to a front-lot distribution by 118. overhead lines would cost APS approximately \$327,000, which would be paid for completely by APS, out of its construction budget. (Tr. I at 104.) The cost would then be applied to APS's rate base. (Tr. I at 195.)

Mr. Wilson testified at the second hearing that an owner could choose to have the lines 119. serving that owner's parcel converted to underground service at the owner's expense. (Tr. II at 348.) Indeed, Mr. Wilson testified that an individual with the financial means could have any line, or all of the lines, within Hillcrest Bay converted to underground. (Tr. II at 350-51.)

The Second Hearing; Objections and Withdrawals of Signature

- The scheduling of the second hearing in this matter raised the question whether 120. property owners again were afforded an opportunity to provide objections and/or withdrawals of signature that could be considered by the Commission as timely for purposes of determining whether the standard for approval of the UCSA has been met.
- HBI asserts that the Commission may not consider withdrawals or objections made 121. after January 8, 2008, the date 10 days before the date of the original hearing in this matter. HBI further asserts that after January 8, 2008, the question of whether there is still 60-percent support for the UCSA is no longer relevant—that the Commission need only determine feasibility and that timely opposition is not greater than 40 percent. HBI asserts that the UCSA statutes intentionally differentiate between the showing of 60-percent support that must be made for the second petition and the showing of no more than 40-percent objection that must be made at the time of hearing. According to HBI, statutory language is presumed not to be superfluous, and looking at both criteria at the same time would render one of them superfluous, as it is not possible to have more than 40 percent objecting if there is at least 60-percent support. HBI also asserts that even if the Commission were to disregard the statutory prohibition on late objections, many of the objections are still invalid under A.R.S. § 40-345, which requires each objection to be accompanied by an affidavit of an owner attesting to the validity of the signatures on the objection.
- APS and Verizon question whether the UCSA statutes allow the Commission to 122. conduct an additional hearing in this case, after the statutory 60-day time limit for the Commission's

hearing has passed, but assert that the scheduling of another hearing would appear to make the withdrawal provisions of A.R.S. § 40-344(A) applicable again. APS and Verizon assert that since the issuance of the original ROO, 16 letters have been filed in which owners request to change their votes from supporting votes to opposing votes. APS and Verizon state that whether or not there is explicit statutory authority to conduct additional hearings on the joint petition, or to allow for the withdrawal of support after the initial hearing, the Commission has the discretion to weigh the withdrawals as part of its economic feasibility analysis. APS and Verizon both concur with HBI that the withdrawals and objections filed herein were not accompanied by affidavits of property owners, but assert that the Commission still has the discretion to weigh any withdrawals received in its analysis of economic feasibility. Verizon further asserts that the Commission should reject HBI's argument regarding the invalidity of withdrawals and objections based on A.R.S. § 40-345, as Decision No. 67437 (December 3, 2004) demonstrates that the Commission has, in the recent past, held that requests for withdrawals of signatures from a petition to establish an UCSA complied with A.R.S. § 40-345 even though they were not accompanied by affidavits.

- 123. Staff asserts that A.R.S. § 40-344 requires any person wishing to withdraw from the petition or object to the UCSA to file an objection with the Commission not later than 10 days prior to the date set for hearing, which Staff interprets as the original hearing in this matter. Staff asserts that late withdrawals should not be counted, but that the Commission may consider the late withdrawals in weighing the economic feasibility of the UCSA.
- 124. In the past, the Commission has held a second hearing in an UCSA case and allowed objections and withdrawals of signature to be filed by owners after they received notice of the second hearing. (Decision No. 55490 (March 19, 1987) at 8.) The Commission has also invited owners to provide objections at an UCSA hearing. (See Decision No. 40939 (July 21, 1970) at 1.)
- 125. As noted by Verizon, the Commission also has previously recognized as valid objections and withdrawals of signature that are not accompanied by an affidavit.³⁸ (See Decision

We note that the alternative to recognizing an objection or withdrawal of signature without an accompanying affidavit is to quiet the voice of an owner who would object to being legally obligated to pay for an UCSA that the owner does not support. That standard is higher than the standard to vote in favor of the UCSA through the second petition, which need not be accompanied by such an affidavit. It appears that the Commission has previously chosen, in spite of the guidance offered by A.R.S. § 40-345(1), not to deprive objectors of a voice through a technical requirement that

No. 55490 at 10; Decision No. 67437 (December 3, 2004) at 5.) We also note that A.R.S. § 40-345 is expressly provided as a "guide" and that A.R.S. § 40-345(1) does not state that a withdrawal of signature or objection with "signatures" that does not have an attached affidavit is invalid. Indeed, even A.R.S. § 40-344(A), stating that objections shall be filed not later than 10 days before the hearing date, does not state that a later filed objection is invalid or shall be disregarded. We note that other provisions within A.R.S. § 40-345 expressly state that certain signatures cannot be counted, that certain protests shall be valid, and that certain objections shall be disregarded. (*See* A.R.S. § 40-345(2), (4), (5), (7).)

Owner Support and Opposition

and withdrawals of signature, the Commission received written opposition to the UCSA from the owners of 18 parcels.³⁹ The owners of 14 of the parcels for which opposition was provided specifically stated that they would be unable to pay the costs, could not afford the costs, or would experience financial hardship as a result of the costs.⁴⁰ Of these, the owners of three parcels⁴¹ also stated that they might or would be forced to sell their properties if the UCSA were approved. The other objecting owners asserted that the prices were excessive, that costs were allocated unfairly, and that the signatures on petitions had not been properly verified.

127. Between December 6, 2007, and January 8, 2008, the Commission received written support for the UCSA from the owners of 23 parcels, all of whom had signed the second petition.⁴² These owners stated that the UCSA would improve quality of life, increase property values, beautify Hillcrest Bay, improve views, bring Hillcrest Bay to the 21st century, help eliminate outage problems caused by the weather, improve service reliability, enhance safety, improve the cleanliness of

DECIGIONI NO

exceeds the technical requirement for supporting the UCSA in the first place. In addition, we again note that the requirement in A.R.S. § 40-345(1), when all of its language is given effect and none of it is rendered superfluous, only refers to objections and/or withdrawals containing the signatures of more than one owner.

The Commission received letters in opposition from the owners of Parcels 014A, 015, 025, 035A, 043A, 047A, 086, 087, 088, 089, 090, 094A, 132A, 135A, 154, 208, 247A, and 251A.

These were the owners of Parcels 015, 025, 035A, 043A, 047A, 086, 087, 088, 089, 090, 094A, 132A, 154, and 208.

These were the owners of Parcels 015, 035A, and 094A.

The Commission received letters in support from the owners of Parcels 052B, 052C, 060A, 063A, 064A, 099, 102, 110A, 119, 144, 147, 190, 191, 199, 210, 225, 227, 229, 231, 238, 239, 242A, and 245A. The Commission also received an unsigned letter in support, which was considered invalid because it did not identify a Hillcrest Bay property or property owner.

Hillcrest Bay, avoid escalating maintenance and repair costs for the current facilities, be consistent with the recent upgrading of residences in Hillcrest Bay, take advantage of the cost-sharing proposed with the PSCs, and prevent 40 additional poles from being installed on the streets of Hillcrest Bay.⁴³

After January 8, 2008, and before the initial ROO was issued on May 16, 2008, the 128. Commission received written opposition to the UCSA from the owners of 36 parcels, representing new opposition from the owners of 24 parcels. 44 as shown in Exhibit B hereto. The Commission also received written support for the UCSA from the owners of 15 parcels, all of whom had signed the second petition.⁴⁵ The owners of 35 of the 36 parcels for which opposition was provided in this time period specifically stated that they were on fixed incomes, would be unable to pay the UCSA costs, could not afford the UCSA costs, would experience financial hardship as a result of the UCSA costs, or were concerned about other owners experiencing financial difficulties as a result of the costs.⁴⁶ Two of the owners submitting written opposition requested that their signatures be removed from the second petition: Donald and Roberta Anderson, owners of Parcel 138, who filed a letter on February 14, 2008, requesting to rescind their "yes" votes and signatures for the UCSA because they had not realized the substantial cost and burden it would cause homeowners in Hillcrest Bay, and Shane Jolicoeur, owner of Parcel 170A, who submitted a letter directly to the Hearing Division on February 19, 2008, requesting to change his previous "yes" vote to a "no" vote for numerous reasons, among them concern that full-time residents might not be able to afford the costs.⁴⁷ If the late requests for withdrawal of signature from Mr. and Mrs. Anderson and Mr. Jolicoeur were considered to be valid, the owners supporting establishment of the UCSA as of the end of February 19, 2008, one month and one day after the initial hearing, was reduced from 151 to 149 parcels (62.08 percent), with square footage of 788,185.9 SF (58.91 percent).

23

24

25

26

27

28

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

The owner for Parcel 119 supported the UCSA, but also complained that Verizon's service is "sparse" and that Verizon's conversion costs are "out of line."

The Commission also received additional opposition from Ms. Davis, the owner of Parcel 208, during this time period. The owners of 12 of the 36 parcels had already provided letters in opposition by January 8, 2008.

The Commission received letters in support from the owners of Parcels 011, 036A, 078, 079, 081, 082, 106A, 115, 118A, 119, 158, 188B, 189A, 198, and 269A.

These were the owners for Parcels 005A, 006, 007, 008, 015, 019, 020, 021, 035A, 039, 040, 045A, 047A, 050, 054, 086, 087, 088, 089, 090, 100, 114, 135A, 138, 170A, 180A, 182, 208, 240, 247A, 251A, 252, 253, 267A, and 270A.

The Hearing Division sent a copy of the letter from Mr. Jolicoeur to counsel for APS and Verizon and had it docketed.

23

24

25

26

27

28

1

2

In approximately August 2008, in response to the July 2008 Procedural Order. HBI 129. sent each owner a new petition form⁴⁸ asking the owner to check one of the following:

- I SUPPORT the UCSA* (The removal of the overhead wires and Γ telephone poles and relocating the utility system underground).
- I OPPOSE the UCSA* (Leaving the existing utility system AS IS and allowing 42 additional poles added to the streets of Hillcrest Bay).

HBI received responses to the new petition for 185 parcels, with 119 of them in support and 66 of them opposed.⁴⁹ as shown in Exhibit B-1 hereto, which is incorporated by reference herein. Owners of six parcels newly expressed support, as they had not signed the second petition. The owners of two of those parcels have since filed letters in opposition. In addition, the owners of 15 parcels who had signed the second petition expressed opposition in the new petition, as shown in Exhibit B-1 hereto. The new petition forms did not request owners to explain the reasons behind their support or opposition. We note, however, that the wording of the parenthetical provision accompanying the box to indicate support may have been misleading, as it implies that 42 poles will be added in Hillcrest Bay imminently if the UCSA is not approved, while the evidence in this case does not support or establish that conclusion.

Between the time the initial ROO was discussed at the Open Meeting on July 1, 2008, 130. and the issuance on May 11, 2009, of the Procedural Order regarding a second hearing, the Commission received letters from the owners of 15 parcels supporting the UCSA and letters from the owners of 40 parcels opposing the UCSA. The letters in support were all from owners who had signed the second petition. Of the 40 parcels expressing opposition, 14 had signed the second petition and thus were changing their prior positions.⁵⁰ The owners who explained the change from their prior positions cited the worsened economy, their own inability to afford the costs of the UCSA, and concern for neighbors who would "lose everything" if the UCSA were approved.

40

One of the letters opposing the UCSA was from Ms. Davis, who had opposed it previously.

Official notice was taken of the actual new petition forms at the second hearing, as they were not provided as exhibits by HBI. (See Tr. II at 110.)

Petition forms from Ted Bultsma and Yvonne Sutton were not counted here because they are not owners. In addition, Ms. Sutton did not provide an address. Petitions from Louise Denver, Darren Cummins, Marvin Jordan, Leah Wagner, Melody Clark, and Jamie Brandel Kourkos are not counted here because their positions were unclear as a result of the markings, or lack thereof, on their petition forms.

131. Between the time the Procedural Order of May 11, 2009, was issued and the present, the Commission has received letters supporting the UCSA from the owners of 18 parcels and letters opposing the UCSA from the owners of 44 parcels, as shown on Exhibit B-1. All of the owners who wrote letters in support had signed the second petition. Of the 44 parcels for which opposition letters were filed, the owners for 6 parcels had signed the second petition and thus were changing their prior positions, three of them for the first time.⁵¹ Each of the owners who explained the change from his or her prior position cited the economy as a reason for the change.

Current Owner Support and Opposition

- 132. When all of the current owners who have expressed support⁵² and have not subsequently expressed opposition are counted, the current level of owner support for the UCSA is 122 of 238 parcels, which comprises 51.26 percent of the parcels and 50.09 percent of the square footage of the proposed UCSA, as shown on Exhibit B-1. When all of the current owners who have expressed opposition⁵³ and have not subsequently expressed support are counted, the current level of owner opposition to the UCSA is 98 of 238 parcels, which comprises 41.18 percent of the parcels and 40.43 percent of the square footage of the proposed UCSA, as shown on Exhibit B-1.
- 133. HBI asserts that the current level of owner support and opposition is irrelevant. APS, Verizon, and Staff all assert that it is at least probative of economic feasibility. We agree with APS, Verizon, and Staff that it is relevant and is probative of economic feasibility.

Estimated UCSA Costs

than would its overhead plan, APS did not include its construction costs in the costs to be paid by the owners, only its trenching-related costs.⁵⁴ (See Tr. I at 52.) APS also did not include the undepreciated original cost of the existing plant to be removed (estimated at \$104,593) for the same reason. (LFE I A-11.) In total, APS offset approximately \$300,000 in costs as avoided costs from

Three of them (Parcels 138, 162, and 208) had done so previously.

Owner support here is counted if it was provided through the second petition, the new petition, or a letter to the Commission.

Owner opposition here is counted if it was provided through the new petition or a letter to the Commission. Silent owners are not counted as opponents.

Mr. Wilson testified that the APS service cost does not include a charge for the actual wire, only the costs to install the conduit, including any concrete or pavement cuts, trenching, backfill, and service restoration. (Tr. I at 88.)

the overhead plan, because they represented an investment that APS would be making anyway over the next 5 to 15 (or even more) years. (See Tr. I at 87; Tr. II at 273-74.)

an APS designer, a Verizon representative, a La Paz County inspector, an HBI representative, a trenching contractor, and an electrician. (Tr. I at 88-89.) These individuals looked at each parcel and determined the best option for placement of the meter and what needed to be done to restore service to the parcel. (Tr. I at 89.) In some cases, service may be maintained in the existing location, which may be set back on the lot, or it may be more economical to put a pedestal out front and backfeed that pedestal. (Tr. I at 89.) Because APS and Verizon need permission from each owner before starting work on the owner's property, each owner would ultimately be consulted as to the location of facilities. (Tr. I at 89.)

136. APS provided the following breakdown and explanation of its costs of conversion, estimated at \$766,134.13 total:

Public Costs:

Service Costs:

50 percent of cost of excavation in street right of way:	\$366,021.50
Cost to install APS conduit system:	\$182,739.00
9.6 percent A&G load: ⁵⁵	\$ 52,681.00
Total APS Public Costs:	\$601,441.50

50 percent of cost of trenching, backfill, & surface

restoration on private property:	\$150,267.00
9.6 percent A&G load:	<u>\$ 14,425.63</u>
Total APS Service Costs:	\$164,692.63 ⁵⁶

21 (LFE I A-11.)

Official notice is taken of APS's March 21, 2008, filing providing responses to questions raised in the Procedural Order of February 22, 2008. APS explained therein that its 9.6 percent A&G Load (for overhead costs) is comprised of APS shared services such as information technology, tax services, human resources, treasury, finance, vehicle maintenance, contract services, warehousing, engineering, corporate oversight, and construction supervision, along with associated payroll taxes and benefits. APS stated that these overhead costs are charged to all APS construction projects as permitted by the Federal Energy and Regulatory Commission ("FERC") Uniform System of Accounts and routinely accepted by the Commission in setting APS rates and determining APS construction accounting practices. APS included an excerpt from the FERC Uniform System of Accounts to support of its position. Among other things, the excerpt states: "The addition to direct construction costs of arbitrary percentages or amounts to cover assumed overhead costs is not permitted."

APS states that its chargeable service costs are \$159,442.12. (LFE I A-11.)

2 \$1,245,326.02 total:

1

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

Public Costs:

137.

1 00110 00000
Cable
Verizon Labor ⁵⁷
Contract Labor ⁵⁸
Conduit, Concrete/Asphalt
Total Verizon Public Costs:59

\$ 67,596.00 \$187,495.18 \$406,204.79

Verizon provided the following breakdown of its costs of conversion, estimated at

\$190,251.20 \$851,547.17

Service Costs:60

\$393,778.85

(LFE I VZ-2.) Verizon does not intend to assess a service cost for vacant parcels or those that do not have service to them; instead Verizon plans to stub out a conduit to the property line (a public cost) so that it will be easier and less expensive to install service in the future. (Tr. I at 142.) In addition, if an owner chooses not to have Verizon run a line to the owner's house, Verizon will not charge a service cost to the owner because Verizon will not be doing any work on the owner's property and will not insist that an owner have service. (Tr. I at 145-47.) Although Verizon had agreed to split evenly with APS the trenching costs associated with the service cost, Verizon does not intend to split the trenching cost for owners who do not desire Verizon service; APS's trenching costs would thus be increased. (Tr. I at 148-49.) APS has asserted that it should be permitted to recover an amount up to but not to exceed the total service cost (APS and Verizon) for each such parcel as all of the trenching, backfill, and surface restoration costs would still be incurred by APS. (LFE I A-11.)

138. When asked why Verizon's public costs and service costs are higher across the board than are APS's costs, Mr. Kearns explained that Verizon's service costs are in line with the estimates of Verizon's engineer who was on-site and visually inspected each property and made measurements, (Tr. I at 136), and that Verizon's public costs are higher because Verizon believes that there may be

23

24

25

26

27

28

This represents \$366,021.15 for the contracted trench and restoration work, plus \$24,372.00 for the contracted conduit installation, plus \$15,811.64 in tax.

This includes a load of \$69,671.95 that was added to the total price for material and is reflected in the figures for cable and conduit. (See LFE I VZ-2.)

This includes costs for material, engineering, hand dig, cutting and removing concrete, placing concrete, drop (as labor and as direct input), network interface device ("NID"), service wire, splicing, rock saw, loadings, tax, and contractor overage. (LFE I VZ-2.)

Verizon will be doing all of the work except the trenching and conduit; this includes removal of the overhead cable and strand, all the placing and splicing of the cable and terminals, the tiedown of the service drop, and the installation of the network interface device. (Tr. I at 132-33.)

This represents \$366.021.15 for the contracted trench and restricted trench and re

some additional concrete and asphalt that may need to be done, and its material costs are a lot higher because of the amount of copper and individual wires, (Tr. I at 16-22). Mr. Kearns also explained that everything that Verizon believes the job is going to cost is included in its estimates, whereas there are other costs (private costs) that are not reflected in APS's estimates. (Tr. I at 137.) Furthermore, Mr. Kearns testified that APS's costs are lower due to the credit that APS is providing. (Tr. I at 144-45.)

139. The estimated cost of removing Verizon's existing overhead facilities is \$44,756.64, the estimated salvage value of those removed facilities is \$8,420.24, and the remaining undepreciated original cost of the existing overhead facilities is \$698.55. (LFE I VZ-1.) The copper wire that is being removed will be wrecked out—chopped up, removed, and hauled out as waste. (Tr. I at 133, 135.)

140. The original estimated public costs and service costs for each parcel within Hillcrest Bay, other than Parcel 274, are shown in Exhibit C, attached hereto and incorporated herein, which was prepared by Staff and included in the Staff Report.⁶¹ The total of the combined public costs and service costs for each parcel range from a low of \$4,410.51 to a high of \$32,480.22, with a breakdown as follows:

```
29 parcels
$4,000 to $4,999:
                          38 parcels
$5,000 to $5,999:
$6.000 to $6.999:
                          32 parcels
$7,000 to $7,999:
                          37 parcels
                          26 parcels
$8,000 to $8,999:
                          15 parcels
$9,000 to $9,999:
                          22 parcels
$10,000 to $10,999:
                            9 parcels
$11,000 to $11,999:
$12,000 to $12,999:
                           10 parcels
$13,000 to $13,999:
                            4 parcels
$14,000 to $14,999:
                            6 parcels
                            4 parcels
$15,000 to $15,999:
                            1 parcel
$16,000 to $16,999:
$17,000 to $17,999:
                            3 parcels
                            1 parcel
$27,315.62:
$30,520.91:
                            1 parcel
                            1 parcel
$32,480.22:
```

1

6

7

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

Exhibit C shows the total square footage for Hillcrest Bay as 1,297,248.74 and a total of 239 parcels because Parcel 274 is not included in the Exhibit.

141. The original estimates obtained by HBI for the private costs are included in Exhibit D, attached hereto and incorporated herein.⁶² The private costs in Exhibit D total approximately \$902,527⁶³ and range, per individual address, from a low of \$0 to a high of \$11,146.44, with a breakdown as follows:

\$ 0:	8 addresses
\$1 to \$999:	10 addresses
\$1,000 to \$1,999:	25 addresses
\$2,000 to \$2,999:	20 addresses
\$3,000 to \$3,999:	29 addresses
\$4,000 to \$4,999:	26 addresses
\$5,000 to \$5,999:	17 addresses
\$6,000 to \$6,999:	23 addresses
\$7,000 to \$7,999:	19 addresses
\$8,000 to \$8,999:	13 addresses
\$9,000 to \$9,999:	3 addresses
\$10,000 to \$10,999:	5 addresses
\$11,146.44:	1 address

- 142. Staff testified that the size of the private cost depends upon the amount of work that is required and could be impacted by the length of the trench needed, whether or not concrete or asphalt has to be cut through and restored, and whether or not the service panel needs to be upgraded or replaced. (Tr. I at 187-88.) Staff has not made a determination as to the reasonableness of the individual items factored into each parcel's private costs, but did not notice any private cost totals that appeared to be extreme. (Tr. I at 188.) Staff testified that the types of costs included in the private cost estimates are costs that would normally be the responsibility of the owner. (Tr. I at 185.)
- 143. Some of the difficulty in reestablishing service from the front-lot position is that some of the homes are elevated above the street, with concrete walls to the street, which presents some

Exhibit D was provided by APS as LFE I A-11-B. The private cost estimates in Exhibit D were provided by street address rather than by parcel number, and there are discrepancies between some of the street addresses included in Exhibit D and the street addresses included in the joint report. (See Exhibit A-3; LFE I A-12.) When APS asked Mr. Sears for copies of the private cost letters sent by HBI to the owners, APS was informed that Mr. Sears did not have those, only spreadsheets, which APS used to create LFE I A-11-B. (Tr. I at 171.)

This figure includes \$194,202 in trenching costs and \$708,325.50 for conversion of metering devices and relocation of electrical metering. (Ex. I S-1; Ex. I S-2; Ex. I S-3.) The trenching costs were estimated by Tee Pee Contractors, Inc., the firm that provided APS its trenching estimate. (Ex. I S-2; Ex. I S-3.) The meter conversion and relocation costs were estimated by CMK Engineering, based upon a walk-through of Hillcrest Bay conducted in June 2006 that involved Pike Smith from APS, Dale Hiberling from the County Inspector, Alex Romero, CMK Engineering, Keith Barron Construction, Mr. Sears, and another owner. (Tr. I at 160; Ex. I S-1; Ex. I S-3.) Mr. Sears testified that every hook-up was agreed upon by the contractors, the county inspector, and APS. (Tr. I at 160.) If an owner's service panel needs to be converted to 200 amp, the private cost includes the cost of the service panel, which will be the property of the owner. (Tr. I at 162.)

challenges in reestablishing service. (Tr. I at 64.) The high cost of trenching in some estimates is due to the type of fill that anyone digging a trench in Hillcrest Bay is going to encounter when they try to put in underground conduit. (Tr. I at 67.) The fill in Hillcrest Bay is full of relatively large rocks. (Ex. I A-7, Photos 20 and 21; Tr. I at 67.)

- 144. If not paid in full by an owner within 30 or 60 days, as applicable, the public costs and service costs can be paid to the PSCs through equal periodic installments over a period not to exceed 15 years, with interest not to exceed 8 percent per year. (See A.R.S. §§ 40-347(B), 40-348(B).) The term for repayment and percentage of interest are determined by the Commission. (A.R.S. § 40-347(B).) The owners are required to pay the private costs out of pocket and do not have an opportunity to add the private costs to the cost amounts to be financed if not paid in full within 30 or 60 days, as applicable. (See A.R.S. §§ 40-347(B), 40-348(B).)
- 145. HBI has obtained revised cost estimates for the UCSA from Tades, a contractor that was not involved in providing the previous estimates.⁶⁴ The first revised cost estimate from Tades ("Tades I"), which is attached hereto and incorporated herein as Exhibit E-1, incorporates the public cost and service cost estimates previously provided by APS and Verizon and only revises the private cost estimates, for an overall reduction of \$51,097. The total cost of the UCSA under Tades I would be \$2,858,435.15. The second revised cost estimate from Tades ("Tades II"), which is attached hereto and incorporated herein as Exhibit E-2, assumes Tades would be permitted to perform all of the work associated with the UCSA. (See Tr. II at 130-31.) The total cost of the UCSA under Tades II would be \$2,246,403.57, which represents an overall reduction of \$664,124.50. Tades did not send its cost estimates to the owners other than HBI, which requested the estimates. (Tr. II at 148-50.)
- 146. Mr. Kellogg estimates that Tades would use 10 to 15 workers for the UCSA with approximately 50-percent local labor and that the UCSA work would take approximately 3 to 6 months. (Tr. II at 129, 132.) If Tades is permitted to do the entire project, as contemplated in Tades II, Tades has agreed to provide free conversions as to private costs to 5 low-income owners selected by HBI and to give a 15-percent discount to other low-income owners identified by HBI. (Tr. II at

DEGIGIONIN

⁶⁴ Mr. Kellogg, partial owner of Tades, was employed at CMK engineering, one of the contractors that provided estimates. (Tr. II at 133.)

132, 136.) It is unclear which costs would be discounted by 15 percent for these other low-income owners, as Mr. Kellogg testified in one area that it would be the private costs and in another area that it would be the public costs and service costs. (See Tr. II at 132, 136.) If a number of owners choose to use a contractor other than Tades for their private cost work, Tades's offer of the 5 free private cost jobs and the 15-percent discounts could be impacted. (See Tr. II at 138, 154-55.) The Tades estimates expire in April 2010. (Tr. II at 124.)

- 147. The Tades II estimated costs do not include the network interface device needed for telecommunications service. (See Tr. II at 140.) For a home that currently has a rear-access connector box, Tades would run the telephone wire only to a new connector box placed in the front, and any wiring needed to allow the new connector box to interface with the home equipment would not be included and would be left to the owner. (Tr. II at 144-45.)
- 148. In Tades II, Tades determined the estimated service costs for each parcel by estimating the total trenching costs for the project and then dividing them by the square footage, thus attributing the service costs for a parcel based on the square footage of the parcel as opposed to the work needed to serve that parcel. (See Tr. II at 158, 169, 176.) Tades II would result in increased service costs for some owners, as compared to the joint report. (See Exhibits C and E-2 hereto.) APS and Verizon are prohibited from recovering any costs that exceed the estimated costs in the joint report. (See A.R.S. § 40-347(B).)
- approved contractor as of the second hearing date, (Tr. II at 153), and further that the Tades II cost estimates assume that Tades would be permitted to do the project by APS and Verizon, which had not been established, (Tr. II at 169). Verizon also had had no discussions with Tades regarding the UCSA project and intended to do all of the work itself except for the trenching and placement of conduit in public areas and service areas. (Tr. II at 400.) As of the second hearing, Tades was not an authorized contractor for Verizon. (Tr. II at 411.)
 - 150. HBI has created a financial assistance program ("FAP") to assist selected low-income

We note that Mr. Sears testified that the financial assistance program, of which the Tades discounts are considered to be a component, would be available only as to private costs. (Tr. II at 64-65; 119.)

owners with their costs. ⁶⁶ (See Tr. II at 64-65.) The first component of the FAP includes the five free electrical connections (private costs) to low-income owners and a 15-percent discount to select low-income owners offered by Tades. (See Ex. II H-1.) The second component of the FAP would provide assistance to low-income owners through a fund created by HBI that currently holds \$9,000 contributed by HBI and to which an additional \$20,200 has been pledged by 19 other owners. (Id.) HBI has selected three low-income owners thus far to receive free electrical connections from Tades. (See Exhibit E-1; Exhibit E-2.) These owners were identified through a process that included a solicitation letter from HBI, self-identification as low-income by owners, requests for assistance by owners, submission of tax returns to an independent certified public accountant ("CPA") hired by Ms. Babcock on behalf of HBI, and a determination of eligibility by the CPA. (See Ex. II H-1; Tr. II at 197-200.) HBI intends to reopen the FAP upon approval of the UCSA. (Ex. II H-1.) HBI has not yet determined all the details for the FAP, such as whether only full-time residents will be eligible for the FAP, how assistance will be provided, and how the low-income owners to receive the Tades discount will be identified. (Tr. II at 194, 202-04.) HBI has determined that the income threshold for the FAP is 185 percent of the federal poverty level. (Tr. II at 194.)

Standard for Approval

151. A.R.S. § 40-346(A) provides:

The corporation commission . . . shall hold a hearing . . . to establish the fact that the requirements for the establishment of an underground conversion service area have been satisfied, and that owners of no more than forty per cent of the real property within the underground conversion service area, or no more than forty per cent of the owners of real property, have not objected to the formation of the underground conversion service area, and if the commission . . . so determines, and if the commission . . . further determines after considering all objections, that the cost of conversion as reflected in the joint report prepared pursuant to § 40-342 is economically and technically feasible for the public service corporations . . . involved and the property owners affected and that the underground conversion service area is a reasonably compact area of reasonable size, the commission . . . shall then issue an order establishing the area as an underground conversion service area.

(A.R.S. § 40-346(A) (emphasis added).) APS, Verizon, Staff, and HBI have filed briefs analyzing the meaning of the language underlined above and setting forth their positions as to the standard for

It is unclear whether the entire FAP is limited to private costs, or only the portion that would involve HBI- and other owner-contributed funds. (See, e.g., Tr. II at 64-65.)

Commission approval of an UCSA, which diverge in some respects.

or more of the property owners (or owners controlling 40 percent or more of the area) have objected to the UCSA and (2) whether the conversion is feasible. HBI asserts that the 60-percent support standard need only be met at the time of the petition and that it is not the Commission's role to determine whether the 60-percent standard has been met. According to HBI, once the proponents of an UCSA have met the 60-percent-support standard for the first petition and second petition, as determined by the PSCs involved, the UCSA project cannot be derailed unless opponents come forward with 40 percent or more opposition no later than 10 days before the date set for hearing. HBI asserts that this is consistent with the Commission's prior interpretation of the UCSA statutes, quoting Decision No. 55490's statement that "[a]side from the Commission's finding regarding feasibility of conversion, the Commission's only function herein is to determine whether 40% or more of all property owners have objected to the formation of the underground CSA." (HBI Post-Hearing Brief at 9 (quoting Decision No. 55490 at 5 (emphasis in original)).)

153. APS asserts that the UCSA statutes should be interpreted to require the Commission to make two separate findings: (1) that owners of more than 60 percent of the real property in the affected area on a square footage basis have supported the UCSA and (2) that more than 60 percent of the owners of property in the UCSA have supported the UCSA. APS adds that if the percentage of objections, using either form of measurement, exceeds 40 percent, then the initial requirements for proceeding with the UCSA are no longer met, and the UCSA should not be established. APS asserts that the Commission dismissed a petition in Decision No. 67437 in part based on the failure of the petition, after timely withdrawals, to meet the statutory requirements in A.R.S. §§ 40-343(A) and 40-346(A). (APS Closing Brief at 5 (citing Decision No. 67437 at 7).) APS acknowledges that in that Decision, the Commission also relied on the Maricopa County Board of Supervisors' refusal to approve the UCSA.

28 . .

2122

23

24

25

26

2728

154. Verizon asserts that the Commission must first analyze whether the petitioners have satisfied threshold criteria⁶⁷ and then consider the factors in A.R.S. § 40-346(A), including determination of the level of objection and whether the project is economically feasible for the affected owners. Verizon characterizes the double negative in A.R.S. § 40-346(A) as "clear error" and asserts that the Commission has resolved this error previously by ignoring the negative language of the statute and instead focusing on the requirement for 60-percent approval, which if attained necessarily indicates less-than-40-percent disapproval. Verizon asserts that the Commission should interpret A.R.S. § 40-346(A) to require two separate findings: (1) that the owners of at least 60 percent of the parcels support the petition, and (2) that owners of at least 60 percent of the land support the petition. Verizon reasons that if the percentage of objections on either basis exceeds 40 percent, then one of these necessarily will not be met, and the petition should be denied. Verizon adds that after making this inquiry, the Commission must also determine (1) whether the cost of conversion is economically and technically feasible for the PSCs, (2) whether the cost of conversion is economically and technically feasible for the owners affected, and (3) whether the UCSA is a reasonably compact area of reasonable size. Verizon observes that the Commission apparently has presumed in prior cases that the 60-percent-support requirement is a reasonable indication that an UCSA project is economically feasible for the affected owners as a whole, but points out that it is within the Commission's discretion to find that a severe economic impact on less than 40 percent of owners renders an UCSA project economically infeasible. Verizon states that in this case, the Commission should focus on the economic feasibility of the project when making its decision.

155. Staff asserts that in its prior decisions considering UCSAs, the Commission has focused on whether there is support from more than 60 percent of property owners owning 60 percent of the property subject to the UCSA or whether forty percent or more of the property owners owning forty percent or more of the property object. Staff asserts that if more than 40 percent object, the petition fails, and that if 60 percent or more are in favor and the conversion is economically and

Verizon asserts that these include the preparation of a cost study by the PSCs, the provision of the cost study to the owners, a petition supported by the owners of at least 60 percent of the parcels within the proposed UCSA who own at least 60 percent of the land in the proposed UCSA, and the recording of liens against each parcel within the proposed UCSA for the underground conversion costs for which the parcel will be liable.

9

10

11

12 13

14 15

16

17

18 19

20 21

22 23

24

25

26 27

technically feasible, the project goes forward. Staff states that this is a common sense interpretation of the statute that appears to approximate the legislative intent of providing a means for the conversion of overhead facilities to underground when more than a simple majority of the affected property owners understand the costs of conversion and are willing to pay. Staff characterizes HBI's interpretation of A.R.S. § 40-346(A) as "novel" and asserts that it should be disregarded because it would allow an UCSA to be established if at the time of the hearing there is 40-percent objection, 10percent silence, and only 50-percent support. Staff believes that this is inconsistent with the apparent legislative intent for more than a simple majority of support to be required for an UCSA to move forward.

Technical and Economic Feasibility

- To approve establishment of an UCSA, the Commission must find inter alia, after 156. considering all objections, that the cost of conversion, as reflected in the joint report, is economically and technically feasible for both the PSCs involved and the property owners involved. (A.R.S. § 40-346(A).) The parties have not presented any evidence to suggest that the UCSA is not technically feasible. Nor have the PSCs asserted that the UCSA is not economically feasible for the PSCs. There has been a great deal of evidence presented regarding the economic feasibility of the UCSA for the owners.
- Mr. Wilson testified that he has concern for some friends in Hillcrest Bay for whom 157. the UCSA is going to be a hardship. (Tr. I at 112.)
- Staff's original position was that the UCSA project is economically feasible and 158. should be approved. (Tr. I at 182-83.) Staff testified at the first hearing that Staff's recommendation on financing was one of the things that helped to make the UCSA economically feasible. (Tr. I at 183.) At the second hearing, Staff no longer recommended approval of the UCSA. (See Tr. II at 447.)
- Mr. Sears has expressed concern about some of the owners who have said that they 159. cannot afford the assessments, and he personally explored the availability of grants for low-income owners with Maricopa County. (Tr. I at 156.) Mr. Sears was also instrumental in having the FAP created by HBI. (See Tr. I at 158.) Mr. Sears is skeptical, however, about the genuineness of claims

5

24

25

26

27

18

19

20

21

22

23

of financial hardship from owners who do not live full time in Hillcrest Bay, but have vacation houses, investment homes, or rental properties there. (Tr. I at 158.) Owner Robyn Stein also testified to her belief that it is a question of lifestyle choice rather than economic feasibility for those owners who do not live at Hillcrest Bay full time. (Tr. II at 186.)

At the first hearing, owner Steven Benton testified that Hillcrest Bay includes a mix of 160. homes ranging from two-story luxury homes down to single-wide trailers, that a number of the homes are actually second homes or vacation homes, and that the owners range from the wealthy down to the probably very poor. (Tr. I at 24.) Mr. Benton testified that some of the owners just cannot afford the conversion. (Tr. I at 24.) Mr. Benton testified that the conversion costs for his parcel are more than \$30,000 and that he does not understand why some homeowners will be assessed as little as \$4,500 while others will be assessed more than \$30,000.68 (Tr. I at 25.) Mr. Benton also testified that he already has an unrestricted view, with no utility poles or wires in the way, and that he would thus receive nothing from the conversion, although, with financing at 8-percent interest, he personally would have to pay almost \$300 per month for 15 years and would end up paying more than \$50,000. (Tr. I at 25-26, 28.) Mr. Benton also testified that some of the Hillcrest Bay owners would be forced to sell their homes if the UCSA were approved. (Tr. I at 25, 26, 28.) At the second hearing, Mr. Benton testified that he is a full-time resident of Hillcrest Bay and that the proposed liens on his home resulted in denial of refinancing for his mortgage until he was able to get the liens temporarily lifted with the help of Billie Dodson and Mr. Wilson, which allowed the loan to go through. (Tr. II at 519, 521-22.) Mr. Benton further testified that his home had appraised at \$500,000 in 2007, but had appraised at \$300,000 in April 2009. (Tr. II at 522.) Mr. Benton added that his take-home pay is only \$1,500 per month, although he earns additional income through golf lessons during the cooler months when seasonal visitors are in the area. (Tr. II at 523-24.) Mr. Benton concluded by saying

Mr. Wilson testified that the costs are so high for Mr. Benton's parcel, and for that of his neighbor to the west, because those parcels extend 50 feet farther than the original lots in the rear, due to an abandoned 100-foot transmission line easement, and APS intends to run underground service out to the center of the easement across and back to the existing meter locations, which is a total of approximately 270 feet, all of which is concrete and driveway that needs to be cut and patched. (Tr. I at 71-72.) Mr. Wilson stated that one option to try to reduce Mr. Benton's costs, and those of his neighbor, would be to get an easement across the parcels along the original property line and come straight across rather than going around, which would reduce the service length by approximately 100 feet, thereby reducing the service costs and trenching costs proportionately. (Tr. I at 72.)

that neighbors should not force other neighbors to pay thousands of dollars they cannot afford so that they can enjoy a better view. (Tr. II at 524.)

- 161. At the first hearing, owner Nando Haase testified that, although he cannot argue with the fact that it would beautify Hillcrest Bay, he would experience financial hardship from the UCSA, as he lives on Social Security and is not sure that he could afford the UCSA even if financing is offered. (Tr. I at 30.) Mr. Haase also testified that, in contrast to the testimony received about frequent power outages, the last power outage he recalls is the one in October 2007 when the pole broke. (Tr. I at 30.) Mr. Haase further testified that the conversion cost for his parcel is \$18,000. (Tr. I at 31.) Mr. Haase stated that he had not calculated what the cost would be with the financing available under the statutes, but that just anything is a hardship. (Tr. I at 33.) At the second hearing, Mr. Haase reiterated that he cannot afford the UCSA costs. (Tr. II at 208.) Mr. Haase also testified that his home had been up for sale for a year and that he had dropped the price three times, from \$319,000 to \$284,000, and had still had only one person come to look at it. (Tr. II at 212-14.)
- 162. Owner Janet Calvin testified that she is not bothered by the poles and lines and that she does not want to spend any more money for utilities because she already has service. (Tr. II at 216.)
- 163. Owner Marjorie Ward testified that Hillcrest Bay is "pure paradise as it is," that she cannot afford to pay the UCSA costs, and that she would not be benefited because her property already has a view. (Tr. II at 218-20.)
- 164. Owner Joy Muzic testified that her family has owned their Hillcrest Bay property since 1970 and that her husband put their utility lines underground when electric service became available approximately three years later. (Tr. II at 467.) Ms. Muzic considers herself to be low income, as she is thus categorized by her California gas utility, but said that she does not meet HBI's FAP standard, although she only receives Social Security income. (Tr. II at 467, 471, 474.)
- 165. Owner Lynne Muzic testified that her family has owned their Hillcrest Bay property since 1970 and that they put their utility lines underground in the 1970s. (Tr. II at 485.) Ms. Muzic also testified that she and her husband are living on a fixed income and barely making ends meet because the economy forced them to close their business two years ago, after 37 years. (*Id.*) Ms.

Muzic expressed concern about people losing their homes over the UCSA costs. (Tr. II at 487.)

- 166. Billie Dodson, HBI's current treasurer, an owner for 35 years, and a full-time resident for the past 11 years, testified that she will receive no benefit from the UCSA because her property has no view and no bird droppings or hanging or dangerous lines, 15 years is the rest of her life, and she does not plan to sell her home and thus will not realize any increase in value. (Tr. II at 489.) Ms. Dodson stated that she is on a fixed income and that the benefits of the UCSA do not outweigh the costs. (*Id.*) She added that in her role as HBI treasurer, she receives the La Paz County Recorder notices, which showed that four Hillcrest Bay properties were in foreclosure at the time of the second hearing. (Tr. II at 490.) Ms. Dodson also testified that a home had fallen out of escrow in approximately February 2009 because of the proposed liens of APS and Verizon. (Tr. II at 491-92.)
- 167. Owner Wayne Dunham testified that he built his home in 1974 and put his electrical utilities underground. (Tr. II at 517.) Mr. Dunham testified that the UCSA would be throwing money away, that he is retired with only Social Security income, that he is down to his Hillcrest Bay house and his permanent residence, and that he cannot take on the debt of the UCSA costs. (Id.)
- dramatically since the start of the UCSA process and that although she could afford the UCSA costs in the beginning, she cannot afford them now, as she has had to quit her job to take care of four terminally ill sisters. (Tr. II at 526-27, 530.) Ms. Bond also stated that two local realtors had told her that when people do not buy in Hillcrest Bay, it is because of the broken-down trailers and cars and junk in front yards, not the utility poles and lines. (Tr. II at 530.)

The PSCs' and Staff's Recommendations

169. At the time of the first hearing, Staff concluded that the joint petition met the statutory requirements to establish an UCSA and recommended that the joint petition be approved and that the Commission order that repayment of the conversion costs be made in monthly installments over a period of 15 years, with interest at the lesser of (a) the lowest prime interest rate published in the *Wall Street Journal* at the time the conversion is completed, or (b) 8 percent. (Ex. I S-4; Tr. I at 181-82.) Staff testified that the Commission's previous decisions granting UCSAs have used 15 years as the term of repayment. (Tr. I at 183-85.)

2 rec
3 bo
4 ma

170. At the time of the first hearing, APS and Verizon both declined to make recommendations regarding the approval of the UCSA. (See Tr. I at 38, 41; Tr. II at 36.) However, both expressed concern regarding Staff's recommended financing terms, with APS asserting that the maximum 8-percent interest rate would not allow APS to earn the cost of capital approved in its most recent rate case, which would mean that some of the costs would be borne by other ratepayers, (Ex. I A-10; Tr. I at 40, 113), and Verizon expressing concern regarding how the 15-year payback period would be administered and about cost recovery in the event that owners were to move, (Tr. I at 130).

171. At the time of the second hearing, Staff declined to make a recommendation as to whether the UCSA should be approved, although it did indicate that the owner withdrawals of support are probative on the issue of economic feasibility. (See Tr. II at 447.) APS and Verizon, however, both asserted that the joint petition should be dismissed because the level of owner support is no longer sufficient to move forward. (Tr. II at 37-38.)

The Commission's Mailing Costs

172. The Commission incurred \$2,905.55 in mailing costs for the mailings related to the first hearing provided for in A.R.S. § 40-344.

Analysis and Conclusion

173. The standard for Commission approval of an UCSA, as to the level of owner support needed or the level of owner objection rendering approval inappropriate, is obscured by the language of A.R.S. § 40-346(A), which includes both a double negative and a percentage that is the flipside of the percentage that qualifies a petition to come before the Commission. The PSCs, Staff, and HBI have briefed the issue, reaching varying conclusions as to what the Commission must determine in this regard, but all agreeing that the double-negative portion of the statute is an error that must be disregarded to give the statute effect.⁶⁹ The interpretation of the statutory requirement put forth by APS, Verizon, and Staff would result in resolution of the issue in the manner most in keeping with the statutory intent expressed by the Legislature in the Act that created the UCSA statutes—to

If followed literally, the language of A.R.S. § 40-346(A) pertaining to percentages would require the Commission to deny the UCSA in this case because too many owners (comprising at least 51.26 percent of the parcels and 50.09 percent of the square footage of the UCSA) have not objected. (See FOF 132.) The statutory provision literally requires the Commission to find "that owners of no more than forty per cent of the real property . . . or no more than forty per cent of the owners . . . have not objected." (A.R.S. § 40-346(A).)

provide a procedure to accomplish conversion when "landowners, cities, public service 1 2 3 4 5 7 10 11 12 13 14 15 16 17 18 19 20

corporations[,] and public agencies desire to convert existing overhead electric and communication facilities to underground locations." (Laws 1968, Ch. 160, § 1 (emphasis added).) This stated intent, coupled with the requirements in A.R.S. §§ 40-342 and 40-343 for 60-percent support, suggests that an UCSA should not be approved if it is no longer desired by a supermajority of the owners who own a supermajority of the square footage of the proposed UCSA. Also, as Staff points out, HBI's interpretation of the owner support/objection standard for approval of an UCSA under A.R.S. § 40-346(A) could result in establishment of an UCSA even if there is only 50-percent support at the time of the hearing. We note that HBI's interpretation would also result in the Commission's apparently being obligated to order establishment of an UCSA if 100 percent of owners objected to the establishment of the UCSA at a time after the hearing, or even nine or fewer days before the hearing, so long as the Commission found the UCSA to be technically and economically feasible. This seems untenable and inconsistent with the intent of the Legislature in adopting the UCSA statutes. Because the language of A.R.S. § 40-346(A) as to the level of owner support needed for approval or the level of owner objection rendering approval inappropriate is impossible to follow literally without reaching an absurd result, and because there is another determination under A.R.S. § 40-346(A) (economic feasibility for the owners) that the Commission must make to approve establishment of an UCSA, the necessity for which is not disputed by the parties hereto, we note the quandary as to the percentagerelated language of A.R.S. § 40-346(A), but need not and do not resolve it herein.

It is undisputed that to approve the establishment of an UCSA, the Commission must determine, "after considering all objections, that the cost of conversion as reflected in the joint report prepared pursuant to § 40-342 is economically and technically feasible for . . . the property owners affected." (A.R.S. § 40-346(A).) The term "economically and technically feasible" is not defined in the UCSA statutes, has not been analyzed in prior Arizona case law, and has not been analyzed in prior Commission decisions⁷⁰ concerning the establishment of UCSAs. Because the Legislature did

21

22

23

24

See Decision No. 40939 (October 21, 1970) (providing no analysis and granting the UCSA); Decision No. 55490 (March 19, 1987) (analyzing other issues and granting the UCSA); Decision No. 57051 (August 22, 1990) (providing no analysis and granting the UCSA); Decision No. 67437 (December 3, 2004) (providing no analysis and denying establishment of an UCSA because the petition did not meet the statutory requirements in A.R.S. §§ 40-343(A) and 40-346(A), and the PSCs had failed to obtain approval of the UCSA from the County Board of Supervisors).

1
 2
 3

4

5

6

7 8

10

11

9

12

13

14 15

16

18

17

19 20

2122

2324

25

2627

28

not define "economically and technically feasible" in A.R.S. § 40-341, the applicable definitions section, we must look to the common ordinary definitions of the terms at issue and can use dictionary definitions for that purpose. (See, e.g., Dowling v. Stapley, 179 P.3d 960, 964-65 (Ariz. App. Div. 1 2008).)

means "marked by careful, efficient, and prudent use of resources: thrifty." "Technically" is the adverb form of "technical," which means "having special and usually practical knowledge especially of a mechanical or scientific subject." "Feasible" means "capable of being done or carried out." Thus, "economically feasible" means capable of being done as a careful, efficient, and prudent use of resources, and "technically feasible" means capable of being done with the special and practical knowledge of undergrounding of facilities. Although the statutory requirement—to determine whether the cost of conversion is capable of being done—is somewhat awkward, it appears that the Legislature intended for the Commission to determine, after considering all objections, (1) whether the costs of conversion in the joint report would be a careful, efficient, and prudent use of resources for the Hillcrest Bay property owners and (2) whether the undergrounding of facilities available.

176. In order for an expenditure of funds to be a careful, efficient, and prudent use of resources, the benefits resulting from the expenditure must outweigh the burden of the expenditure. Thus, to determine economic feasibility, we must determine what benefits would result from the establishment of the UCSA and whether those benefits outweigh the costs of establishing the UCSA.

177. The property owners supporting the UCSA have cited numerous benefits that they expect to result from the establishment of the UCSA, benefits that can be assigned to the following broad categories: (1) improved aesthetics, (2) avoidance of the additional poles otherwise planned by APS, (3) improved service and reliability, (4) improved safety, (5) increased property values, (6)

Merriam-Webster Online Dictionary (visited May 13, 2008) http://www.merriam-webster.com/dictionary/feasible.

²⁰⁰⁸⁾ http://www.merriam- 13, (visited May Merriam-Webster Online Dictionary webster.com/dictionary/economically>. http://www.merriam- 2008) Dictionary (visited May 13, Merriam-Webster Online webster.com/dictionary/economical>. http://www.merriam- (visited May 13. 2008) Dictionary Merriam-Webster Online webster.com/dictionary/technical>.

1 e e 2 e 3 H 4 a 5 p 6 g 7 s 1 1 9 n

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

elimination of issues related to bird droppings, and (7) temporary job creation. There is ample evidence that removal of the overhead lines and utility poles would improve the aesthetics of Hillcrest Bay and that establishment of the UCSA would avoid the eventual installation of approximately 42 additional poles otherwise planned (at least tentatively) by APS and the potential parking inconvenience and additional unattractiveness that those poles may bring. The work generated by the UCSA also would likely result in temporarily increased employment or income for some construction workers, although not necessarily for anyone local to Hillcrest Bay or its environs. In addition, logic would indicate that if the poles and lines are removed from the skies, birds would no longer be perching upon them and leaving their droppings below.

There is not sufficient evidence to establish that the undergrounding of the power lines 178. and telephone lines would result in improved service and reliability to Hillcrest Bay. No new service offerings, such as broadband, will be offered as a result of the UCSA, and electrical service reliability will not be increased by the underground location of the facilities. Any increase in electrical service reliability will result from the installation of new facilities, whether underground or overhead, and thus will eventually result even if the UCSA is not approved, because APS intends to install new facilities either way (although they may be a long time coming). Furthermore, the evidence establishes that APS does not have service reliability problems in Hillcrest Bay that would be remedied by the establishment of the UCSA, as the vast majority of electrical outages in the past few years have been caused by loss of transmission source rather than the Hillcrest Bay facilities. The evidence establishes that that service reliability issue should be resolved through the WAPA line project and the new underbuilt three-phase feeder from the Colorado substation, which will eliminate use of the Buckskin substation. The evidence does not establish that there are currently any telecommunications service reliability problems in Hillcrest Bay or that any additional telecommunications services will be offered to Hillcrest Bay if the UCSA is approved.⁷⁵

25

26

27

We note that the transfer of Verizon's CC&N to NewILEC has been approved and that there is no evidence in this docket concerning what NewILEC's position will be as to providing additional services to Hillcrest Bay or keeping the existing telephone lines on APS's poles in the event that APS moves its lines to front-lot locations. It is possible that NewILEC's attitude toward maintaining the status quo will be different than that of Verizon.

26

27

28

179. As for safety, the evidence establishes that a utility pole fell into the street in October 2007 due to the degradation of the down guy and the pole itself and that, as a result of modifications (such as awnings and decks) made to homes in Hillcrest Bay, some lines are now located within the reach of individuals, at least individuals using a stick or other reach-extending device. There is no evidence, however, to indicate that anyone has been harmed as a result of the current location of the lines or the fallen utility pole. We are concerned about the safety of facilities and believe that any safety concerns resulting from the age of the current facilities or the location of the overhead power lines would be addressed by the establishment of the UCSA. However, we also believe that APS and Verizon are required to address any safety issues regardless of whether the UCSA is approved. APS is responsible, under Arizona Administrative Code ("A.A.C.") R14-2-208(A)(1), for the safe transmission and distribution of electricity until it passes the point of delivery to the customer, and Verizon is responsible, under A.A.C. R14-2-505(B)(2)(a), for all facilities up to the service access point. In addition, under A.A.C. R14-2-206(C)(2) and R14-2-505(B)(3)(b), respectively, if either APS or Verizon discovers that a customer or customer's agent has constructed facilities adjacent to or within an easement or right-of-way and that such construction poses a hazard, the utility is required to notify the customer or the customer's agent and to take whatever actions are necessary to eliminate the hazard at the customer's expense. Thus, it is incumbent upon both APS and Verizon to ensure that any actual safety issues created by the integrity of the current facilities or customer additions are addressed, regardless of whether the UCSA is approved. The evidence establishes that APS has begun a process to identify and address the encroachments that may exist in Hillcrest Bay. This is appropriate. While HBI has asserted that APS's plan to address these encroachments is a reason to support establishment of the UCSA, we cannot support that argument. Any owner who has encroached upon an APS easement or right-of-way, thereby creating a potential safety hazard, should not be permitted to complain about the potential safety hazard that the owner created.

180. The evidence in this matter also does not establish that the presence of bird droppings has caused illness in anyone or even that it is an actual health risk in Hillcrest Bay, as opposed to an inconvenience. (See Tr. II at 58-59; 67-68.) No one who is qualified to speak to the issue has been consulted by HBI, and no probative evidence has been presented on the subject of the bird droppings'

6

7

18

25 26

27

28

23

24

presenting a health risk in Hillcrest Bay. It would be pure speculation to assume that the bird droppings present in some Hillcrest Bay parcels present a current health risk that needs to be abated through the establishment of the UCSA. Additionally, we note that an owner who builds an uncovered patio under a utility line should foresee that birds will perch on the utility line and leave droppings on the owner's patio, particularly in an area such as Hillcrest Bay that is surrounded primarily by nature.

- Finally, whether and to what extent establishment of the UCSA would result in 181. increased property values for the homes in Hillcrest Bay has not been established by the evidence in this proceeding. Although Mr. Garcia, who has a wealth of experience in the real estate industry, has expressed his opinion that establishment of the UCSA would increase property values, as have other owners, Mr. Garcia's opinion and analysis are expressly based on a normalized real estate market, which Mr. Garcia acknowledged does not currently exist and may not exist for some time. What we can determine as to property values is that each parcel for which the owner does not pay for the conversion costs, including any service costs, in cash within 30 or 60 days will be subject to two new liens, one in favor of APS and one in favor of Verizon. These liens would effectively reduce the profit that could be derived from sale of the property and could also result in foreclosure on the property, if periodic payments are not made in a timely manner. In addition, the evidence establishes that any increase in value would only be realized upon sale of a parcel.
- Thus, in the final analysis, even after the second hearing, the evidence establishes that 182. the principal benefits to be derived from establishment of the UCSA are improved aesthetics and avoidance of the additional poles otherwise likely to be installed eventually by APS. Not even the benefit of improved aesthetics will be realized by all owners, as the evidence shows that some properties will not be benefited by the UCSA because they already enjoy unobstructed views, already have underground facilities, or are owned by owners who are not bothered by the poles and lines.
- 183. HBI and a number of other owners have been extremely generous in pledging their own funds to defray the expense of the UCSA for some low-income owners through the FAP. These owners should be lauded for their willingness to help their neighbors. In the end, however, the level of assistance to defray the private costs still amounts to only approximately 3.24 percent of the

original total private cost estimate of \$902,527 and to only approximately 3.43 percent of the Tades I total private cost estimate of \$851,429.92. This level of support would only make a small dent in those private costs and would make no dent in the much larger public costs and service costs. In addition, the FAP may contravene A.R.S. § 40-347(C), which requires that funds that become available from private sources to pay any part of underground conversion costs be applied on a pro rata basis to reduce the underground conversion cost charged against each parcel. Also, the evidence does not establish that Tades II can be relied upon in determining economic feasibility, assuming that it is permissible under A.R.S. § 40-346(A) to consider public costs and service costs other than as expressed in the joint report referenced in the statute. Neither APS nor Verizon has authorized Tades to do any of the work, it is unclear whether Tades II includes all of the work that Verizon included in its own service cost estimates, and the Tades II quote bases service costs on square footage as opposed to parcel-specific work, in contravention of the UCSA statutes. (See A.R.S. §§ 40-347(A)(4) and (B), 40-348(A) and (B), 40-349(A), 40-350(A).)

184. The financial burdens of establishing the UCSA are significant, even when considering only the public costs and service costs, which can be financed over a term of up to 15 years with interest. The public costs and service costs to be assessed per parcel are shown in Exhibit C and range from a low of \$4,410.51 to a high of \$32,480.22. For 62 of the Parcels, those costs exceed \$10,000. Not only would the establishment of the UCSA result in significant public costs and service costs, but it would result in significant private costs, totaling between \$851,429.92 and \$902,527 and ranging, per parcel, from a low of \$0 to a high of \$11,146.44 based on the original private cost estimate or from a low of \$0 to a high of \$10,735 based on Tades I. For 75 parcels, the Tades I private costs still exceed \$5,000. The statutory scheme does not allow for these private costs to be financed along with the public costs and service costs, so they would need to be paid out of pocket by the owner or financed through means other than the PSCs. During these times of recession, ⁷⁶ that financing could prove difficult to obtain, particularly for those owners who would be unable to pay out of pocket.

Official notice has been taken that the U.S. has been in recession since December 2007.

 185. In addition to considering the costs themselves, it is also necessary to consider the owners upon whom they will fall and the times that we are in. The homes in Hillcrest Bay range from two-story luxury homes to single-wide trailers, and the owners range from the affluent to those with a low or fixed income or even currently without income. The evidence suggests that it is primarily full-time residents of Hillcrest Bay who have fixed incomes and who are least able to afford the costs of the UCSA. This is consistent with the statements of the opponents to the UCSA, many of whom have stated that they cannot afford the costs and some of whom have even stated that they would be forced out of their homes as a result of the costs. Even supporters of the UCSA have acknowledged that there are owners who cannot afford to pay the costs they would incur for the establishment of the UCSA.

186. The national and Arizona economy has changed dramatically since the joint petition was filed in 2007. The country is currently in recession, and the owners have been impacted, as a number of them have recounted in their comments to the Commission and in testimony. There have even been several foreclosures in Hillcrest Bay since the first hearing in this matter. The evidence establishes both that nonpayment of UCSA costs can result in foreclosure and that a number of owners believe that they cannot afford to pay the UCSA costs. The validity of these fears is bolstered by the significant drop in support for and the increased opposition to the UCSA for economic reasons.

187. When balancing the benefits that would be derived from the establishment of the UCSA against the burdens that would result from the establishment of the UCSA, we find that the overall benefits are outweighed by the overall burdens. The costs of conversion would not be a careful, efficient, and prudent use of resources for the owners. Thus, the establishment of the UCSA is not economically feasible for the owners affected and cannot be approved by the Commission in light of the evidence in this case.

CONCLUSIONS OF LAW

1. Parcel 274 was included within the proposed UCSA in the first petition, the second petition, and the joint petition and must be included within the total square footage of the UCSA and the owner count for purposes of determining percentages of ownership approval and objections.

7 8

10

9

12

11

13 14

15 16

17 18

19 20

21

22 23

24

25

26

- 2. The request for withdrawal filed by Ms. Erna Davis, owner of Parcel 208, was timely filed and legally sufficient and results in Ms. Davis's parcel being eliminated from the owner count and square footage of the owners supporting the UCSA and instead added to the owner count and square footage of the owners opposing the UCSA.
- To approve the establishment of an UCSA, among other things, the Commission must 3. determine, after considering all objections, that the cost of conversion as reflected in the joint report is economically feasible for the owners involved.
 - Notice of the proceedings in this matter was provided as required by law. 4.
 - Parcel 274 would not be benefited by the establishment of the UCSA. 5.
- Parcels that already have an unobstructed view and parcels already served by 6. underground utility lines would not be benefited by the establishment of the UCSA.
- 7. It is not economically or technically feasible to eliminate from the UCSA, under A.R.S. § 40-346(B), the parcels that would not be benefited or for which the conversion is not economically feasible, as doing so would result in the existence of parallel overhead and underground systems.
 - The cost of conversion is not economically feasible for the property owners affected. 8.
 - The joint petition for establishment of an UCSA should be denied. 9.
- If any electric lines before the point of delivery on a parcel are hanging within reach of 10. a person, APS is responsible, under A.A.C. R14-2-208(A)(1), to take whatever action is necessary to ensure the safe transmission and distribution of electricity.
- If APS discovers that a customer or customer's agent has constructed facilities 11. adjacent to or within an easement or right-of-way and that such construction poses a hazard, APS is required, under A.A.C. R14-2-206(C)(2), to notify the customer or the customer's agent and to take whatever actions are necessary to eliminate the hazard at the customer's expense.
- If Verizon or NewILEC, as applicable, discovers that a customer or customer's agent 12. has constructed facilities adjacent to or within an easement or right-of-way and that such construction poses a hazard, Verizon or NewILEC, as applicable, is required, under A.A.C. R14-2-505(B)(3)(b), to notify the customer or the customer's agent and to take whatever actions are necessary to eliminate

1	the hazard at the customer's expense.
2	13. Pursuant to A.R.S. § 40-344(I), APS and Verizon each must reimburse the
3	Commission \$1,452.78 for the mailing performed under A.R.S. § 40-344 for the original hearing.
4	<u>ORDER</u>
5	IT IS THEREFORE ORDERED that the joint petition of Arizona Public Service Company
6	and Verizon California, Inc. for establishment of an underground conversion service area in the area
7	known as Hillcrest Bay Mobile Manor is hereby denied.
8	
9	···
10	
11	
12	
13	
14	
15	
16	
17	
18	•••
19	•••
20	• • • • · · · · · · · · · · · · · · · ·
21	
22	
23	•••
24	•••
25	
26	
27	•••
28	•••

DECISION NO.

	TE TO ELIPETIED OFFICE	D that recovered to A.P.S. 8.40-344(I) for the mailing performed	
1	IT IS FURTHER ORDERED that, pursuant to A.R.S. § 40-344(I), for the mailing performed		
2	under A.R.S. § 40-344 for the original hearing, Arizona Public Service Company and Verizor		
3	California, Inc. shall each submit to the Arizona Corporation Commission's Business Office the		
4	amount of \$1,452.78, payable to the	"State of Arizona," for deposit into the State's General Fund.	
5	IT IS FURTHER ORDERE	D that this Decision shall become effective immediately.	
6	BY ORDER OF THE ARIZONA CORPORATION COMMISSION.		
7	D , 0.22.01		
8			
9	CHAIRMAN	COMMISSIONER	
10			
11	COMMISSIONER	COMMISSIONER COMMISSIONER	
12			
13		IN WITNESS WHEREOF, I, ERNEST G. JOHNSON, Executive Director of the Arizona Corporation Commission,	
14		have hereunto set my hand and caused the official seal of the Commission to be affixed at the Capitol, in the City of Phoenix,	
15		this, 2010.	
16			
17			
18		ERNEST G. JOHNSON EXECUTIVE DIRECTOR	
19			
20			
	DISSENT		
21			
22	DISSENT		
23	SNH:db		
24			
25			
26			
27			
28			
	ł ·		

1		
2	SERVICE LIST FOR:	ARIZONA PUBLIC SERVICE COMPANY AND VERIZON CALIFORNIA, INC.'S JOINT PETITION
3		FOR THE ESTABLISHMENT OF AN UNDERGROUND CONVERSION SERVICE AREA
4	DOCKET NO.:	E-01345A-07-0663 AND T-01846B-07-0663
5	210 22 002	210 22 015
6	310-32-002 Jennifer D. Fletcher 22482 Alma Aldea #79	310-32-015 Fred A. & Lynne S. Muzic 16411 Underhill Ln.
7	Sancho Santa Margarita, CA 92688	Huntington Beach, CA 92647
8	310-32-003 Michael Little c/o Jennifer D. Fletcher 22483 Alma Aldea #79	310-32-016 Wayne D. & Zelma M. Dunham, Trustees, Dunham Family Trust
9	Sancho Santa Margarita, CA 92688	P.O. Box 68 San Clemente, CA 92674
10	310-32-005A Albert L. & Maria G. Reyes 11751 Roswell Ave.	310-32-017 Wayne D. & Zelma M. Dunham, Trustees,
11	Chino, CA 91710	Dunham Family Trust P.O. Box 68
12	310-32-006 Veronica Pedregon	San Clemente, CA 92674
13	855 Bay View Drive Parker, AZ 85344	310-32-018 Carl Alvarado & Sherry Craven 791 Bay View Dr.
14	310-32-007 David P. & Patricia Carmichael	Parker, AZ 85344
15	912 S. Easthills Dr. West Covina, CA 97191	310-32-019 Kelli Smith
16	310-32-008 Veronica Pedregon	927 High Country Glendora, CA 91740
17	855 Bay View Drive Parker, AZ 85344	310-32-020 Duane E. & Ruth V. Ferguson, Trustees,
18	310-32-009	Ferguson Trust 2814 Manor View Dr. Parker A.7, 85244
19	Larry Cartwright 75 Keegan Court Susanville, CA 96130	Parker, AZ 85344 310-32-021
20	310-32-010	Duane E. & Ruth V. Ferguson, Trustees, Ferguson Trust
21	Larry Cartwright 75 Keegan Court Susanville, CA 96130	2814 Manor View Dr. Parker, AZ 85344
22	310-32-011	310-32-022 Mac & Joyce Frazier
23	Robert L. & Roberta A. Golish 501 N. Clentine St.	1777 Lewis Ave. Long Beach, CA 90813
24	Anaheim, CA 92801 310-32-012A	310-32-024 Clark & Piper Slone
25	Wyman & Donna J. Johnson 17806 Quantum Pl. Pierre, SD 57501	40641 Bear Creek St. Indio, CA 92203
26	310-32-014A	310-32-025 Brian & Kelly Strauss
27	Richard S. & Joy M. Muzic, Trustees, Muzic Living Trust	20592 Porter Ranch Rd. Trabuco Canyon, CA 92679
28	10313 Felson St. Bellflower, CA 90706	

1	310-32-026	310-32-038
1	Charles E. Stirewalt	Kent A. & Teresa B. Thompson
2	2932 Ballesteros Ln.	13811 Mayport Ave.
2	Tustin, CA 92672	Norwalk, CA 90650
3	310-32-027	310-32-040A
	Edward Woodworth Deuel III & Nancy Lee Deuel,	Albert & Amelia Nevares
4	Trustees,	4756 Murietta St.
	Edward & Nancy Deuel Family Trust	Chino, CA 91710
5	6892 Via Carona Dr.	212.22.24
	Huntington Beach, CA 92647	310-32-041
6	310-32-028	Ruben Gomez, Jr. & Diane Gomez; William C. & Constance F. Riach and Jed William Riach
U	Rick Wood	P.O. Box 112
~	21 Palmera	Running Springs, CA 92382
7	Santa Margarita, CA 92504	raming opings, or 72502
_		310-32-043A
8	310-32-029	Johnny A. & Billie Dodson
	John Jacob Westra & Calvin Nyles Westra,	816 Bay View Dr.
9	Trustees, Westra Family Trust	Parker, AZ 85344
	4379 Hwy 147	210 22 0454
10	Lake Almanor, CA 96137	310-32-045A
	310-32-030	Nando F. Haase & Donna C. Merrill 830 Bay View Dr.
11	Sergio and Maria Sanchez	Parker, AZ 85344
	12635 Farndon Ave.	1 dikor, 112 035 1 1
12	Chino, CA 91710	310-32-047A
12	·	Fred & Lynne Muzic
1.2	310-32-031	16411 Underhill Ln.
13	Betty Jane Bryant & Goldie June Jordan	Huntington Beach, CA 92647
	78976 Spirit Court	
14	Palm Desert, CA 92211	310-32-048A
	310-32-032	Elizabeth A. Hacke 858 Bay View Dr.
15	Betty Jane Bryant & Goldie June Jordan	Parker, AZ 85344
	78976 Spirit Court	Tarkor, The booms
16	Palm Desert, CA 92211	310-32-049
		Michael Schaper
17	310-32-033	7383 SVL Box
	Gale M. & Eileen Dalton	Victorville, CA 92392
18	2910 S. Manor View	210 22 050
10	Parker, AZ 85344	310-32-050 Varanica Padragan
19	310-32-034	Veronica Pedregon
19	Roger Andrew & Sally Jeanne Shore, Trustees,	855 Bay View Dri. Parker, AZ 85344
00	Shore Family Revocable Living Trust	Tarket, 712 03311
20	21225 Pinebluff Dr.	.310-32-052B
	Trabuco Canyon, CA 92679	Roy & Margaret Hokenson
21		951 Swan Dr.
	310-32-035	Parker, AZ 85344
22	Steve Benton & Delia Alvarado	210 22 0520
ļ	2948 S. Noble View Dr. Parker, AZ 85344	310-32-052C
23	Faikei, AZ 63344	Roy & Margaret Hokenson 951 Swan Dr.
	310-32-036A	Parker, AZ 85344
24	Linda Ledbetter	Turker, 112 05544
27	570 Rim View Dr.	310-32-053
25	Twin Falls, ID 83301	Timothy & Jola Nette Hubbs
ر ک		P.O. Box 474
~ I	310-32-037	Running Springs, CA 92382
26	Kenneth J. & Eileen K. Thompson, Trustees	210,22,054
	78710 Darrell Dr.	310-32-054
27	Bermuda Dunes, CA 92201	Jack M. & Barvara Jo Hutchens, Trustees, Hutchens Family Trust
1		151 N. Holgate
28		La Habra, CA 90631
H		•

DOCKET NO. E-01345A-07-0663 ET AL.

1 2	310-32-056A Larry W. & Shearl Lynn Thompson 12642 Lamplighter Garden Grove, CA 92845	310-32-072 Richard R. Gervais 5234 Carlingford Ave. Riverside, CA 92504
3	310-32-057 Hillcrest Bay Inc. 924 Bay View Dr. Parker, AZ 85344	310-32-073 Richard Gervais 5234 Carlingford Ave. Riverside, CA 92504
5	310-32-060A Roy M. & Margaret Hokenson 951 Swan Dr. Parker, AZ 85344	310-32-074 Gerald W. & Michelle C. Gatlin & Jeffrey W. & Tracy A. Gatlin 17618 Regency Circle Bellflower, CA 90706
7 8 9	310-32-061A Barbara A. Demerest 11616 Reche Canyon Rd. Colton, CA 92324	310-32-075 Gerald W. & Michelle C. Gatlin & Jeffrey W. & Tracy A. Gatlin 17618 Regency Circle Bellflower, CA 90706
10 11	310-32-062A Brian D. Wood & Arthur Wood, Jr. 3217 S. North Shore Dr. Ontario, CA 91761	310-32-076 Dowell A. & Katherine S. Kubicka, Trustees, Dowell A. Kubicka & Katherine S. Kubicka Family Trust
12 13	310-32-063A Juliana Perez 4169 Mentone Ave. Culver City, CA 90232	6819 Tahiti Dr. Cypress, CA 90630 310-32-077
14 14	310-32-064A Michael Joseph & Tamara Lynn Wilkinson 4 Bella Firenze Lake Elsinore, CA 92532	Dowell A. & Katherine S. Kubicka, Trustees, Dowell A. Kubicka & Katherine S. Kubicka Family Trust 6819 Tahiti Dr. Cypress, CA 90630
16 17	310-32-065A John D. Yarbrough, II, & Jacqueline Y. Yarbrough, Trustees, Yarbrough Revocable Trust P.O. Box 616 Parker, AZ 85344	310-32-078 Terence W. Bitrich 1021 N. Puente St. Brea, CA 92821
18 19	310-32-066 Louise Denver 889 Swan Dr. Parker, AZ 85344	310-32-079 Terence W. Bitrich 1021 N. Puente St. Brea, CA 92821
20 21	310-32-068A Karen L. & James Bibby 873 Swan Dr.	310-32-080 Randy J. & Rachael Anne Stewart 1826 Comarago Court Coronado, CA 92833
22	Parker, AZ 85344 310-32-069 Carlson T. & Darlene E. Loftis, Trustees,	310-32-081 Geoffrey William Lambrose 784 Swan Dr.
2324	Carlson T. Loftis & Darlene E. Loftis Revocable Living Trust 54 West Forest Trail	Parker, AZ 85344 310-32-082 Cooffee William Lambrose
25	Free Soil, MI 49411 310-32-071A Colors & Darlors F. Lottis	Geoffrey William Lambrose 784 Swan Dr. Parker, AZ 85344
26	Carlson & Darlene E. Loftis 54 West Forest Trail Free Soil, MI 49411	310-32-083 Stuart & Denise Currie; Richard J. & Andrea S. Wilke, Trustees, Wilke Family Revocable Trust;
2728		and David M. & Dorothy D. Glynn 4545 Sunfield Ave. Long Beach, CA 90808

DOCKET NO. E-01345A-07-0663 ET AL:

1	310-32-084	310-32-097
	Stuart & Denise Currie; Richard J. & Andrea S. Wilke,	Filmore H. Anderson & Virginia L. Anderson
2	Trustees, Wilke Family Revocable Trust; and David M. & Dorothy D. Glynn	920 E. Swan Dr. Parker, AZ 85344
•	4545 Sunfield Ave.	
3	Long Beach, CA 90808	310-32-098 Arthur C. Wood III; Steven D. Wood; Brian D. Wood
4	310-32-085	2968 Thoroughbread St.
7	John M. & Peggy J. Steiner, Trustees,	Ontario, CA 91764
5	Steiner Family Trust 3220 Saratoga Ave.	310-32-099
	Lake Havasu City, AZ 86406	Link T. & Sandra C. Johnson, Trustees,
6	·	Link T. Johnson and Sandra C. Johnson
7	310-32-086 Trevor Goldi & Sierra Smith-Goldi & Earline R. Pool	Revocable Living Trust 1112 W. Houston Ave.
7	2775 Hillcrest Dr.	Fullerton, CA 92633
8	Parker, AZ 85344	310-32-100
Ŭ	310-32-087	Afred & Sheryl Beauvais
9	Clifton D. & Viola J. Lee, Trustees,	5318 Elk Court
	C. Lee Family Revocable Trust 229 W. Tudor St.	Fontana, CA 92336
10	Covina, CA 91722	310-32-101
11	310-32-088	Mark S. & Jeannine Long 548 Woodhaven Court
11	Clifton D. & Viola J. Lee, Trustees,	Upland, CA 91786
12	C. Lee Family Revocable Trust	310-32-102
	229 W. Tudor St. Covina, CA 91722	Scott D. & Grace D. Babcock
13		15944 E. Milvern Dr.
14	310-32-089 Donald E. Lee	Whittier, CA 90604
14	14049 Farmington St.	310-32-103
15	Oakhills, CA 92344	Linda Seidenglanz; Bill & Carol Crane 15040 Kinai Rd.
	310-32-090	Apple Valley, CA 92307
16	Ronald D. & Mary P. Lee	310-32-104A
17	14049 Farmington St. Oakhills, CA 92344	Richard M. Hoyt; Mark A. & Kathy A. Hoyt
1 /	210 22 001	38821 Kilimanjaro Dr.
18	310-32-091 Jo-Anne M. Lynn	Palm Desert, CA 92211
	872 E. Swan Dr.	310-32-106A
19	Parker, AZ 85344	William H. & Shari D. Dage P.O. Box 1297
20	310-32-092	Banning, CA 92220
20	Jo Ann C. Goldbach, Trustee, Jo Ann C. Goldbach Revocable Trust	310-32-107
21	880 E. Swan Dr.	Gerald C. & Carol L. McGinnis, Trustees,
	Parker, AZ 85344	McGinnis Family Trust 3370 Lees Ave.
22	310-32-094A	Long Beach, CA 90808
23	Donald & Virginia Vaughn	210.22.1084
23	888 E. Swan Dr. Parker, AZ 85344	310-32-108A Gary L. & Suzanne A. Smith
24	,	531 Apache Dr.
	310-32-095 Cummins Investments, Inc.	Placentia, CA 92870
25	P.O. Box 665	310-32-110A
26	Lake Havasu City, AZ 86405	Ronald K. & Lorraine C. Johnson
26	310-32-096	885 Crystal View Dr. Parker, AZ 85344
27	Thomas P. & Cynthia A. McGregor, Trustees,	•
	McGregor Trust 914 Swan E. Drive	
28	Parker, AZ 85344	

		
1 2	310-32-111 Troy & Tammie Ward 41775 Cascade Ct. Temecula, CA 92591	310-32-126 Leah C. Wagner 7516 Shoup Ave. West Hills, CA 91307
3	310-32-112 Richard A. & Kimberly E. Hampton 1143 Andrew Ln.	310-32-127 Leah C. Wagner 7516 Shoup Ave.
5	Corona Ln., CA 92881	West Hills, CA 91307
6	310-32-113 Nancy Suzanne Archer 860 Crystal View Dr. Parker, AZ 85344	310-32-128 Dennis A. & Phyllis A. Ingram 828 Crystal View Dr. Parker, AZ 85344
7 8	310-32-114 Raymond G. Grossman, Sr. & Ann M. Grossman 118 N. Morada West Covina, CA 91790	310-32-129 Charles E. & Judy Rutledge, Trustees, Rutledge Family Trust P.O. Box 185
9	310-32-115	Lucerne Valley, CA 92356
10	Charles T. & Ellen L. O'Neill 22062 Broken Bow Dr. El Toro, CA 92630	310-32-130 Dan & Teri Peters 5838 Applecross Dr.
11	310-32-116 Victoria Kukuruda	Riverside, CA 92507 310-32-132A
13	30670 Watson Rd. Homeland, CA 92548	Merle D. & Janet J. Calvin 862 Crystal View Dr.
14 15	310-32-118A Raymond D. & Patricia Easley 4161 Ricardo Dr. Yorba Linda, CA 92886	Parker, AZ 85344 310-32-133 William & Harlayne Bond 6042 W. Potter Dr. Glendale, AZ 85308
16 17	310-32-119 Jacqueline J. & Sandra J. Johnson 809 Crystal View Dr. Parker, AZ 85344	310-32-135A Glenn E. Ecker & Patricia A. Tanges 880 Crystal View Dr. Parker, AZ 85344
18 19	310-32-120A Sharon Error, Trustee, Sharon Error Trust P.O. Box 575745 H Salt Lake City, UT 84157	310-32-136 Robert W. & Camille A. Hughes 13803 Pequot Dr.
	310-32-122A	Poway, CA 92064
20	Marvin L. & Joan K. Jordan P.O. Box 228 La Quinta, CA 92253	310-32-137 Gregory C. & Gwendolyn Mesna; Nathan J. & Whitney Mesna
22	310-32-123	P.O. Box 2344 Running Springs, CA 92382
23	Louis M. & Linda D. Wilson 4421 E. Valley Gate Anaheim Hills, CA 92807	310-32-138 Roberta A. & Donald A. Anderson
24	310-32-124 Victor M. & Priscilla M. Horta	1143 Sharon Rd. Santa Ana, CA 92706
25	8057 Armagosa Dr. Riverside, CA 92508	310-32-139 Albert O. LaFreniere 1691 Chandler Dr.
26	310-32-125 Boyce L. & Teresa A. Harker;	Lake Havasu City, AZ 86403
27	Trent W. & Laura M. Harker 79-165 Canterra Circle La Quinta, CA 92253	310-32-140 Caleb J. & Kristina A. Brandel & Judith B. Shipley 7307 Lenox
28	La Yuma, On 1220	Riverside, CA 92504

1 2	310-32-141 Ted & Carla Bultsma and Leslie Gossinberger P.O. Box 3612 Running Springs, CA 92382	310-32-156A Delvin G. & Gertrude A. Warren; Jenna Messina 278 Agate Way Broomfield, CO 80020
3	310-32-142	310-32-157
4	Virginia Donohue 28384 Champions Dr. Menifee, CA 82584	Thomas J. Gealy, IV & Denise M. Gealy; Edward F. Ferrall, Sr. & Margaret Ferrall; & Edward Ferrall, Jr. & Susan L. Ferrall
5	310-32-143	18250 Devonwood Cir Fountain Valley, CA 92708
6	Robert & Lori Nielson P.O. Box 401971 Hesperia, CA 92340	310-32-158 Donald & Melody Clark
7	310-32-144	16900 Taft Street Riverside, CA 92508
8	John L & Jane R. Sears, Trustees, Sears Living Trust 10532 Mira Vista Dr. Santa Ana, CA 92705	310-32-159 Paul L. & Carol A. Pudewa
9	310-32-145	3531 Lama Ave Long Beach, CA 90808
10	Dan R. & Vivian T. Good, Trustees, Dan R. Good and Vivian T. Good Declaration of Trust	310-32-160
11	P.O. Box 53 Hwy 108 Strawberry, CA 95375	Ricky & Karen L. Bullard 814 Anderson Court Redlands, CA 92374
12	310-32-146 Judi L. Noble	310-32-161
13	1444 E. 13th St. Upland, CA 91786	Gerald D. Flores 25092 Portsmouth Mission Viejo, CA 92692
14	310-32-147 Dennis R. & Catherine Roustan, Trustees,	310-32-162
15	Roustan Living Trust 1640 E. Appalachian Rd. Flagstaff, AZ 86004	Gary W. Smith 791 Linger Dr. Parker, AZ 85344
16	310-32-148	310-32-164
17	Linda Kay Clamp & David Edward Seaver 3457 El Camino Real	Thomas F. Anderson, Ernest Vanier, & Robert K. Anderson 2918 Redwood Circle
18	Palo Alto, CA 94306 310-32-150A	Fullerton, CA 92635
19	Scott K. Jones, Sr. & Carole A. Jones, Trustees, Jones Revocable Trust	310-32-165 Tom W. & Kathryn A. Ayers, Trustees,
20	7991 Inwood Ln. La Palma, CA 90623	Ayers Revocable Trust 4063 Lakeview Rd. Lake Havasu City, AZ 86406
21	310-32-151A Pamela A. Leggett, Trustee,	310-32-166
22	Pamela A. Leggett Revocable Trust P.O. Box 1395 Parker, AZ 85344	Judith B. Shipley 14325 Laurel Drive Riverside, CA 92503
23	310-32-153A	310-32-167
24	Cynthia I Miles & Sandra L. Magana 961 N. Cleveland St.	John W. Kourkos & Jamie Brandel; William W. & Geraldine Brandel
25	Orange, CA 92867	14255 Judy Ann Drive Riverside, CA 92503
26	310-32-154 Laurence A. & Marjorie Ward 867-E Linger Dr.	310-32-168 David & Susan Thomas
27	Parker, AŽ 85344	2508 Dashwood Lakewood, CA 90712
28		

ı		
1	310-32-169A	310-32-183C
	David & Susan Thomas 2508 Dashwood	William M. & Joan Whittlinger; Ted & Mary Whittlinger
2	Lakewood, CA 90712	786 Linger Drive Parker, AZ 85344
3	310-32-170A	310-32-184
4	Shane Jolicoeur 852 Linger Dr.	Craig A. & Cindy S. Martin, Trustees,
_	Parker, AZ 85344	Martin Family Revocable Trust 49071 Denton Rd., Apt. 106
5	310-32-172C Robert & Danielle Franck	Belleville, MI 48111
6	134 Villa Rita Dr	310-32-186A Ronald & Sylvia Nelson
7	La Habra Hgts, CA 90631	835 Max View Dr.
	310-32-173A Scott Jones, Sr. & Carole A. Jones, Trustees,	Parker, AZ 85344
8	Jones Revocable Trust 7991 Inwood Ln.	310-32-188B Jerome P. & Karen M. Bowe
9	La Palma, CA 90623	849 Max View Dr. Parker, AZ 85344
10	310-32-174	·
10	Theodore R. & Mary L. Marical 711 Rosewood Ln.	310-32-189A Dudley and JoAnn Palmer
11	La Habra, CA 90631	1201 Mt. View Dr. Forest Grove, OR 97116
12	310-32-175 Theodore R. & Mary L. Marical	310-32-190
12	711 Rosewood Ln.	Timothy Gordon & Robin Alicia Evans
13	La Habra, CA 90631	24482 Chamalea Mission Viejo, CA 92691
14	310-32-176 Andrew P. & Debra D. Grimes	310-32-191
15	904 Linger Dr. Parker, AZ 85344	Timothy G. & Robin A. Evans 24482 Chamalea
16		Mission Viejo, CA 92691
16	310-32-177 Edward Mark & Beverly A. Lauer	310-32-192
17	914 Linger Dr. Parker, AZ 85344	Khanim Poplet 981 Charles St.
18	310-32-178	Banning, CA 92220
	Constance Ann Estabrook	310-32-193 Keith Blanchard
19	1426 Cleveland Loop Dr. Roseburg, OR 97470	10529 Cantrell Ave.
20	310-32-180A	Whittier, CA 90604
21	Janice Powers 934 Linger Dr.	310-32-195A Scott K. Jones, Jr. & Zahira V. Delgadillo, Trustees,
	Parker, AZ 85344	Scott K. Jones, Jr. and Zahira V. Delgadillo Jones Revocable Trust
22	310-32-181	5732 Placerville Pl.
23	Rick J. McCurdy 6417 Sherman Way	Yorba Linda, CA 92886
24	Bell, CA 90201	310-32-196 Richard L. & Nancy L. Fisher
24	310-32-182 William E. & Jeannette L. Horn	582 W. Mount Carmel Dr. Claremont, CA 91711
25	954 Linger Dr.	·
26	Parker, AZ 85344	310-32-197 Mildred R. Dann
	310-32-183A Gary J. Schmitt	931 E. Max View Dr. Parker, AZ 85344
27	3229 Kluk Ln Suite 100	,
28	Riverside, CA 92501	


28

1	310-32-198 Robert & Bonnie Strong	310-32-211 Jerry & Kelly Goodman
2	3602 Fairman Lakewood, CA 90712	68440 Tahquitz Rd. #4 Cathedral City, CA 92234
3	310-32-199 Philip S. & Ina L. Wigley 250 E. Forest Ave	310-32-213A Joseph & Alis E. Troya; Peter W. & Ilene Kraemer 3551 Ames Pl. Carlsbad, CA 92008
5	Arcadia, CA 91006 310-32-200	310-32-214
6	William A. Baca 9700 La Capilla Ave Fountain Valley, CA 92708	Melvin E. Hegler 18729 Lemarsh Northridge, CA 91324
7 8	310-32-201 Annette M. Kincaid 1975 W. Linden St. Riverside, CA 92507	310-32-215 John R. & Judith L.P. McLean 5081 Norris St. Irvine, CA 92604
9	310-32-202 Kevin D. Martin; Kevin D. & Melanie Martin 1214 Las Arenas Way	310-32-216A Frank I. & Jan (aka Janet) Robles P.O. Box 31417
11	Costa Mesa, CA 92627	Tucson, AZ 85751
12	310-32-203 James C. Schmidt, Jr. & Carol L. Schmidt 26045 Matlin Rd	310-32-218A Anne Grisham 816 Noble view Dr. Parker, AZ 85344
13	Ramona, CA 92065 310-32-204	310-32-219
14	Howard A. & Helen F. Twardoks 15933 Malden St. North Hills, CA 91343	Wesley E. Bergstrom Sr. & Therese Bergstrom, Wesley E. Bergstrom Jr. 25681 Palmwood Dr.
15	310-32-205	Moreno Valley, CA 92557
16 17	Melvin Edward Hegler 18729 Lemarsh Northridge, CA 91324	310-32-220 Michael S. & Marie B. Mendez 4091 Carroll Ct. Chino, CA 91710
18	310-32-206 Antonio & Ilen Elias-Calles, Trustees, Antonio Elias-Calles and Ilen Elias-Calles Family Trust 18922 Flagstaff Ln.	310-32-221 Kevin R. & Cynthia Anne Runge 4485 Sunburst Dr.
19	Huntington Beach, CA 92646	Oceanside, CA 92056
20	310-32-207 Antonio & Ilen Elias-Calles, Trustees, Antonio Elias-Calles and Ilen Elias-Calles Family Trust	310-32-222 Hollis I. Harvey 130623
22	18922 Flagstaff Ln. Huntington Beach, CA 92646	Big Bear Lake, CA 92315
23	310-32-208 Ema Davis	310-32-223 John W. & Catherine M. Marchesi, Trustees, Marchesi Family Trust 3224 Hill View Dr. South
24	922 Max View Dr. Parker, AZ 85344	Chino, CA 91710
25	310-32-209 Randy R. & Lisa T. Poole 8019 E. Gray Rd.	310-32-224 Matthew Annala 13122 Olympia Way
26	Scottsdale, AZ 85260	Santa Ana, CA 92705
2728	310-32-210 Robyn L. Stein 2338 N. Eaton Ct. Orange, CA 92867	310-32-225 Richard L. & Helen T. Powell 874 Noble View Dr. Parker, AZ 85344
1		•

1	310-32-226	310-32-238
2	Charles S. & Barbara A. Manning, Trustees 29214 Old Wrangler Rd Canyon Lake, CA 92587	Thomas W. & Teddie Jo Lorch, Trustees, Thomas W. Lorch and Teddi Jo Lorch Trust 2948 Via Blanco
3	310-32-227	San Clemente, CA 92673
4	Harold Eric & Kathie Jo Jones 4715 E. Warwood Rd	310-32-239 Thomas W. & Teddie Jo Lorch, Trustees, Thomas W. Lorch and Teddi Jo Lorch Trust
5	Long Beach, CA 90808 310-32-228	2948 Via Blanco San Clemente, CA 92673
6	Michelle M. Gayler P.O. Box 1413 Thormal CA 02274	310-32-240 Rodney W. Kawagoye & Judy C. Wilson
7	Thermal, CA 92274 310-32-229	2971 Dunlap Dr. Parker, AZ 85344
8	Malliett Investments, LLC 5373 W. First St.	310-32-242A
9	Ludington, MI 49431 310-32-230	Vernon G. & Loretta J. Kraus 2963 Dunlap Dr. Parker, AZ 85344
10	Robert P. & Carol E. Bischoff, Trustees, Bischoff Living Trust	310-32-243
11	651 Center Crest Redlands, CA 92373	Clyde L. & Jeanne F. Hentzen 2949 Dunlap Dr. Parker, AZ 85344
12	310-32-231 Thomas J. & June K. Kraus	310-32-245A
13	10765 Barnes Rd Eaton Rapids, MI 48827	Philip J. Garcia & Deborah A. Laurence 3152 Walker Lee Dr. Los Alamitos, CA 90720
14	310-32-232 Kenneth B. Hepler, Jr.	310-32-247A
15	40735 La Colima Temecula, CA 92591	Douglas & Karen Greer 37293 Marina View Parker, AZ 85344
16	310-32-233 Kent A. & Teresa B. Thompson	310-32-248
17	13811 Mayport Ave. Norwalk, CA 90650	Edward F. Mueller 6684 Vinal Haven Ct. Cypress, CA 90630
18	310-32-234 Bertha M. Stites, Trustee	310-32-249
19	P.O. Box 432 Acme, MI 49610	Budget LLC 1849 Sawtelle Blvd.
20	310-32-235	Los Angeles, CA 90025
21	Ronald J. & Phyllis McDonnell, Trustees, Ronald & Phyllis McDonnell Family Trust	310-32-251A Douglas & Karen Greer
22	P.O. Box 71 Marsing, ID 83639	37293 Marina View Parker, AZ 85344
23	310-32-236 Robert & Kathleen Thurman	310-32-252 Daryl C. Reykdal & Keith Woulard
24	415 Portola St. San Dimas, CA 91773	P.O. Box 79 Yucaipa, CA 92399
25	310-32-237 Norman R. & Dianna L. Dump	310-32-253 David M. & Renee L. Welker
26	9329 Lake Canyon Rd. Santee, CA 92071	2875 Hillcrest Dr. Parker, AZ 85344
27		310-32-254 Jane Schue, Trustee, Schue Living Trust
28		3706 Bluegrass Dr. Lake Havasu City, AZ 86406

1	310-32-255	310-32-271A
•	Lonnie & Corky Gault	Gregory K. & Michelle L. Walsh
2	1836 E. Meadowmere	15611 Obsidian Ct.
2	Springfield, MO 65804	Chino Hills, CA 91709
		Chino Tims, CA 71707
3	310-32-256	310-32-272
	George & Debbie Radvansky	Hillcrest Bay Inc.
4	2855 Hillcrest Dr.	924Bay View Dr.
-1	Parker, AZ 85344	Parker, AZ 85344
_	Tankor, NED 655 / /	laikei, AZ 65544
5	310-32-257	310-32-273
	Gerald & Shawna Johnson	Hillcrest Bay Inc.
6	P.O. Box 80	924 Bay View Dr.
Ū	Cabazon, CA 92230	Parker, AZ 85344
7	333333	I dikel, AZ 05544
/	310-32-259A	310-32-274
	Steven Norris	La Paz County
8	P.O. Box 2512	1108 Joshua Ave.
	Running Springs, CA 92382	Parker, AZ 85344
9	Namming optimizer, City 22302	1 dikei, AZ 65544
7	310-32-260A	91312703
4.0	Larry E. & Laura S. Greseth	Hillcrest Water Company, Barbara Dunlap
10	1026 Yavapai Hill Dr.	915 E. Bethany Home Rd.
	Prescott, AZ 86301	
11	1.122011, 1120 00001	Phoenix, AZ 85014
	310-32-261	Martin Brannan
10	Brian Bolton	La Paz County Attorney
12	#2 Vista Del Sol	1320 Kofa Avenue
	Laguna Beach, CA 92651	Parker, AZ 85344
13	Bagaila Boacii, Cit 72031	raikei, AZ 65544
	310-32-262	George Noult
14	Brian Bolton	George Nault
14	#2 Vista Del Sol	La Paz County Assessor
	Laguna Beach, CA 92651	1112 Joshua Avenue, Suite 204
15	Buguna Beach, Off 72031	Parker, AZ 85344
	310-32-263	Jeffrey Crockett
16	Andre M. & Linda E. Duran & Rudy E.	Robert J. Metli
10	& Simonette E. Lovato	SNELL & WILMER L.L.P.
17	23147 Donahue Ct.	One Arizona Center
17	Moreno Valley, CA 92553	400 East Van Buren Street
	indicate validy, CA 72333	Phoenix, AZ 85004
18	310-32-264	Thochix, AZ 83004
	Charles Joseph Swan	Thomas U. Campball
19	2801 Hillcrest Dr.	Thomas H. Campbell Michael T. Hallam
17	Parker, AZ 85344	
	- minery , and 000 11	LEWIS AND ROCA, L.L.P.
20	310-32-265	40 N. Central Avenue, Ste. 1900
	Michael E. & Melanie A. Stewart	Phoenix, AZ 85004
21	2793 Hillcrest Dr.	Michael W. Dotton
۱ ـ	Parker, AZ 85344	Michael W. Patten
	i unnoi, Nei Ouutti	Timothy J. Sabo
22	310-32-267A	Jeffrey D. Gardner
	Jim Thurman	ROSHKA DEWULF & PATTEN, PLC
23	9352 Creekside Ct., Apt. 31	One Arizona Center
	Santee, CA 92071	400 East Van Buren Street, Ste. 880
~ .	Santee, CA 92071	Phoenix, AZ 85004
24	310-32-269A	Jamies Alexand Chief Co. 1. 1. 1. 1. 1.
		Janice Alward, Chief Counsel, Legal Division
25	William H. & Shari D. Dage	ARIZONA CORPORATION COMMISSION
	P.O. Box 1297	1200 West Washington Street
26	Banning, CA 92220	Phoenix, AZ 85007
26	210 20 2704	
Į.	310-32-270A	Steven M. Olea, Director, Utilities Division
27	Beth S. Shamnurg & Jeffrey G. Johnson	ARIZONA CORPORATION COMMISSION
	2775 Hillcrest Dr.	1200 West Washington Street
- 20 l	Parker, AZ 85344	Phoenix, AZ 85007
28		
ll:		

EXHIBIT A



310-32-016

3 310-32-003 6 310-32-006A 6 310-32-006 6 310-32-008 7 310-32-008 8 310-32-010 10 310-32-011 11 310-32-012A 12 310-32-014A

2 310-32-034A 3 310-32-035A 4 310-32-038A 5 310-32-037 3 310-32-038 7 310-32-038 6 310-32-039

310-32-041 310-32-043A 310-32-046A 310-32-047A 310-32-048A 310-32-048 310-32-048

28 310-32-030 29 310-32-031 30 310-32-032 31 310-32-033

310-32-027 310-32-028

310-32-029

Parcel SF Signed 1st Supporting Signed 2nd Supporting Suppor		Albert & Ameila Neveres Ruben Gomez, Jr. & Diane Gomez; William C. & Constance F. Rlach & Jed William Rlach A. Johnny A. & Billia Dodson A. Nando F. Haase & Donna C. Merrill A. Fred & Lynne Muzic A. Elizabeth A. Hacke Michael Schaper Veronica Padregon Roy & Margaret Hokenson	9 Family Trust 10hn Jacob Westra & Caivin Nyles Westra, Trustees, Westra 2882 Manor View Drive 2884 Manor View Drive 2894 Manor View Drive 2894 Manor View Drive 2895 Noble View Drive 2895 Noble View Drive 2896 Manor View Drive 2896 Manor View Drive 2896 Manor View Drive 2896 Manor View Drive 2897 Noble View Drive 2898 Noble View		Owner Namels Jennifer D. Fletcher Jennifer D. Fletcher & Mikel W. Lilite Baff Bay View Drive Jennifer D. Fletcher & Mikel W. Lilite Baff Bay View Drive Baff Bay View Drive
Signed 2nd Supporting Petition 2nd Petition 2nd Petition 2nd Petition 1 578.0 1 5686.6 1 5687.3 1 4002.1 1 4002	Page 1	4108.83 4050.6 7960.65 1 6285.65 6487.45 6440.43 4134.33 4020.73 4076	4174.06 1 4552.26 1 5006.86 1 5462.27 1 9045.17 1 9038.22 1 7818.46 1 4230.81 1 4230.81 1 4210.27 3876.76	4107.84 4178.42 1 4303.32 1 4639.41 1 4629.81 1 4002.21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Parcel SF 7333.52 4542.54 4872.78 4872.78 5364.75 5376.05 5776.05 5686.85 5677.77 7754.45 7108.56 4292.65 3955.82
	S'ISHARPRINGIUNDERGROUNDS BEVICEAREBIENTIBIE B.X DECISION NO.		1 5006,86 1 5462,27 1 9638,22 1 7818,46 1 4010,27		SF Signed 2nd Supporting Timely Petition 2nd Petition Objection 1 5778.08 1 5868.85 1 5577.77 1 7754.45 1 1 7754.45

Docket Nos. E-01345A-07-0663

	_	_	_			Τ_	1.	.7.			_	<u></u>	_		_	J		-1	7	12	K	1	3 6	8	68	0		86	_	æ	64	e,	82	0	6	;	56	58	57	7	5	5	27	ដ	23	<u>G1</u>	망	<u>4</u>	à	1	T		
85 310-32-096	84 310-32-085	200000000000000000000000000000000000000	A3 310-32-094A	82 310-32-092		1 310-32-091	00 010-02-000	200-25-000		78 310-32-088		77 310-32-087		76 310-32-086	75 310-32-085	74 310-32-084			73 310-32-083	2 310-32-082	1310-32-001	010000000		9 310-32-079		7 310-32-077		310-32-078		310-32-075	1 310-32-074	310-32-073	310-32-072	310-32-071A		3	310-32-068A	58 310-32-066	310-32-065A		310-32-064A	310-32-063A	310-32-062A		310-32-060A	310-32-057	310-32-066A	310-32-054	310-32-053	310-32-0520	Parcel No.		Α
Filmore H. Anderson & Virginia L. Anderson	Cuminita investinanta, inc. (alginoc by Denon Carania)	Cummine investmente inc /stonact hu Darren Cummins)	Donald & Virginia Vaughn	Trust	Jo Ann C. Goldbach, Irustee, Jo Ann C. Goldbach Revocable	JO-AMB W. LYM	C Appe M I upp	Bonald O & Mary P Lee	Donald E. Lee	Clifton D. & Viola J. Lee, Trustees, C. Lee ramily Revocable Trust		Clifton D. & Viola J. Lee, Trustees, C. Lee Family Revocable Trust and Swan Dilve		Trevor Goldi & Sierra Smith-Goldi & Earline R. Pool	John M. & Peggy J. Steiner, Trustees, Steiner Family Trust	Wilke remity Revocable Trust, a David M. a Dorony C. Glynn	Stuart & Denise Currie; Richard J. & Andrea S. Wilke, Trustees,		Stuart & Deniae Currie; Richard J. & Andraa S. Wilke, Trusiese, Wilke Family Revocable Trust; & David M. & Dorothy D. Glynn	Geoffey william Lamorose	Gacillay evillari Carrolosa	Cookrey William pmbrose	Randy I & Rachael Anna Siewari	Terence W. Blirich	Terence W. Bitrich	and Katherine S. Kubicka Family Trust	Dowell A. & Ketherine S. Kubicka, Trustees, Dowell A. Kubicka	and Katherine S. Kubicka Family Trusi	Dowell A. & Kaiherine S. Kubicka, Trustees, Dowell A. Kubicka	Gerald W. & Michelle C. Gailin & Jeffrey W. & Tracy A. Gailin	Gerald W. & Michelle C. Gailin & Jeffrey W. & Tracy A. Gailin	Richard Gervala	Richard R. Gervals	Carlson & Dariene E. Lonis	Dariene E. Loris Revocable Living Trust	Carlson T. & Darlene E. Loftis, Trustees, Carlson T. Loftis and	Karen L. & James Bibby	Louise Denver	Yerbrough Revocable Trust	John D. Yarbrough, II, & Jacqueline Y. Yarbrough, Trustees,	Michael Joseph & Tamara Lynn Wilkinson	Juliana Perez	Brian D. Wood & Arthur Wood	Barbara A. Demerest	Roy M. & Margaret Hokenson	Hilicrest Bay Inc.		Jack M. & Barbara Jo Hulchens, Trustees, Hulchens Family Trust	I implify & Joia Nette Hubbs				В
920 Swan Drive	914 Swan Drive	906 Swan Drive	888 Swan Drive	and owen bridge	a Bo Carron Deline		872 Swan Drive	864 Swan Drive			out of the outer	IST BOD OWAN DIE	222	BALLI UBMS RZB	CO CWEIL DIVO	POO CONTRACTOR	ato swee Orlus		786 Swan Drive	Control Colors	703 Swan Driva	784 Swan Drive	783 Swan Drive	761 Swan Drive	797 Swan Drive	au/ awar Dive	207 2000	BIO SWBN Drive		B21 SWBN Drive	82/ Swan Drive	B37 SWBN Drive	D40 DWBN DIVE	DAR CHART DIVE	eno civeni Drive	ag7 Swan Orlya	873 Swan Drive	889 Swan Drive	895 Swen Drive		913 Swan Drive	817 Swan Drive	927 Swan Drive	933 Swan Drive	951 Swan Drive	924 Bay Vlew Drive	814 Bay View Drive	900 Bay View Drive	DB4 DBY VIEW DIIVO	and Day View Drive	and Bay, May, Drive	Darral Address	C
4108,22	4108.22	4108.22	0410.44	PV VICE	4108.22		4108.22	4108.22	4100.44	1100	4108.22		410A 22	11.000.11	A 108 33	4108 22	4108.22		4108.22		4106.22	5260.21	4255.88	4081.80	4001.00	2001	4092	100%	4003	100.100	1001 86	1001.00	1001.66	4091 86	A1A3 72	4091.86	7/.018	4091,86	4694.15		5192	5192	5192	5182	8677.17	6866.11	8121.88	4142.21	1	4139 84	4121	Parcel SF Pe	D
	1		-	1	_												_		_		-		_	-	-		•	-	•	-	-	-	-	-	-	_			_		_	-	-		-		-		-	1		Signed 1st Petition	-
4108.22	4108.22		24.01.40	A216 44	4108.22		4108.22				-						4108.22	-	4108.22		4108.22		4255.88	100,100	1001.00	1001 88	4092	1	4093	100.00	4091.66	1001.00	4091 AA	4091.86	B1B3.72	4091,86			4694.15		5192	5192	5192		8877.17		8121.60			4139.94	- 1	SF Supporting 1st Petition	7
			-		_				+						-				-		_	_	-	-	†	-				1	_	-	_	_	_	_			-		-	-	-		-	-				-	_	Signed 2nd Petition	G
4108.22	4108.22	43.801	410A 22		4108.22		4105.22	100 22							1		4108.22		4106,22		4108.22	5260.21	4200,00	100.00	4091 AB	4091.86			-		4091.86		4091.86	4091.B6	6183.72	4091,86			4094.15	, n	7810	2810	r az	6100	88//.1/	0000.11	6886 11			4139.94	4121	SF Supporti 2nd Petii	
	1	-																	-			-		+		-					-						1				-	-	+	+	1	+	1	-				Late Objection	+
	-	1				_			_		1	_		-	<u>-</u>			- <u>-</u>			-	-	-							_						_	1	1	-		-	1	1		1			-				<u> </u>	+
				8216.44					4108.22	4108.2	4108.22		4108.22		4108.22																																_	1				_ <	
\perp	\pm	\pm	_	ľ	t	_	1	1	2	$\stackrel{\sim}{}$	۲	_	ľ		٢		t				I	1	1																			1										All SI w/Ob	

S:\SHARPRING\UndergroundServiceArea\Exhit

Docket Nos. E-01345A-07-0663 T-01846B-07-0663

DOCKET .

A A A A A A A A A A A A A A A A A A A	B Sleven D. Wood, Brian D. Wood Johnson Trustees Link T. Johnson and	C Parcel Address 928 Swan Drive	D Parcel SF 4108.22	E Signed 1st S	F SP Supporting 1st Petition 4108.22	G Signed 2nd Petition	SF Supporting 2nd Petition 4108.22	 Timely Objection	Late Objection	
	son and	928 Swan Drive	4108.22		4108,22	_ -	4108.22			_ }
86 310-32-100		944 Swan Drive	4108.22	1		-	7.00.25			_
90 310-32-101		952 Swan Drive	4203.49		4203.48	-	4203.49			١.
91 310-32-102	ock	855 Crystal View Drive	4205.66		4205.99		4205.99			
92 310-32-103	Linda Seldengianz; Bill & Carol Crane	947 Crysial View Drive	3937.76	_	3937.76	-	3937.76			ļ
93 310-32-104A	Rainy A. Hoyi	939 Crystal View Drive	4977	_	4877	_	4977			١
94 310-32-106A		921 Crystal View Drive	7094	-	7094	-	7094			
85 310-32-107	Gerald C. & Carol L. McGlnnls, Trustees, McGlnnls Family Trust	915 Crystal View Drive	3937.76		3937.76		3937.76			
	Ш	905 Crystal View Drive	6056.65]		_ .	6056,65		1	
7 310-32-110A	nson	885 Crysial View Drive	6056.65		6056,65		6056,65		1	
98 310-32-111		877 Crystal View Drive	3637.76							
	Nancy Suzanne Archer	861 Crystal View Drive	3937.76	-	3937 76				1	
01 310-32-114	ı, Sr. & Ann M. Grossman	853 Crystal Vlaw Drive	3837.76						1	
02 310-32-115	L. O'Neill	843 Crysial View Drive	3937.76			-	3637.76			
04 310-32-118A	Raymond D. & Pairicia Easiey	827 Crystal View Drive	7875.52	-	7875.52	-	7875.52		1	
	Jacqueline J. & Sandra J. Johnson	809 Crystal Vlew Drive	3637,76	-	3637.76	-	3937.76			
	Sharon Error, Trustae, Sharon Error Trust	801 Crystal View Drive	5908.64		5906.64		5906,64			
04 310-32-122A	Marvin L. & Joan K. Jordan	785 Crystal View Drive	5886,15		5886,15	-	5886.15		\dagger	
109 310-32-124	Victor M. & Priscilla M. Hona	796 Crystal View Drive	4079,88		4547,13	-	4547.13		\dagger	
10 310-32-125	Boyce L. & Terese A. Harker; Trent W. & Laura M. Harker	804 Crystal View Drive	3934.9	_	3934.9	-	3934.6		1	
11 310-32-126		812 Crystal View Drive	4079.88		4079.89		4079.89			
12 310-32-127	Leah C. Wagner	820 Crysial View Drive	4079.69	1	4079.89	1	4079.89	9		
13 310-32-128	Charles E & Indy Bulledge Trustees Bulledge Family Tous	828 Crystal View Drive	4078,89	_	4079.69					
15 310-32-130	Dan & Terl Peters	844 Crystal View Drive	4079.89				1		1	
116 310-32-132A	Merle D. & Janet J. Calvin	864 Crysial View Drive	8159.78	-4	8159,78			-		
	William & Harlayne Bond	872 Crystal View Drive	4079.89							
18 310-32-135A	Glenn E. Ecker & Patricia A. Tanges	880 Crystal View Drive	8159.78	-	8159.78					
170 310-32-130	Coperior, & Carrille A. Hughes	ODE Crystal View Drive	4078.08		40/9.68		40/9.89	9		
121 310-32-138	Roberta A. & Donald A. Anderson	916 Crystal View Drive	4079.88	-	40,8708	_ -	4079.89	B) E	N. T. C.	
22 310-32-139	Albert O, Lafrentere	922 Crystal View Drive	4078.88	1	4079.89	1	4079.89	θ	_	
23 310-32-140	Caleb J. & Kristine A. Brandel & Judih B. Shipley	930 Crystal View Drive	4079.89			-1	4079.89	Đ		
24 310-32-141	Leslie Gossenberger	938 Crystal View Drive	4079.69							
	Gary & Yvonne Sullon	846 Crystal View Drive	4079,89	_	4079.89	-1	4079.88	Ф		
128 310-32-143	Robert & Lori Nielson	954 Crystal View Drive	4016.46		4016.49	-	4016.49	9	l	
127 310-32-144	John L & Jane R. Sears, Trustees, Sears Living Trust	955 Linger Drive	4402.98	_	4402.98	_	4402.98	В		
28 310-32-145	Dan R. & Vivian T. Good, Trustees, Dan R. Good and Vivian T. Good Declaration of Trust	945 Linger Drive	4070.03	<u>.</u>	4070 03		4070 03	.		
129 310-32-146	Judi L. Noble	937 Linger Drive	4070.03		4070.03		4070.03	٥١	1	
30 340 33 447	Donald D. & Cottonian December Treatment December 1 hits Treatment	DOZ I Isosat Dalus	4070 0				1070	5		
131 310-32-148	Linda Kay Clamp & David Edward Seaver	919 Linger Drive	4070.03	4	4070.03	-	4070.03	3	+	
	Scott K. Jones, Sr. & Carole A. Jones, Trustees, Jones Revocable									
200	Total	803 Linger Drive	8140.06	1	6140.06	_	6140.06	Ď.	-	

Parcel No.

					,			-	7	
B	C	. 0	m		6	I	-		7	
			Clared 1st	SF	Signed 2nd	Supporting	Timely	Late	SF w/Timely	All SF
Owner Name/s	Parcel Address	Parcel SF		1st Petition	Petition	1	Objection	Objection	Objections	w/Obje
	895 Linger Drive	6105.04	<u>.</u>	6105.04						
Cynihla I Miles & Sandra L. Magana	875 Linger Drive	6105.04	_	6105.04	_	6105.04	-		50 040F	
ł I	867 Linger Drive	4070.03	_	4070.03		21.27	-		4070.00	Ī
en; Jenna Messina	853 Linger Drive	8140.1	1	B140.1	-	8140.1				
Thomas J. Gesly, IV & Denise M. Gesly; Edward F. Ferrall, Sr. &	839 i Inner Orlve	4070.03	-	4070,03						
Ponald & Malody Clark	829 Linger Drive	4070.03		4070,03	_	4070.03				
Paul L. & Carol A. Pudewa	819 Linger Drive	4070.03	1	4070.03	-	4070.03				
	811 Linger Drive	4070.03			-	40/0.03				
	801 Linger Drive	4070.03			1	40706.00		1		
	791 Linger Drive	4746.29				4/40.40				
Thomas F. Anderson, Ernest Vanler, & Robert K. Anderson	794 Linger Drive	5099,88	-	5098.88	-	00.8800				
Tom W. & Kathryn A. Ayers, Trustees, Ayers Revocable Trust	804 Linger Drive	5099.88		5099.88		5000 88				
Judith B. Shipley	812 Linger Drive	99.8609			-	0000				
Prendel	820 Linger Drive	5099,88	1	5099.88	_	5099.88		-		T
	830 Linger Drive	5099.88	_	5099.88	-	5099.8				
David & Susan Thomas	840 Linger Drive	6374.65	_	6374.65	. -	6374.65	710			
		A374 A5			-	100		The state of the state of		
Copen & Caning Figures	Bas I loner Orine		1	6374.85	-	6374.65	CS.			
Theodora & & Mary Marical	880 Linger Drive	6.9903	1	5098.88						
Theodore R. & Mary L. Marical	896 Linger Drive	5099,88		5099.86		5000				\dagger
Andrew P. & Debra D. Grimes	904 Linger Drive	98.6803		5000 98	+	5099 88	20 0	1	1	
Edward Mark & Beverly A. Lauer	914 Linger Drive	5000 88	2	0000.00						
Constance Ann Estabrook	1920 Linger Drive	10199.76	_	10199.76						
Blok McCurdy	940 Linger Drive	5099.88	8	5099.86					-	1
William E. & Jeennelle L. Horn	954 Linger Drive	4856,48	1	4856.48	-	973	4		-	
Gary J. Schmitt	813 Noble View Drive	7661.09	-	7664 08	+	7664.08	8			
William M. & Joan Whitlinger, Led & Mary Whitlinger	/00 Citigat Ditya								_	
Trust	825 Noble View Drive	5215.19	1	5215,19		11000			+	+
Ronald & Sylvia Nelson	855 Max View Drive	1038.74	1 -	1038.74	+	10439.75	75			
Jerome P. & Karen M. Bowe	DAR WIEW CITYO	8149.85	1	6119 85	1	6119.85	5			
Robert Rester & Patricia Ann Hoffman	875 Max View Drive	5519.87	1	5519.87	-	5519.87	87			
Timothy G. & Robin A. Evans	883 Max View Drive	5399,87	1 1	5399,87		5399.87	87			$\frac{1}{1}$
Kharim Poplet (aka Michale Kharim Casha)	899 Max View Drive	5398.87	37	5389.87	- - -	5398 67	87	1		
Kelih Bianchard	897 Max VIew Drive	70,8800	1	10.8800	-		- 19	-		
Scott K. Jones, Jr. & Zahira V. Delgadillo Jones, Truslees, Scott IV. Jones, Jr. & Zahira V. Delgadillo Jones, Rayncable Trusl	907 Max View Drive	10799.74	74 1	10799.74		10799.74	7.4			
Richard L. & Nancy L. Fisher	923 Max View Drive		87	5399.87		8800	87			1
Mildred R. Dann	931 Max View Drive		1 2	7805.81		7805	81			
Robert & Bonnie Strong	937 Max View Drive	10157 26	26	7000.0	-\-	10157.26	26			
Philip S, & Ina L. Wigley	2829 Dillicrast Drive		23							1
William A. & Gayl C. Baca	854 Max View Drive	6214,31	31		1	6214.31	31	-		
Annelle M. Kincald										

DOCKET NO. E-(

144 310-32-165

148 310-32-167 147 310-32-168 148 310-32-170A 150 310-32-172C 151 310-32-173A 152 310-32-174 153 310-32-176 154 310-32-176 155 310-32-178 156 310-32-178 158 310-32-180A 158 310-32-181 158 310-32-181 158 310-32-183 159 310-32-183

162 310-32-164 163 310-32-166A 164 310-32-166B 165 310-32-160 168 310-32-160 167 310-32-161 166 310-32-161 166 310-32-161

170 310-32-186 171 310-32-186 172 310-32-187 173 310-32-187 174 310-32-189 175 310-32-200 176 310-32-201

S:\SHARPRING\LindergroundServiceArea\Exhibit

	Docket
	Nos.
T-01846B-07-0663	E-01345A-07-0663

218 310-32-248	21/2/07/2	7474 05 015 747	20-01-01-0-02	20-010-012	7012 20 012 710		212 310-32-239	211 310-32-238	2	210 310-32-237	209 310-32-236	208 310-32-235		207 310-32-234	202 2020 202	204 010-02-00	203 310-32	202 310-32-229	201 310-32-228	200 310-32-	188/310-32-226	198 310-32-225	197 310-32-224	198 310-32-223	185 310-32-222	105 340 32	193 310-32-	192 310-32-219	1910-32-4100	191 310.32	100/310-32-216A	189 310-32-215	188 310-32-214	187 310-32-	186 310-32-	85 310-32-210	184 310-32-209		182 310-32-207	181 310-32-208	-20-010-041	80 310-32-204	170 310-32-203	76 310 32-	1 Parcel No.	
		1	\perp																																											
Edward F. Mueller	Lougias & Naten Greet	Danieles Versa Crear	Dhillip I Carrie & Deborah A I surence	Childe & bearing J. Niaus	Vernon C 9 oratto Venus C. control	Rodney M. Kawannya & Judy C. Williann	Thomas W. & Teddl Jo Lorch, Trustaes, Thomas W. Lorch and Teddl .to Lorch Trust	Teddi Jo Lorch Trust	Thomas W. & Teddl Jo Lorch, Trustees, Thomas W. Lorch and	Norman R. & Dianna L. Dump	Robert & Kalhleen Thurman	McDonnell Family Trust	Ronald J. & Phyllis McDonnell, Truslees, Ronald & Phyllis	Berlha M. Silles, Trustee	Kent A & Terese B Thompson	Tiomes J. e Julie N. Nraus	Robert P. & Carol E. Bischoff, Trustees, Bischoff Living Trust	Maillett Investments, LLC (signed by Randall Maillett)	Michelle M. Gayler	Harold Eric & Kathle Jo Jones	Charles S, & Barbara A. Manning, Trustees	en T. Powell	Matthew Annala	Tost	Holle I. Harvey	KOVIN X, & CYNINIA ANNE ZUNGE	Michael S. & Maria B. Mendaz	Bergairom Jr.	Wasley F Bernstrom Sr & Theresa Bernstrom Wasley F	XSI Properties, inc. OR Anne Grisham (Grisham signed 2nd	Frank I. & Jan (aka Janet) Robles	John R. & Judith L.P. McLean, DALLSA NOC C/O; Attn: Bill Receipt Area 7th Ft.	Melvin E. Hegier	Joseph & Alls E. Troys; Peter W. & liene Kraemer	Jerry & Kelly Goodman	Robyn L. Stein	Randy R. & Lisa T. Poole	Erna Davis	Antonio & lien Ellas-Calles, Trustaes, Antonio Ellas-Calles and Iten Ellas-Calles Family Trust	Nicono e ilen Cilas-Calles Inusides, Antonio Ellas-Calles and llen Ellas-Calles Familly Trust	Apical a Blas Colles Testage Astesia Elles Colles	Notice Character I wardoks	James C. Schmidt, Jr. & Carol L. Schmidt	Sevin D. Menin; Kevin D. & Melanie Manin	Owner Name <i>ls</i>	
2925 Hillicrest Drive	2822 Hillcrest Dri	AGAG DUMAD DIVE	2049 Dunian Dilva	2020 Dunlan Driv	SORT Distance Crise	2971 Dunlan Driv	nd 2975 Dunian Drive	2979 Duniap Drive			2978 Dunlap Drive			2962 Dunlan Drive	2977 Oils Coun	298 / Olls Court			902 Noble View Drive	892 Noble View Drive	882 Noble View D	874 Nobie View Drive	866 Noble View Drive	856 Nobie View Drive	848 Nobie Vlew Drive	842 Nobie View Drive	834 Noble View Drive	824 Nobie View D	BIS NODIO VIEW DRIVE	248	808 Nobie View Drive	865 Noble View Drive	901 Nable View Drive	911 Noble View D	929 Noble View Drive	943 Noble View D	934 Max View Drive	923 May View Drive		902 Max View Drive	894 Max View Drive	886 Max View Drive	876 Max View Drive	866 Max View Drive	Parcel Address	-
6	ď																rive	rive	rive	rive	rive	rlve	rive	7V 6	rive	rive	rive	rive	IVB		ive	ive	lve	ive	-lua	ev.	B E			CO			8		Parce SR	
22143.16	R./R/CI	120704	44/8.82	7.6/401	100.00	5753 46	ביי ביי ביי ביי	7100,14		5023.26	4035.0	4035.9		59 CSEC	4035.97	5991.8	5543.9	6001.18	4499.89	4499.86	4499.89	4489,88	4499.89	4407.9	4565,26	4500	4500	4500	6750		9741.29	5158.81	4499.88	8650.19	4325.08	4099.6	4041 19	4124.71	, ,	4124.71	4124.71	4124.71	4124.71	4124.71		
7 6	-	3 2		.				-		-1	-	7		-			-	-1	1	-	-	-	-	<u>.</u>		-	-				-		-			- -	-				_	1		1	Signed 1st Petition	
	13/9/.83	8858.84	44/8.82	104/8.2		0000.00	n n n n	7100.14		5023.26	4035.97		2007.00	3063 60	4035.87	5991.6	5543.0	6001.18	4499.89	4499.89	4499,89	4499.89	100	4407 9		4500	4500	4500			9741.29		4499.88			4000 A	4124./1	1121			4124.71	4124.71	4124.71	4124,71	SF Supporting 1st Petition	
		-		-		-	•	_			1				-	_	1	1	-	_		-1	-	_	1	1	-		1		<u>-</u>	_	- -	1	-	1	NAME OF TAXABLE PARTY O	1		-4		1			Signed 2nd Petition	•
2000		8959.84		10479.2		00.000		7100,14		5023.26	4035.9			394/.8	4035.97	5991.6	5543.9	6001.16	4499.89	4499.89	4499.89	4499.89	1,000	4407 0	4565.26	4500	4500	4500	6750		9741 29	5158 81	4499 88	8650 19	0.0001	4041.10	Contraction of the second	- Company		4124.71	4124.71	4124.71	4124.71	4124.71	SF Supporting 2nd Petition	
4		4		2		0	•	-		,	7				7	-	2				7																运搬汽油的 规则	잼							Timely Objection	_
						+				1	+			-					1	-		+						-		+	+			+											Late	
	1 13797.93									+			-	+																							4124.71								SF w/Timely	
	33	-			-					1		•	\dagger					1		1	1	1													1	1									All SF	

N V	2 N	ĮŅ.	22	21	22	22	26	24	12	122	22	245	244	243	24	24	240	238	23	237	23	23	22	23:	23	23	23(226	22B	227	226	225	224	223	222	221	220	-		П
258	118	55	12	땁	123	12	le S	100	100	12	100	5	1	اندا	N	91	0310	931	831	7310	6310	5310	1316	3316	2316	1316	3316	310	310	7310	3310	1310	1310	1310	310	310	310	Par		\sqcap
																241 91312703	310-32-274	310-32-273	238 310-32-272	310-32-271A	236 310-32-270A	235 310-32-269A	234 310-32-267A	233 310-32-265	232 310-32-264	231 310-32-263	-32-262	229 310-32-281	310-32-260A	310-32-259A	310-32-257	225 310-32-256	224 310-32-255	223 310-32-254	310-32-263	221 310-32-252	310-32-251A	Parcel No.		А
		2nd Petition SF Support if Late Withdrawals Considered:	2nd Petition Owner Support if Late Withdrawais Considered:		2nd Petition SF Support With Withdrawal of Parcel 208;	2nd Petition Owner Support With Withdrawal of Parcel 208;		2nd Petition Original SF Support:	2nd Petition Original Owner Support:		1st Petition SF Support:	1st Patition Owner Support;			Total Parcels = 240	Hillcrest Water Company, Barbara Dunlap	La Paz County	Hillerest Bay Inc.	Hillcrest Bay Inc.	Gregory K, & Michelle L, Walsh	Bath S, Shamnurg & Jeffrey G, Johnson	William H. & Shari D. Dage	Jim Thurman	Michael E. & Melanie A. Stewart	Charles Joseph Swan	Andre M. & Linda E. Duran & Rudy E. & Simonelle A. Lovato	Brian Bolton	Brian Bollon	Larry E. & Laura S. Greseth	Ted & Carla Bultama & Leslie Gossenberger	Gerald & Shawna Johnson	George & Debble Radvansky	E.V. Gault	Jane Schue, Trustee, Schue Living Trust	David M. & Renee L. Welker	Kaihi A. Bevan	Douglas & Karen Greer	Owner Name/s		В
		58,908%			59.690%			58.998%	53.333%		61.4/2%	63.333%			Total:	2989 Dunlap Dr., Tract B	2865 Manor View Dr.	2765 Hillcrest Bay	2769 Hillcrest Bay	2773 Hilicrest Bay	2775 Hilicrasi Bay	2779 Hillcrest Bay	2785 Hillcrest Drive	2793 Hillcrest Drive	2801 Hillcrest Drive	2809 Hillcrest Drive	2815 Hillcrest Drive	2823 Hillcrest Drive	2835 Hillcrest Drive	2837 Hillcrest Drive	2851 Hillcrest Drive	2855 Hillcrest Drive	2863 Hilicrest Drive	2871 Hillcrest Drive	2875 Hillcrest Drive	2889 Hillcrest Drive	2891 Hillcrest Drive	Parcel Address		С
		**	*		%	8		%	36		26	1%			1337983.42	B 5651.6	40734.68	10039.86	4222.51	5155.52	5950.27	7177.07	9893.45	3989.82	3999.82	3999,82	3999,82	3999.62	5998.73	5999.73	3999.82	3999.62	3999.82	4006.66	10264.02	11908	6	Parcel SF		D
	+								-	Ī					152					1	_	1				_			_	1	1	_	1	1			1	Petition	Signed 1st	ER.
	-														2 822485.85					5155,52	5950.27	7177.07				3999.82			5999.73	5999.73	3999,82	3999,82	3989.82	4006.66			6875.75		SF 1st Supporting	F
	1														151	-			-			1			1	_			-	_				1				Petition	Signed 2nd	G
			1			+									798640.64	Γ			4222.51			/1//.0/			3889.82	3999.82			5999.73	5989.73	3999.82			4006.66				2nd Petition	SF Supporting	Ξ
	1	+	+		+		+	+		1	+	+			4 18							-															1	Objection	Timely .	_
			+	+		+	+	+	+	+	†	+	-	-						1																		Objection	Late	-
		-		+		+			-	+	+		-		36, 111615.52	Γ																					08/5/5		٧	^
\vdash		\dagger	\dagger	+	\dagger	\dagger	\dagger	\dagger	\dagger	+	1	1	†	\dagger	ľ	1	\dagger	T	1	T	†	T	T	1	\dagger		\uparrow	T	T	T	Ī		Ī	T			Ī	w/Ob	All SE	

1	1			1	+	2874 Manor View Drive	OPP 2			836 Bay View Drive 8285.65 1 1 1		872 Bay View Drive 4020.73 1 1	Marsha Ruith Crawford & Roy & Margaret Hokenson 880 Bay View Drive 4076
		+	-	-1/0-0		rive	5868.85 1 557.77 1 1 557.77 1 1 7754.45 1 1 4 429.2.65 1 1 4 429.2.65 1 1 4 429.2.65 1 1 4 429.8 8 1 1 4 429.8 8 1 1 1 4 429.8 8 1 1 1 1 4 429.2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 557.4.87 1 1 7754.48 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
_		H				5866.85 1 5577.77 1 5577.77 1 7754.45 1 1 1 7754.45 1 1 1 7754.45 1 1 1 7754.45 1 1 1 7754.45 1 1 1 1 7754.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5868.85 1 5868.85 1 5577.77 1 5577.77 1 7754.45 1 1 7108.56 1 1 4292.65 1 1 4292.65 1 1 4292.65 1 1 4292.65 1 1 4292.65 1 1 1 4292.65 1 1 1 4292.65 1 1 1 4292.65 1 1 1 4292.65 1 1 1 4292.65 1 1 1 4292.65 1 1 1 1 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5868.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5868.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5868.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	4	-				5866.85 1 5667.77 1 1 7754.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5868.85 1 5687.77 1 7754.45 1 4 7754.45 1 4 7768.56 1 1 4 7108.56 1 1 4 7108.56 1 1 4 7108.56 1 1 4 7108.56 1 1 4 7107.94 4 7107.94 1 1 7107.94 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5866.85 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	$\left \cdot \right $	\parallel				197 Bay View Drive 4177,94 791 Bay View Drive 4176,42 791 Bay View Drive 479,42 791 Bay View Drive 4303,32 781 Bay View Drive 4839,41 2814 Manor View Drive 4829,81 2828 Manor View Drive 422,47 2844 Manor View Drive 4002,21 2858 Manor View Drive 4002,21 2868 Manor View Drive 4002,21 12868 Manor View Drive 4002,21 12868 Manor View Drive 4002,21 13868 Manor View Drive 4002,21 14868 Manor View Drive 4002,21 15868 Manor View Drive 4002,21	197 Bay View Drive 4107,94 1791 Bay View Drive 4179,44 1791 Bay View Drive 4303,32 1 1 2810 Manor View Drive 4839,41 2814 Manor View Drive 4839,81 2814 Manor View Drive 4822,47 2815 Manor View Drive 4002,21 2815 Manor View Drive 4002,21 2816 Manor View Drive 4002,21 2817 Manor View Drive 4002,21 2818 Manor View Drive 4002,21 2819 Manor View Drive 4002,21 2819 Manor View Drive 4002,21 2810 Manor View Drive 5006,86 2820 Manor View Drive 5008,86 2830 Manor View Drive 7818,48 2844 Nobie View Drive 7818,48 2844 Nobie View Drive 7818,48 2844 Nobie View Drive 40010,27 2858 May View Drive 4008,77 285 Bay View Drive 4008,77 286 Bay View Drive 4008,77 38 Bay View Drive 4008,77 38 Bay View Drive 8084,77 39 Bay View Drive 4008,77 30 Bay View Drive 4008,77 30 Bay View Drive 4008,77 30 Bay View Drive 4008,77 31 Bay View Drive 4008,77	197 Bay View Drive 4003.02 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	197 Bay View Drive 4107.94 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	197 Bay View Drive 4107.94 41 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	197 Bay View Drive 400.04 791 Bay View Drive 4107.94 791 Bay View Drive 4107.94 791 Bay View Drive 4303.32 1 1 1 1 1 2814 Manor View Drive 4252.47 2814 Manor View Drive 4052.81 2815 Manor View Drive 4002.21 2816 Manor View Drive 4002.21 2817 Manor View Drive 4002.21 2818 Manor View Drive 4002.21 2818 Manor View Drive 4002.21 2819 Manor View Drive 4002.21 2810 Manor View Drive 4002.21 2810 Manor View Drive 4002.21 2811 Manor View Drive 4002.21 2812 Manor View Drive 4002.21 2813 Manor View Drive 4002.21 2814 Manor View Drive 4002.21 2815 Manor View Drive 4002.21 2816 Manor View Drive 4002.21 2817 Manor View Drive 4002.21 2818 Manor View Drive 4002.21 2819 Manor View Drive 4002.21 2819 Manor View Drive 5006.86 2819 Manor View Drive 5006.86 2810 Manor View Drive 5006.86 2810 Manor View Drive 6004.27 2818 Manor View Drive 7818.48 2818 Manor View Drive 7818.48 2819 Manor View Drive 7818.48 2810 Bay View Drive 400.81 2810 Bay View Drive 400.81 2810 Bay View Drive 400.81 2811 Manor View Drive 7818.48 2811 Manor View Drive 7818.48 2812 Manor View Drive 7818.48 2813 Mary View Drive 7818.48 2814 Manor View Drive 7818.48 2815 Mary View Drive 400.81 2816 Bay View Drive 400.85 2816 May View Drive 7880.85 2816 May View Drive 7880.85 2816 May View Drive 7880.85 2816 May View Drive 6487.45 2811 Mary Mary Drive 6487.45 2811 Mary Mary Mary Mary Mary Mary Mary Mary	197 Bay View Drive 4107.942 1 1 1 1 1 1 1 1 1	797 Bay View Drive 4107.94 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
						797 Bay View Drive 4197.94 791 Bay View Drive 4179.42 1 781 Bay View Drive 4393.32 1 781 Bay View Drive 4393.32 1 2800 Manor View Drive 4639.41 1 2814 Manor View Drive 4859.81 1 2828 Manor View Drive 4252.47 1 2844 Manor View Drive 8004.42 1 2852 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	197 Bay View Drive	797 Bay View Drive 4107.94 1 1 1 1 791 Bay View Drive 4303.32 1 1 1 1 1 781 Bay View Drive 4303.32 1 1 1 1 1 781 Bay View Drive 4803.41 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	797 Bay View Drive 4107.944 1 1 1 1 791 Bay View Drive 4303.32 1 1 1 1 1 781 Bay View Drive 4303.32 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	797 Bay View Drive 4107,94 791 Bay View Drive 4178,42 1 1 781 Bay View Drive 4303,32 1 1 1 2814 Manor View Drive 4639,41 1 1 1 2814 Manor View Drive 4629,81 1 1 1 2814 Manor View Drive 4022,81 1 1 1 2814 Manor View Drive 4002,21 1 1 1 2860 Manor View Drive 4002,21 1 1 1 2860 Manor View Drive 4002,21 1 1 1 2862 Manor View Drive 4002,21 1 1 1 2882 Manor View Drive 4002,21 1 1 1 2882 Manor View Drive 4002,21 1 1 1 2894 Manor View Drive 4052,28 1 1 1 2904 Manor View Drive 4052,28 1 1 1 2904 Manor View Drive 4052,27 1 1 1 2910 Manor View Drive 4052,27 1 1 1 2910 Manor View Drive 9045,17 1 1 1 294 Noble View Drive 9638,22 1 1 1 1	797 Bay View Drive	797 Bay View Drive 4107.94 791 Bay View Drive 4303.32 1 1 781 Bay View Drive 4839.41 1 1 2814 Manor View Drive 4839.41 1 1 2828 Manor View Drive 4829.81 1 1 2828 Manor View Drive 4022.21 1 1 1 2860 Manor View Drive 4002.21 1 1 1 2860 Manor View Drive 4002.21 1 1 1 2860 Manor View Drive 4002.21 1 1 1 2882 Manor View Drive 4002.21 1 1 1 2882 Manor View Drive 4002.21 1 1 1 2882 Manor View Drive 4052.82 1 1 1 2882 Manor View Drive 4052.27 1 1 1 2892 Manor View Drive 5006.86 1 1 1 2994 Manor View Drive 506.86 1 1 1 2994 Noble View Drive 9645.77 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 796 Bay View Drive 4050.65 1 1 1 1 80 Bay View Dr	Typy Day View Drive 4107.944 1 1 1 1 1 1 1 1 1
					1	791 Bay View Drive 4779.42 1 1 781 Bay View Drive 4393.32 1 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4252.47 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	791 Bay View Drive	791 Bay View Drive	791 Bay View Drive 4179.42 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	791 Bay View Drive	791 Bay View Drive	791 Bay View Drive	791 Bay View Drive 4179.42 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
						781 Bay View Drive 4303.32 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4222.47 1 2844 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	781 Bay View Drive	781 Bay View Drive	781 Bay View Drive	781 Bay View Drive	781 Bay View Drive	281 Bay View Drive	781 Bay View Drive
						2800 Manor View Drive	2800 Manor View Drive	2800 Manor View Drive	2810 Manor View Drive	2800 Manor View Drive	2810 Manor View Drive 4639.41 1 1 1 1 1 1 1 1 1	2800 Manor View Drive	2810 Manor View Drive
	++++	$\frac{1}{1}$				2814 Manor View Drive	2814 Manor View Drive 452.9.81 1 2828 Manor View Drive 425.24 7 2828 Manor View Drive 8004.42 1 1 2852 Manor View Drive 4002.21 1 1 2852 Manor View Drive 4002.21 1 1 2874 Manor View Drive 4002.21 1 1 2874 Manor View Drive 4002.21 1 1 2882 Manor View Drive 4002.21 1 1 2882 Manor View Drive 474.06 1 1 2882 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5006.86 1 1 2904 Manor View Drive 9045.17 1 2952 Noble View Drive 9045.17 1 2953 Noble View Drive 7818.48 1 1 780 Bay View Drive 7818.46 1 1 790 Bay View Drive 4020.81 1 1 790 Bay View Drive 4020.81 1 1 790 Bay View Drive 6038.22 1 1 790 Bay View Drive 7818.46 1 1 790 Bay View Drive 4020.81 1 1 790 Bay View Drive 4020.81 1 1	2814 Manor View Drive 4252.47 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2814 Manor View Drive 4826.81 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2814 Manor View Drive 4252.47 1 1 1 1 2828 Manor View Drive 4052.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 2828 Manor View Drive 4552.28 1 1 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 1 1 1 2910 Manor View Drive 6482.27 1 1 1 1 1 1 1 1 2944 Noble View Drive 6482.27 1 1 1 1 1 1 1 1 1 2944 Noble View Drive 6482.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2814 Manor Vlew Drive	2814 Manor View Drive 4252.47 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4174.06 2828 Manor View Drive 4174.06 1 1 1 1 1 1 2828 Manor View Drive 54652.28 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2814 Manor View Drive
rice			nto I		dia l	2028 Manor View Drive 4252.47 2844 Manor View Drive 8004.42 1 2852 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	2828 Manor View Drive 4252.47 2844 Maror View Drive 4002.21 2852 Manor View Drive 4002.21 2858 Manor View Drive 4002.21 2858 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 5006.86 2884 Manor View Drive 5462.27 2895 Manor View Drive 5462.27 2910 Manor View Drive 5462.27 2910 Manor View Drive 5463.27 2910 Manor View Drive 9638.22 2944 Nobile View Drive 7818.48 2944 Nobile View Drive 7818.46 2958 Nobile View Drive 7818.46 2968 Nobile View Drive 8084.7	2828 Manor View Drive 8004.42 1 1 1 1 2844 Manor View Drive 4002.21 1 1 1 1 1 2852 Manor View Drive 4002.21 1 1 1 1 1 2860 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 2872 Manor View Drive 4002.21 1 1 1 1 1 2872 Manor View Drive 4174.06 1 1 1 1 1 2872 Manor View Drive 4174.06 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2828 Manor View Drive 8004.42 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2828 Manor View Drive 8004.42 1 1 1 1 1 2844 Manor View Drive 4002.21 1 1 1 1 1 1 2852 Manor View Drive 4002.21 1 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 1 2882 Manor View Drive 4174.05 2882 Manor View Drive 4174.05 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2828 Manor View Drive 8004.42 1 1 1 1 2844 Manor View Drive 8004.42 1 1 1 1 2862 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 5462.27 1 1 1 1 1 1 2944 Noble View Drive 9045.17 1 1 1 1 1 1 2944 Noble View Drive 9045.17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2828 Manor View Drive	2828 Manor View Drive 8004.42 1 1 1 1 2862 Manor View Drive 4002.21 1 1 1 1 1 2862 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2868 Manor View Drive 4174.06 1 1 1 1 2868 Manor View Drive 4455.2.8 1 1 1 1 1 2904 Manor View Drive 5462.27 1 1 1 1 1 2904 Mobile View Drive 9045.17 1 1 1 1 1 2904 Noble View Drive 9045.17 1 1 1 1 1 1 2904 Noble View Drive 9045.22 1 1 1 1 1 1 1 2904 Noble View Drive 9045.32 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
rive	rive	rive	rive	rive	rive	2844 Manor View Drive 8004.42 1 2852 Manor View Drive 4002.21 1 2850 Manor View Drive 4002.21 1 2858 Manor View Drive 4002.21 1	2844 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2872 Manor View Drive 4002.21 1 2882 Manor View Drive 4774.06 2882 Manor View Drive 5006.66 1 2892 Manor View Drive 5006.66 1 2894 Manor View Drive 5482.27 1 2910 Manor View Drive 5482.27 1 2910 Manor View Drive 9648.22 1 2910 Manor View Drive 7818.46 1 2844 Noble View Drive 7818.46 1 2844 Nyblew Drive 7818.46 1 2854 Nyblew Drive 7818.46 1 2856 Nable View Drive 7818.46 1 2857 Nable View Drive 7818.46 1 2858 Nyblew Drive 7818.46 1 2858 Nyblew Drive 7818.46 1 2859 New Drive 7818.46 1	2844 Manor View Drive	2844 Manor View Drive	2844 Manor View Drive	2844 Manor View Drive	2844 Manor View Drive 4002.21 1 1 1 1 1 1 1 2862 Manor View Drive 4002.21 1 1 1 1 1 1 2868 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 2904 Manor View Drive 4552.28 1 1 1 2904 Manor View Drive 5006.66 1 1 1 1 2910 Manor View Drive 6045.27 1 1 1 1 2910 Manor View Drive 9638.22 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1	2844 Manor View Drive
rive	TIVE	rive	rive	rive	rive	2852 Manor View Drive 4002.21 1 2858 Manor View Drive 4002.21 1 2858 Manor View Drive 4002.21 1	264 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 2882 Manor View Drive 4552.28 2882 Manor View Drive 5462.27 1 2910 Manor View Drive 7818.48 1 2810 Manor View Drive 7818.48 1 1 2844 Nobie View Drive 7818 Nobie View Drive	282 Manor View Drive 4002.21 1 1 1 1 1 2822 Manor View Drive 4002.21 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 2828 Manor View Drive 4002.21 1 1 1 1 1 1 1 2827 Manor View Drive 4002.21 1 1 1 1 1 1 2828 Manor View Drive 4174.06 2828 Manor View Drive 4174.06 2828 Manor View Drive 5006.86 1 1 1 1 2828 Manor View Drive 5006.86 1 1 1 1 28210 Manor View Drive 5462.27 1 1 1 1 1 2828 Mobile View Drive 9638.22 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2944 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	282 Manor View Drive 4002.21 1 1 1 1 1 282 Manor View Drive 4002.21 1 1 1 1 1 1 286 Manor View Drive 4002.21 1 1 1 1 1 1 1 286 Manor View Drive 4002.21 1 1 1 1 1 1 1 287 Manor View Drive 4002.21 1 1 1 1 1 1 288 Manor View Drive 4174.06 288 Manor View Drive 4174.06 1 1 1 1 1 288 Manor View Drive 5006.86 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 1 1 2910 Manor View Drive 6306.86 1 1 1 1 1 1 1 1 2910 Manor View Drive 6306.86 1 1 1 1 1 1 1 1 1 1 1 2944 Noble View Drive 638.8 22 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2888 Manor View Drive 4002.21 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 1 2882 Manor View Drive 5006.86 1 1 1 1 2904 Manor View Drive 5006.86 1 1 1 1 1 2910 Manor View Drive 6045.27 1 1 1 1 1 1 2924 Noble View Drive 6038.22 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2842 Manor View Drive	2822 Manor View Drive
rive rive	rive rive	rive rive	rive rive	rive rive	rive	2860 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	2860 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2882 Manor View Drive 4174.06 1 2882 Manor View Drive 4562.28 1 2896 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5462.27 1 1 2910 Manor View Drive 9045.17 1 2910 Manor View Drive 9638.22 1 1 2914 Noble View Drive 7818.48 1 1 782 Bay View Drive 7818.46 1 1 782 Bay View Drive 4010.27 1 1 788 Bay View Drive 4010.27 1 1 788 Bay View Drive 4010.27 1 1	2868 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4174.06 12882 Manor View Drive 4174.06 12882 Manor View Drive 5006.86 1 1 1 1 2870 Manor View Drive 5006.86 1 1 1 1 1 2870 Manor View Drive 5462.27 1 1 1 1 1 2870 Manor View Drive 5462.27 1 1 1 1 1 1 2870 Manor View Drive 5462.27 1 1 1 1 1 1 1 1 2870 Manor View Drive 5462.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2860 Manor View Drive 4002.21 1 1 1 1 2884 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4174.06 1 1 2882 Manor View Drive 4452.28 1 1 1 2886 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5045.27 1 1 1 1 2904 Manor View Drive 9045.17 1 1 1 1 2910 Manor View Drive 9038.22 1 1 1 1 1 2924 Noble View Drive 9038.22 1 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive	2860 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4174.06 1 1 2882 Manor View Drive 4452.28 1 1 1 1 2886 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5006.86 1 1 2904 Manor View Drive 9045.17 1 1 1 1 2910 Manor View Drive 9045.17 1 1 1 1 1 2922 Noble View Drive 9038.22 1 1 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2860 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4074.06 12822 Manor View Drive 4174.06 12822 Manor View Drive 5006.68 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive 4002.21 1 1 1 1 1 2878 Manor View Drive 4002.21 1 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4152.28 1 1 1 2882 Manor View Drive 4052.28 1 1 1 2882 Manor View Drive 5006.86 1 1 1 2904 Manor View Drive 5006.86 1 1 1 2904 Manor View Drive 9045.17 1 1 1 1 1 1 2914 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
rive	rrive	rive	rive	rive	rive	2850 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	2850 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4702.21 1 2882 Manor View Drive 4774.06 2882 Manor View Drive 4582.28 2 2882 Manor View Drive 5006.66 1 2892 Manor View Drive 9045.17 1 2904 Manor View Drive 9045.17 1 2910 Manor View Drive 9638.22 1 2910 Manor View Drive 9638.22 1 2914 Noble View Drive 9638.22 1 2915 Noble View Drive 7818.46 1 782 Bay View Drive 7818.46 1 782 Bay View Drive 4010.27 1 796 Bay View Drive 4010.27 1	2868 Manor View Drive 4002.21 1 1 1 1 2814 Manor View Drive 4002.21 1 1 1 1 2814 Manor View Drive 4002.21 1 1 1 1 2814 Manor View Drive 402.22 1 1 1 1 2816 Manor View Drive 4352.28 1 1 2816 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5462.27 1 1 1 1 2910 Manor View Drive 5045.21 1 1 1 1 2910 Manor View Drive 5045.21 1 1 1 1 1 2910 Manor View Drive 5038.22 1 1 1 1 1 1 1 2944 Noble View Drive 5038.22 1 1 1 1 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4552.28 1 1 2904 Manor View Drive 5006.68 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 2910 Manor View Drive 9045.17 1 1 1 1 2948 Nobile View Drive 9638.22 1 1 1 1 1 1 1 2948 Nobile View Drive 7818.48 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive 4002.21 1 1 1 1 2814 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4074.06 4174	2868 Manor View Drive 4002.21 1 1 1 1 2874 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4002.21 1 1 1 1 2882 Manor View Drive 4052.28 1 1 2904 Manor View Drive 5006.68 1 1 1 1 2936 Manor View Drive 9045.27 1 1 1 1 2936 Noble View Drive 9045.27 1 1 1 1 1 2936 Noble View Drive 9045.27 1 1 1 1 1 1 2936 Noble View Drive 9045.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive 4002.21 1 1 1 1 1 2814 Manor View Drive 4002.21 1 1 1 1 1 2882 Manor View Drive 4074.06 4174.06 4174.06 4174.06 506.66 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2868 Manor View Drive 4002.21 1 1 1 1 2814 Manor View Drive 4002.21 1 1 1 1 2817 Manor View Drive 4002.21 1 1 1 1 2818 Manor View Drive 4002.21 1 1 1 1 2818 Manor View Drive 4474.06 1 1 1 1 2818 Manor View Drive 5462.28 1 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 2910 Manor View Drive 9045.17 1 1 1 1 2910 Manor View Drive 9045.17 1 1 1 1 1 2914 Noble View Drive 9638.22 1 1 1 1 1 1 1 1 2914 Noble View Drive 7818.48 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Trive	rive	rive	rive rive rive	rive rive	rive rive		2874 Manor View Drive 4002.21 2882 Manor View Drive 4572.06 2882 Manor View Drive 4552.26 3895 Manor View Drive 5006.86 3996 Manor View Drive 5462.27 2910 Manor View Drive 9045.17 2952 Noble View Drive 9638.22 2948 Noble View Drive 7816.48 782 Bay View Drive 7818.46 782 Bay View Drive 4010.27 795 Bay View Drive 4010.27 796 Bay View Drive 4010.27 796 Bay View Drive 8084.7	2874 Manor View Drive 400221 2882 Manor View Drive 4174.06 2882 Manor View Drive 4552.28 3888 Manor View Drive 5006.86 3898 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5462.27 1 1 2910 Manor View Drive 9645.27 1 1 1 1 2940 Noble View Drive 9638.22 1 1 2944 Noble View Drive 7618.46 1 1 7294 Noble View Drive 7418.46 1 1 730 Bay View Drive 4010.27 1 1	2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 4552.28 3886 Manor View Drive 506.86 2904 Manor View Drive 506.86 2904 Manor View Drive 6462.27 1 1 2910 Manor View Drive 8045.17 2952 Noble View Drive 8045.17 1 1 2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.45 1 1 790 Bay View Drive 4230.81 796 Bay View Drive 4010.27 1 1 796 Bay View Drive 4050.6 1 1 810 Bay View Drive 4050.6	2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 4452.28 3856 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6945.27 1 1 2921 Mahor View Drive 6938.22 1 1 2948 Noble View Drive 6938.22 1 1 2944 Noble View Drive 7818.46 1 1 792 Bay View Drive 4230.81 1 1 190 Bay View Drive 4010.27 1 1 8084.7 1 10 Bay View Drive 8084.7 1 1 816 Bay View Drive 4050.6 1 1 816 Bay View Drive 7960.65	2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 4452.28 2898 Manor View Drive 506.66 2904 Manor View Drive 506.68 1 1 2910 Manor View Drive 6462.27 1 1 2912 Noble View Drive 6938.22 1 1 2948 Noble View Drive 7818.48 2944 Noble View Drive 7818.48 790 Bay View Drive 4230.48 1 1 796 Bay View Drive 4010.27 1 1 10 Bay View Drive 8084.7 816 Bay View Drive 4050.6 1 1 13 Bay View Drive 7860.65 1 1 816 Bay View Drive 7860.65 1 1 816 Bay View Drive 8285.65 1 1 844 Bay View Drive 6487.45 1 1 858 Bay View Drive 6487.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>2874 Manor View Drive 4002 21 2882 Manor View Drive 4174.06 2882 Manor View Drive 4052.28 3886 Manor View Drive 5066.86 1 1 2904 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6945.27 1 1 <td>2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 5006.86 3886 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6938.22 1 1 2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.46 1 1</td></td>	2874 Manor View Drive 4002 21 2882 Manor View Drive 4174.06 2882 Manor View Drive 4052.28 3886 Manor View Drive 5066.86 1 1 2904 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6945.27 1 1 <td>2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 5006.86 3886 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6938.22 1 1 2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.46 1 1</td>	2874 Manor View Drive 4002.21 2882 Manor View Drive 4174.06 2882 Manor View Drive 5006.86 3886 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5462.27 1 1 2910 Manor View Drive 6938.22 1 1 2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.46 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7754.45 1 1 817 Bay View Drive 4262.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7108.56 1 1 1 817 Bay View Drive 4292.65 1 1 1 818 Pay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 979 Bay View Drive 4107.94 1 979 Bay View Drive 4107.94 1 979 Bay View Drive 4303.32 1 979 Bay View Drive 4303.32 1 979 Bay View Drive 4303.32 1 979 Bay View Drive 4839.41 1 979 Bay View Drive 479 B004.42 1 1 979 Bay View Drive 479 B004.42 1 1 979 Bay View Drive 479 B004.22 1 1 979 Bay View Drive 479 Bay View Drive 479 B004.22 1 1 979 Bay View Drive 479 Bay	817 Bay View Drive 4292.65 1 811 Bay View Drive 3955.65 1 805 Bay View Drive 3955.65 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4179.42 1 791 Bay View Drive 4393.32 1 2806 Manor View Drive 4829.81 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 2866 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	811 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 3955.62 797 Bay View Drive 4107.94 1 791 Bay View Drive 479.42 1 1 281 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.41 1 2815 Manor View Drive 4826.47 1 2816 Manor View Drive 4002.21 1 2818 Manor View Drive 4002.21 1 2818 Manor View Drive 4002.21 1	805 Bay View Drive 3955.52 797 Bay View Drive 4177.94 791 Bay View Drive 4779.42 781 Bay View Drive 4393.32 2800 Manor View Drive 4839.41 2814 Manor View Drive 4839.41 2828 Manor View Drive 4829.81 2828 Manor View Drive 4925.47 2844 Manor View Drive 4002.21 2850 Manor View Drive 4002.21 2868 Manor View Drive 4002.21		2882 Manor View Drive 4552.28 3896 Manor View Drive 5006.86 2904 Manor View Drive 5462.27 1 2910 Manor View Drive 9045.17 2952 Nobie View Drive 9638.22 1 2948 Nobie View Drive 7818.46 1 782 Bay View Drive 7818.46 1 782 Bay View Drive 4230.81 796 Bay View Drive 4010.27 1 796 Bay View Drive 8084.7 1	2862 Manor View Drive	2862 Manor View Drive	2862 Manor View Drive 4552.28 1 3896 Manor View Drive 5006.86 1 12904 Manor View Drive 5462.27 1 1 2910 Manor View Drive 9045.17 1 1 2914 Noble View Drive 9638.22 1 1 1 2944 Noble View Drive 7818.48 1 1 1 2944 Noble View Drive 7818.46 1 1 1 782 Bay View Drive 4230.81 1 1 1 796 Bay View Drive 4010.27 1 1 1 810 Bay View Drive 8084.7 1 1 1 816 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.55 1 1 1	2862 Manor View Drive	2862 Manor View Drive 4652.28 1 3896 Manor View Drive 5606.86 1 1 2904 Manor View Drive 5462.27 1 1 1 2910 Manor View Drive 9045.17 1 1 1 2914 Noble View Drive 9638.22 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 430.81 1 1 1 792 Bay View Drive 430.81 1 1 1 798 Bay View Drive 4010.27 1 1 1 816 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7860.55 1 1 1 836 Bay View Drive 487.45 1 1 1 858 Bay View Drive 6487.45 1 1 1 868 Bay View Drive 6440.42 1 1 1 868 Bay View Drive 6440.42 1 1 1	2882 Manor View Drive
837 Bay View Drive 5577.77 1 831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7764.45 1 1 817 Bay View Drive 4292.65 1 1 816 Bay View Drive 4292.65 1 1 816 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 3577.71 1 831 Bay View Drive 7764.55 1 1 1 817 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4779.42 1 798 Bay View Drive 479.42 1 798 Bay View Drive 4303.32 1 781 Bay View Drive 4859.41 1 781 Bay View Drive 48002.21 1 781 Bay View Drive 4002.21 1	817 Bay View Drive 7108.56 1 811 Bay View Drive 3955.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4779.42 1 791 Bay View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	811 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1	805 Bay View Drive 4170.94 1797 Bay View Drive 4170.94 1791 Bay View Drive 4170.42 1 1 791 Bay View Drive 4373.32 1 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.41 1 2828 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2882 Manor View Drive	5006.66 1 5462.27 1 5462.27 1 5638.22 1 7818.46 1 7230.81 4010.27 1 1	3896 Manor View Drive 5066.66 1 1 1 1 2904 Manor View Drive 5462.27 1 1 1 2910 Manor View Drive 6462.27 1 1 1 1 2910 Manor View Drive 6945.77 1 1 1 1 2932 Noble View Drive 6938.22 1 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 782 Bay View Drive 7818.46 1 1 1 1 782 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3856 Manor View Drive 5006.86 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 2910 Manor View Drive 5462.27 1 1 1 1 1 2910 Manor View Drive 6046.17 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2896 Manor View Drive	2896 Manor View Drive 5006.86 1 1 1 2904 Manor View Drive 5462.27 1 1 1 2910 Manor View Drive 6462.27 1 1 1 2910 Manor View Drive 6046.7.27 1 1 1 2910 Manor View Drive 6046.7.2 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 2946 Noble View Drive 4230.81 1 1 1 1 2956 Bay View Drive 4010.27 1 1 1 1 1 1 2956 Bay View Drive 8084.7 1 1 1 1 1 1 2956 Bay View Drive 4050.6 1 1 1 1 1 1 2956 Bay View Drive 7860.65 1 1 1 1 1 1 1 2956 Bay View Drive 8285.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3896 Manor View Drive 5006.66 1	3896 Manor View Drive 5006.66 1
837 Bay View Drive 5577.77 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 7764.65 1 1 81 Bay View Drive 4292.65 1 1 81 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7766.56 1 1 1 817 Bay View Drive 7766.56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 7108.56 1 818 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 41707.94 1 791 Bay View Drive 41707.94 1 791 Bay View Drive 4303.32 1 2814 Manor View Drive 4859.41 1 2818 Manor View Drive 4859.41 1 2818 Manor View Drive 4002.21 1 2819 Manor View Drive 4002.21 1 2820 Manor View Drive 4002.21 1 2831 Manor View Drive 4002.21 1	817 Bay View Drive 7108.56 1 811 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4107.94 1 791 Bay View Drive 4393.32 1 781 Bay View Drive 4393.32 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 28874 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1	811 Bay View Drive 4292.65 805 Bay View Drive 3955.62 797 Bay View Drive 4179.42 791 Bay View Drive 479.42 791 Bay View Drive 479.42 791 Bay View Drive 4303.32 791 Bay View Drive 4859.41 2800 Manor View Drive 4826.47 2844 Manor View Drive 4002.21 2852 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2874 Manor View Drive 4002.21	805 Bay View Drive 3955.52 197 Bay View Drive 4179.44 791 Bay View Drive 4179.42 1 1 181 Bay View Drive 4379.32 2800 Manor View Drive 4639.41 2814 Manor View Drive 4639.47 2814 Manor View Drive 4639.47 2815 Manor View Drive 4052.47 2816 Manor View Drive 4052.21 2817 Manor View Drive 4002.21 2818 Manor View Drive 4002.21 2819 Manor View Drive 4002.21		5462.27 1 9045.77 9045.77 9638.22 1 7818.48 1 7818.46 1 4230.81 4010.27 1 1	2904 Manor View Drive	2904 Manor View Drive 5482.27 1 1 1 1 1 1 1 1 1	2904 Manor View Drive 5482.27 1 1 1 1 1 1 1 1 1	2904 Manor View Drive 5482.27 1 1 1 1 1 1 1 1 1	2904 Manor View Drive 5482.27 1 1 1 1 1 1 1 1 1	2904 Manor View Drive 5482.27 1 1 1 1 1 2910 Manor View Drive 9045.17 1 1 1 1 1 2925 Noble View Drive 9038.22 1 1 1 1 1 1 2925 Noble View Drive 7818.46 1 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7108.56 1 1 818 Day View Drive 4292.65 1 1 818 Day View Drive 4292.65 1 1 818 Day View Drive 4107.64 1 1 791 Bay View Drive 4107.64 1 1 791 Bay View Drive 4107.64 1 1 791 Bay View Drive 4303.32 1 1 2800 Manor View Drive 4592.81 1 1 2814 Manor View Drive 4002.47 1 2865 Manor View Drive 4002.21 1 1 2866 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1	831 Bay View Drive 7764.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 3955.62 1 805 Bay View Drive 4170.794 1 797 Bay View Drive 4170.794 1 798 Bay View Drive 4303.32 1 781 Bay View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	817 Bay View Drive 7108.56 1 811 Bay View Drive 3955.65 1 805 Bay View Drive 3955.65 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 41707.94 1 791 Bay View Drive 41707.94 1 791 Bay View Drive 4393.32 1 2804 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1	811 Bay View Drive 3955.62 1 0.05 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	805 Bay View Drive 3955.52 197 Bay View Drive 4177.94 198 Bay View Drive 4178.42 198 Bay View Drive 4393.32 2800 Manor View Drive 4839.41 2814 Manor View Drive 4839.41 2828 Manor View Drive 4825.47 2828 Manor View Drive 4002.21 2852 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2874 Manor View Drive 4002.21 2882 Manor View Drive 4002.21 2882 Manor View Drive 4002.21 2883 Manor View Drive 4002.21 2884 Manor View Drive 4002.21 2885 Manor View Drive 4002.21 2886 Manor View Drive 4002.21	2882 Manor View Drive 2882 Manor View Drive 3896 Manor View Drive	IVVB 945.2.7 1 IVVB 9638.22 1 1 IVVB 7818.48 1 1 IVVB 4230.81 1 8084.7 1 1	2914 Manor View Unive 945.2.7 1 1 1 1 2916 Manor View Drive 945.1.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 945.2.7 1 1 1 1 2916 Manor View Drive 9638.22 1 1 1 1 1 2948 Noble View Drive 9638.22 1 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 4330.81 1 1 1 1 2949 Niew Drive 4330.81 1 1 1 1 2950 Bay View Drive 4010.27 1 1 1 1 1 1 1 2950 Bay View Drive 8084.7 1 1 1 1 1 1 1 2950 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2914 Manor View Unive 945.2.7 1 1 1 1 2916 Manor View Drive 9638.22 1 1 1 1 1 2952 Noble View Drive 9638.22 1 1 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 945.2.7 1 1 1 1 2916 Manor View Drive 9638.22 1 1 1 1 1 2948 Noble View Drive 9638.22 1 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 2949 Niew Drive 4230.81 1 1 1 1 2949 Niew Drive 8084.7 1 1 1 1 1 2949 Niew Drive 8084.7 1 1 1 1 1 2949 Niew Drive 8084.7 1 1 1 1 1 2949 Niew Drive 8285.65 1 1 1 1 1 1 2949 Niew Drive 8285.65 1 1 1 1 1 1 2949 Niew Drive 8285.65 1 1 1 1 1 1 1 2949 Niew Drive 8285.7.45 1 1 1 1 1 1 1 1 2949 Niew Drive 6487.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2914 Manor View Unive 945.2.7 1 1 1 1 2910 Manor View Drive 945.1.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2914 Manor View Unive 945.2.7 1 1 1 1 2916 Manor View Drive 9638.22 1 1 1 1 1 1 2948 Noble View Drive 9638.22 1 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 1 1 2949 Noble View Drive 4230.81 1 1 1 1 1 2949 Noble View Drive 4230.81 1 1 1 1 1 2949 Noble View Drive 4230.81 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 4262.56 1 1 81 Bay View Drive 4262.56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 811 Bay View Drive 7768.56 1 1 1 811 Bay View Drive 7768.56 1 1 1 811 Bay View Drive 4292.65 1 1 1 805 Bay View Drive 3955.65 1 1 781 Bay View Drive 4107.94 1 781 Bay View Drive 4107.94 1 1 781 Bay View Drive 4393.32 1 1 2800 Manor View Drive 4839.41 1 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 1 2862 Manor View Drive 4002.21 1 4 2862 Manor View Drive 4002.21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7764.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4707.94 1 791 Bay View Drive 4303.32 1 2814 Manor View Drive 4859.41 1 2828 Manor View Drive 4859.41 1 2828 Manor View Drive 4004.22 1 1 2852 Manor View Drive 4004.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2883 Manor View Drive 4002.21 1 2884 Manor View Drive 4002.21 1 2885 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1	817 Bay View Drive 7108.56 1 1 811 Bay View Drive 395.52 1 1 825.62 1 1 825.62 1 1 825.62 1 1 825.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	811 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4177.94 1 791 Bay View Drive 4779.42 1 781 Bay View Drive 4393.32 1 2806 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.47 1 2828 Manor View Drive 4902.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1	805 Bay View Drive 3955.82 197 Bay View Drive 4107.94 1791 Bay View Drive 4178.42 1 1 1 2814 Manor View Drive 4839.41 2828 Manor View Drive 4839.41 2828 Manor View Drive 4939.47 2844 Manor View Drive 4252.47 2852 Manor View Drive 4002.21 2858 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2874 Manor View Drive 4002.21 2885 Manor View Drive 4002.21 2886 Manor View Drive 4002.21 2887 Manor View Drive 4002.21 2888 Manor View Drive 4002.21 2889 Manor View Drive 4006.86	4174.06 4552.28 5006.86 1	ive	2910 Manor View Drive 9645.17 1 1 1 2952 Noble View Drive 9638.22 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2954 Noble View Drive 7818.46 1 1 1 1 2956 Bay View Drive 4010.27 1 1 1 1 2956 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 9045.17 1 1 1 2910 Manor View Drive 9638.28 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2956 Bay View Drive 4230.81 1 1 1 2956 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 6045.17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 9045.17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 6045.17 1 1 1 2910 Manor View Drive 6038.22 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2949 View Drive 7818.48 1 1 1 1 2949 View Drive 7818.48 1 1 1 1 2949 View Drive 4030.51 1 1 1 1 2949 View Drive 4010.27 1 1 1 1 1 2956 Bay View Drive 8084.7 1 1 1 1 1 1 2956 Bay View Drive 8084.7 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 2950.65 1 1 1 1 1 1 2950.65 1 1 1 1 1 1 1 2950.65 1 1 1 1 1 1 1 2950.65 1 1 1 1 1 1 1 2950.65 1 1 1 1 1 1 1 2950.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2910 Manor View Drive 9045.17 1 1 1 2910 Manor View Drive 9638.22 1 1 1 1 1 2926 Noble View Drive 7818.48 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 2924 Noble View Drive 4230.81 1 1 1 2924 Noble View Drive 4230.81 1 1 1 1 2925 Noble View Drive 4230.81 1 1 1 1 1 2925 Noble View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 4262.56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 357.7.7 1 831 Bay View Drive 7768.56 1 1 811 Bay View Drive 4292.65 1 1 805 Bay View Drive 3955.62 1 1 806 Bay View Drive 4107.94 1 1 791 Bay View Drive 4179.42 1 1 791 Bay View Drive 4393.32 1 1 2806 Manor View Drive 4529.81 1 1 2814 Manor View Drive 4629.81 1 1 2814 Manor View Drive 4002.21 1 1 2865 Manor View Drive 4002.21 1 1 2866 Manor View Drive 4002.21 1 1 2867 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 1 2869 Manor View Drive 4002.21 1 1 2860 Manor View Drive 4002.21 1 1	831 Bay View Drive 7764.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4179.42 1 791 Bay View Drive 4393.32 1 2800 Manor View Drive 4639.41 1 2814 Manor View Drive 4639.41 1 2814 Manor View Drive 4639.41 1 2814 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2883 Manor View Drive 4002.21 1 2884 Manor View Drive 4002.21 1 2885 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 2887 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1 2898 Manor View Drive 4002.21 1 2899 Manor View Drive 4002.21 1 2898 Manor View Drive 4002.21 1 2898 Manor View Drive 4002.21 1 2899 Manor View Drive 4002.21 1 2899 Manor View Drive 4002.21 1 2899 Manor View Drive 5006.86 1	817 Bay View Drive 7108.56 1 1 811 Bay View Drive 395.56 1 7 80.5 Bay View Drive 395.56 1 7 7 81 Bay View Drive 4107.94 1 7 81 Bay View Drive 4107.94 1 7 81 Bay View Drive 4107.94 1 7 81 Bay View Drive 439.3 2 1 1 2 80.0 Manor View Drive 439.4 1 1 2 814 Manor View Drive 4829.4 1 1 2 814 Manor View Drive 4252.4 7 2 828 Manor View Drive 4002.2 1 1 2 852 Manor View Drive 4002.2 1 1 2 852 Manor View Drive 4002.2 1 1 2 865 Manor View Drive 4002.2 1 1 2 865 Manor View Drive 4002.2 1 1 2 885 Manor View Drive 4002.2 1 1 2 885 Manor View Drive 4002.2 1 1 2 885 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 8 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 2 8 9 8 Manor View Drive 4002.2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	811 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 478.42 1 1 781 Bay View Drive 4393.32 1 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4252.47 1 2824 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2883 Manor View Drive 4002.21 1 2884 Manor View Drive 4002.21 1 2885 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 2887 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1 2889 Manor View Drive 4002.21 1 2889 Manor View Drive 4002.21 1 2889 Manor View Drive 5006.86 1 1 2890 Manor View Drive 5006.86 1 1	805 Bay View Drive 3955.82 197 Bay View Drive 4107.94 797 Bay View Drive 4107.94 798 Bay View Drive 4303.31 2814 Manor View Drive 4839.41 2828 Manor View Drive 4839.41 2828 Manor View Drive 4825.47 2828 Manor View Drive 4002.21 2852 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2868 Manor View Drive 4002.21 2874 Manor View Drive 4002.21 2882 Manor View Drive 4002.21 2883 Manor View Drive 4003.21 2884 Manor View Drive 4003.21 2885 Manor View Drive 4003.21 2886 Manor View Drive 4003.21 2887 Manor View Drive 4003.21 2888 Manor View Drive 4003.21 2888 Manor View Drive 4003.21 2889 Manor View Drive 4003.21 2880 Manor View Drive 4003.21 2881 Manor View Drive 4003.21 2882 Manor View Drive 4003.21 2883 Manor View Drive 4003.21 2884 Manor View Drive 4003.21 2885 Manor View Drive 4003.21 2886 Manor View Drive 4003.21 2886 Manor View Drive 4003.21 2887 Manor View Drive 4003.21 2888 Manor View Drive 4003.21 2889 Manor View Drive 4003.21 2880 Manor View Drive 4003.21 2881 Manor View Drive 4003.21 2882 Manor View Drive 4003.21 2883 Manor View Drive 5006.86 3896 Manor View Drive 5006.86 3896 Manor View Drive 5006.86 3896 Manor View Drive 5006.86	2882 Manor Vlew Drive 4174.06 2882 Manor View Drive 4552.28 3896 Manor View Drive 5006.86 1 2904 Manor View Drive 5462.27 1	ive ive	2952 Noble View Drive 9638.22 1 1 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 1 1 1 1 1	2952 Noble View Drive 9638.22 1 1 1 1 1 1 1 1 1	2952 Noble View Drive 9638.22 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 4230.81 1 1 1 2944 Noble View Drive 4230.81 1 1 1 2944 Noble View Drive 4010.27 1 1 1 1 2944 Noble View Drive 8084.7 1 1 1 2944 Noble View Drive 4050.6 1 1 1 1 2944 Noble View Drive 4050.6 1 1 1 1 2944 Noble View Drive 4050.6 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 2944 Noble View Drive 7960.55 1 1 1 1 1 1 1 1 1	2952 Noble View Drive 9638.22 1 1 1 1 1 1 1 2948 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1	2952 Noble View Drive 9638.22 1 1 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2948 Noble View Drive 7818.48 1 1 1 1 2948 Noble View Drive 4230.81 1 1 1 1 2948 Noble View Drive 4230.81 1 1 1 1 2948 Noble View Drive 4010.27 1 1 1 1 2948 Noble View Drive 4050.6 1 1 1 1 1 2948 Noble View Drive 4050.6 1 1 1 1 1 2948 Noble View Drive 4285.65 1 1 1 1 1 2948 Noble View Drive 4285.65 1 1 1 1 1 2948 Noble View Drive 6487.45 1 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 2948 Noble View Drive 6440.42 1 1 1 1 1	2952 Noble View Drive 9638.22 1 1 1 1 1 1 1 2948 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7764.45 1 1 81 Bay View Drive 7708.56 1 1 81 Bay View Drive 4292.65 1 1 805 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 357.7.7 1 831 Bay View Drive 7708.56 1 811 Bay View Drive 4292.65 1 818 Yelw Drive 4292.65 1 819 Bay View Drive 4107.94 1 791 Bay View Drive 4107.94 1 791 Bay View Drive 4303.32 1 2800 Manor View Drive 4393.41 1 2814 Manor View Drive 4252.47 1 2815 Manor View Drive 4002.21 1 2816 Manor View Drive 4002.21 1 2817 Manor View Drive 4002.21 1 2818 Manor View Drive 4002.21 1 2819 Manor View Drive 5402.27 1 2819 Manor View Drive 5402.27 1 2819 Manor View Drive 5402.27 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 4292.65 1 818 bay View Drive 4292.65 1 818 bay View Drive 3955.62 1 797 Bay View Drive 4797.94 7 797 Bay View Drive 4797.94 7 791 Bay View Drive 4799.42 1 1 2800 Manor View Drive 4639.41 1 2814 Manor View Drive 4639.41 1 2815 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2862 Manor View Drive 4002.21 1 2862 Manor View Drive 4002.21 1 2863 Manor View Drive 4002.21 1 2864 Manor View Drive 4002.21 1 2865 Manor View Drive 5462.28 1 2864 Manor View Drive 5462.27 1 2865 Manor View Drive 5462.27 1	817 Bay Vlew Drive 7108.56 1 811 Bay Vlew Drive 4292.65 2 1938 Bay Vlew Drive 3955.62 1 1937 Bay Vlew Drive 4107.94 1 1938 Vlew Drive 4107.94 1 1938 Vlew Drive 4393.32 1 2800 Manor Vlew Drive 4839.41 1 2814 Manor Vlew Drive 4904.42 1 2815 Manor Vlew Drive 4004.22 1 1 2816 Manor Vlew Drive 4004.21 1 2816 Manor Vlew Drive 4004.21 1 2817 Manor Vlew Drive 4004.21 1 2818 Manor Vlew Drive 4005.21 1 2819 Manor Vlew Drive 4005.21 1	811 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 907 Bay View Drive 4107.94 1 791 Bay View Drive 4707.94 1 791 Bay View Drive 4709.32 1 781 Bay View Drive 4859.41 1 2800 Manor View Drive 4859.41 1 2814 Manor View Drive 4002.21 1 2828 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2860 Manor View Drive 4002.21 1 2861 Manor View Drive 4002.21 1 2862 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2860 Manor View Drive 5462.26 1 2860 Manor View Drive 5462.27 1 2860 Manor View Drive 5462.27 1	805 Bay View Drive 3955.82 197 Bay View Drive 4170.42 1 1 791 Bay View Drive 4373.42 1 1 281 Bay View Drive 4393.32 1 1 2814 Manor View Drive 4859.41 1 2828 Manor View Drive 4004.42 1 1 2852 Manor View Drive 4004.42 1 1 2852 Manor View Drive 4002.21 1 1 2865 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.27 1 1 2869 Manor View Drive 4002.27 1 1 2860 Manor View Drive 5006.66 1 1 2804 Manor View Drive 5006.66 1 1 2805 Manor View Drive 5006.66 1 1 2806 Manor View Drive 9045.77 1	2882 Manor View Drive 4174.06	Ve Ve	2948 Noble View Drive 7818.48 1 1 1 2944 Noble View Drive 7818.48 1 1 1 7 7 7 8 1 8 1 1 1 1 1 1 1 1 1 1	2948 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 2944 Noble View Drive 7818.46 1 1 1 1 1 2944 Noble View Drive 4230.81 1 1 296 Bay View Drive 4010.27 1 1 1 296 Bay View Drive 8084.7 1 1 1 296 Bay View Drive 8084.7 1 1 1 296 Bay View Drive 4050.6 1 1 1	2948 Noble View Drive 7818.48 1 1 1 1	2948 Noble View Drive 7818.46 1 1 2944 Noble View Drive 7818.46 1 1 782 Bay View Drive 4230.51 1 1 790 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.55 1 1 1 836 Bay View Drive 8285.65 1 1 1 844 Bay View Drive 6487.45 1 1 1 858 Bay View Drive 6487.45 1 1 1	2948 Noble View Drive 7818.48 1 1 1 2944 Noble View Drive 7818.48 1 1 1 782 Bay View Drive 4230.81 1 1 1 790 Bay View Drive 4010.27 1 1 1 810 Bay View Drive 8084.7 1 1 1 816 Bay View Drive 4050.6 1 1 1 836 Bay View Drive 8285.65 1 1 1 854 Bay View Drive 6487.45 1 1 1 868 Bay View Drive 6440.42 1 1 1 868 Bay View Drive 6447.43 1 1 1 868 Bay View Drive 6447.43 1 1 1	2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.46 1 1 782 Bay View Drive 4230.81 1 1 796 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 810 Bay View Drive 4050.6 1 1 1 818 Bay View Drive 786.65 1 1 1 836 Bay View Drive 8285.65 1 1 1 861 Bay View Drive 6487.45 1 1 1 866 Bay View Drive 6487.45 1 1 1 867 Bay View Drive 6440.42 1 1 1 867 Bay View Drive 4134.33 1 1 1 87 Bay View Drive 4020.73 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 7708.56 1 1 81 Bay View Drive 4292.56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 811 Bay View Drive 7768.56 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 811 Bay View Drive 7108.56 1 1 811 Bay View Drive 4292.65 1 1 805 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	817 Bay View Drive 7108.56 1 1 811 Bay View Drive 4292.65 2 1 1 815 Bay View Drive 385.62 1 1 978 Bay View Drive 4107.94 1 791 Bay View Drive 4107.94 1 791 Bay View Drive 4393.32 1 1 2810 Manor View Drive 4839.41 1 1 2814 Manor View Drive 4839.41 1 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4002.21 1 1 2852 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 2904 Manor View Drive 4003.22 1 2904 Manor View Drive	811 Bay View Drive 4292.65 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4179.42 1 791 Bay View Drive 479.42 1 791 Bay View Drive 4393.32 1 2806 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.47 1 2828 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4003.22 1 2868 Manor View Drive 4003.23 1 2868 Manor View Drive 4003.23 1 2869 Manor View Drive 9048.17 1 2860 Manor View Drive 9048.17 1 2860 Manor View Drive 9638.22 1	805 Bay View Drive 3955.82 197 Bay View Drive 4107.94 791 Bay View Drive 4707.94 791 Bay View Drive 4303.32 2800 Manor View Drive 4839.41 2814 Manor View Drive 4839.41 2814 Manor View Drive 4825.21 2814 Manor View Drive 4002.21 2815 Manor View Drive 4002.21 2816 Manor View Drive 4002.21 2817 Manor View Drive 4002.21 2818 Manor View Drive 4002.21 2819 Manor View Drive 4003.21 2819 Manor View Drive 4003.22 2819 Manor View Drive 4003.23 2819 Manor V	2882 Manor View Drive 4174.06 2882 Manor View Drive 4552.28 3898 Manor View Drive 5005.86 1 2904 Manor View Drive 5462.27 1 2910 Manor View Drive 9045.17 2932 Nobie View Drive 9638.22 1	lve Ive	2944 Noble View Drive 7818.46 1 1 1 1 782 Bay View Drive 4230.81 1 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2944 Noble View Drive 7818.46 1 1 1 782 Bay View Drive 4230.81 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2944 Noble View Drive 7818.46 1 1 782 Bay View Drive 4230.81 1 1 790 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 4050.65 1 1 1	2944 Noble View Drive 7818.46 1 1 1 1 782 Bay View Drive 4230.81 1 1 1 790 Bay View Drive 8084.7 1 1 1 1 790 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2944 Noble View Drive 7818.46 1 1 1 782 Bay View Drive 4230.81 1 1 796 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2944 Noble View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 7 Bay View Drive 4292.65 1 1 81 7 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7764.45 1 1 811 Bay View Drive 4292.65 1 1 818 Day View Drive 4292.65 1 1 818 Day View Drive 4292.65 1 1 818 Day View Drive 4197.94 1 1 791 Bay View Drive 4197.94 1 1 791 Bay View Drive 4393.32 1 1 2800 Manor View Drive 4528.81 1 1 2814 Manor View Drive 4628.81 1 1 2816 Manor View Drive 4002.21 1 1 2862 Manor View Drive 4002.21 1 1 2868 Manor View Drive 5008.86 1 1 2810 Manor View Drive 5008.86 1 1 2810 Manor View Drive 5008.86 1 1 2810 Manor View Drive 9638.22 1 1 2826 Noble View Drive 7818.48 1 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 787 Bay View Drive 4797.94 1 781 Bay View Drive 4798.42 1 1 781 Bay View Drive 4839.41 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4839.41 1 2815 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2860 Manor View Drive 5006.86 1 1 2860 Manor View Drive 5006.86 1 1 2861 Nobile View Drive 9638.22 1 1 2862 Nobile View Drive 7686.48 1 1	817 Bay View Drive 4292.65 1 811 Bay View Drive 3955.65 1 805 Bay View Drive 3955.65 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4179.42 1 791 Bay View Drive 4393.32 1 2806 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.41 1 2814 Manor View Drive 4829.41 1 2815 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 2896 Manor View Drive 4002.21 1 2896 Manor View Drive 4002.21 1 2897 Manor View Drive 4002.21 1 2898 Manor View Drive 4002.21 1 2899 Manor View Drive 5006.86 1 1 2910 Manor View Drive 5006.86 1 1 2910 Manor View Drive 50462.27 1 1 2910 Manor View Drive 50462.27 1 1 2952 Noble View Drive 9638.22 1 1 2958 Noble View Drive 7818.48 1 1	811 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4178.42 1 781 Bay View Drive 4393.32 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2824 Manor View Drive 4902.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.21 1 2860 Manor View Drive 5006.86 1 1 2860 Manor View Drive 5006.86 1 1 2860 Manor View Drive 9638.22 1 1 2860 Manor View Drive 7686.86 1 1	805 Bay View Drive 3955.82 197 Bay View Drive 4107.94 797 Bay View Drive 4178.42 1 791 Bay View Drive 4393.31 1 2814 Manor View Drive 4839.41 1 2814 Manor View Drive 4825.47 2828 Manor View Drive 4925.47 2844 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Maror View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2882 Manor View Drive 4002.21 1 2883 Manor View Drive 4002.21 1 2884 Manor View Drive 4002.21 1 2885 Manor View Drive 4002.21 1 2886 Manor View Drive 4002.21 1 2887 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1 2888 Manor View Drive 4002.21 1 2889 Manor View Drive 4002.21 1 2880 Manor View Drive 4052.28 1 2890 Manor View Drive 5063.22 1 1 2910 Manor View Drive 9638.22 1 2924 Noble View Drive 9638.22 1	4174.06 4152.28 5006.56 5462.27 9045.17 9045.17 9638.22 7818.48 1		782 Bay View Drive 4230.81 1 1 1 790 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	782 Bay View Drive 4230.51 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	782 Bay View Drive 4230.81 1 1 1 796 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	782 Bay View Drive 4230.81 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	782 Bay View Drive 4230.81 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	782 Bay View Drive 4230.81 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 7754.45 1 1 81 Bay View Drive 4292.65 1 1 81 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 3377.71 1 831 Bay View Drive 7708.56 1 1 817 Bay View Drive 4292.65 1 1817 Bay View Drive 4292.65 1 1818 Bay View Drive 3955.62 1 1818 Bay View Drive 4170.42 1 1818 Bay View Drive 4170.42 1 1818 Bay View Drive 4303.32 1 1810 Manor View Drive 4859.41 1 1814 Manor View Drive 4252.47 1 1815 Manor View Drive 4002.21 1 1815 Manor View Drive 4002.21 1 1816 Manor View Drive 4002.21 1 1816 Manor View Drive 4002.21 1 1817 Manor View Drive 4002.21 1 1818 Manor View Drive 5462.27 1 1818 Manor View Drive 5462.27 1 1818 Manor View Drive 9043.17 1 1818 Manor View Drive 9043.17 1 1818 Manor View Drive 7818.46 1 1818 Manor View Drive 7818.46 1	831 Bay View Drive 7764.45 1 1 817 Bay View Drive 4292.65 1 1 811 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	817 Bay View Drive 4292.65 1 1 811 Bay View Drive 3955.62 1 1 819 Will be Drive 3955.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	811 Bay View Drive 3955.62 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	805 Bay View Drive 3955.82 1897 Well Drive 4170.94 1797 Bay View Drive 4170.42 1 1 1 181 Bay View Drive 4303.32 1 1 1 181 Bay View Drive 4859.41 1 2814 Manor View Drive 4859.41 1 2828 Manor View Drive 4004.47 1 2844 Manor View Drive 4004.47 1 2852 Manor View Drive 4002.21 1 1 1 1 2858 Manor View Drive 4002.21 1 1 1 1 2868 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 4002.27 1 1 2869 Manor View Drive 4002.27 1 2860 Manor View Drive 4002.27 1 1 2860 Manor View Drive 4002.27 1 2910 Manor View Drive 5462.27 1 2904 Manor View Drive 5462.27 1 2952 Nobie View Drive 9045.77 1 2952 Nobie View Drive 9045.77 1 2952 Nobie View Drive 9638.22 1 1 2944 Nobie View Drive 7816.48 1 1 2944 Nobie View Drive 7816.48	2882 Manor View Drive 4174.08 2882 Manor View Drive 4552.28 3898 Manor View Drive 5065.86 1 2894 Manor View Drive 5462.27 1 2910 Manor View Drive 9045.17 2952 Noble View Drive 938.8 22 1 2948 Noble View Drive 7818.46 1		790 Bay View Drive 4010.27 1 1 1 1 7996 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	790 Bay View Drive 4010.27 1 1 1 1 796 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	790 Bay View Drive 4010.27 1 1 1 1 7996 Bay View Drive 8084.7 1 1 1 810 Bay View Drive 4050.5 1 1 1 816 Bay View Drive 7960.55 1 1 1 1	790 Bay View Drive 4010.27 1 1 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	790 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	790 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 7754.45 1 1 81 Bay View Drive 4262.65 1 1 81 Bay View Drive 4262.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 357.7.7 1 831 Bay View Drive 7764.45 1 811 Bay View Drive 4292.65 1 818 Bay View Drive 4292.65 1 819 Bay View Drive 3955.62 1 791 Bay View Drive 4197.94 1 791 Bay View Drive 4393.41 1 2814 Manor View Drive 4839.41 1 2814 Manor View Drive 4829.81 1 2828 Manor View Drive 4902.21 1 2852 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 5006.86 1 1 2860 Manor View Drive 5006.86 1 1 2860 Manor View Drive 5006.86 1 1 2861 Mobile View Drive 9638.27 1 1 2864 Nobile View Drive 7818.48 1 1 2864 Nobile View Drive 7818.48 1 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 4292.65 1 818 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 787 Bay View Drive 4767.42 1 781 Bay View Drive 4767.42 1 781 Bay View Drive 4767.42 1 781 Bay View Drive 4859.41 1 2800 Manor View Drive 4859.41 1 2814 Manor View Drive 4859.41 1 2828 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2868 Manor View Drive 5008.66 1 2894 Manor View Drive 5008.66 1 2894 Nabie View Drive 9638.22 1 2948 Nobie View Drive 9638.22 1 2948 Nobie View Drive 7818.48 1	B17 Bay View Drive 7108.56 1 B11 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1	811 Bay View Drive 3955.62 1 1	805 Bay View Drive 3955.82 1979 Bay View Drive 4107.94 1791 Bay View Drive 4178.42 1 1 198 bay View Drive 4303.32 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2882 Manor View Drive		790 Bay View Drive 4010.27 1 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	796 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1	790 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.55 1 1 1 1	796 Bay View Drive 4010.27 1 1 1 796 Bay View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	790 Bay View Drive 4010.27 1 1 796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.65 1 1 1 844 Bay View Drive 8285.65 1 1 1 848 Bay View Drive 6487.45 1 1 1 858 Bay View Drive 6440.42 1 1 1 866 Bay View Drive 4134.33 1 1 1	796 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 831 Bay View Drive 7754.45 1 9 817 Bay View Drive 7708.56 1 9 817 Bay View Drive 4292.65 1 9 815 Bay View Drive 4292.65 1 9 805 Bay View Drive 4707.94 1797 Bay View Drive 4707.94 1797 Bay View Drive 4707.94 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 817 Bay View Drive 7708.56 1 1 811 Bay View Drive 4292.65 1 1 818 Bay View Drive 3955.62 1 787 Bay View Drive 3955.62 1 1 781 Bay View Drive 4179.42 1 1 781 Bay View Drive 4393.32 1 1 781 Bay View Drive 4393.32 1 1 2806 Manor View Drive 4393.41 1 2814 Manor View Drive 4393.41 1 2815 Manor View Drive 4393.41 1 2816 Manor View Drive 4002.21 1 2817 Manor View Drive 4002.21 1 2818 Manor View Drive 4002.21 1 2819 Manor View Drive 5402.27 1 2819 Manor View Drive 6403.22 1 2819 Manor View Drive 6403.22 1 2829 Manor View Drive 6403.22 1 2829 Manor View Drive 6403.27 1 2839 Manor View Drive 6403.30 1 2840 Noble View Drive 6403.30 1 2841 Noble View Drive 7818.48 1 2842 Noble View Drive 7818.48 1 2843 Noble View Drive 7818.48 1 2844 Noble View Drive 7818.48 1 2845 Noble View Drive 7818.48 1 2846 Noble View Drive 7818.48 1 2847 Noble View Drive 7818.48 1 2848 Noble View Drive 7818.48 1	831 Bay View Drive 7768.45 1 817 Bay View Drive 4292.65 1 818 bay View Drive 4292.65 1 818 bay View Drive 3955.62 1 797 Bay View Drive 4779.42 1 797 Bay View Drive 4779.42 1 798 Bay View Drive 4779.42 1 798 Bay View Drive 4779.42 1 798 Bay View Drive 4859.41 1 2814 Manor View Drive 4859.41 1 2815 Manor View Drive 4902.21 1 2852 Manor View Drive 4002.21 1 2865 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2869 Manor View Drive 5462.28 1 2864 Nobile View Drive 5462.27 1 2948 Nobile View Drive 9045.17 1 2949 Nobile View Drive 9045.17 1 2940 Nobile View Drive 9045.17 1 2940 Nobile View Drive 9045.17 1 2941 Nobile View Drive 9045.17 1	817 Bay View Drive 4292.65 11 Bay View Drive 3955.62 12 Bay View Drive 3955.62 12 The Bay View Drive 4107.94 12 The Bay View Drive 4107.94 12 The Bay View Drive 4393.32 12 The Bay View Drive 4393.41 13 The Bay View Drive 4393.41 14 The Bay View Drive 44002.21 15 The Bay View Drive 4552.28 16 The Bay View Drive 4552.27 17 The Bay View Drive 5462.27 18 The Bay View Drive 5462.27 19 The Bay View Drive 5462.27 10 The Bay View Drive 5462.27 11 The Bay View Drive 5462.27 12 The Bay View Drive 7818.48 13 The Bay View Drive 7818.48 14 The Bay View Drive 7818.48 15 The Bay View Drive 7818.48 16 The Bay View Drive 7818.48 17 The Bay View Drive 7818.48 18 The Bay View Drive 7818.48 19 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 11 The Bay View Drive 7818.48 12 The Bay View Drive 7818.48 13 The Bay View Drive 7818.48 14 The Bay View Drive 7818.48 15 The Bay View Drive 7818.48 16 The Bay View Drive 7818.48 17 The Bay View Drive 7818.48 18 The Bay View Drive 7818.48 19 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 11 The Bay View Drive 7818.48 12 The Bay View Drive 7818.48 13 The Bay View Drive 7818.48 14 The Bay View Drive 7818.48 15 The Bay View Drive 7818.48 16 The Bay View Drive 7818.48 17 The Bay View Drive 7818.48 17 The Bay View Drive 7818.48 18 The Bay View Drive 7818.48 19 The Bay View Drive 7818.48 19 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 10 The Bay View Drive 7818.48 11 The Bay View Drive 7818.48 12 The Bay View Drive 7818.48 18 The Bay View Drive 7818.48 18 The Bay	811 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4179.42 1 791 Bay View Drive 4797.94 1 791 Bay View Drive 4793.32 1 791 Bay View Drive 4839.41 1 2800 Manor View Drive 4839.41 1 2814 Manor View Drive 4902.21 1 2828 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2874 Manor View Drive 4002.21 1 2888 Manor View Drive 7008.86 1 2898 Nobile View Drive 5402.27 1 2910 Manor View Drive 9045.17 1 2940 Manor View Drive 9045.17 1 2952 Nobile View Drive 9045.17 1 2953 Nobile View Drive 7818.46 1 2844 Nobile View Drive 7818.46 1 2855 Nobile View Drive 4230.81 1 2857 Nobile View Drive 4230.81 1 2858 Nobile View Drive 4230.81 1	805 Bay View Drive 3955.82 1797 Bay View Drive 4170.42 1791 Bay View Drive 4373.32 1891 Manor View Drive 4859.41 2814 Manor View Drive 4859.81 2828 Manor View Drive 4002.21 2860 Manor View Drive 4002.21 2860 Manor View Drive 4002.21 2861 Manor View Drive 4002.21 2862 Manor View Drive 4002.21 2862 Manor View Drive 4002.21 2863 Manor View Drive 4002.21 2864 Manor View Drive 5006.66 2862 Manor View Drive 5462.27 2910 Manor View Drive 5462.37	2882 Manor View Drive 4174.06 2882 Manor View Drive 4552.28 2882 Manor View Drive 5055.86 1 2904 Manor View Drive 5452.27 1 2910 Manor View Drive 9045.17 2952 Noble View Drive 9038.22 1 2948 Noble View Drive 7818.46 1 2944 Noble View Drive 7818.46 1 2948 Noble View Drive 7818.46 1		796 Bay View Drive 8004.7 1	796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1	796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4080.6 1 1 1 816 Bay View Drive 7960.65 1 1 1	796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.65 1 1 1 836 Bay View Drive 8285.65 1 1 844 Bay View Drive 6487.45 1 1 1 1 858 Bay View Drive 6487.45 1 1 1 1	796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1 1 816 Bay View Drive 8285.65 1 1 1 1 836 Bay View Drive 8285.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	796 Bay View Drive 8084.7 1 1 810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7960.65 1 1 1 1 826 Bay View Drive 8285.65 1 1 1 1 1 826 Bay View Drive 6487.45 1 1 1 1 866 Bay View Drive 6440.42 1 1 1 866 Bay View Drive 4134.33 1 1 1 1 8672 Bay View Drive 4134.33 1 1 1 1 1 8672 Bay View Drive 4134.33 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 831 Bay View Drive 7754.45 1 1 81 Bay View Drive 7708.56 1 1 81 Bay View Drive 4292.56 1 1 81 Bay View Drive 4292.56 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	831 Bay View Drive 7754.45 1 1 811 Bay View Drive 7768.56 1 1 811 Bay View Drive 7768.56 1 1 811 Bay View Drive 3955.65 1 1 805 Bay View Drive 3955.65 1 1 781 Bay View Drive 3955.65 1 1 781 Bay View Drive 4107.94 1 1 781 Bay View Drive 4003.32 1 1 2814 Manor View Drive 4839.41 1 1 2814 Manor View Drive 4829.41 1 1 2818 Manor View Drive 4002.21 1 1 2852 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 1 2868 Manor View Drive 4002.21 1 1 2874 Manor View Drive 4002.21 1 1 2882 Manor View Drive 4002.21 1 1 2882 Manor View Drive 4002.21 1 1 2896 Manor View Drive 4002.21 1 1 2896 Manor View Drive 4002.21 1 1 2896 Manor View Drive 4002.21 1 1 2897 Manor View Drive 4002.21 1 1 2898 Manor View Drive 4003.22 1 1 2898 Manor View Drive 4003.22 1 1 2898 Manor View Drive 4006.86 1 1 2904 Manor View Drive 9638.22 1 1 2910 Manor View Drive 9638.22 1 1 2944 Noble View Drive 9638.22 1 1 2948 Noble View Drive 7818.48 1 1 2844 Noble View Drive 4230.81 1 2858 May View Drive 4230.81 1 2868 May View Drive 4230.81 1 2878 Noble View Drive 4230.81 1 2889 View Drive 4230.81 1 2898 Noble View Drive 9638.22 1 1 2898 Noble View Drive 4230.81 1 2898 Noble View Drive 4230.81 1 2898 Noble View Drive 4230.81 1	831 Bay View Drive 7754.45 1 817 Bay View Drive 7108.56 1 1 81 Bay View Drive 4292.65 1 1 805 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	817 Bay View Drive 7108.56 1 1 811 Bay View Drive 4292.65 2 1 1 818 Bay View Drive 385.62 1 1 978 Bay View Drive 4107.94 1 1 791 Bay View Drive 4107.94 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	811 Bay View Drive 3955.62 1 805 Bay View Drive 3955.62 1 797 Bay View Drive 4107.94 1 791 Bay View Drive 4707.94 1 791 Bay View Drive 4393.32 1 2800 Manor View Drive 4829.81 1 2814 Manor View Drive 4922.47 1 2824 Manor View Drive 4002.21 1 2852 Manor View Drive 4002.21 1 2865 Manor View Drive 4002.21 1 2866 Manor View Drive 4002.21 1 2867 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 4002.21 1 2868 Manor View Drive 5006.86 1 1 2904 Manor View Drive 5006.86 1 1 2904 Noble View Drive 9638.22 1 1 2944 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.48 1 1 786 Bay View Drive 4230.81 1 786 Bay View Drive 4230.81 1 786 Bay View Drive 4230.81 1 787 Bay View Drive 4230.81 1 788 Bay View Drive 4230.81 1	805 Bay View Drive 3955.82 1979 Bay View Drive 4107.94 1 1979 Bay View Drive 4178.42 1 1 1989 View Drive 4303.32 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2882 Manor View Drive 4174.06 2882 Manor View Drive 4552.28 3896 Manor View Drive 5005.86 1 2904 Manor View Drive 5462.27 1 2910 Manor View Drive 945.17 2952 Noble View Drive 9638.22 1 2948 Noble View Drive 7818.48 1 782 Bay View Drive 7818.46 1 782 Bay View Drive 7818.46 1 782 Bay View Drive 4230.81 790 Bay View Drive 4010.27 1		210 Ray View Drive 4050 8 1	810 Bay View Drive 4050.6 1 1	810 Bay View Drive 4050.6 1 1 1 816 Bay View Drive 7860.65 1 1 1	810 Bay View Drive 4050.6 1 1 1 1 816 Bay View Drive 7860.65 1 1 1 836 Bay View Drive 8285.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	810 Bay View Drive 4050.6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	810 Bay View Drive 4050.8 1 1 1 816 Bay View Drive 7960.65 1 1 1 836 Bay View Drive 8285.65 1 1 1 1 848 Bay View Drive 6487.45 1 1 1 1 1 864 Bay View Drive 6440.42 1 1 1 1 866 Bay View Drive 4134.33 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
837 Bay View Drive 5577.77 1 1 1 1 1 1 1 831 Bay View Drive 7754.45 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	131 Bay View Drive	B31 Bay Vlew Drive 7754.45 1 1 1 11817 Bay Vlew Drive 4292.68 1 2 282 Manor Vlew Drive 4639.41 1 <td>817 Bay Vlaw Drive 4292.65 805 Bay Vlaw Drive 3955.62 180 Bay Vlaw Drive 4107.94 797 Bay Vlaw Drive 4107.94 1791 Bay Vlaw Drive 4303.32 2800 Manor Vlaw Drive 4639.41 2814 Manor Vlaw Drive 4639.41 284 Manor Vlaw Drive 4629.81 285 Manor Vlaw Drive 4002.21 285 Manor Vlaw Drive 4002.21 286 Manor Vlaw Drive 4002.21 2874 Manor Vlaw Drive 4002.21 2885 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4002.21 2887 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4002.21 2887 Manor Vlaw Drive 4002.21 2888 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4052.28 2886 Manor Vlaw Drive 4052.28 2887 Manor Vlaw Drive 4054.22 2888 Manor Vlaw Drive 406.86 2880 Manor Vlaw Drive 406.87 2940 Noble Vlaw Drive 9045.17 2941 Noble Vlaw Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 294</td> <td> 111 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1 </td> <td>805 Bay View Drive 3955.82 797 Bay View Drive 4107.94 791 Bay View Drive 4303.32 1 1 1 1 1 2814 Manor View Drive 4639.41 2828 Manor View Drive 4639.41 2828 Manor View Drive 4002.21 2829 Manor View Drive 4002.21 2820 Manor View Drive 4002.21 2820 Manor View Drive 4002.21 2821 Manor View Drive 4174.06 2828 Manor View Drive 5462.28 2838 Manor View Drive 5462.27 2910 Manor View Drive 9045.17 2910 Manor View Drive 9045.17 2910 Manor View Drive 9045.17 2918 Manor View Drive 9045.17 2919 Manor View Drive 9045.17 2910 Manor View Drive 9045.18 2910 Manor View Drive 9045.28 2910 Manor View Drive 9045.28 2910 Manor View Drive 9045.28 2910</td> <td>2882 Manor View Drive 4174.06 2882 Manor View Drive 4452.28 1 3856 Manor View Drive 5006.56 1 2944 Manor View Drive 506.56 2951 Manor View Drive 5482.27 1 1 1 2952 Noble View Drive 8045.17 2953 Noble View Drive 7818.48 2944 Noble View Drive 7818.46 2948 Noble View Drive 7818.46 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 2948 Noble View Drive 4010.27 1 1 1 1 1 1 1 2948 Noble View Drive 8084.7 1 1 1 1 294 Noble View Drive 4010.27 1 1 1 1 1 1 1 294 Noble View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <</td> <td>7980.65 1 1 1 8285.65 1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	817 Bay Vlaw Drive 4292.65 805 Bay Vlaw Drive 3955.62 180 Bay Vlaw Drive 4107.94 797 Bay Vlaw Drive 4107.94 1791 Bay Vlaw Drive 4303.32 2800 Manor Vlaw Drive 4639.41 2814 Manor Vlaw Drive 4639.41 284 Manor Vlaw Drive 4629.81 285 Manor Vlaw Drive 4002.21 285 Manor Vlaw Drive 4002.21 286 Manor Vlaw Drive 4002.21 2874 Manor Vlaw Drive 4002.21 2885 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4002.21 2887 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4002.21 2887 Manor Vlaw Drive 4002.21 2888 Manor Vlaw Drive 4002.21 2886 Manor Vlaw Drive 4052.28 2886 Manor Vlaw Drive 4052.28 2887 Manor Vlaw Drive 4054.22 2888 Manor Vlaw Drive 406.86 2880 Manor Vlaw Drive 406.87 2940 Noble Vlaw Drive 9045.17 2941 Noble Vlaw Drive 7818.46 1 1 1 1 1 1 1 1 1 1 1 1 294	111 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1	805 Bay View Drive 3955.82 797 Bay View Drive 4107.94 791 Bay View Drive 4303.32 1 1 1 1 1 2814 Manor View Drive 4639.41 2828 Manor View Drive 4639.41 2828 Manor View Drive 4002.21 2829 Manor View Drive 4002.21 2820 Manor View Drive 4002.21 2820 Manor View Drive 4002.21 2821 Manor View Drive 4174.06 2828 Manor View Drive 5462.28 2838 Manor View Drive 5462.27 2910 Manor View Drive 9045.17 2910 Manor View Drive 9045.17 2910 Manor View Drive 9045.17 2918 Manor View Drive 9045.17 2919 Manor View Drive 9045.17 2910 Manor View Drive 9045.18 2910 Manor View Drive 9045.28 2910 Manor View Drive 9045.28 2910 Manor View Drive 9045.28 2910	2882 Manor View Drive 4174.06 2882 Manor View Drive 4452.28 1 3856 Manor View Drive 5006.56 1 2944 Manor View Drive 506.56 2951 Manor View Drive 5482.27 1 1 1 2952 Noble View Drive 8045.17 2953 Noble View Drive 7818.48 2944 Noble View Drive 7818.46 2948 Noble View Drive 7818.46 1 1 1 790 Bay View Drive 4010.27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 2948 Noble View Drive 4010.27 1 1 1 1 1 1 1 2948 Noble View Drive 8084.7 1 1 1 1 294 Noble View Drive 4010.27 1 1 1 1 1 1 1 294 Noble View Drive 8084.7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <	7980.65 1 1 1 8285.65 1						
837 Bay View Drive 5577.77 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	131 Bay View Drive	B31 Bay View Drive 77.54.45 1 1 1 1 1 1 1 1 1	B17 Bay Vlaw Drive 4292.65 1 1 1 1 1 1 1 1 1	1311 Bay View Drive 3955.62 1 1 1 1 1 1 1 1 1	806 Bay View Drive 3935.82 797 Bay View Drive 4107.94 191 Bay View Drive 4107.942 1791 Bay View Drive 4303.32 181 Manor View Drive 4639.41 12814 Manor View Drive 4639.41 12828 Manor View Drive 4629.81 12828 Manor View Drive 4002.21 12828 Manor View Drive 4002.21 12838 Manor View Drive 4002.21 12862 Manor View Drive 4002.21 12862 Manor View Drive 4002.21 12862 Manor View Drive 4002.21 12863 Manor View Drive 4002.21 12864 Manor View Drive 4006.86 1386 Manor View Drive 5006.66 1474.06 1 12904 Manor View Drive 9638.22 1 1 12944 Noble View Drive 9638.22 1 1 12944 Noble View Drive 7818.46 1790 Bay View Drive 403.81 190 Bay View Drive 403.81 191 Bay View Drive 403.65 1980 Wrive Drive 403.65 1980 Manor View Drive 7818.46 1 1 1 1 1 1 1 1 1 1 <td>2882 Manor View Drive 4452.28 1 1 1 2882 Manor View Drive 4552.28 1 1 1 2886 Manor View Drive 5006.86 1 1 1 2994 Manor View Drive 9045.17 1 1 1 2924 Noble View Drive 9038.22 1 1 1 1 2924 Noble View Drive 7818.48 1 1 1 1 2924 Noble View Drive 7818.48 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 4230.81 1 1 1 1 1 2924 Noble View Drive 4230.81 1 1 1 1 1 2924 Noble View Drive 4050.6 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1</td> <td>7960.55 1 1 1 8285.65 1 1 1 6487.45 1 1</td> <td>+</td> <td>+</td> <td></td> <td></td> <td></td> <td></td>	2882 Manor View Drive 4452.28 1 1 1 2882 Manor View Drive 4552.28 1 1 1 2886 Manor View Drive 5006.86 1 1 1 2994 Manor View Drive 9045.17 1 1 1 2924 Noble View Drive 9038.22 1 1 1 1 2924 Noble View Drive 7818.48 1 1 1 1 2924 Noble View Drive 7818.48 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 7818.46 1 1 1 1 1 2924 Noble View Drive 4230.81 1 1 1 1 1 2924 Noble View Drive 4230.81 1 1 1 1 1 2924 Noble View Drive 4050.6 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 1 2924 Noble View Drive 8285.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7960.55 1 1 1 8285.65 1 1 1 6487.45 1 1	+	+				
837 Bay View Drive 577.77 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	13.1 Bay View Drive	B31 Bay View Drive 7754.45 1 1 1 1 1 1 1 1 1	817 Bay View Drive 4292.65 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	111 Bay View Drive 395.6.62 1 1 1 1 1 1 1 1 1	806 Bay View Drive 3935.82 797 Bay View Drive 4107.94 791 Bay View Drive 4203.23 1 781 Bay View Drive 4303.32 1 2814 Manor View Drive 4639.41 1 2814 Manor View Drive 4639.41 1 2814 Manor View Drive 4629.81 1 2828 Manor View Drive 4022.21 2860 Manor View Drive 4002.21 2860 Manor View Drive 4002.21 2860 Manor View Drive 4002.21 2862 Manor View Drive 4052.86 2863 Manor View Drive 4052.27 2910 Manor View Drive 4052.27 2910 Manor View Drive 5066.86 1 1 2924 Noble View Drive 9452.27 1 1 2932 Noble View Drive 7818.46 1 1 194 Noble View Drive 400.22 1 1 1 1 1 1 <	2882 Manor View Drive 4174.06 2882 Manor View Drive 4452.28 3896 Manor View Drive 5005.68 1 1 2904 Manor View Drive 5045.27 1 1 2910 Manor View Drive 9045.17 2925 Noble View Drive 9638.22 1 1 2948 Noble View Drive 7818.48 1 1 2944 Noble View Drive 7818.46 1 1 1928 Bay View Drive 4010.27 198 Bay View Drive 4010.27 196 Bay View Drive 8084.7 810 Bay View Drive 4050.65 836 Bay View Drive 7960.65 1 1 844 Bay View Drive 8285.65 1 1 858 Ray View Drive 8285.65 1 1 858 Ray View Drive 8440.49 858 Ray View	7980.65 1 1 1 8285.65 1 1 1 1 6487.45 1 1 1 1						

Docket Nos. E-01345A-07-0663 T-01846B-07-0663

	Current Support and
	d Opposition
K Z O P	Docket Nos. E-01345A-07-0663 T-01846B-07-0663

,			آ_	<u>سا</u>		_,1	_,,		1	JI	J			75		71,	ы	ol.	al.	آھ	ol	وارم	23	20 0	2	2010	وارد	23 5	57 8	2 5	<u>,,</u>	ابرا	53	اوا	2	5	4	4	S)	_	4	_			T]
85 310-32-098	84 310-32-097	83 310-32-096			80 310-32-092	79 310-32-091	78 310-32-090	77 310-32-089			74 310-32-086		72 310-32-084	71 310-32-083		70 310-32-082	9 310-32-081	68 310-32-080	67 310-32-079	6 310-32-078	65 310-32-077	64 310-32-076	3 310-32-075	62 310-32-074	1 310-32-073	60 310-32-072	59 310-32-071A	A 310-32-069	7 310-32-068A		5 310-32-065A	4 310-32-064A	3 310-32-063A	310-32-062A	1310-32-061A	0 310-32-060A	9 310-32-057	8 310-32-056A	310-32-054			Parcel No.			A	
Arthur C. Wood III; Steven D. Wo	1	┙	۱)		┙					Clifton D. & Viola J. Lee, Trustees	_1	hn M. & Peggy J	David M. & Dorothy D. Glynn	Citized & Denise Citizer Richard I & Andrea S Wilker &		\perp		\perp	┙	- 1	Dowell A. & Katherine S. Kubicka, Trustees	Dowell A. & Katherine S. Kubicka, Trustees	Gerald W. & Michelle C. Gatlin & Jeffrey W. Gatlin	Gerald W. & Michelle C. Gatlin & Jeffrey W. Gatlin	Richard Gervals	-1	Carlson & Darlene E. Lottis	_	Karen L. & James Bibby		John D. Yarbrough, II. & Jacqueline Y. Yarbrough, Trustees 895 Swan Drive	54 310-32-064A Michael Joseph & Tamera Lynn Wilkinson	310-32-063A Juliana Perez	52 310-32-052A Brian D. Wood & Arthur Wood			Hiltcrest Bay Inc.	Larry W. & Shearl Lynn Thompson			-	Owner Name/s			8	,
928 Swan Drive	920 Swan Drive	914 Swan Drive	906 Swan Drive	888 Swan Drive	880 Swan Drive	872 Swan Drive	864 Swan Drive	854 Swan Drive	846 Swan Drive	836 Swan Drive	828 Swan Drive	820 Swan Drive	810 Swan Drive	1 90 OWALL CHIVE	700	792 Swan Drive	784 Swan Drive	783 Swan Drive	791 Swan Drive	797 Swan Drive	807 Swan Drive	815 Swan Drive	821 Swan Drive	827 Swan Drive	837 Swan Drive	845 Swan Drive	859 Swan Drive	867 Swan Drive	873 Swan Drive	889 Swan Drive	895 Swan Drive	913 Swan Drive	917 Swan Drive	927 Swan Drive	933 Swan Drive	951 Swan Drive	924 Bay View Drive	914 Bay View Drive	900 Bay View Drive	894 Bay View Drive	880 Bay View Drive	Parcel Address				,
4108.22	4108.22	4108.22	4108.22	8216.44	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22 1		4108 33	4108.22	5260.21 1	4255.88 1	4091.86 1	4091.86 1	4092	4092	4091.86 1	4091.86	4091.86 1	4091.86	8183,72 1	4091.86 1	8183.72	4091.86	4694.15	5192 1	5192 1	5192 1	5192	6877.17 1	6886.11 1	8121.88	4142.21	4139.94 1	4121 1	Parcel SF Petition		Signed	C	
				-				-	.\-	-		-					 																					-	1		-	上			-	-
. -	_	-	+			-		+					-			-	-		_	-					-	_	_	-			-	-	_	_			1			_		Support		New	6	-
			\dagger	-	-			-	-												-	_	-	-											1	_		_	_		-	Opposed I		Zew F	-	I
-																											_	-										-		-		Letter L		Pre-PO Po	-	_
_	_	-	-																-	-													-			-		-			-	Letter		Post-PO P	,	_
					-	-	-	- -	-	-	-										-														_				-			errer	Opposition	Pre-PO		,
			+		-		1		1	+	-				***								r							_									-			Letter	Opposition	Post-PO		-
	-		-													+				-	+											1										Full Part on//	Supported at Opposed at			3
	-			+													+				+											+										Bin tool 1 0000	Opposed at			
4108.22	4108 22	4108.22	4108.22	4108.22			4108.22		-				4708.22		4108.22	- 1	410A 22	5260.21	4255 88	4091.86	4091.86		\dagger		1001.00	1001 88	1001 86	1001.00	1001 86		4694,15	,	5193	5103	200		0000.11	8888		100.00	4130 04		Support			
2	9	2	2	7	8216.44	4108.22		4108.22	4108.22	4108.22	4108.22	4108.22										4092	4092	4001 AS	4091 86					4081.00	1					5100	8877 17	100	8121 AR	11 00 01		4121	Cpposed	Current		ŀ

Current Support and Opposition

Docket Nos. E-01345A-07-0663 NON P DECISION DECI

Current Support and Opposition

_	r				_							_		_	_		,	,			_	_				, [_	_		.,-		I				اند	_				-		_	<u>.</u>	БI	-110	J. □
	169	9 0	200	3	3	2	<u></u>	83	5	60	59	158	157 3	156	155	1543	1533	152	0	ğ	148	40	4	1 6	200	3 1	<u>۔</u>	143	1	3	<u>د</u>	403	39 3	38 3	37 3	36 3	35 31		34	333	32 34	33	30 31	- P			Н
310-32-197	3100	2 0	2	3 0		0	370	2	200	310-3	310-32	110-32	157 310-32-182	156 310-32-181	10-3	154 310-32-178	153 310-32-177	152 310-32-176	151 310-32-1/5	150 310-32-1/4	0.32	į		3 6	140 010-02-100	3 5	144 310-32-167	310-32-100	3 0	310-32-165	141 310-32-164	140 310-32-162	139 310-32-161	138 310-32-160	37 310-32-159	136 310-32-158	135 310-32-157		0-32-	133 310-32-154	0-32	0-32-	0.33 2-	Parcel No.			_⊳
2-197	169 310-32-196		210-22-163	310-32-192	310-32-191	164 310-32-190	163 310-32-189A	162 310-32-188B	161 310-32-186A	160 310-32-184	159 310-32-183C	158 310-32-183A	182	181	155 310-32-180A	-178	17	16	10	1	148 310-32-1/3A	210-32-1/20	4/310-32-1700	40 310-32-100A			167	90	100	3	A A	162	161	160	159	158	157		134 310-32-156A	호	153A	151A	150A	Ŏ.			
_1	- 12	킨	1	_	4	_					_		L	L	Ľ	-	┸	┸	╀	Tracocore 7. o. Mary r. Morica	1	1		4	1	4	Brandal Common C	John W. & Jamie Brandel Kourkos: William W. & Geraldine	India D Chicley	Tom W & Kalhryn A Ayers, Truslees	Thomas F. Anderson, Ernest Vanier, & Robert K. Anderson 1794 Linger Drive	Gary W. Smith	Gerald D. Flores	Ricky & Karen L. Bullard	Paul L. & Carol A. Pudewa	Donald & Melody Clark	Ferrall	Thomas J. Gealy, IV & Denise M. Gealy; Edward F. Fer Sr. & Margaret Ferrall; & Edward Ferrall, Jr. & Susan L.	-	Laurence A. & Marjorie Werd	132 310-32-153A Cynthia I Miles & Sandra L. Magana	131 310-32-151A Pamela A. Leggett, Trustee	130 310-32-150A Scott K. Jones, Sr. & Carole A. Jones, Trustees	Owner Name/s			В
36	92	36	38	38	88	87	86	84	185				Cal	94	200	200	000	010	000	80.0	ROD	88	RA	85	84	83(1.		-08 -08	nderson 794	18/	1801	811	819	829	L	n L.	┺	١	875	895	903	Tal.			
931 Max View Drive	923 Max View Drive	907 Max View Drive	897 Max View Drive	899 Max View Drive	883 Max View Drive	875 Max View Drive	867 Max View Drive	849 Max View Drive	855 Max View Drive	825 Nobie View Drive	786 Linger Drive	AALIC MAIN SIGON ELB	By Linger Drive	940 Linger Drive	934 Luiger Drive	920 Linger Drive	DOOL inger Drive	914 Linger Drive	204 Linger Drive	Stinger Drive	890 Linger Drive	Linger Driva	R64 & 874 Linner Drive	852 I Inner Drive	840 Linger Drive	830 Linger Drive	820 Linger Drive	9	812 Linger Drive	804 Linger Drive	Linger Drive	/91 Linger Drive	801 Linger Drive	811 Linger Drive	819 Linger Drive	829 Linger Drive	839 Linger Drive		853 Linger Drive	867 Linger Drive	875 Linger Drive	895 Linger Drive	903 Linger Drive	Parcel Address			C
ve	Ve	YB	Ve	Ve	ve	é	8	Væ	á	nve	-	IVa	+	+	+	+	1	-	+		-		Orive .											<u> </u>	-				ŀ	-	L	-	-	Parc	P		
5399.87	5399.87	10799.74	5399.87	5399.87	5399.87	5519.87	6119,85	10439.75	11039.74	02 10.19	/004.00	766 1 71	273 17	4855.48	5000 88	10199 76	5099 88	5099.88	5099 88	5099 88	5099.88	6374.85	6374.85	6374.85	6374.85	5099.88	5099.88		5099.88	5099.88	5099.88	07:04/4	40/0.03	40/0.03	40/0.03	40/0.03	40/0.03		8140.1	4070.03	6105.04	6105.04	8140.06			(a)	D
_	-	_		-	_		-	-	-	•	-		-					_	_			_				_	_		-	_		-		-	. -	_			_		-		-	- deritori	<i>.</i>	Signed	п
									1			1				1								1																-				100000	Opposed	,	7
-	-	_		-		-	\ \ -	-	1	+	-	1	4			1		-				1			_	-					_		1	-	1								-	4	Support	New	G
	T			1		1			+	†	_			-		-	_						1						-	-							-			-				-	Opposed	New	I
	\dagger			1		-	-	-								1														<u> </u>				1		1									Letter	Pre-PO	-
	-		+				-		1	1	1																	-									1								Letter	Post-PO	
	+	-				+			1																			•	-				-							1	4				Letter	Pre-PO	7
-	+						1		-						_					-	-												-								-				Letter	Post-PO	-
	1						-			1				-								-		-			+		+								1							1	7/09 Hearing	D	
		+												-	-			-			-		-		-	+	-												+		-				7/09 Hearing 7/09 Hearing	Onnoned at	
	5399.87	5399.87	10799.74	5399.87	5399.87	5399.87	5519.87	6119.85	10439.75	11039.74		7664.08	8721.47			-		00.8800	200.88	500	-	03/4,00	277	-	0011	6374 85	5099 88		+	1	5099.88	-		4070.03	4070.03	4070.03	4070.03			8140.1				8140.06	22	Current	
	.87	.87	.74	.87	.87	.87	.87	.85	.75	.74	5215.19	Γ	4/	4835,48	20.6800	10199.76	30.000	Т	800	0000.00	5000 88	T	1	6374 AS	T	8	T	5099.88		5099.88	1	_	4746.29	Г	33	13		4070.03		П	4070.03	6105.04		5		Current	

Docket Nos. E-01345A-07-0663 NO. T-01846B-07-0663 ION NO.

Current Support and Opposition

Docket Nos. E-01345A-07-0663 T-01846B-07-0663

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		7100.14 6585.65 6753.46 10479.2 4479.92	2957 Dunlap Drive 2949 Dunlap Drive	213 310-32-243 Clyde L. & Jeanne F. Henizen
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 411 411 4099.6 4099.6 4409.8 5158.8 5158.8 4409.8 5158.8 4409.8 600.18		7100.14 6585.65 5753.46 10479.2	2957 Dunlap Drive	12
10157.26 2214.31 4124.71 4124.77 4124.77 4124.77 41 1 1 4099.6 450.96 45		7100.14 6585.65 5753.46	Total delines	
10157.28 2214.31 4124.71 4124.77 4124.77 4124.77 4124.77 4124.77 4134.77 4134.77 4134.77 4134.77 4134.77 4134.77 4134.77 4134.77 4134.88 4499.88 4407.9 4407.9 4499.88 4499.88 4407.9 4499.88		7100.14 6585.65	ACINI CRICIES LANG	
10157.28 2214.31 24124.71 24124.77 2412		7100.14	2975 Dunlap Drive	┸
10157.28		2023.20	2979 Duniap Drive	L
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 409.6 600.19 6850.19 6850.19 6750 4550.26 4407.9 4490.89 4490.89 4490.89 6501.18		מנינים	2988 Dunlap Drive	1
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 41		4035.97	2978 Dunlap Drive	Γ
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 409.8 409.8 518.8 518.8 518.8 518.8 518.8 6001.8 650.19 4499.8 650.3 4499.8 6001.18 650.3 650.3 650.3 6001.18 650.3 6503.8 6001.18 650.3		4035.97	2970 Duntap Drive	1
10157.28		3952.69	2962 Duniap Drive	010-04-20-4
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 41 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		394 / .0	Zata Cila Conti	1
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 411 1 1 1 4041.18 409.8 5188.81 5188.81 9741.99 6750 4409.89		30.70	2073 Olic Court	1
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 411 41 41 41 41 41 41 41 41 41 41 41 4		4035.07	2977 Otls Court	
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 411.8 409.6 411.8 411.8 4124.71 411.8 411.8 4124.71 411.8 411.8 4124.71 412.71 411 411 4124.71 412.71 412.71 412.71 413.88 4139.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88 4499.88		5991 8	2987 Otis Court	Thomas J. & June K. Kraus
10157.28 6214.31 4124.71 4124.		5543.8	918 Nable View Drive	01 310-32-230 Robert P. & Carol E. Bischoff, Trustees
10157.28 6214.31 4124.71 4124.		6001.18	910 Noble View Drive	L
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 411.71 4124		4499.89	902 Noble View Drive	L
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 411 1 1 1 4041.18 4099.6 431 8650.19 431 8650.19 431 8650.19 431 8650.19 431 9741.29 6750 4365.26 4405.26 4499.89 4499.89		4499.89	892 Noble View Drive	L
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 411 1 1 1 4041.18 409.6 4499.88 5158.81 9741.29 9741.29 9741.29 9741.29 9741.29 450.0 450.0 4407.9 4407.9 4407.9		4499.89	882 Noble View Drive	
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 413 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4499.89	1874 Nobie View Drive	1
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 411 1 1 1 4041.18 4099.6 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 43 6850.19 4407.8		4499.89	866 Noble View Drive	l
10157.26 6214.31 4124.71 4124.		4407.9	OCO NODIA VIEW DIIVE	1
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 4124.71 41 4124.71 41 4124.71 41 1 1 4041.18 41 1 1 4099.6 439.88 5158.81 5158.81 5750 4500 4500		4205.20	ONO MODIO VIEW DILVE	4
10157.26 6214.31 4124.71 4124.71 4124.71 4124.71 41 1 1 1 1 1 1 1 1 1 1 4041.18 4099.6 43.499.68 5158.81 9741.29 6750 4500		1000	DAS POOLS AIGH CHAS	310-32-222
10157.28 6214.31 4124.71 4124.71 4124.71 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4500	BAD Noble View Drive	310-32-221
10157.28 6214.31 4124.71 4124.71 4124.71 4124.71 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4500	834 Notie View Drive	_
		4500	824 Noble View Drive	190 310-32-219 Bergstrom Jr.
		0,00	_	
		6750	816 Noble View Drive	
		9741 29	808 Noble View Drive	88 310-32-216A Frank I. & Jan Robles
		5158.81	885 Noble View Drive	87 310-32-215 John R. & Judith L.P. McLean
		4499.88	901 Noble View Drive	86 310-32-214 Melvin E. Hegier
	-	8650.19	911 Noble View Drive	85 310-32-213A Joseph & Alis E. Troya; Peter W. & Ilian Kraemer
		4325.09	929 Noble View Drive	84 310-32-211 Jerry & Kelly Goodman
		4099.6	943 Noble View Drive	Ľ
		4041.18	934 Max Vlew Drive	L
	0 1	4124.71	922 Max View Drive	310-32-208
		4124.71	912 Max View Drive	L
1 10157.28 1 6214.31 1 4124.71 1 4124.71 1 4124.71 1 4124.71		4124.71	902 Max View Drive	310-32-206
1 10157.28 1 6214.31 1 4124.71 1 4124.71 1 4124.71		4124.71	894 Max View Drive	310-32-203
1 10157.26 1 6214.31 1 4124.71 1 4124.71		4124./1	BB6 MBX VIEW Drive	L
1 10157.28 1 6214.31 4 4224.71		4124./1	876 Max View Drive	310-33-304
1 10157.26		4124./1	DOD MAX VIEW UNVE	lomas C Cobmide to 8 Comin
10157.28		02 14.31	OOA MAX VIEW DIVE	1
10157.26		20.1808	Apply Thinking Dive	1
		0201 02	Sent Hillerest Drive	┙
7805.81		10157.26	2929 Dunian Drive	2 310-32-199 Philip S. & Ina L. Wigley
Letter Letter //05 Hearing //05 Hearing SF		쁴	937 Max View Drive	171 310-32-198 Robert & Bonnie Strong
Support Support Opposition Opposition Supported at Opposed at Support	Pre-ROD	Parcel SF Petition	Parcel Address	Parcel No. Owner Name/s
New Pre-PO Post-PO Pre-PO		Spel		

Page 5

Current Support and Opposition

	Ť.			-11		,I,		ភោ			- N	s li	315	316	il.	IN	l.	-ln	12	ſΝΙ	N	N	N۱	N	نجرا	12	Ŋ	N	N	N	N	N)(C 한	_				N().	E.
255 255 256	7	252	n (C	750	249	40	П	246	245	244	243	43	240	239 81312/03	238 310-32-274	237 310-32-273	236/310-32-272	235 310-32-271A	234 310-32-270A	233 310-32-269A		231 310-32-265	230 310-32-264	29 310-32-283	228 310-32-262	27 310-32-261	226 310-32-260A	225 310-32-259A	224 310-32-257	223 310-32-256	222 310-32-255	21 310-32-254	20 310-32-253	219 310-32-252	218/310-32-251A	7 310-32-249	6 310-32-248	J.	Parcel No.		A
Current % of Square Footage Opposed:	Current % of Square Footage in Support:	Children to Cit alongs of bosses	Current % of Parcels Opposed:	Current No. of Parcels Opposed:		Current % of Parcels in Support:	Current No. of Parcels in Support:		When Parcel 274 is included (238 Parcels & 1337983.42 SF):		** Two parcels lost through creation of 024A and 040A.	 New owner since position taken; current owner has not commented. 	10001 - 01000 - 1000	Total Parcels = 238**	L	1	1	Ľ				Michael E. & Melanie A. Stewart	Charles Joseph Swan	Lovalo	Andre M & Linds E Duran & Rudy E & Simonette A	Brian Bollon	Greseth Family Limited Partnership	Steven D. Norris*		George & Debbie Radvansky		_ 1	- 1	Daryl C. Reykdal & Keith Woulard		Adam G. Madrigal	_	-	Owner Name/s		B
40.43%	50,09%		41.18%	9.6		51.26%	122		SF):					Total:	2000 Mentor View Dr.	2065 Manas View Dr	2709 HILLIES DAY	27/3 Hillcrest Bay	2775 Hillcrest Bay	2779 Hillcrest Bay	2785 Hillcrest Drive	2793 Hillcrest Drive	2801 Hillcrest Drive	2809 Hillicrest Drive	COTO LINCIESI DIA	2815 Lillorest Drive	2835 Hillcrest Drive	2837 Hillcrest Drive	2851 Hillcrest Drive	2855 Hillcrest Drive	2863 Hillcrest Drive	2871 Hillcrest Drive	2875 Hillcrest Drive	2889 Hillcrest Drive	2891 Hillcrest Drive	2915 Hillcrest Drive	2925 Hittcrest Drive	Ve	Parcel Address		
														1337883.42	5651.6	40734 68	10020 86	4222 61	250.27	7177.07	9893,45	3999.82	3999.82	3999.82	3000.04	20.00 02	2000 62	5999.73	3999.82	3999.82	3999.82	4006.66	10264.02	11809	6875.75	6800.7	22143.16	13797.93	Parcel SF		c
														150	-		-	-		_			_	_			-	_	-			_	_			_			Petition P	, ed.	ļ
Current % of Square Footage Opposed:	Current % of Square mootage in Support:		Current %	Current No. of Parcels Opposed:		Current %	Current No. of Parcels in Support		When Parcel 274 is Not Incl					40					-		_												_		_			_	Pre-ROO		
of Square F	or Square r	2	of Parcels	. of Parcels		of Parcels	of Parcels	-	el 274 IS No	-				119		1	1	-		-		-	-				_		-					-					1	New	
ootage Or	voorage in		Opposed:	Opposed		n Support	in Support	,						66				-	-		-							Ī		_		-	_		_		_		ě.		
posed:	Support	-		-			14		237 Parc					14		1			1	1											Ī								Letter	Pre-PO	
			-			-	-	+	els & 129/	-		-						1	1	1							-	1											Letter	Post-PO	
41.70%	21.00	61 660	41.35%			51.46%		+	ided (237 Parcels & 129/248.74 SF);	2				18						-										+		 -							Letter	Pre-PO	
	200	70	%	98	-	76	721	3	+	-				40									+										-		-				Latter	Post-PO Opposition	
	-	+								-	-			44													1	+	+	-							-		7/09 Hearing	Supported a	
	+	+	-						+	+	-		-	12						+	+		+					+	+	+			-	+	+		1		7/09 Hearing 7/09 Hearing	t Opposed at	
		1	+	$\frac{1}{1}$		+			+	-	+	-	+	12 670208.87	5651.6		10039.86	4222.51				2000	3999 82	38,6965				5999.73	2000	3999 82	+	1	-	1 1000	1	0000.7	200	1		Current	
	+	+	-	1	+	+	+	-	+	+	-		\dagger	87 540927.3	Т		86	П	5155,52	5950.27	7177.07	9893.45	3 6	3 2				73	-	T	3999 82	1	4006 66	CO FSCOP	00/3.75	1	7 2413.10	33443 48	SF	Current	

EXHIBIT C

Total Parcels = 239 Total XES Votes = 151

798,640.64 1,297,248.74

Total Square Feet with YES Votes =

Total Square Feet =

10 o	Total XES V of XUS Votes to Total Par	I XE otal	otes == cels ==	151 63.18%	8%				Total Squi % of Squi	ire Ke are Fe	Total Square Keet with XLS Voles = % of Square Keet with XLS Voles =	Votes =	61.56%
	PARCEL		APS		APS	7	VERIZON	VE	VERIZON		TOTAL		SQUARE
	SIZE	A	PUBLIC	Ś	SERVICE	P	PUBLIC	SE	SERVICE	CO	CONVERSION	VOTES	FEET WITH YES VOTES
L	(39 Ft)	Ę	2 400 02	6	2 408 20	1	100) -	3 574 RD	مع	14 287 04	0	
_ I.	7333.32	- 1	3,400.03	ء ج	2,490.30	ء د	╬	ş 6	20.71.66	ي اج	5 087 89	0	
	4542.54	ء احر	2,106.03	۶	•	ء ا		۶ و	687.51	3 64	0 075 02	0	
	8319.61	م	3,857.21	م	1	٦	+	١	10.700	۽ اِ	7 577 61		
	4672.78	₩.	2,166.43	60	819.75	69	.33	ا دع	1,520.12	اور	7,573.03		
	5014.76	€3	2,324.99	65	915.94	5-5		اج	1,573.62	٠	8,106.37	> 0	
1	5356.75	↔	2,483.54	69	915.94	64)	3,516.31	ا ج	1,592.17	جي	8,507.96		000000
4	5776.06	جي	2,677.95	5		63	3,791.55	6	1,239.54	€>	7,709.04	_	97.76
_	5866.85	€>	2,720.04	65		6 2	3,851.15	43	1,239.54	6-5	7,810.73	_	5866.83
+-	5577.77	69	2.586.01	65	1,300.20	65	3,661.39	↔	2,061.58	\$	9,609.18	-	5577.77
	7754.45	جها	3.595.18	↓	1.339.22	65	5,090.22	6-5	2,246.03	€3	12,270.65		7754.45
_	7108.56	63	3,295.73	╄	915.94	6-5	4,666.24	64	2,789.33	69	11,667.24		
_	4292.65	65	1,990.19	╀—	1,589.33	63	2,817.80	65	2,445.60	چې	8,842.92	0	
_	3955.62	65	1,833.94	65	1,300.74	6-3	2,596.57	& 5-	2,087.94	&	7,819.19	٥	
	4107.94	64	1,904.56	65	,	63	2,696.56	₽	,	66	4,601.12		
	4179.42	64)	1,937.70	€>	2,442.49	64)	2,743.48	63	3,430.44		10,554.11	1	4179.42
	4303.32	63	1,995.14	┞	,	6-3-	2,824.81	()	1,592.13	64	6,412.08	_	
	4639.41	65	2,150.96	63	1	€\$.	3,045.43	€A3	2,103.32		7,299.71	_	
	4629.81	65	2,146.51	 	2,579.59	6>	3,039.13	64	3,626.00	{	11,391.23	_	
	4252.47	65	1,971.57	643	2,579.59	63	2,791.43	÷	3,888.74		11,231.33	0	
1	4002.21	65	1,855.54	-	3,259.51	6-9	2,627.15	64	4,405.19		12,147.39	-	4002.2
•	4002.21	€>	1,855.54		2,932.71	\$	2,627.15	65	4,029.39	{	11,444.79	\downarrow	4002.2
1	4002.21	\$	1,855.54	-	1,262.26	Н	2,627.15	\$	1,957.72		7,702.67		
1	4002.21	55	1,855.54	\$	•	64 3	2,627.15		,	(5	4,482.69	-	4002.2
1	4002.21	11	1,855.54	**	1	63	2,627.15	\$	•		4,482.69	_	4002.2
1	4002.21	1 \$	1,855.54	₩	896.70	-	2,627.15	69	2,275.89		7,655.28		
1	4174.06	\$ 9	1,935.21	\$	3 742.78	\$	2,739.96	€>}		€>	5,417.95		
1	4552.28	\$	2,110.57	\vdash	-	\$	2,988.23	65	1,355.72		6,454.52	0 7	
1	5006.86	\$ 9	2,321.32	-	\$ 1,603.57	\$ 1		€5	2,397.85		9,609.37		5006.86
	5462.27	7 \$	2,532.46	-		-4		-+	1,336.88	-+	7,454.91	_	2407.71
1	9045.17	\$ 1	4,193.60	-	\$ 915.94	4	5,937.48	∻ >	1,515.28	\$3	12,562.30	0	

Staff is in the process of obtaining individual parcel information for the approximate \$928,000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5)

#902,528 corrected at hearing (Tr. at 181, line 6.

Staff is in the process of obtaining individual parcel information for the approximate \$928,000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5) \$ 902,528

1,297,248.74 798,640.64 61.56%	SQUARE FEET WITH	YES VOTES	9638.22		7818.46		4010.27			4050.6				6440.42	4134.33		4076	4121	4139.94			6886.11	8877.17		5192	5192	5192	4694.15			4091.86	8183.72
Yotes =	VOTES	1= YES	1	0	-	0	-	0	0	-	0	0	0	-	1	۵.	1	1	. 1	٥	0			0		-1	-	:	0	0	-	1
Total Square Feet = Total Square Feet = Total Square Feet with XES Votes = % of Square Feet with XES Votes =	TOTAL	COST	32,480.22	30,520.91	17,271.43	10,140.11	4,491.72	5,301.47	4,602.25	7,708.89	9,764.44	10,262.71	7,266.30	8,481.33	5,813.86	5,250.14	5,379.76	5,439.15	11,566.95	12,093.72	14,603.74	7,712.82	10,854.43	10,423.40	7,350.96	5,815.32	8,140.48	6,598.02	10,700.19	10,634.23	4,583.10	15,490.21
re H Fre Fr	COI		64	(4)	643	55		€	5-5	60	65	جئ	÷	\$	↔	↔	6	59	\$	↔	69	63	جئ		_	69	(2)	€9	64	⇔	€\$	64
Total Squa % of Squa	VERIZON SERVICE	COST	12,163.43	12,242.32	4,928.00	3,196.37	ī	848.42		2,964.87	848.09	982.34	1	1,267.71	1,183.19	746.67	816.97	825.99	4,053.68	4,316.16	3,251.28	r	911.52	3,480.49	1,535.64	•	1,505.41	1,340.32	4,491.62	1,468.02	1	3,676.47
	VI SI		69	54,	5/3	69	64	69	64	6/3	63	€^3	69	59	\$	60	69	64)	6 %	5	64	64	69	↔	↔	\$	\$	\$	(A)	\$		6/3
	VERIZON PUBLIC	COST	6,326.77	5,132.25	5,132.24	2,777.21	2,632.44	2,609.78	2,697.22	2,658.92	5,225.57	5,438.91	4,258.53	4,227.66	2,713.88	2,639.33	2,673.04	2,702.55	2,717.56	2,719.05	5,331.41	4,520.22	5,827.20	3,408.16	3,408.16	3,408.16	3,408.16	3,081.36	2,686.00	5,372.00	2,686.00	5,372.00
	7 2	-	↔	جئ	€5	€9	5 3	÷ħ	€3	69	s	5	\$	₩,	÷.	64	\$	6-5	64	\$\$	\$	8	69	4	\$	69		\$	\$	€>	69	€>
%	APS SERVICE	COST	9,521.47	9,521.47	3,586.33	2,205.01	-		1	207.13	r	•	-	•	,	,		1	2,876.32	3,138.06	2,255.51	ı	•	1,127.59	•	•	819.75	,	1,625.47	,	1	2,647.53
239 151 63.18%	SE		€9	63	64	↔	↔	69	69	69	6∻	64	↔	↔	↔	69	₩	6-3	↔	6 ≎	\$	\$	\$	\$	\$	\$	₩	\$	64	89	\$	€>
	ARS PUBLIC	COST	4,468.55	3,624.87	3,624.86	1,961.52	1,859.28	1,843.27	1,905.03	1,877.97	3,690.78	3,841.46	3,007.77	2,985.96	1,916.79	1,864.14	1,889.75	1,910.61	1,919.39	1,920.45	3,765.54	3,192.60	4,115.71	2,407.16	2,407.16	2,407.16	2,407.16	2,176.34	1,897.10	3,794.21	1,897.10	3,794.21
Total tal XE. Total I	æ		64	64	643	÷	53	↔	\$	₩	€5	€÷	64		643	ــــ		65	69	8	54	\$	€\$		64)	64	\$	-	\$	\$ 2		\$ 2
Total Parcels = Total XES Votes = % of XES Votes = %	PARCEL SIZE	(Sq Ft)	9638.22	7818.48	7818.46	4230.81	4010.27	3975.75	4108.95	4050.6	7960.65	8285.65	6487.45	6440.42	4134.33	4020.73	4076	4121	4139.94	4142.21	8121.88	6886.11	8877.17	5192	5192	5192	5192	4694.15	4091.86	8183.72	4091.86	8183.72
0 %		PARCEL ID	310-32-034A	310-32-035A	310-32-036A	310-32-037	310-32-038	310-32-039	310-32-040	310-32-041	310-32-043A	310-32-045A	310-32-047A	310-32-048A	310-32-049	310-32-050	310-32-052B	310-32-052C	310-32-053	310-32-054	310-32-056A	310-32-057	310-32-060A	310-32-061A	310-32-062A	310-32-063A	310-32-064A	310-32-065A	310-32-066	310-32-068A	310-32-069	310-32-071A

Staff is in the process of obtaining individual parcel information for the approximate \$928x000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 6)

1,297,248.74 798,640.64 61.56%	SQUARE FEET WITH	XES VOTES	4091.86	4091.86		4091.86			4091.86	4091.86	4255.88	5260.21	4108.22	4108.22	4108.22							4108.22.	4108.22		4108.22	4108,22	4108.22	4108.22	4108.22		4203.49	4202.99
Feet = Votes = Votes =	VOTES	1= YES	-			-	0	0	,-	T	1		_	~	-	٥	Ь	٥	0	0		-		0	-	-	_		_		- -	
Total Square Feet == Total Square Feet with XES Votes == % of Square Feet with XES Votes ==	TOTAL	- 1	7,851.47	4,583.10	4,583.10	9,697.46	7,717.41	8,322.25	7,354.42	7,476.98	7,409.48	14,356.83	14,664.47	6,122.00	5,794.08	5,729.32	9,116.87	4,601.43	13,454.25	13,756.29	5,953.09	5,513.05	5,625.74	10,738.92	6,903.41	5,472.07	5,513.05	5,580.67	5,580.67	8,179.10	9,003.92	6,817.53
re Fe re Fe	CON		€	()	69	64	çeş	65	5-3	5-5	59	5 %	63	\$	6 -5	ક્ક	64)	62	€5	643	55	65									-+	65
Total Squa % of Squa	VERIZON SERVICE	COST	1,967.63	,	•	3,024.79	1,948.85	2,245.85	1,701.46	1,766.29	1,630.51	4,873.28	5,712.28	1,520.57	1,192.65	1,127.89	2,673.79	•	5,103.08	5,336.57	1,351.66	911.62	1,024.31	1,536.06	1,482.23	870.64	911.62	979.24	979.24	2,230.05	2,610.24	1,383.04
	VE)	60	64	€ >	69	€9	€>	63	\$\$	€>	6-7	6 7	65	64)	645	6/3	59	جئ	5 3	6 9	69	\$ \$	54	64	\$	÷\$					\$ 2
	VERIZON PUBLIC	COST	2,686.00	2,686.00	2,686.00	2,686.00	2,686.09	2,686.09	2,686.00	2,686.00	2,793.67	3,452.94	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	5,393.48	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,696.74	2,759.28	2,760.9
	VE		6-5	64	6-5	69	↔	63	64	€	643	↔	65	69	60	↔	⇔	63	63	↔	\$	\$	\$	6-3	€9	64	\$	(\$	↔	69		6-3
,e	APS SERVICE	COST	1,300.74			2,089.57	1,185.30	1,493.14	1,069.86	1,127.59	1,012.15	3,591.83	4,350.76			١.	1,841.65	•	3,749.74	3,818.29	,	•	1	,	819.75	•		•	ŀ	1,347.62	1,685.54	723.55
239 151 63.18%	SEI	U	69		6-3	↔	69	€-5	6 5	6 5	6-3	65	6-5	643	6-3	643	€>	64	۶۵	64	↔	\$	\$	69	\$ >	67	€÷>	↔	\$	₽	-	63
cels = otes = cels =	APS PUBLIC	COST	101	╀	╌	1,897.10	1,897.17	1,897.17	1,897.10	1,897.10	1.973.15	2,438.78	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	3,809.38	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,904.69	1,948.86	1,950.02
Total Pai Total YES V to Total Par	14		65	59	60	65	€-5	643	8-5	643	543	65	5-7	6-5	643	65	6-3	6-5	60	65	69	69	65)	\$	\$ 2	\$	\$ 2	\$ 2	\$ 2	2 \$	\perp	\$ 6
Total Rai Total XES V % of XES Votes to Total Par	PARCEL	(Sq Ft)	4091.86	4091.86	4091.86	4091.86	4092	4092	4091.86	4091.86	4255.88	5260.21	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	8216.44	4108.22	4108.22	4108.22	4108.22	4108.22	4108.22	4203.49	4205.99
30 %		PARCEL ID	310-32-072	310-32-073	310-32-074	310-32-075	310-32-076	310-32-077	310-32-078	310-32-079	310-32-080	310-32-081	310-32-082	310-32-083	310-32-084	310-32-085	310-32-086	310-32-087	310-32-088	310-32-089	310-32-090	310-32-091	310-32-092	310-32-094A	310-32-095	310-32-096	310-32-097	310-32-098	310-32-099	310-32-100	310-32-101	310-32-102

1,297,248.74 798,640.64 61.56%	SQUARE FELT WITH	X KS Y O X KS	3937.75	4977	7094	3937.76	6056.65	60.96.09				2000	01.1040	3937.76	1875.52	3937.76	5906.64	5886.15	4547.13		3934.9	4079.89	40.77.09							4079.89	4079.89	40/9.89
Feet = cotes =	VOTES	I= XES	-		-		-	-	0	٥	>	. اد	4			-		-		0			-	5	>							
Total Square Feet with XES Votes = % of Square Feet with XES Votes =	NON	COST	10,125.53	10,168.42	11,723.77	4,410.51	8,620.70	8,257.99	8,162.76	5,149.54	5,574.99	4,410.51	4,410.51	5,302.69	10,380.42	5,130.00	7,798.95	7,468.65	6,908.68	6,026.44	5,409.08	6,116.60	4,569.69	6,502.88	5,481.31	6,391.26	10,596.15	8,835.64	11,186.35	6,145.17	9,345.98	5,546.38
re He re He	CON	-	6-5	€5	643	643	5-5	6-3	اجع	643	£-5	62)	÷-3	63	63	£5	65			50	647	63	-+	+	-+	-+	-+	-+	-+	-	-+	55
Fotal Squal % of Squa	VERIZON SERVICE	COST	3,356.09	3,004.52	2,284.97	ŧ	1,836.92	1,474.21	2,259.11	739.03	1,164.48			892.18	1,559.41	719.49	1,183.19	875.84	1,815.65	1,456.75	1,001.78	1,546.91	•	1,933.19	911.62	1,821.57	1,456.75	2,580.41	2,046.95	1,575.48	3,148.48	976.69
•	VE	- 1	€\$	جئ	€3	6 5	6-3	60	6-5	جئ	جئ	60	6-3-	63	63	59	64	5 >	\Box		æ	-		-	5-5				\dashv	69	\$0	{
	VERIZON PUBLIC	COST	2,584.85	3,267.03	4,656.68	2,584.85	3,975.74	3,975.74	2,584.85	2,584.85	2,584.85	2,584.85	2,584.85	2,584.85	5,169.69	2,584.85	3,877.27	3,863.82	2,984.85	2,678.14	2,582.97	2,678.14	2,678.14	2,678.14	2,678.14	2,678.14	5,356.29	2,678.14	5,356.29	2,678.14	2,678.14	2,678.14
	VE P.		€>	66	₽	6-3	6-3	64)	6/3	69	5)	65	ç.q.	69	↔	55	₩	64	64	6-9	\$	\$	6-6-	64)	63	63	64	جه	€\$	69	6-3	65
\$	APS SERVICE	COST	2,358.93	1,589.39	1,493.14		•	-	1,493.14	1	-	•		,	,	•		,	ı	,	,	,	,	,	•	•	,	1,685.54	ı	1.	1,627.81	•
239 151 63.18%	SE	U	₩	64	₽	جها	65	6-5	643	69	جع	₩	6/)	64	63	€5	64	65	65	65	₩	Н	63	69	6-3	69	↔	8	ĕ >	65	64)	643
rcels = Totes = cels =	APS PUBLIC	COST	1.825.66	2,307.48	3,288.98		2,808.04	2,808.04	1,825.66	1,825.66	1,825.66	1,825.66	1.825.66	1,825.66	3,651.32	1.825.66	2,738.49	2,728.99	2,108.18	1,891.55	1,824.33	1,891.55	1,891.55	1,891.55	1,891.55	1,891.55	3,783.11	1,891.55	3,783.11	1,891.55	1,891.55	1,891.55
otal XE otal]	, E		بئ	69	64		, 	64		643	€5	⇔	جع		63	ـــ					65	₩.	\$	\$	69	\$	\$	8	\$	\$ 6		9 \$
Total Pai Total XES V % of XES Votes to Total Par	PARCEL SIZE	(Sq Ft)	7.76	1	-		6056.65	6056.65	3937.76	3937.76	3937.76	3937.76	3937.76	3937.76	7875.52	3937.76	5906.64	5886.15	4547.13	4079.89	3934.9	4079.89	4079.89	4079.89	4079.89	4079.89	8159.78	4079.89	8159.78	4079.89	4079.89	4079.89
30 %		PARCEL ID	210 32 103	310-32-104A	310 27 106 A	310-32-1007	310-32-108A	310-32-110A	310-32-111	310-32-112	310-32-113	310-32-114	310-37-115	310-32-116	310-32-118A	310-32-110	310-32-120A	310-32-122A	310-32-123	310-32-124	310-32-125	310-32-126	310-32-127	310-32-128	310-32-129	310-32-130	310-32-132A	310-32-133	310-32-135A	310-32-136	310-32-137	310-32-138

Staff is in the process of obtaining individual parcel information for the approximate \$928,000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 6)

% of XES Votes to Total Parcels = 63.18% Total Parcels = 239 Total YES Votes = 151

61.56%

1,297,248.74 798,640.64

Total Square Feet with XES Votes = % of Square Feet with XES Votes =

Total Square Feet =

	PARCEL	APS		APS	>	VERIZON	>	VERIZON		TOTAL		SCORRE
	SIZE	PUBLIC	ß	SERVICE	Α.	PUBLIC	SE	SERVICE	CO	CONVERSION	VOTES	FEET WITH
PARCEL ID	(Sq Ft)	COST		COST		COST		COST		COST	1= YES	YES VOTES
310-32-139	4079.89	\$ 1,891.55	\$	1	69	2,678.14	÷	•	€*>	4,569.69		4079.89
310-32-140	4079.89	\$ 1,891.55	\$	-	65	2,678.14	64	1	64	4,569.69		4079.89
310-32-141	4079.89	\$ 1,891.55	\$		↔	2,678.14	64	69.976	(4)	5,546.38	0	
310-32-142	4079.89	\$ 1,891.55	\$	ı	6-3	2,678.14	6-5		65	4,569.69	Ţ	4079.89
310-32-143	4016.49	\$ 1,862.16	\$	-	₩,	2,636.53	69	1,095.03	6/3	5,593.72	1	4016.49
310-32-144	4402.98	\$ 2,041.35	\$	1,589.33	65	2,890.23	65	2,319.30	\$	8,840.21	I	4402.98
310-32-145	4070.03	\$ 1,886.98	&5 22	1	€9	2,671.67	<u></u> >	,	es.	4,558.65	1	4070.03
0-32-146	4070.03	\$ 1,886.98	&÷ ⊗	1	€9	2,671.67	64)	1,197.43	64	5,756.08	1	4070.03
310-32-147	4070.03	\$ 1,886.98	65 80	1,454.66	69	2,671.67	€>	2,351.18	65	8,364.49	1	4070.03
310-32-148	4070.03	\$ 1,886.98	∞	1	65	2,671.67	69	'	ॐ	4,558.65	1	4070.03
310-32-150A	8140.06	\$ 3,773.96	9	•	5-5	5,343.34	5-5		65	9,117.30		8140.06
310-32-151A	6105.04	\$ 2,830.47	7	,	65	4,007.50	643	1,326.60	is,	8,164.57	0	
310-32-153A	6105.04	\$ 2,830.47	7	1	64	4,007.50	į,	1,242.08	643	8,080.05		6105.04
310-32-154	4070.03	\$ 1,886.98	\$,	65	2,671.67	جو	1,069.04	65	5,627.69	0	
310-32-156A	8140.1	\$ 3,773.98	\$ 8	1	64	5,343.37	جئ	1,146.29	45	10,263.64	1	8140.1
310-32-157	4070.03	\$ 1,886.98	\$ 8	,	⇔	2,671.67	6 ~>	2,552.04	6°>	7,110.69	0	
310-32-158	4070.03	\$ 1,886.98	\$ 80	,	69	2,671.67	÷÷	1,524.36	65	6,083.01	1	4070.03
310-32-159	4070.03	\$ 1,886.98	\$ 80	,	64	2,671.67	₩	913.65	€ \$	5,472.30	1	4070.03
310-32-160	4070.03	\$ 1,886.98	\$ 80	•	64	2,671.67	69	920.35	69	5,479.00	1	4070.03
310-32-161	4070.03	67	\$ 80	1,788.87	↔	2,671.67	69	2,555.71	& \$	8,903.23	1	4070.03
10-32-162	4746.29	\$	\$ 29	•	63	3,115.59	65	1,400.40	\$	6,716.51	-	4746.29
310-32-164	5099.88	€4	\$ 5	1	6 ⊅	3,347.69	↔	2,546.92	643	8,259.06	1	5099.88
310-32-165	5099.88	\$ 2,364.45	15 \$	2,932.71	\$	3,347.69	\$ ->	4,056.88	69	12,701.73	Ţ	5099.88
310-32-166	5099.88	\$ 2,364.45	\$ 5	•	69	3,347.69	\$	19.616	69	6,685.75	1	5099.88
310-32-167	5099.88	\$ 2,364.45	45 \$		65	3,347.69	50	2,013.15	& ⇒	7,725.29	1	5099.88
310-32-168	5099.88	\$ 2,364.45	45 \$	•	\$	3,347.69	دم	1,013.05	65	6,725.19	1	5099.88
310-32-169A	6374.85	\$ 2,955.56	26 \$	1	\$	4,184.61	64 3	1,429.01	5-5	8,569.18	1	6374.85
310-32-170A	6374.85	\$ 2,955.56	3 6 \$	•	\$	4,184.61	64	19.676	€>	8,113.78	, 1	6374.85
310-32-172C	6374.85	€	\$ 99	1,454.66	\$	4,184.61	÷	3,121.72	64	11,716.55	0	
310-32-173A	6374.85	\$ 2,955.56	\$ \$	1	€5	4 184 61	جئ	922.89	69	8.063.06	1	6374.85

Staff is in the process of obtaining individual parcel information for the approximate \$928,800 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5)

Staff is in the process of obtaining individual parcel information for the approximate \$928,000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5)

																					-, 1				100							ᅴ
1,297,248.74 798,640.64 61.56%	SQUARE FEET WITH	XES VOTES			5099.88	5099.88					8721.47	7664.08		11039.74	10439.75	6119.85	5519.87	5399.87	5399.87	5399.87	10799.74	5399.87	5399.87	7805.81	10157.26		6214.3	4124.7	4124.71	4124.71	4124.71	4124.7
Teet = Votes = Votes =	VOTES	1= YES	0	0	1	1	0	0	٥	0			0	-	1	Ţ	1	1	-	1		_		-	1	D					-	-
Total Square Feet = Total Square Feet = Total Square Feet with XES Votes = % of Square Feet with XES Votes =	TOTAL CONVERSION	COST	5,712.14	7,143.26	7,270.86	6,397.82	6,688.83	12,155.04	10,880.85	10,893.96	13,855.47	10,018.70	9,928.29	15,957.72	16,492.60	10,672.83	9,744.01	6,048.14	7,483.77	10,109.82	17,043.64	8,844.54	7,228.24	15,489.96	12,269.45	13,352.27	8,054.39	5,624.81	5,610.40	4,619,89	4,619.89	4,619.89
ire F	CO		64	جر	وميا	55	↔	64	8-8	63	6	5-5	Çe,	69	÷	\$	÷	69	ક્ક	↔	69	€5	⇔	543	↔	\$	€\$	63		6-3	€\$	\$
Total Squi % of Squi	VERIZON SERVICE	COST	-	1,431.12	1,558.72	685.68	976.69	730.76	3,098.38	3,865.11	2,420.66	1,434.51	2,420.71	3,592.61	2,844.62	2,314.44	3,561.46	,	1,435.63	2,416.74	2,948.54	1,880.46	1,180.10	3,922.35	892.77	1,820.77	1,094.03	1,004.92	990.51	,		
	VE		⊊ Ą-	69	6-3	69	60	S	6-9	69	دع	\$	\$	5 -3-	(^	64)	8	5/5	\$	₩	69	59	63	جه	\$	\$	89	69	ć-5	5-5	{	\$
	VERIZON PUBLIC	COST	3,347.69	3,347.69	3,347.69	3,347.69	3,347.69	6,695.38	3,347.69	3,187.92	5,725.00	5,030.90	3,423.38	7,246.77	6,852.92	4,017.23	3,623.38	3,544.61	3,544.61	3,544.61	7,089.22	. 3,544.61	3,544.61	5,123.93	6,667.48	6,165.03	4,079.23	2,707.56	2,707.56	2,707.56	2,707.56	2,707.56
	VIII P		69	ęs,	€9	\$	59	€-3	6-3	↔	69	64	60	÷	64	64)	69	5	جه	65	69	64	\$	69	\$	69	69	\$	\$	₽Э	63	63
%	APS SERVICE	COST	-	-	•	-	•	-	2,070.33	1,589.33	1,666.29	,	1,666.29	•	1,954.89	1,503.82	1	,	•	1,644.94	1,998.81	915.94	ı	2,824.68	1	1,012.15	•	1	•	•	ı	•
239 151 63.18%	SI		64)	63	₩	↔	643	€5	÷	↔	69	643	€3	69	↔	65	↔	8	63	\$	\$	\$	\$	\$	€÷	₩	\$	\$	\$	69	↔	\$
	APS PUBLIC	COST	2,364.45	2,364.45	2,364.45	2,364.45.	2,364.45	4,728.90	2,364.45	2,251.60	4,043.52	3,553.29	2,417.91	5,118.34	4,840.17	2,837.34	2,559.17	2,503.53	2,503.53	2,503.53	5,007.07	2,503.53	2,503.53	3,619.00	4,709.20	4,354.32	2,881.13	1,912.33	1,912.33	1,912.33	1,912.33	1,912.33
Total P Total YES to Total Pa	14		69	₩	€4)		64		64	÷	\$	65	ده	69	643	5	65	64	65	\$	\$ 1	\$ 1	\$ 1	\$ 1	\$	\$ 7	1	₩	1 \$	\$ 1	1 \$	
Total Parcels = Total XES Votes = % of XES Votes to Total Parcels ==	PARCEL SIZE	(Sq Ft)	5099.88	5099.88	5099.88	5099.88	5099.88	10199.76	5099.88	4856.48	8721.47	7664.08	5215.19	11039.74	10439.75	6119.85	5519.87	5399.87	5399.87	5399.87	10799.74	5399.87	5399.87	7805.81	10157.26	9391.82	6214.31	4124.71	4124.71	4124.71	4124.71	4124.71
10 %		PARCEL ID	310-32-174	310-32-175	310-32-176	310-32-177	310-32-178	310-32-180A	310-32-181	310-32-182	310-32-183A	310-32-183C	310-32-184	310-32-186A	310-32-188B	310-32-189A	310-32-190	310-32-191	310-32-192	310-32-193	310-32-195A	310-32-196	310-32-197	310-32-198	310-32-199	310-32-200	310-32-201	310-32-202	310-32-203	310-32-204	310-32-205	310-32-206

Staff is in the process of obtaining individual parcel information for the approximate \$92\$,000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5)

SQUARE FEET WITH	XES VOTES	4124.71		4041.18	4099.6		8650.19	4499.88	5158.81	9741.29	6750	4500	4500	4500	4565.26	4407.9		4499.89	4499.89	4499.89	4499.89	6001.18	5543.9	5991.8	4035.97	3947.8			4035.97	5023.26	7100.14
ÝOTES	1= YES	1	0		1	0		Ī	1		1			-	-	 	0	-		-	1	-		-	_	-	0	٥	-	-	1
TOTAL		4,619.89	6,226.24	4,526.34	7,553.37	9,920.80	10,726.37	6,741.91	10,080.31	12,997.16	8,826.27	6,277.94	8,177.45	6,731.66	7,268.66	7,474.53	7,408.23		6,053.17	9,880.68			8,723.21	7,710.38	6,045.41		4,427.23	5,844.55	5,465.93		
)	65	\$	6.5	5	9	6	0	4	9	\$. 10	\$ 0,	\$ 17	27	33 \$	4	1.1	-	35 \$	\$ 62	\$ 81	6.5	\$ 08	\$ 42	91 \$	65	<i>\$</i>	\$ 50	43 \$	45 \$	\$
VERIZON	COST	'	1,606.35	,	1,856.35	2,960.79	1,037.69	1,701.80	2,582.84	2,086.39	1,265.91	1,237.70	3,137.21	1,691.42	1,340.53	2,537.44	2,368.11	2,665.33	1,013.05	2,888.29	1,225.18		1,597.80	999.24	1,524.9	,	,	1,324.05	945.43	551.45	,
> 10	ì	69	64	63	65	64	643	6-5	64	69	جد	5-5	↔	673	53	€>	50	63		∻>	65	69	50	**	÷43	⇔	جئ	\$3	50	63	↔
VERIZON	COST	2,707.56	2,707.56	2,652.73	2,691.08	2,839.10	5,678.21	2,953.84	3,386.37	6,394.43	4,430.87	2,953.91	2,953.91	2,953.91	2,996.75	2,893.46	2,953.84	2,953.84	2,953.84	2,953.84	2,953.84	3,939.33	3,639.16	3,933.17	2,649.31	2,591.44	2,594.65	2,649.31	2,649.31	3,297.40	4,660.71
> ~	(جع	69	€3	₩	65	€>	67	65	↔	60	6 >	6/3	خج	65	89	₩	65	64)	65	↔	69	\$	↔	65	۶۶)	↔	خ۶	6/3	64	69
APS SERVICE	COST	ŧ	1	,	1,105.25	2,115.67	1	•	1,719.33	1	-	•	-	•	814.80	•	1	,	,	1,952.27	•	1	915.94	,	,	•		,	1	,	•
(C)		\$	€ 9	↔	↔	\$	69	\$	\$	⇔	_	6-3	64)	ક્ક	\$	€9	↔	\$	s	6-3		↔	↔	\$	\$	6-3	64)	64)	643	6-5	60
APS PUBLIC	COST	1,912.33	1,912.33	1,873.61	1,900.69	2,005.24	4,010.47	2,086.27	2,391.77	4,516.34	3,129.49	2,086.33	2,086.33	2,086.33	2,116.58	2,043.63	2,086.28	2,086.28	2,086.28	2,086.28	2,086.28	2,782.32	2,570.31	2,777.97	1,871.19	1,830.3	1,832.58	1,871.19	1,871.19	2,328.93	3,291.83
μ.		ç	↔	↔	63	69	64)	64)	63	60			65		65	643			₩	_	63	_4	63	⇔	\$ \$		\$	-+	1		₹
PARCEL SIZE	(Sq Ft)	4124.71	4124.71	4041.18	4099.6	4325.09	8650.19	4499.88	5158.81	9741.29	6750	4500	4500	4500	4565.26	4407.9	4499.89	4499.89	4499.89	4499.89	4499.89	6001.18	5543.9	5991.8	4035.97	3947.8	3952.69	4035.97	4035.97	5023.26	7100.14
	PARCEL ID	310-32-207	310-32-208	310-32-209	310-32-210	310-32-211	310-32-213A	310-32-214	310-32-215	310-32-216A	310-32-218A	310-32-219	310-32-220	310-32-221	310-32-222	310-32-223	310-32-224	310-32-225	310-32-226	310-32-227	310-32-228	310-32-229	310-32-230	310-32-231	310-32-232	310-32-233	310-32-234	310-32-235	310-32-236	310-32-237	310-32-238

1,297,248.74 798,640.64 61.56%

Total Square Feet with XES Votes = % of Square Feet with XES Votes =

Total XES Votes = 151

Total Parcels = 239

% of XES Votes to Total Parcels = 63.18%

Staff is in the process of obtaining individual parcel information for the approximate \$928.000 in additional cost contained in estimates provided to the owners by Hillcrest Bay (see page 5)

1,297,248.74 798,640.64 61.56%	SQUARE	VIES VOTES	6585 65		10479 2	7: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	8959.84			6800.7				4006 66			78 000F	20.0005	5000 73	3233.13		7900 R7	3999 82			7177 07	20.3		4777 51	16.777	5651.6	798,640,64
e Feet = Votes = Votes =	VOTES	1= YES	-	0		C	-	0	0	-	0	0	0	-	0	c	-	-	-	10		-	-	0	0		0	0	-	0		151
Total Square Feet = Fotal Square Feet with XES Votes = % of Square Feet with XES Votes =	TOTAL	COST	7.376.29	10,681.03	15,655.82	7,256.09	12,757.54	17,767.82	27,315.62	10,723.15	7,701.21	14,041.31	14,186.37	4,487.67	5.335.28	5.425.44	6.761.44	6 720 03	8 211 97	4.480.01	4,480.01	5,357.83	9,376,96	6,052.55	12,555.41	9,175.01	7,896.72	7,084.16	4,729,44	11,245.19	6,330.09	2,008,000.07
uare	Ŭ)	6 3	65	6-5	55	50	5-7	64	چئ	€	65	₩,	€5	50	50	69	50	5-5	160	165	55	65,	643	├	63	65	65	65	₩	49	\$ \$
Total Sqi % of Sq	VERIZON SERVICE	COST		2,510.65	2,387.94	1,418.59	1,517.48	1,493.65	1,598.14	1,901.45		702.59	1,712.37		855.27	945.43	1,461.68		864.59		,	877.82	2,922.81	1,572.54	1,474.21	1,136.31	1,232.10	1,309.70	,	,	,	393,908.28
	> 0		64	6-3	543	چئ	643	6-5	6-5	69	\$	60	₩,	6-3	64	54.	50	6-5	65	643	5-5	5-5-	643	\$	5-3-	69	50	€5	÷÷	64	6 43	6 \$
	VERIZON PUBLIC	COST	4,322.99	3,776.72	6,878.81	2,940.73	5,881.47	9,057.31	14,535.34	4,464.15	4,513.42	7,817.37	6,737.56	2,630.07	2,625.58	2,625.58	2,625.58	3,938.38	3,938,38	2,625.58	2,625.58	2,625.58	2,625.58	2,625.58	6,494.31	4,711.21	3,905.91	3,384.21	2,771.76	6,590.42	3,709.85	851,541.81
			643	↔	6-5	6-3	₩	69	69	↔	63	<u> </u>	6-5	6-3	6-3	6-5	6-5	60	65	643	60	6 0	€3	6-3	ج،	6 9	89	چئ	6-3	6-5	69	6-5
239 151 63.18%	APS SERVICE	COST		1,726.19	1,530.61	819.75	1,204.55	819.75	915.94	1,204.55	•	1	977.75		•	•	819.75		627.35	ı	ì	*	1,974.14	•	•	1	•		1	,	,	161,108.46
239 151 63.1	S	•	ક્ક	69	64	⇔	63	وم	€\$	₩.	€9	643	₩	63	63	65	6-3	€3	جن	6-3	64	€>	69	63	↔	6 →	جه	↔	69	69	69	€\$
l Parcels = ES Votes = Parcels =	APS PUBLIC	COST	3,053.30	2,667.47	4,858.46	2,077.02	4,154.04	6,397.11	10,266.20	3,153.00	3,187.79	5,521.35	4,758.69	1,857.60	1,854.43	1,854.43	1,854.43	2,781.65	2,781.65	1,854.43	1,854.43	1,854.43	1,854.43	1,854.43	4,586.89	3,327.49	2,758.71	2,390.25	1,957.68	4,654.77	2,620.24	601,441.52
Tot tal I Tots			69	64)	ومؤ	co	64)	مه	60				- 1		65		64	6-5	€>												—	جئ
Tota Total Y. % of XES Votes to Total	PARCEL SIZE	(Sq Ft)	6585.65	5753.46	10479.2	4479.92	8959.84	13797.93	22143.16	6800.7	6875.75	11909	10264.02	4006.66	3999.82	3999.82	3999.82	5999.73	5999.73	3999.82	3999.82	3999.82	3999.82	3999.82	9893.45	7177.07	5950.27	5155.52	4222.51	10039.86	5651.6	1,297,248.74
%		PARCEL ID	310-32-239	310-32-240	310-32-242A	310-32-243	310-32-245A	310-32-247A	310-32-248	310-32-249	310-32-251A	310-32-252	310-32-253	310-32-254	310-32-255	310-32-256	310-32-257	310-32-259A	310-32-260A	310-32-261	310-32-262	310-32-263	310-32-264	310-32-265	310-32-267A	310-32-269A	310-32-270A	310-32-271A	310-32-272	310-32-273	91312/03	IOIAL

\$ 402.528

EXHIBIT D

Hillcrest Bay Underground Conversion Private Costs (Staff Exhibit S-2)

•	•			Total Private
House #	Street Name	Trenching	Electrical	Costs
	Bay View Drive	\$1,875.20	\$4,101.00	\$5,976.20
	Bay View Drive	\$0.00	\$3,417.50	\$3,417.50
	Bay View Drive	\$0.00	\$750.00	\$750.00
	Bay View Drive	\$2,226.56	\$3,417.50	\$5,644.06
	Bay View Drive	\$0.00	\$980.00	\$980.00
	Bay View Drive	\$0.00	\$2,734.00	
	Bay View Drive	\$0.00	\$3,417.50	\$3,417.50
816	Bay View Drive	\$3,204.06	\$4,101.00	\$7,305.06
817	Bay View Drive	\$0.00	\$800.00	\$800.00
830	Bay View Drive	\$3,204.06	\$4,101.00	
831	Bay View Drive	\$0.00	\$2,734.00	\$2,734.00
837	Bay View Drive	\$0.00	\$2,734.00	\$2,734.00
	Bay View Drive		\$3,417.50	\$3,417.50
	Bay View Drive		\$2,734.00	\$2,734.00
	Bay View Drive	\$0.D0	\$2,734.00	\$2,734.00
	Bay View Drive	\$3,501.88	\$2,734.00	\$6,235.88
	Bay View Drive	\$0.00	\$2,050.50	\$2,050.50
	Bay View Drive		\$3,417.50	\$3,417.50
	Bay View Drive	\$0.00	\$950.00	\$950.00
	Bay View Drive	\$2,028.89	\$3,417.50	\$5,446.39
	Bay View Drive	\$2,028.89		\$2,028.89
	Bay View Drive	\$0.00	\$0.00	\$0.00
	Bay View Drive	<u> </u>	\$0.00	\$0.00
	Bay View Drive	\$730.10	\$2,734.00	\$3,464.10
	Bay View Drive	\$0.00		\$2,734.00
	Bay View Drive	\$963.88	\$3,417.50	\$4,381.38
	Bay View Drive	\$0.00	\$4,101.00	\$4,101.00
979	Bay View Drive		\$2,734.00	\$2,734.00
	Crystal View	\$2,028.89	\$6,151.50	\$8,180.39
	Crystal View	\$1,669.03	\$6,151.50	\$7,820.53
	Crystal View	\$4,311.44	\$6,835.00	\$11,146.44
	Crystal View	\$941.71	\$6,835.00	\$7,776.71
	Crystal View	\$2,096.79	\$6,835.00	\$8,931.79
	Crystal View	\$2,127.73		\$7,595.73
	Crystal View	\$1,930.06		\$7,398.06
	Crystal View	\$4,311.38	\$6,151.50	\$10,462.88
	Crystal View	\$1,732.38		\$5,149.88
	Crystal View	\$941.71	\$4,101.00	\$5,042.71
	Crystal View	\$941.71	\$4,784.50	\$5,726.21
	Crystal View	\$941.71	\$4,784.50	\$5,726.21
	Crystal View	\$941.71	\$5,468.00	\$6,409.71
	Crystal View	\$941.71	\$4,784.50	\$5,726.21
	Crystal View	\$0.00	\$4,784.50	\$4,784.50
		\$0.00	\$1,300.00	\$1,300.00
	Crystal View	\$1,875.22	\$6,835.00	\$8,710.22
	Crystal View	\$2,761.11	\$4,784.50	\$7,545.61
	Crystal View	\$989.31	\$4,284.00	\$5,273.31
	Crystal View	\$0.00	\$1,450.00	\$1,450.00
906	Crystal View	\$0.00	φ1, 1 00.00	¥1,700.00

Hillcrest Bay Underground Conversion Private Costs

(Staff Exhibit S-2)

				Total Private
House #	Street Name	Trenching	Electrical	Costs
	Crystal View	\$1,238.21	\$5,468.00	\$6,706.21
	Crystal View	\$0.00	\$1,400.00	\$1,400.00
	Crystal View	\$1,337.04		\$1, 337:04
	Crystal View	\$0.00	\$1,400.00	\$1,400.00
933	Crystal View	\$0.00	\$2,734.00	\$2,734.00
954	Crystal View	\$0.00	\$6,151.50	\$6,151.50
955	Crystal View	\$0.00	\$3,417.50	\$3,417.50
	Dunlap		\$3,417.50	\$3,417.50
	Dunlap	\$1,435.88	\$3,417.50	\$4,853.38
	Dunlap	\$0.00	\$1,650.00	\$1,650.00
	Dunlap	\$0.00	\$1,600.00	\$1,600.00
	Dunlap	\$0.00	\$5,468.00	\$5,468.00
	Dunlap	\$1,337.04	\$6,835.00	\$8,172.04
	Dunlap	\$0.00	\$1,600.00	\$1,600.00
	Dunlap	\$989.31	\$5,468.00	\$6,457.31
	Dunlap	\$1,337.04	\$6,151.50	\$7,488.54
	Dunlap	\$1,337.04		\$1,337.04
	Hillcrest Bay Drive	\$744.03	\$3,417.50	\$4,161.53
	Hillcrest Bay Drive	. \$971.11	\$3,417.50	\$4,388.61
	Hillcrest Bay Drive	\$1,435.88	\$5,468.00	\$6,903.88
	Hillcrest Bay Drive	\$2,127.73	\$5,468.00	\$7,595.73
	Hillcrest Bay Drive	\$2,127.73	\$5,468.00	
	Hillcrest Bay Drive	\$0.00	\$3,417.50	
	Hillcrest Bay Drive	\$1,435.88	\$3,417.50	
	Hillcrest Bay Drive	\$0.00	\$1,100.00	\$1,100.00
	Hillcrest Bay Drive	\$0.00	\$3,417.50	\$3,417.50
	Hillcrest Bay Drive	\$2,348.16	\$5,468.00	\$7,816.16
	Hillcrest Bay Drive	\$4,089.97	\$6,835.00	\$10,924.97
	Hillcrest Bay Drive	\$0.00	\$1,200.00	\$1,200.00
	Hillcrest Bay Drive	\$1,435.88	\$3,417.50	\$4,853.38
	Hillcrest Bay Drive	\$0.00		\$3,417.50
	Hillcrest Bay Drive	\$0.00	\$3,417.50	\$3,417.50
	Hillcrest Bay Drive	\$0.00	\$6,151.50	
	Hillcrest Bay Drive	\$0.00	\$3,417.50	
	Linger Drive	\$3,277.15	\$3,417.50	
	Linger Drive	\$3,285.84	\$4,784.50	
	Linger Drive	\$2,158.44	\$3,417.50	
		\$0.00	\$2,734.00	\$2,734.00
	Linger Drive	. \$0.00	\$3,417.50	\$3,417.50
	Linger Drive	\$1,432.36	\$3,417.50	
	Linger Drive	\$842.86	\$2,734.00	\$3,576.86
	Linger Drive	\$5,861.77	\$3,417.50	
	Linger Drive	\$3,298.57	\$3,417.50	
	Linger Drive			
	Linger Drive	\$3,868.49		
	Linger Drive	\$0.00	\$2,734.00	
	Linger Drive	\$744.02	\$4,101.00	
	Linger Drive	\$744.02	\$2,734.00	
857	Linger Drive	\$0.00	\$3,417.50	\$3,417.50

Hillcrest Bay Underground Conversion Private Costs (Staff Exhibit S-2)

				Total Private
House#	Street Name	Trenching	Electrical	Costs
864	Linger Drive	\$0.00	·	\$0.00
867	Linger Drive	\$1,432.26	\$3,417.50	\$4,849.76
	Linger Drive	\$1,534.71		
882	Linger Drive	\$1,337.04	\$3,417.5D	\$4,754.54
	Linger Drive	\$1,930.06	\$5,468.00	\$7,398.06
896	Linger Drive	\$2,096.69	\$6,151.50	\$8,248.19
	Linger Drive	\$1,831.21	\$5,468.00	\$7,299.21
	Linger Drive	\$1,337.04	\$3,417.50	\$4,754.54
	Linger Drive	\$1,139.36	\$4,101.00	\$5,240.36
	Linger Drive	\$0.00	\$1,450.00	\$1,450.00
934	Linger Drive	\$1,432.26	\$4,784.50	\$6,216.76
	Linger Drive	\$1,040.53	\$3,417.50	\$4,458.03
940	Linger Drive	\$0.00	\$3,417.50	\$3,417.50
954	Linger Drive	\$0.00	\$4,101.00	\$4,101.00
955	Linger Drive	\$0.00	\$3,417.50	\$3,417.50
2814	Manor View	\$0.00	\$3,417.50	\$3,417.50
2828	Manor View	\$0.00	\$2,734.00	\$2,734.00
2834	Manor View	\$0.00	\$4,784.50	\$4,784.50
2844	Manor View	\$0.00	\$2,734.00	\$2,734.00
2852	Manor View	\$0.00	\$1,800.00	\$1,800.00
2868	Manor View	\$0.00	\$0.00	\$0.00
2874	Manor View	\$0.00	\$1,200.00	\$1,200.00
2882	Manor View	\$0.00	\$2,734.00	\$2,734.00
2896	Manor View .	\$0.00	\$600.00	\$600.00
2904	Manor View	\$1,040.53	\$3,417.50	\$4,458.03
2910	Manor View	\$0.00	\$3,417.50	\$3,417.50
2944	Manor View	\$0.00	\$6,835.00	\$6,835.00
2948	Manor View	\$0.00	\$6,835.00	\$6,835.00
2952	Manor View		\$6,835.00	\$6,835.00
3958	Manor View	\$0.00		\$0.00
849	Max View Drive	\$0.00	\$1,600.00	\$1,600.00
864	Max View Drive	\$0.00	\$5,468.00	\$5,468.00
866	Max View Drive	\$3,204.06	\$6,151.50	\$9,355,56
866	Max View Drive	\$941.71	\$6,151.50	\$7,093.21
867 1	Max View Drive	\$0.00	\$1,600.00	\$1,600.00
874	Max View Drive		\$6,835.00	\$6,835.00
875	Max View Drive	\$1,697.00	\$4,101.00	\$5,798.00
876	Max View Drive	\$1,040.53	\$5,468.00	\$6,508.53
882 1	Vlax View Drive		\$6,151.50	\$6,151.50
	Max View Drive		\$4,784.50	\$4,784.50
	Max View Drive	\$1,337.04	\$4,101.00	\$5,438.04
	Max View Drive		\$1,500.00	\$1,500.00
	Max View Drive	\$0.00	\$4,101.00	\$4,101.00
	Max View Drive .	\$1,930.06	\$6,151.50	\$8,081.56
	Max View Drive	\$1,930.06	\$6,835.00	\$8,765.06
	Max View Drive	\$0.00	\$1,300.00	\$1,300.00
	Max View Drive	\$1,534.71	\$4,784.50	\$6,319.21
	Max View Drive	\$0.00	\$1,400.00	\$1,400.00

Hillcrest Bay Underground Conversion Private Costs

(Staff Exhibit S-2)

				Total Private
House #	Street Name	Trenching	Electrical	Costs
	Max View Drive	\$2,080.56	\$6,835.00	\$8,915.56
	Max View Drive	\$0.00		
	Noble View Drive	\$3,841.00	\$6,835.00	\$10,676.00
	Noble View Drive	\$0.00	\$3,417.50	\$3,417.50
	Noble View Drive	\$3,352.06	\$6,835.00	\$10,187.06
	Noble View Drive	\$989.31	\$5,468.00	\$6,457.31
	Noble View Drive	\$0.00	\$3,417.50	\$3,417.50
	Noble View Drive	\$3,868.49	\$5,468.00	\$9,336.49
	Noble View Drive	\$0.00		\$5,468.00
	Noble View Drive	\$3,103.33	\$5,468.00	\$8,571.33
	Noble View Drive	. \$0.00	\$1,600.00	\$1,600.00
	Noble View Drive	\$3,868.49		\$10,019.99
	Noble View Drive	\$0.00		\$0.00
	Noble View Drive	\$3,425.53		\$3,425.53
	Noble View Drive	\$0.00		\$0.00
	Noble View Drive	\$0.00		\$0.00
	Noble View Drive	\$1,435.88	l	\$6,903.88
T	Noble View Drive	\$0.00		\$1,650.00
	Noble View Drive	\$0.00		\$1,400.00
	Otis Court	\$0.00		\$6,835.00
	Otis Court	\$2,127.73		\$8,279.23
	Otis Court	\$1,435.88		\$7,587.38
	Swan Drive	\$0.00		\$2,734.00
	Swan Drive	\$0.00		\$3,417.50
	Swan Drive	\$0.00		\$4,101.00
	Swan Drive	\$0.00		\$2,734.00
	Swan Drive	\$0.00		\$800.00
	Swan Drive	\$0.00		\$800.00
	Swan Drive	\$4,910.56		\$7,644.56
	Swan Drive	\$0.00		\$750.00
	Swan Drive	\$0.00		\$2,734.00
	Swan Drive	\$0.00		\$800.00
		\$2,621.91		\$6,722.91
	Swan Drive	\$0.00		\$2,734.00
	Swan Drive			
	Swan Drive	\$0.00		\$2,734.00
	Swan Drive	\$0.00		\$3,417.50
	Swan Drive	\$0.00	\$3,417.50	\$3,417.50
	Swan Drive	\$2,285.86	\$4,101.00	\$6,386.86
	Swan Drive	\$4,467.60	\$4,101.00	\$8,568.60
	Swan Drive	\$4,311.44	\$4,101.00	\$8,412.44
	Swan Drive	\$3,298.47	\$4,101.00	\$7,399.47
	Swan Drive	\$1,347.64	\$4,784.50	\$6,132.14
	Swan Drive	\$0.00	\$1,400.00	\$1,400.00
895	Swan Drive	. \$1,337.04	\$3,417.50	\$4,754.54
906	Swan Drive	\$0.00	\$800.00	\$800.00
913	Swan Drive	· \$0.00	\$1,300.00	\$1,300.00
914	Swan Drive	\$842.86	\$3,417.50	\$4,260.36
920	Swan Drive.	. \$1,139.36	\$3,417.50	\$4,556.86

Hillcrest Bay Underground Conversion Private Costs

(Staff Exhibit S-2)

				Total Private
House #	Street Name	Trenching	Electrical	Costs
927	Swan Drive	\$2,761.11	\$2,734.00	\$5,495.11
928	Swan Drive	\$842.86	\$3,417.50	\$4,260.36
933	Swan Drive	\$0.00	\$3,417.50	\$3,417.50
936	Swan Drive	\$1,210.78	\$3,417.50	\$4,628.28
944	Swan Drive	\$0.00	\$4,101.00	\$4,101.00
951	Swan Drive	\$1,040.53	\$2,050.50	\$3,091.03
952	Swan Drive	\$0.00	\$3,417.50	\$3,41 7.50
	TOTALS	\$194,201.71	\$708,325.50	\$902,527.21

EXHIBIT E-1

\$ 7,260		S. C. Tarrey	6		\$ 4,258.55	-	\$ 3,007.79	45 0.5001%	6487.45	844 BAY VIEW DR	92647	HUNTINGTON BCH CA	18411 UNDERHILL LANE	310-32-047A MUZIO FRED & LYNNE JT	10-32-047A
	5 6,600.00 \$	5 3,000.00	10,262.76	\$ 882.34 \$			\$ 3,841.49	0.6367%	8285.65	B36 BAY VIEW DR	AZ 85344 E	PARKER /	830 BAY VIEW DR	DONNA C SWI JI	310-32-045A
\$ 10,061	6,801.00	4,001,001 \$1. 2,000.00 \$	8,764.51 \$; (7	S 648.08 S	\$ 5,225,61		\$ 3,690.81	65 0.6137%	7960.65	818 BAY VIEW DR	AZ 85344 (PARICER	BIS BAY VIEW DRIVE	BENEFICIARY	910-32-0434
\$ 10,842	2,834,00	2,934.00 \$	7,708.92 \$	\$ 2,984.87 \$	\$ 2,658.83	\$ 207.13	\$ 1,877.99	80 0.3122%	4050.60	BID BAY VIEW DR	CA 92382 I	RUNNING SPRINGS	P O BOX 112	FHW 8; RIACH JED WILLIAM SIM 1/2	10-32-041
\$ 4,802	5	5.	4,602.28		\$ 2,697.24	-	\$ 1,805.04	.85 0.3167%	4108.05	804 BAY VIEW DR	CA 91718	CHINO	4756 MURIETTA ST	NEVARES ALBERT & AMELIA HAV JT	110-32-040
8 8,819	3317.50	\$ 3,317:50 \$	5,301.50	S 848.42 S	\$ 2,609.80		\$ 1,843.28	75 0.3065%	3975.75	796 BAY VIEW DR	CA 81710	CHINO	4758 MURIETTA ST	NEVARES ALBERT & AMELIA HAV JT	10-32-039
\$ 4,481		- The state of the	4.491.75		\$ 2,632.46		\$ 1,858.28	0.3091%	4010.27	780 BAY VIEW DR	CA 90850	NORWALK	13811 MAYPORT AVE	JT	10-32-038
\$ 13,457	5 3317.50 S	のでは、	10,140,15	\$ 3,186.37 \$	\$ 2,777.23	\$ 2,205.01	\$ 1,861.54	61 0.3261%	4230.61	782 BAYVIEW DR	CA 92201	BERMUDA DUNES	78710 DARRELL DR	THOMPSON EILEEN K TRUSTEE	10-32-037
\$ 24,008		5年 大大	17,271.48 \$ 34	\$ 4,928.00 \$	\$ 5,132.27	\$ 3,586.33	\$ 3,624.68	46 0.5027%	7818.46	2944 NOBLE VIEW DR	89301	TWIN FALLS	570 RIM VIEW DRIVE	LEDBETTER LINDA	10-32-038A
\$ 37,255	1 d 785.00		30,520.96 \$5	\$ 12,242.32 \$	5,132,28	\$ 9,521.47 \$	\$ 3,624.89	48 0.6027%	7818.48	2948 NOBLE VIEW DR	AZ 85344	PARKER	2948 S NOBLE VIEW DRIVE	HWJT	310-32-035A
\$ 30,215	\$ 76,735.00.		32,480,29 \$	\$ 12,163.43 \$	\$ 6,326.81	\$ 8,521.47	\$ 4,488,58	22 0.7430%	8838.22	2952 NOBLE VIEW DR	CA 82878	TRABUCO CANYON	21225 PINEBLUPF DRIVE	TRUSTERS BENTON STEVE & ALVARADO DELIA	910-32-034A
\$ 15,870	9,317.50	3	12,562.38	\$ 1,515.28 \$	\$ 5,937.52	\$ 915.94	\$ 4,183.62	17 0.6973%	R 9045.17	2910 MANOR VIEW DR	AZ 85344	PARKER	2910 S MANOR VIEW	SHORE ROGER A & SALLY J	10-32-033
\$ 11,572	\$ 117.50	3,317.60 \$ 600.00	7,454.86 5	\$ 1,336.66 \$	\$ 3,585,60	-	\$ 2,532.48	0.4211%	R 5482.27	2904 MANOR VIEW DR	CA 92211 2	PALM DESERT C	78978 SPIRIT COURT	JUNE SW JT	10-32-032
\$ 10,100	15	800.00 \$	9,609.41	\$ 2,387.65 \$	3,286,65	\$ 1,603.57 \$	\$ 2,321,34	86 0,3860%	5006.86	2898 MANOR VIEW DR	CA 82211	PALM DESERT C	78978 SPIRIT COURT	BRYANT BETTY J &; JORDAN GOLDIE	110-32-031
\$ 6,454		STATE OF THE PARTY	6,454.55	\$ 1,355,72 \$	\$ 2,988.25	5	\$ 2,110.58	7,805£'0	R 4552.26	2882 MANOR VIEW DR	AZ 85344	Parker	2882 Menar Vlew Dr	SANCHOZ, Sergio	10-22-030
\$ 6,051			5,417,89	\$	2,739.98	\$ 742.78 \$	\$ 1,935.23	0.3218%	4174.08	2882 MANOR VIEW DR	CA 88137 2	LAKE ALMANOR C	4378 HWY 147	CALVIN NYLES AS CO-TRUSTEES	10-32-028
\$ 6,755	\$ 1,100.00	45	7,655.31	\$ 2,275,88 \$	2,627,17	\$ 686.70 \$	\$ 1,855.55	0.3085%	A 4002.21	2874 MANOR VIEW DR	AZ 85344	PARKER	28/4 MANOR VIEW DRIVE	WESTRA JOHN JACOB &; WESTRA	1000000
\$ 10,483			4,482.72 5		\$ 2,627.17	-	\$ 1,855,65	0.3085%	A 4002.21	2868 MANOR VIEW DR	82547	STON BCH	BB92 VIA CARONA UR	Blood Birth	10.00
\$ 4,482	\$		4,482.72 \$		\$ 2,627.17	-	1,050.55	1	7.2004	- 1	1,0			DEUEL EDWARD WOODWORTH III &;	757
9,40	7,700.00		07.207	277768		1,202,20	100,00				9097		2932 BALLESTEROS I ANE	STIREWALT CHARLES & S/M	10-32-026
					, , ,			ASBUT U			CA 92887	YORBA LINDA	5000 WINDY DIRCLE	MCCLOSKEY ANOREW R & SHANNA S	\$10-32-025
1 17			11,444,62	\$ 4,028.39 \$		\$ 2,632.71	\$ 1,855.55			2844 MANOR VIEW DR	CA 92203	NDIO	40041 BEAR CREEKST	SLONE CLARK & PIPER HW	10-32-024
\$ 16,831	05 P98 P . m S		12,147.42	5 4,405,18 5	\$ 2,627.17	_	\$ 1,855.56	0.3085%	4002.21	2834 MANOR VIEW DR	CA 92258 2	N PALM SPRINGS	P O BOX 580918	SLONE CLARK & PIPER A HW	10-32-023
	2 034 00	634 00 \$	5	\$ 3,886.74 \$	2,791.45	5 2,578.58 \$	\$ 1,871.58	47 0.3276%	R 4252.47	2828 MANOR VIEW DR	CA 90813 2	LONG BEACH C	1777 LEWIS AVENUE	FRAZIER MAC & JOYCE HAW JT	110-32-022
\$ 14,706	8	317.50, 5	11,381.26 \$ 3.20	\$ 3,626.00 \$	3,038.14	\$ 2,578.59 \$	\$ 2,148.53	B1 0.3569%	R 4829.81	2814 MANOR VIEW DR	2 B5344 2	PARKER	2814 MANOR VIEW OR	TRUSTEES	110-32-021
\$ 7,29		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7,289.75 \$	\$ 2,103.32 \$	\$ 3,045.45		\$ 2,150,98	0.3576%	A 4838.41	2800 MANOR VIEW DR	AZ 85344 2	PARKER	2814 MANOR VIEW DR	FERGUSON DUANE E & RUTH V HAV	110-32-020
5 11,813	5.401.00	\$ 11,400.00	8.412.11	\$ 1,582.13 \$	\$ 2,624,63		\$ 1,865.15	32 0.3317%	4303.32	781 BAY VIEW DR	CA 91740 7	OLENDORA C	927 HIGH COUNTRY	FERGUSON DUANE E & RUTH V HAV	910-24-018
\$ 11,204	\$ 650.00	\$	10,554,13	\$ 3,430.44 \$	\$ 2,743.48	\$ 2,442,48	\$ 1,837,71	42 0.3222%	4178.42	781 BAY VIEW DR	AZ 85344 7	TARKER	THE BAT VIEW DRIVE	0.74.0.00	
\$ 4,801		50 H	4,601,14 \$		3 2,686.57		3 1,304.37	T	40.701.6				Var and company	ALVARADO CARL SIM; CRAVEN SHERRY SAN JT	110-32-018
8,68	880.00	4	(C) (B) (C)	4,007,04	A	1,200,73	- 1	\neg		- 1	92674		P D 80X 88	TRUSTEES	110-32-017
			1	2007	3 408 40	- }	\$ 1.839.65		3855.62		92674		P O BOX 88	TRUSTEES	10-32-016
1		4 9 17 60	1	- 1	2 817.82		5 1,990.21		4292.65	BIT BAYVIEW DR		EAC.	18411 UNDERHILL LN	MUZIC FRED A & LYNNE S JT	310-32-015
1			11,687.29 \$34	2.768.33	4,484.27			0.5480%	7108.56	817 BAYVIEW DR	CA 90706 8	BELLFLOWER C	10313 FELSON ST	TRUSTEES	10-32-014A
			12,270.71	\$ 2,246.03 S		\$ 1,338.22	\$ 3,595.21		7754.45	BAY VIEW DR	SD 57501 B	PIERRE	17808 DUANTUM PL	JOHNBON WYMAN & DONNA J HW	110-32-012A
	2.634.00		9,609.22	\$ 2,061.58 \$		\$ 1,300,20	\$ 2,588.03	77 0,4300%	5577.77	837 BAY VIEW DR	CA 92801 8	ANAHEIM	501 N CLENTINE ST	GOLISH ROBERT L & ROBERTA A HAV	310-32-011
\$ 11,128				\$ 1,239.54 \$			\$ 2,720.06	85 0.4523%	5888.85	BA3 BAY VIEW DR	CA 92118 B	CORONADO	445 B AVENUE	CARTWRIGHT LARRY	310-32-010
\$ 10,34	00 159 2 1	**************************************	\$	\$ 1,238.54 \$,	\$ 2,677.96	0.4453%	5778.06	849 BAY VIEW DR	CA 92118 8	CORDIVADO	445 B AVENUE	CARTWRIGHT LARRY	310-32-009
\$ 11,142	\$ 2,634,00	· 1000 1000 1000 1000 1000 1000 1000 10	6,508.00	\$ 1,592.17 \$	\$ 3,516.33	\$ 915.94	\$ 2,489.56	75 0.4129%	5356.75	855 BAYVIEW DR	AZ 85344 E	PARKER	855 BAY VIEW DRIVE	PEDREGON VERONICA	10-32-008
\$ 10,056			8,106,40	\$ 1,579.62 \$	\$ 3,291.64	\$ 915.94	\$ 2,325.00	76 0.3866%	5014.70	881 BAY VIEW DR	CA 91791 6	WEST COVINA	912 SOUTH EASTHILLS OR	TLWH	10-32-007
\$. 6,423	\$ 30.00	\$	7,573.67	\$ 1,520.12 \$	\$ 3,067.35	\$ 619.75	\$ 2,166.45	78 0,3602%	4672.78	867 BAY VIEW DR	AZ 85344 E	PARKER	855 BAY VIEW DRIVE	PEDREGON VERONICA CARMICHAEL DAVID P & PATRICIA	10-32-008
		2.634.00 \$ 1,850.00 \$	9,975.88 \$	\$ 657.51 \$		5	\$ 3,857,23	61 0.6413%	8318.61	876 BAY VIEW DR	CA 91710 E	CHINO	11751 ROSWELL AVE	REVES ALBERT L & MARIA G HW JT	10-32-005A
		9 10 10 10 10 10	-	- 3	\$ 2,981.88		\$ 2,106.06	54 0.3502%	4542.54	885 BAY VIEW DR	92888	RCH STA MARGAR CA	9 VIA PARPLONA	JENNIFER C/O	10-32-003
\$ 16,92		2,634,00 \$ 5	14,287.09	\$ 3,574.80 \$	\$ 4,613.94	\$ 2,498.30	\$ 3,400.05	52 0.5653%	7333.52	897 BAYVIEW DR	92686	RNCH STA MARGA CA	22482 ALMA ALDEA #76	FLETCHER JENNIFER D	310-32-002
Total Convers		Private Property Private Property Subjected Private Electric Tranching Cost	Cost - El		Verizon Fubilia Verizon Sevide	APS Service Cost	APS Public Cost	ZE % of Eq.Fi	PARCEL SIZE	SITUS ADDRESS	ST CODE	опу	ADDRESS	PARCEL ID Owner Names	RCEL ID
	-	حاجب دويون بأخورون يوغر أسيجو بإمامة		1	ANCED BY UTILITY UP TO 15 YEARS	FINAN			1		1				

2,696,76 \$ 870,84 \$ 5,472.10 \$ 3317.50 2,696,76 \$ 911,62 \$ 5,513.08 \$ 3,317.50	60 60	15 15	, , ,	o 6	7% \$ 1,904.70 7% \$ 1,904.70	108.22 0.3167% 108.22 0.3167%	4108.22 4108.22	H 814 SWANDR	CA 92054 AZ 85344	OCEANSIDE PARKER	1380 KNOLL DRIVE	10-32-088 TRUSTEES ANDERSON FILMORE H S/M 8; 10-32-097 ANDERSON VIRGINIA L S/W
3167% \$ 1,804.70 \$ 819.75 \$ 2,898.78 \$ 1,482.23 \$ 6,903.44 \$ 2000.00	\$ 1,904.70 \$ 819.75 \$ 2,898.78 \$ 1	\$ 1,904.70 \$ 818.75 \$	\$ 1,904.70 \$ 8	5	12		4108.22	5 908 SWAN DR	TYAZ 86405	LAKE HAVASU CT	P O BOX 685	110-32-095 CUMMINS INVESTMENTS INC
0.6354% \$ 3,606.40 \$. \$ 5,363.51 \$ 1,536.06 \$ 10,738.67 \$	5 3,808.40 45 - 5 5,383.51 46	\$ 3,809.40 \$. \$	5	5	12	7-	8218.44	4 888 SWANDRIVE	AZ 85344	PARKER	A88 SWAN DRIVE	110-32-084A VAUGHN DONALD & VIRGINIA HAV
7% \$ 1,804.70 \$. \$ 2,880.78 \$ 1,024.31 \$ 5,825.77 \$	\$ 1,804.70 \$. \$ 2,888.78 \$	\$ 1,804.70 \$	67	67	1~	1.22 0.3167%	4108.22	4 880 SWANDR	A2 85344	PARKER	880 SWAN DR	_
\$ 1,804,70 \$. \$ 2,888,76 \$ 811.82 \$ 5,513.08	\$ 1,804.70 \$. \$ 2,698.76 \$	\$ 1,804.70 \$. \$	5	5		.22 0.3187%	4108.22	4 872 SWANDR	AZ 85344	PARKER	872 E SWAN DR	310-32-081 LYNN JO-ANNE M
\$ 1,804,70 \$. \$ 2,696,76 \$ 1,351,68 \$ 5,953.12 \$ 4,001;00	\$ 1,804.70 \$ - \$ 2,698.76 \$	\$ 1,804.70 \$ - \$	\$	\$		22 0,3187%	4108.22	4 B64 SWANDR	CA 92344	DAKHILLS	14049 FARMINGTON ST	110-32-090 LEE RONALD D & MARY P HW JY
\$ 1,904.70 \$ 3,818.28 \$ 2,886.78 \$ 5,338.57 \$ 13,756.32 \$: 3,817.50.	\$ 1,904.70 \$ 3,818.29 \$ 2,896.78 \$	\$ 1,904.70 \$ 3,818,29 \$	\$ 1,904.70 \$	-	L.ő	.22 0.3167%	4108.22	2 854 SWANDR	CA 91722	COVINA	229 W TUDOR ST	10-32-089 LEE DONALD E
\$ 1,904.70 \$ 3,749.74 \$ 2,686.76 \$ 5,103.08 \$ 13,454.28 \$2,634.00	\$ 1,904.70 \$ 3,749.74 \$ 2,686.76 \$	\$ 1,904.70 \$ 3,749.74 \$	\$ 1,804.70 \$	•	125	.22 0.3167%	4108.22	2 B46 SWANDR	CA 91722	COVINA	229 W TUDOR ST	310-32-088 LEE CLIFTON D & VIOLA J TRUSTEES
\$ 1,904.70 \$. \$ 2,696.76 \$. \$ 4,601.46 \$.			\$ 1,904,70 \$	\$ 1,904.7	×	.22 0.3187%	4108.22	2 836 SWAN DR	CA 91722	COVINA	229 TUDOR	110-32-087 LEE CLIFTON D & VIOLA J TRUSTEES
\$ 1,804.70 \$ 1,841.65 \$ 2,686.76 \$ 2,673.78 \$ 9,116.90 \$ 700.00	1,904.70 \$ 1,841.85 \$ 2,898.78 \$	1,904.70 \$ 1,841.65 \$	1,904.70 \$.22 0.3167%	4108.22	44 828 SWAN DR	AZ 95344	PARKER	2775 HILLCREST DR	GOLDI TREVOR &; SMITH-GOLDI 110-32-088 SIERRA HW JT A; POOL EARLINE R
\$ 1,004.70 \$ - \$ 2,698.78 \$ 1,127.89 \$ 5,729.35 \$ 24,001.00	1,904.70 \$ - \$ 2,698.78 \$	1,904.70 \$ - \$.22 0.3187%	4108.22	8 820 SWANDR	T AZ 88408	LAKE HAVASU CIT	3220 BARATOGA AVENUE	STEINER JOHN M & PEGGY J HW JT 310-32-085 172; STEINER JOHN M & PEGGY J
\$ 1,804.70 \$. \$ 2,888.76 \$ 1,182.85 \$ 5,784.11 \$ 1,182.63.00	\$. \$ 2,896.76 \$. 5	\$ 1,804.70 \$	\$ 1,804.7.	135	.22 0.3167%	4108.22	8 810 SWANDR	CA 90808	LONG BEACH	4545 SUNFIELD AVENUE	INT, WILKE RICHARD & ANDREA TR
\$ 1,904,70 \$ \$ 2,696,78 \$ 1,520,57 \$ 6,122,03 \$	\$ 2,886.76 \$		\$ 1,904.70 \$	1,904.7	13°		4108.22	796	CA 90808	LONG BEACH	4545 SUNFIELD AVENUE	INT; WILKE RICHARD J & ANDREA TR 310-32-663 1/3 INT; GLYNN DAVID M & DOROTHY
\$ 2.586.78 \$ 5,712.26 \$ 14,664.50	\$ 4,350.76 \$ 2,686.78 \$	\$ 4,350.78 \$	4.3	1,904.7	× -	22 0.3167%	4108.22	792 SWANDR	AZ 85344	PARKER	784 SWAN DR	310-32-082 LAMBROSE GEOFFREY WILLIAM SIM
\$ 2,438.80 \$ 3,591.83 \$ 3,452.88 \$ 4,873.28 \$ 14,358.87 \$: 3,377.50	\$ 3,591,63 \$ 3,452,88 \$	\$ 3,591,63 \$	3,5	5 2,438.8	1×	21 0.4055%	5280,21	1 784 SWANDR	AZ 85344	PARKER	784 SWAN DR	10-32-081 LAMBROSE GEOFFREY WILLIAM SVM
\$ 1,873.16 \$ 1,012.15 \$ 2,763.69 \$ 1,630.51 \$ 7,408.51 \$ 2,634.00	\$ 1.012.15 \$ 2,763.68 \$	\$ 1.012.15 \$	S :0	\$ 1,873.10	<u> </u>	88 0.3261%	4255.88	3 783 SWANDR	CA 92883	CORONA	1826 COMARAGO COURT	STEWART RANDY J & RACHAEL ANNE
\$ 1,887.11 \$ 1,127.58 \$ 2,886.02 \$ 1,786.28 \$ 7,477.01 \$ 4,001.00	1,807.11 \$ 1,127.58 \$ 2,886.02 \$	1,807.11 \$ 1,127.58 \$	1,807.11 \$			88 0.3154%	4091,88	781 SWANDR	CA 92821	BREA		
\$ 2,666.02 \$ 1,701.46 \$ 7,354.45 \$	1,897.11 \$ 1,069.86 \$ 2,686.02 \$	1,897.11 \$ 1,069.86 \$	1,897.11 \$			BB 0.3154%	4001.88	787 SWANDR	CA 92821	BREA	1021 N PUENTE ST	110-32-078 BITRICH TERENCE W A SM
\$ 1,493.14 \$ 2,686.11 \$ 2,245.65 \$ 8,322.28 \$ 5.5.5	\$ 1,493,14 \$ 2,686.11 \$	\$ 1,493,14 \$	5	\$ 1,887.16	125	00 0.3154%	4092.00	807 SWANDR	CA 90830	CYPRESS	8819 TAHITI DR	
\$ 1,697,18 \$ 1,165,30 \$ 2,686,11 \$ 1,548,65 \$ 7,717,44 \$ 350,00	S 1,185.30 \$ 2,886.11 \$	\$ 1,185.30 \$	5	\$ 1,887,14	100	00 0,3154%	4082.00	BIS SWANDR	CA 90830	CYPRESS	8819 TAHITI DR	310-32-076 TRUSTEES
\$ 1,697.11 \$ 2,069.57 \$ 2,066.02 \$ 3,024.79 \$ 9,687.48 \$ 2,084.70	1,897.11 \$ 2,089.67 \$ 2,086.02 \$	1,897.11 \$ 2,089.67 \$	1,897.11 \$ 2,01	_		86 0.3154%	4091.88	821 SWANDR	CA 90708	BELLFLOWER	17818 REGENCY CIRCLE	910-32-075 HW; GATLIN JEFFREY W MM
\$ 1,897.11 5 . \$ 2,888.02 \$. \$ 4,583.13 \$.	5 . 5	5 . 5	\$ 1,897.11 \$	\$ 1,897.11	15	88 0.3154%	4091.88	827 SWANDR	CA 90706	BELLFLOWER	17818 REGENCY CIRCLE	GATLIN GERALD W. & MICHELLE C. 310-32-074 H.W.; GATLIN JEPFREY W. MIM.
1,807.11 \$. \$ 2,888.02 \$. \$ 4,583.13 \$	5	5	1,887.11 \$	1,887,11	15-	88 0,3154%	4091.66	837 SWANDR	CA 92504	RIVERSIDE	5234 CARLINGFORD AVE	10-32-073 GERVAIS RICHARD SM
1,697.11 \$ 1,300.74 \$ 2,666.02 \$ 1,667.63 \$ 7,651.50 \$ ~ 13.55.55	\$ 1,300.74 \$ 2,688.02 \$ 1	\$ 1,300.74 \$	•	1,697.11	5	88 0.3154%	4091.88	25	CA 92504	RIVERSIDE	5234 CARLINGFORD AVE	310-32-072 GERVAIS RICHARD R
3,794,23 \$ 2,647,53 \$ 5,372,04 \$ 3,676,47 \$ 15,480,27 \$ 5,317,50	\$ 2,647.53 \$ 5,372.04 \$	\$ 2,647.53 \$	27	3,794.23	× ×	72 0.6308%	8183.72	858 SWANDR	M 94611	FREESOIL	54 WEST FOREST TRAIL	LOFTIS CARLSON & DARLENE E HW
1,097.11 55 2,080.02 55 4,583.13 56 4,583.13	- -	- -	1,687,11 \$	1,897.11	en .	88 0.9154%	4091.88	887	M 48411	FREEBOIL	54 WEST FOREST TRAIL	LOFTIS CARLSON TR &; LOFTIS 310-32-088 DARLENE E TR
3784.23 \$ \$ 5,372.04 \$ 1,468.02 \$ 10,634.29 \$4,001.00	\$ 5,372.04 \$		3,784.23 \$	3,784.23	60	0.6309%	8183.72	879 SWAN DRIVE	AZ 85344	PARKER	873 SWAN DRIVE	310-32-088A BIBBY KAREN L & JAMES C W/H
1,687.11 \$ 1,625.47 \$ 2,686.02 \$ 4,481.62 \$ 10,700.22 \$	\$ 1,625.47 \$ 2,686.02 \$	\$ 1,625.47 \$	50	1,887.11	5	88 0.3154%	4081.88	889 SWANDR	AZ 85344	PARKER	889 SWAN DR	110-32-088 DENVER LOUISE UW
2176.36 \$. \$ 3,081.36 \$ 1,340.32 \$ 6,598.08 \$ 3,337.50	\$ 3,041,36 \$	\$	2,170.38 \$	2,176.36	is.	15 0.3619%	4894.15	885 SWANDR	AZ 85344	PARKER	P O BOX 818	YARBROUGH JOHN DIL &
2,407,17 \$ 619.75 \$ 3,408.18 \$ 1,505.41 \$ 8,140.51 \$ 1,200.00	\$ 619.75 \$ 3,408.18 \$	\$ 619.75 \$	3 61	2,407.17	64	0.4002%	5192,00	919 SWANDR	CA 92532	LAKE ELISINORE	4 BELLA FIRENZE	
2,407.17 \$ \$ 3,406.18 \$ \$ 5,615.35 \$	407.17 \$ - \$	407.17 \$ - \$	2,407.17 \$ -	2,407.17	100	0,4002%	5182.00	917 SWANDR	CA 80232	CULVER CITY	4189 MENTONE AV	310-32-063A PEREZ JULIANA
2407.17 \$ \$ 3,406.18 \$ 1,535.64 \$ 7,350.88 \$ 1,233.400 \$ 2,400.00	\$ 3,408.16 \$		2,407.17 \$	2,407.17	5	0,4002%	5192.00	927 SWANDR	CA 91781	ONTARIO	3217 S NORTH SHORE DR	
\$ 1,127.59 \$ 3,406.16 \$ 3,480.48 \$ 10,423.43	\$ 1,127.59 \$ 3,408,18 \$ 3	\$ 1,127.59 \$	\$ 1,12	2,407.17	5	Ť	5192.00	933 SWANDR	CA 92324	COLTON	11816 RECHE CANYON RO	DEMEREST BARBARA A UN
4,115.73 \$ 5.627.24 \$ 911.52 \$ 10.654.49 \$3.55 1,950.50	\$ 5,827.24 \$		4,115.73 \$	4,115.73	50	7 0.8843%	8877.17	851 SWANDR	AZ 85344	PARKER	860 BAYVIEW	^
3,192.62 \$ - \$ 4,520.25 \$ 7,712.87 \$ 3,712.87	· ·	· ·	3,192.62 \$ -	3,192.62	5	0.5308%	8888.11	924 BAY VIEW DR	AZ 85344	PARKER	924 BAY VIEW DR	310-32-057 HILLCREST BAY INC
\$ 14,803.78	\$ 2,255.51 \$ 5,331.44 \$	\$ 2,255.51 \$	\$ 2,25	3,765.58	5	B 0.6261%	8121.88	914 BAY VIEW DRIVE	CA 92845	GARDEN GROVE	12842 LAMPLIGHTER	1>
1,920.46 \$ 3,138.08 \$ 2,719.07 \$ 4,316.18 \$ 12,083.75 \$ 3317.50	\$ 3,136,08 \$ 2,719.07 \$	\$ 3,136,08 \$	\$ 3,13	1,920.46	50	0.3193%	4142,21	900 BAY VIEW DR	CA 90831	LA HABRA	ISI N HOLGATE	HUTCHENS JACK M & BARBARA JO 110-32-054 TRUSTEES
1,918.41 \$ 2,676.32 \$ 2,717.58 \$ 4,053.68 \$ 11,586.98 \$ 2,834.00	\$ 2,676,32 \$ 2,717.58 \$	\$ 2,678,32 \$	\$ 2,67	1,918.41	60	4 0.3181%	4139.84	894 BAYVEW DR	CA 92382	RUNNING SPRINGS	O BOX 474	110-32-053 JT
2/90.60 \$ 5.375.50 \$ 1,642.96 \$ 10.815.14 \$ 10.815.14	\$ 5,375.50 \$		3,796.60 S	3,786,68	50	0.6313%	8189.00	880 BAY VIEW	AZ 85344	PARKER	BBO BAY VIEW	10-32-052A HOKENSON ROY & MARGARET HAV
1,884,14 \$ \$ 2,638,33 \$ 748,67 \$ 5,250,14 \$ 3317.50	\$ 2,639.33 \$		1,864,14 \$	1,864,14	5	0.3089%	4020.73	872 BAY VIEW DR	AZ 85344	PARKER	355 BAYVIEW DRIVE	10-32-050 PEDREGON VERONICA
1,916.81 \$ 5,2713.90 \$ 1,183.19 \$ 5,813.90 \$ 3,517.50	\$ - \$ 2,713.90 \$	in in	1,918.81 \$	1,916,81	5	3 0.3187%	4134.33	888 BAY VIEW DR	CA 92392	VICTORVILLE	73B3 SVL BOX	110-32-048 SCHAPER MICHAEL J
2,885.86 \$ \$ 4,227.68 \$ 1,287.71 \$ 8,481.37 \$ 3,486.400 \$ 3,000.00 \$ 3,534.00 \$	\$ 4,227.68 \$, ,	2,985.96 \$	2,985,98	~	2 0.4865%	8440,42	858 BAY VIEW DR	AZ 85344	PARKER	858 BAY VIEW	HACKE ELIZABETH A (BENEFICIARY DEED)
Cost Cost Cost	Cost	Cost	Cost	ublio Cast	APS P	% of Sq Fi	PARCEL SIZE	SITUS ADDRESS	ST CODE	CITY	ADDRESS	PARCEL ID Owner Names
ADS Service Vertron Public Vertron Sevice Conversion Private Pro	<u> </u>	<u> </u>	APR Sarvice						ait			

S		\$ 1,197.43 \$	1 1		1,886.88	0.3137%	4070.03	837	\perp	UPLAND	1444 E 13TH STREET	אספרב יויסור מיאי	310-32-148
		•	2.671.69	•	\$ 1,888,99 \$	0.3137%	4070.03	945		STRAWBERRY	P O BOX 53 HWY 108	GOOD DANK & WWAN T TR	310-32-145
_		\$ 2,319.30 \$	2,880.25	£ 1,589.33 \$	\$ 2,041.38 \$	0.3364%	4402.88	5 955 LINGER DR	CA 92705	BANTA ANA	10532 MIRA VISTA DR	SEARS LIVING TRUST	310-32-144
5 2,000.00	\$ 5,593,74	\$ 1,095.09 \$	2,636.54		\$ 1,862.17 \$	0.3096%	IR 4016,49	0 954 CRYSTAL VIEW DE	CA 92340	HESPERIA	P O BOX 401971	NIELSON ROBERT & LORI HAV	310-32-143
\$	\$ 4,588.72	5	2.676,18		\$ 1,691.56 \$	0.3145%	4078.68	3 848 CRYSTAL VIEW DI	CA 92583	MURRIETA	31958 ROSALES AVE	SUTTON GARY & YVONNE HW JT	310-32-142
\$ 3,000,00 \$	\$ 5,548,41	\$ 978.89	2,678.16	- 8	5 1,881.56 5	0.3(45%	A079.69	2 936 CRYSTAL VIEW DE	19 CA 92382	RLINNING SPRING	P O BOX 3812	Gossenberger Lesile S/W JTS	310-32-141
65	\$ 4,566.72	-	2,678.16	5	5 1,881.56 \$	0.3145%	4078.89	4 1830 CRYSTAL VIEW DI	CA 92504	RIVERSIDE	7307 LENOX	18; SHIPLEY JUDITH B LIW ALL AS JT	310-32-140
5	\$ 4,569.72	5	2,676.16		\$ 1,891.56 \$	0.3145%		3 922 CRYSTAL VIEW DI	AZ 86403	LAKE HAVASU C	1891 CHANDLER DR	LAFRENIERE ALBERT O	310-32-139
\$ 5,388,00	5,546.41	\$ 976.68 \$	2,678,16		\$ 1,891.56 \$	0.3145%	A079.88	8 916 CRYSTAL VIEW DE	CA 92708	SANTA ANA	1143 SHARON RD	W/H JT	310-32-138
S 1,350:00 S	\$ 9,346.01	\$ 3,148,48	2,678.16	\$ 1,627.81 \$	\$ 1,881.56 \$	0.3145%	4078.89	2 908 CRYSTAL VIEW DI	ISCA 92382	RUNNING SPRING	PO BOX 2344	ANDERSON ROBERTA A & DONALO A	310-32-137
\$ 4,184,00	\$ 6,145.20	\$ 1,575.48 \$	2,678.16		\$ 1,891.58 \$	0.3145%	JR 4078.89	4 896 CRYSTAL VIEW DE	CA 92054	POWAY	13803 PEQUOT DRIVE	HW JT: MESNA NATHAN J & WHITNEY	310-32-136
8 6735.00 \$	\$ (1,185.40	\$ 2,046.95 \$	5,356.32		\$ 3,763.13 \$	0.6290%	8159.78	4 880 CRYSTAL VIEW DI	AZ 85344	PARKER	680 CRYSTAL VIEW DR		310-32-135A
\$ 4,664.00	\$ 8,835.67	\$ 2,580,41	2,676.16	\$ 1,085.54 \$	\$ 1,841.56 \$	0,3145%	A079.69	8 672 CRYSTAL VIEW DI	AZ 85308	GLENDALE	6042 W POTTER DRIVE	BOND WILLIAM & HARLAYNE HAW JT ECKER GLENN E &; TANGES PATRICIA	310-32-133
5 5,368.00	\$ 10,588,20	\$ 1,456.75 \$	5,356,32		\$ 3,783,13 \$	0.6280%	P 6158.78	4 854 CRYSTAL VIEW DE	AZ 85344	PARKER	862 CRYSTAL VIEW DRIVE		310-32-132A
\$ 4,884,60	6,391.28	\$ 1,821.57 \$	2,674.18	-	5 1,881.58 \$	0.3145%	A079.89	7 B44 CRYSTAL VIEW DR	CA 82507	RIVERSIDE	5838 APPLECROSS DR	PETERS DAN & TERI HAW JT	310-32-130
8	\$ 5,401,34	\$ 911.82 \$	2,678,18		\$ 1,891.58 \$	0.3145%	4079.89	6 B36 CRYSTAL VIEW DE	CA 92356	LUCERNE VALLEY	P O BOX 185	TRUSTEES	310-32-129
\$ 3,800,00 \$	\$ 6,502.91	\$ 1,933.19	2,676.16		\$ 1,891,58 \$	0.3145%	A079.89	4 828 CRYSTAL VIEW DE	AZ 85344	PARKER	828 CRYSTAL VIEW DRIVE	NUTLEDGE CHARLES & 2 JUDY	310-32-128
\$	\$ 4,569.72	5	2,678,16		\$ 1,891,58 \$	0.3145%	A079.88	7 820 CRYSTAL VIEW DR	CA 91307	WEST HILLSY	7518 SHOUP AVE	WAGNER LEAH C	310-32-127
65	6,118.63	\$ 1,546.91 \$	2,678,16		\$ 1,891.58 \$	0.3145%	4079.68	7 812 CRYSTAL VIEW DE	CA 81307	WEST HILLS	7518 SHOUP AVE		310-92-128
en:	\$ 5,409.10	\$ 1,001.78	2,582,98		5 1,824.34 S	0.303%	JB 3834.80	3 804 CRYSTAL VIEW DE	CA 92253	LA QUINTA	79-185 CANTERRA CIRCLE	_	310-32-125
•	\$ 6,026,47	\$ 1,456.75	2,678,18		\$ 1,661.56 \$	0.3145%	- 4078,68	798	CA 92508	RIVERSIDE	8057 ARMAGOSA DRIVE	JT; HARKER TRENT W & LAURA M	310-32-124
\$	\$ 6,908.71	\$ 1,815,65 \$	2,984,87	-	\$ 2,108,19 \$	0.3505%	4547.13	7 788 CRYSTAL VIEW DR	CA 92807	ANAHIEM HILLS	4421 E VALLEY BATE	WILSON LOUIS M & LINDA D JT	310-32-123
\$ 6,051.50	\$ 7,466.66	\$ 675.84	3,863,64		\$ 2,729.00 \$	0.4537%	A 5888.15	3 785 CRYSTAL VIEW DI	CA 92253	LA QUINTA	P O BOX 228	_:-	310-32-1224
5	5 7,796.94	\$ 1,183.18	3,877.29		\$ 2,738.50 \$	0.4553%	5908.84	7 801 CRYSTAL VIEW DI	UT 84157	SALT LAKE CITY	PO BOX 575745 H	ERROR SHARON TRUSTEE	310-92-1204
\$ 6,388,001 \$	\$ 5,130.02	\$ 719.48	2,584.86	,	\$ 1,825.87 S	0.3035%	3937.76	4 808 CRYSTAL VIEW DI	AZ 85344	PARKER	808 CRYSTAL VIEW DR	TL WILL	310-32-118
\$ 16,051.60	10,380,47		5,169,72	, ,	5 3,851.34 5	0.6071%	7875.52	8 827 CRYSTAL VIEW DI	CA 92888	YORBA LINDA	4161 RICARDO DRIVE	LIT STATE OF THE PARTY OF THE P	310-32-1104
\$ 3,317.60 \$ 1,400.00	\$ 5,302.71	\$ 892.16	2,584.86		\$ 1,825.67 S	0.9035%	3937.78	835 CRYSTAL VIEW DI	CA 92548	HOMELAND	30670 WATSON ROAD	KUKURUDA VICTORIA	310-32-118
4	\$ 4,410.53	57	2,584.66		\$ 1,825.87 S	0.3035%	R 3937.76	0 843 CRYSTAL VIEW DI	CA 92830	EL TORO	22082 BROKEN BOW DR	J.L.	310-32-115
**************************************	\$ 4,410.53		2,584,86		\$ 1,825.87 \$	0.3035%	3897.74	0 853 CRYSTAL VIEW DI	CA 91790	W COVINA	118 N MORADA	DNEIL CHARLEST & FLIENT & HAN	310-32-114
	\$ 5,575.01	\$ 1,164,48	2,584.86		\$ 1,825,67 \$	0.3035%	3937.76	4 B61 CRYSTAL VIEW DI	AZ 85344	PARKER	881 CRYSTAL VIEW DR	ARCHER NANCY SUZANNE UM	310-32-113
5 4,664.50		\$ 739,01	2,584,88		\$ 1,825.87 \$	0,3035%	R 3937,76	1 889 CRYSTAL VIEW DI	CA 92881	CORDNA	1143 ANDREW LN	HW Commence in	310-32-112
\$ 1,200,00		\$ 2,259.11		\$ 1,483,14 \$	S (,825.67 S	0.3035%		B777	CA 92591	TEMECULA	41775 CASCADES CT	WARD TROY & TAMMIE HAV JT	310-32-111
66'	\$ 8,258.02	\$ 1,474,21	3,975,76			0.4689%		BES CRYSTAL VIEW D	AZ 85344	PARKER	885 CRYSTAL VIEW OR		310-32-110A
\$ 4,500,00	\$ 8,820,73	\$ 1,836.62	3,975,74		\$ 2,808.05 \$	0.4869%		BOS CRYSTAL VIEW DI	CA 92870	PLACENTIA	531 APACHE DR	SMITH GARY L & SUZANNE A HW JT	310-32-108A
· · · · · · · · · · · · · · · · · · ·	\$ 4,410.53	£0			\$ 1,825,67 \$	0.3035%	-	8 915 CRYSTAL VIEW DE	CA 90808	LONG BEACH	3370 LESS AVE	TRUSTEES	310-32-107
\$ 2,00,000 \$	\$ 11,723.82	\$ 2,284.97		1,483	\$ 3,289,00 \$	0.5468%	7094.00	921 CRYSTAL VIEW DI	CA 92220	BANNING	PO BOX 1297	DAGE WILLIAM H & SHARI D HW JT	310-32-108A
\$		\$ 3,004.52	3,287.05	\$ 1,589.39 \$	\$ 2,307.48 \$	0.3837%	R 4977.00	1 939 CRYSTAL VIEW DI	CA 92211	PALM DESERT	38821 KILIMANJARO DR	12 NT	310-32-104A
Sacr 2:034:00 S3	\$ 10,125.55	\$ 3,356.09	2,584,86	\$ 2,358.63 \$	\$ 1,825.67 \$	0,3035%	R 3837.76	7 947 CRYSTAL VIEW DR	CA 92307	APPLE VALLEY	15040 KINAI ROAD	BILL & CAROL HAW JT	310-32-103
_	5 6,817,56	\$ 1,389.04	2,760.94	\$ 723.55 S	\$ 1,950.03 \$	0.3242%	4205.99	4 955 CRYSTAL VIEW DE	CA 80604	WHITTIER	15944 EAST MILVERN DR	BABCOCK SCOTT D & GRACE D	310-32-102
\$ 3,317.50 \$	\$ 9,003.95	\$ 2,610.24	2,759.30	\$ 1,885.54 \$	\$ 1,848.87 \$	0.3240%	4203.49	8 952 SWAN DR	CA 91788	UPLAND	548 WOODHAVEN COURT	LONG MARK & & JEANNINE HAW JT	310-32-101
\$ 4,001,00 \$	\$ 8,179,13	\$ 2,230.05	2,696.76	\$ 1,347.62 \$	\$ 1,804,70 \$	0.3187%	4108.22	6 944 SWAN DR	CA 92336	FONTANA	5318 ELK COURT	BEAUVAIS ALFRED & SHERYL HW JT	310-32-100
69	\$ 5,580.70	5 979.24	2,686.76		\$ 1,804.70 \$	0.3187%	4108.22	3 936 SWANDR	CA 92633	FULLERTON	1112 W HOUSTON AVE	JOHNSON SANDRA C TRUSTEE	310-32-098
\$ 3,317.50 \$	\$ 5,580.70	\$ 679.24	2,896.78		\$ 1,904.70 \$	2 0.3167%	410A.22	1 828 SWAN DR	CA 91781	ONTARIO	2968 THOROUGHBREAD ST	STEVEN D MIM 4; WOOD BRIAN D SIM	310-32-098
Electric Cost		Cost	Cost Cost		APS Public Cost	% of Sg Ft	PARCEL SIZE	E SITUS ADDRESS	ST CODE	CITY	ADDRESS	WOOD ARTHUR C III MIN	PARCEL ID
Barrata Barratti Priv	Sub-total	Varion Saving	tadan Buhlig	APS Service					diz				

TOTI LOTIMIATE

6		000000	1 0	1	1,100.10	9 3,040,00		0 4 6,000.00	0.4140	10.000	NAX VIEW UN	A 65344	FARREX	1931 E MAX VIEW DR	DANN MILDRED R	310-32-187
	s	1 00 000 I	00 Sec. 407.			2 644 63	2	•		4400	- 1					100
\$ 10,144.50	S	1000年	\$ 1,500,00	\$ 8,844.58	5 1,880.46	\$ 3,544,63	40	ه د		5998.87	NA WƏN XAM ESBI	91711		NE DR	FIGURE SICHAROL & NANCY	40.43
\$ 18,243,72	\$ 1,200,00 \$	8	8	\$ 17,043.72	\$ 2,848.54	\$ 7,088.27 \$	\$ 1,968,81	\$ 5,007.10	.74 0.8325%	Æ 10788.74	907 MAX VIEW DRIVE	CA 92886 1	ORBA LINDA	5732 PLACERVILLE PLACE		310-32-195A
\$ 14,110.86	\$ 4,001.00 \$	\$	\$4 001 00	\$ 10,108.86	2,416.74	\$ 3,544.63 \$	\$ 1,644.84	\$ 2,503.55	67 0.4183%	5389.67	897 MAX VIEW DR	CA 90604 6	NHITTIER	10529 CANTRELL AVE	BLANCHARD KEITH MIM S/B	310-32-193
12,383.81	\$ 4,900.00 \$	\$ 1,100,00	\$ 3,800,00	\$ 7,483.81	1,435,63	\$ 3,544.63 \$		\$ 2,503,55	.87 0.4183%	5398.87	899 MAX VIEW DR	CA 92220 E	BANNING	981 CHARLES STREET	POPLET KHANIM UM	310-32-192
6,040,18	5		6	\$ 6,048.18		\$ 3,544.63 \$	5	\$ 2,503.55	87 0.4163%	5399.87	863 MAX VIEW DR	CA 92881 E	OCBIN NOISSIN	24482 CHAMALEA	EVANS TIMOTHY & & ROBIN A HAW JT	310-32-191
15,145.05	\$ 5.401.00 \$	\$ 1,400.00	\$ 4,001,00	\$ 9,744.05	3,561,46	\$ 3,623.41 \$	69	\$ 2,559.18	87 0.4255%	5519.87	875 MAX VIEW DR	CA 92891 B	OFBIA NOISSIV	24482 CHAMALEA	ALICIA JT	310-32-190
12,172.86	\$ 1,500.00 \$	60股份	S.11. 1,200.00	\$ 10,672.86	2,314,44	\$ 4,017.25 \$	\$ 1,503.42	\$ 2,837.35	85 0.4718%	8119.85	887 MAX VIEW DR	97116	orrest Grove Or	1201 Mount View Dr	Palmer, Dudley	310-32-189A
17,682.67	\$ 1,500,00 \$	9	\$ 1,500.00	\$ 18,492.67	2,844.82	\$ 6,652.80 \$	\$ 1,854.08	\$ 4,840.20	75 0.8048%	10439.75	849 MAX VIEW DR	AZ 85344 8	ARKER	849 MAX VIEW DRIVE F	310-32-188B BOWE JEROME P & KAREN M HW JT	310-32-188
15,957.79	\$	5	5	\$ 15,957.79	3,582.61	\$ 7,246.61 \$	5	\$ 5,118.37	74 0.8510%	11038.74	855 MAX VIEW DR	AZ 85344 8	ARKER	835 MAX VIEW OR	NELSON RONALD & SYLVIA HW JT	310-32-186A
13,245.63	\$ 3,317.50 \$	49	\$ 3,517.50	\$ 9,828.33	2,420.71	\$ 3,423.40 \$	\$ 1,658.29	\$ 2,417.93	19 0.4020%	5215.19	825 NOBLE VIEW DE	A 92860 8	CORDNA	2184 CARTWHEEL CIRCLE		310-32-184
16,938,25	5 6317.50 \$	\$ 3,000.00	\$ 3317.50	\$ 10,018.75	1,434.51	\$ 5,030.93 \$		\$ 3,553.31	0,5008%	7884.08	786 LINGER DR	48111	BELLEVILLE	49071 DENTON RD APT #108	ALL AS JY	310-32-1830
17,179,03	\$ 3,317.50 \$	\$	65	\$ 13,855.53	2,420,66	\$ 5,725.03 \$	\$ 1,686.29	\$ 4,043.55	47 0.6723%	DRIV 8721.47	813 NOBLE VIEW DE	92501	RIVERSIDE	3229 KLUK LANE STE 100 F		310-32-183A
14,895.00	\$ 4,001.00 \$	8	\$ 4,001.00	\$ 10,884.00	3,065.11	\$ 3,167.94 \$	5 1,589.33	\$ 2,251.62	48 0.3744%	4658.48	954 LINGER DR	85344	ARKER AZ	954 E LINGER OR	JT	310-32-182
14,190,30	\$ 9,317.60 \$	en.	3,317,60	\$ 10,880.68	3,098.38	8 3,347.71 \$	\$ 2,070.33	\$ 2,364.48	0.3931%	5098.88	940 LINGER DR	90201	BELL	8417 SHERMAN WAY	MCCURDY RICK J	310-32-181
17,939.01	\$ 5,784.50 S	\$ 1,100,00	5 .4.684.50	\$ 12,155.11	730,76	\$ 6,685,42 \$	én .	\$ 4,728.83	76 0.7863%	10188.76	934 LINGER DR	85344	PARKER AZ	934 LINGER DR	POWERS JANICE	310-32-180A
11,589.88	\$ -4,901,00 S	\$ 2. 800.00	\$ 4,001,00	\$ 6,600.85	976.69	\$ 3,347.71 \$	5	\$ 2,364,46	0.3831%	5099.88	820 LINGER DR	87471	Raseburg Or	1426 Cleveland Loop D/	ESTABROOK CONSTANCE ANN 8/S	310-32-178
10,815,35	\$ 4,417,50 \$	\$ 1,100.00	\$ 1.9,317.50	\$ 6,397.85	685.68	\$ 3,347.71 \$	•	\$ 2,384.46	0.3931%	5099.88	14 LINGER DR	B5344 B	PARKER AZ	914 LINGER DR	A HW JT	310-32-177
14,030.88	S _0,764.00 S	1,400.00	5,366.00	\$ 7,270.89	1,558,72	5 3,347.71 \$		\$ 2,364,46	0.3931%	5098.88	904 LINGER DR	85344	PARKER AZ	904 LINGER DRIVE P	JT	310-32-176
15,094,79	\$ 27,651,50 \$	\$ 1,800,00	\$ 6,051:50	\$ 7,143.28	1,431,12	5 3,347.71 \$		\$ 2,384.46	0.3631%	5088,88	6 LINGER DR	90831 896	A HABRA CA	711 ROSEWOOD LANE	MARICAL THEODORE R & MARY L JT	310-32-175
				2,716.17			•	٠	7	2000.00	- 1_	9000			MANICAL IMECOCORE X & MARY LUI	310-32-174
5712.17	S. 10.			\$ 571917		3 247 71 8		8		5000	_	2			TUROPORR D & MARY I T	
12,480,61	\$ 4,417.60 \$	\$ 1,100,00	\$ 17.50	\$ 8,063.11	822.88	4,184.84		\$ 2,855.56	5 0.4814%	8374.85		80823			JONES SCOTT & CAROLE A	310-32-173A
14,616,60	\$ 5,200.00 \$	6	5,200.00	\$ 11,718.40	3,121.72	4,184.64 \$	S 1,454.88 S	\$ 2,855.58	5 0,4814%	8374.85	4 B74 LINGER	90831 864	A HABRA HGTS CA	134 VILLA RITA DR	FRANCK ROBERT & DANIELLE	310-32-1720
11,347,83	\$ 3,234,00 \$	\$ 1, 600.00	\$ 2,634,00	\$ 6,113.83	973,61	4,184.84 \$		\$ 2,855.58	5 0.4814%	6374.85	2 LINGER DR	85344 852	PARKER AZ	852 LINGER DR P	JOLICOEUR SHANE MIM	310-32-170A
8,566,23	5	65	5	\$ 6,589.23	1,428,01	4,184.84 \$		\$ 2,855.58	5 0.4814%	6374.85	O LINGER DR	80712 840	AKEWOOD CA	2508 DASHWOOD ST	THOMAS DAVID & SUSAN HAW JT	310-32-188A
15,242.72	8,200.00 \$ 8,517.50 \$	3	S 3317.50	\$ 6,725.22	1,013.05	3,347.71 \$	60	\$ 2,364,46	0.3931%	5098.88	O LINGER DR	90712 830	AKEWOOD CA	2508 DASHWOOD U	THOMAS DAVID & SUBAN HAW JT	310-32-168
16,142.62	8 -0,417,50 \$	\$ 100.00	5	\$ 7,725.32	2,013.15 \$	3,347.71 \$		\$ 2,364.48	8 0.3831%	5000.88	0 LINGER DR	92503 820	RIVERSIDE C	4255 JUDY ANN DRIVE RI	JT 1/2: BRANDEL WILLIAM W & GERALDINE JT 1/2	310-32-187
11,105.78	\$ 4,500,00 \$	8	4,500,00	\$ 4,665.76	973.61	3,347.71 \$		\$ 2,364,46	0.3831%	5099.80	2 LINGER DR	92503 B12	RIVERSIDE	4325 LAUREL DRIVE RI	SHIPLEY JUDITH B SW	310-32-166
18,018.26	\$ 9,317:50 \$		\$ 2317.60	\$ 12,701.76	4,058.88	3,347.71 \$	\$ 2,832,71 \$	\$ 2,364.48	0.3931%	5099.88	4 LINGER DR	92544 804	HEMET CA	10795 NICOLE COURT HI	TRUSTEES KATHRYN A	
13,476.58	S. 5217.50 S	5 1,900,00	3/917:50	\$ 6,258.09	2,546.82 \$	3,347.71 \$		\$ 2,384.48	0.3831%	5099.88	LINGER DR	82835 794	FULLERTON CA	2918 REDWOOD CIRCLE FL	ERNEST; ANDERSON ROBERT K	310-32-164
11,400.64	S 4,884.00 S			5 6,716.54	1,400.40 \$	3,115.01 \$		\$ 2,200.53	0.3656%	4748.29	LINGER DR	85344 791	PARKER AZ	181 E LINGER DR P		310-32-162
11,537.28	\$ 12.634.00 \$		2 634 00		2,555,71 \$	2,671.68 \$	\$ 1,788.87 \$	\$ 1,886.89	0.3137%	4070.03	LINGER DR	92892 501	VO OFBIA NOISSIP	Ļ	_	310-32-161
0,000.63	\$ 4417.50 \$	\$ 1,100.00		5 5,479.03	920.35 \$	2,671.68 \$		\$ 1,886,88	0.3137%	4070.03	LINGER DR	92974 811	REDLANDS CA	COURT	7	310-32-160
L	\$ 3,284.00 \$		2,834,00	5 5,472.33	813.65 \$	2,671.68 \$		\$ 1,686.69] _	4070.03	LINGER DR	90808 819	ONG BEACH CA		A HW	310-32-159
12,300.54	\$ 4,217.60 \$	\$ 2,000.00	\$ 3,317.50	6,083.04	1,524.36 \$	2,671.69 \$		\$ 1,868.99	0.3137%	4070,03	LINGER DR	92508 829	RIVERSIDE CA	8900 TAFT STREET RI	CLARK DONALD & MELODY	310-32-158
	\$ 2,634.00 \$			7,110.72	2,552.04 \$	2,871.68 \$		\$ 1,886.99		4070.03	i	92708 838	EFOUNTAIN VALLEY CA	DOD CIRCL	MARGARET HW; FERRALL EDWARD 1	310-32-157
14,683.70	\$ 4,400.00 \$	\$ 7 600.00	\$5. % 3,800.00	10,263,70	1,148.29 \$	5,343.40 S		\$ 3,774.01	0.8275%	8140.10	LINGER DR	80020 853	BROOMFIELD CO	278 AGATE WAY BR	WARREN DELVIN G & GERTRUDE A HW; MESSINA JENNA MW 8/5 ALL JT 2	310-32-158A
10,145.22	\$ 4.517.50 S	\$ 1,200,00	S 17-13,317.50	5,627,72	1,069.04 \$	2,671.69 \$		\$ 1,888.99	0,3137%	4070.03	LINGER DR	85344 867	PARKER AZ	867-E LINGER DR PA	WARD LAURENCE A & MARJORIE JT 8	310-32-154
15,331,80	\$ 7,25(50 \$		\$ 6,051.60	8,080,10	1,242.08 \$	4,007.53 \$		\$ 2,630.46	0.4706%	8105.04	LINGER DR	92887 875	DRANGE CA	BB1 N CLEVLAND STREET OF	CYNTHIA I & MAGANA SANDRA	
15,182.62	\$ 7,018.00 \$	\$		8,164.62	1,328.80 \$	4,007.53 \$		\$ 2,830.46		6105.04	LINGER DR	85344 885	PARKER AZ	O BOX (395	LEGGETT PAMELA A REVOCABLE	
11,017,97	\$ 00.006.1	\$	1,100.00	0,117.37		5,349,98 \$		\$ 3,773.99	0.6275% 1	8140.08	_	90823 903	APALMA CA	_	-	
4,658,68	5				6	2,671,59 \$		\$ 1,886.98		4070.03	1	.			A KAY AND; SEAVER	_
8,714.52	\$ 00.000 \$		1,350,00	8,384.5	2,351.18 \$	2,871.69 \$	\$ 1,454.66 \$	-	0.3137%	4070.03	LINGER DR		STAFF	PALACHIAN RD	ROUSTAN DENNIS R & CATHERINE	
Total Conversion Cost		Private Property Sub-total Private	Privata Property P	Conversion F		Verizon Public Verizon Sevice Cost Cost	APS Service V	APS Public Cost	% of Eq Fl	PARCEL SIZE	SITUS ADDRESS	ZIP SIT	٠ ٢	ADDRESS CITY		PARCEL ID
	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		بنيستنيش جينين سعيان	e de la composition della comp	_	_	_	_				1			·	

	5 1500.00 S	\$ 7,376.33 \$ 10,661.06 \$ 15,655.60	\$ 2,510,85	\$ 8,679.88	2	8		10479.20	2957 DUNLAP DR	MI 48431	LUDINGTON	5388 W JAGGER RD		310-32-242A
100.001 100.00		7,378.33		l	ŀ	Ī	T						_	
100.001 100.00	\$	\$ 7,378.33	•		\$ 1,726.19	\$ 2,687.48	6 0.4435%	5753.46	2971 DUNLAP DR	AZ 85344	PARKER	2971 DUNLAP DRIVE	WILSON JUDY C UW AS JT	310-32-240
1,00,001 \$ 177,850,000 1,00,000 \$ 177,850,000 1,00,000 \$ 177,850,000			,	\$ 4,323.02		\$ 3,053.31	5 0.5077%	6585.65	2975 DUNLAP DR	CA 92673	SAN CLEMENTE	2948 VIA BLANCO	┙	310-32-239
1100.00: \$ 27.25.00 	6	\$ 7,852.58		\$ 4,860.74	5	\$ 3,291.85	4 0.5473%	7100.14	2979 DUNLAP DR	CA 92873	SAN CLEMENTE	2948 VIA BLANCO		310-32-238
1100.00	\$ 00,150,8	\$ 6,177.81	\$ 551.45	\$ 3,287.42	5	\$ 2,328.94	8 0,3872%	5023.26	2988 DUNLAP DR	CA 92071	SANTEE	8329 LAKE CANYON ROAD	_1	310-32-237
1100.00	\$ 4,900.00 \$	\$ 5,485.96	\$ 945.43	\$ 2,649.33	64	\$ 1,871.20	7 0.3111%	4035.97	2978 DUNLAP DR	CA 91773	SAN DIMAS	415 PORTOLA STREET	THURMAN ROBERT & KATHLEEN HAW	310-32-236
	\$	\$ 5,844.58	\$ 1,324.05	\$ 2,648.33	5	\$ 1,871.20	0.3111%	4035.97	2970 DUNLAP DR	ID 83839	MARSING	P 0 BOX 71	_ 1 _	310-32-235
10 10 10 10 10 10 10 10 10 10 10 10 10 1	\$	\$ 4,427.25		\$ 2,584.88	5	\$ 1,832.56	9 0.3047%	3952.69	2862 DUNLAP DR	Mt 49610	ACME	P O BOX 432	MCDONNELL RONALD J & PHYLLIS	310-32-234
The state of the s	\$1.	\$ 4,421,77	55	\$ 2,591.45	5	\$ 1,630.32	0.3043%	3947.80	2973 OTIS CT	CA 90650	NORWALK	13811 MAYPORT AVE		310-32-233
2,000.00	6	\$ 5,045,44	\$ 1,524.91	\$ 2,848.33	\$	\$ 1,871,20	7 0.3111%	4035.97	2977 OTIS CT	CA 92591	TEMECULA	40735 LA COLIMA	THOMPSON KENT A & TERESA B HAW	310-32-232
\$ 7,200.00 \$ 42 7,251.50 \$	\$ 6,051:50	\$ 7,710.42	\$ 999.24	\$ 3,833,19	5	\$ 2,777.89	0.4616%	R 5981.80	2987 OTIS OT PARKER	MI 48827	EATON RAPIDS	10765 BARNES RD		310-32-231
	\$ 8,735.00	\$ 8,723,25	\$ 1,597.50	\$ 3,639,18	\$ 915.94	\$ 2,570.33	0.4274%	5543.80	918 NOBLE VIEW DR	CA 82373	REDLANDS	651 CENTER CREST		310-32-230
, i	5	\$ 6,721,89	S	\$ 3,839.35	\$	\$ 2,782.34	B 0.4826%	8001.18	eta NOBLE VIEW DR	MI 48431	LUDINGTON	5373 W FIRST STREET	-	310-32-229
00.00	\$ 700.00	\$ 6,265.33	\$ 1,225.18	\$ 2,953.86	\$	\$ 2,086,29	0.3469%	4499.89	802 NOBLE VIEW DR	CA 82274	THERMAL	P O BOX 1413		310-32-228
	400.00	\$ 9,880.71	\$ 2,888.29	\$ 2,953.86	\$ 1,852.27	\$ 2,088,29	0.3489%	4498.59	892 NOBLE VIEW DR	CA 90808	LONG BEACH	4735 E WAHWOOD ROAD		20-20-01
15 6 3 100 00 \$ 5 5 8 15 50 S	\$ 18,051.50	5 6,053,20	\$ 1,013.05	\$ 2,953.66	5	\$ 2,086.29	0.3469%	4489.88	882 NOBLE VIEW DR		-12	29214 OLD WRANGLER RO.	JONES HAROLD ERIC & KATHIE JO	310-32-220
\$ 250,000	S4". 6,735.00	\$ 7,705.48	\$ 2,665.33	\$ 2,953.86		\$ 2,086,28	0.3469%	4499.89	8/4 NOBLE VIEW DR	AZ 85344		STA MUBICE VIEW DIX		
	\$6,051,50	5 7,408.26		\$ 2,853.88		. [Т	\dashv	98		DAD NO	NYA NOBI E VIEW DE	POWELL RICHARD L & HELENTHW	310-32-225
がいると					Ì						_	13122 OLYMPIA WAY		310-32-224
3.200.00 \$	\$ 0.051.50	\$ 7,474.58	\$ 2,537.44	2,893,48	`	-			858		 _	3224 HILL VIEW DRIVE SOU	4	310-32-223
	00,005,1	02.896.4	\$ 1340.53		\$ 814.80				848	CA 92315	BIG BEAR LAKE	190823	HARVEY HOLLIS I	310-32-222
	5.368.00	\$ 6,731.68	\$ 1,691.42	\$ 2,953,93	in	5	0.3469%	4500.00	842 NOBLE VIEW DR	CA 92058	OCEANSIDE	4485 SUNBURST DR	MW JT	310-32-221
	5 5 368.00	S 8,177.48	\$ 3,137.21	\$ 2,953,93	٥	\$ 2,086,34	0.3469%	4500,00	834 NOBLE VIEW DR	CA 91710	CHIND	4091 CARROLL COURT	JT	310-32-220
in	5.5.5.8.00	\$ 6,277.97	~	\$ 2,853.93	•	\$ 2,086,34	0.3468%	4500.00	824 NOBLE VIEW DR	CA 92557	MORENO VALLEY	25681 PALMWOOD DR		310-32-218
	\$ 6,735.00 \$	\$ 8,828.32	\$ 1,265.81	\$ 4,430.90		\$ 3,128.51	0.5203%	8750.00	M B18 NOBLE VIEW DR	CA 82504	Riverside	17051 Mackingbird Canyon Ro	A Orisham, Anna	310-32-218A
	\$ 6,735.00 (5	5 12,887.25	6	\$ 6,384.47	•	\$ 4,518.37	9 0.7509%	╁	BOS NOBLE VIEW DR	AZ 85751	TUCSON	P O BOX 31417	A ROBLES FRANK I & JAN HAW JT	310-32-2164
\$ 4,004.50	\$ 4.884.50 \$	\$ 10,080,38	\$ 2,582.84	\$ 3,346,40	\$ 1,718.33	\$ 2,391,76	0.3877%	5150.61	885 NOBLE VIEW DR	CA 92804	IRVINE	5081 NORRIS ST	McClean, John	310-32-215
400.00 \S. 13 0,451.50	5	\$ 8,741.84	\$ 1,701.80	\$ 2,953.85	5	\$ 2,088.29	6 0,3468%	4499.88	901 NOBLE VIEW DR	CA 91324	NORTHRIDGE	18729 LEMARSH ST	HEGLER MELVIN E	310-32-214
4 300 00 S and ass 00		\$ 10,728.43	\$ 1,037.66	\$ 5,879.24	5	\$ 4,010.50	9 0.8888%	8850,19	911 NOBLE VIEW DR	CA 92008	CARLEBAD	3551 AMER PLACE		310-32-213A
14:7	\$ 1,550,00 \$	\$ 9,920.63	\$ 2,960.79	\$ 2,839.12	\$ 2,115.67	\$ 2,005.25	9 0,3334%	4325,09	929 NOBLE VIEW DR	CA 92234	CATHEDRAL CITY	88440 TAHOUTZ RD#4	ODDOMAN JERRY & KELLY HW JT	310-32-211
\$ 1,300.00	\$ 13,300.00	\$ 7,553.40	\$ 1,858.35	\$ 2,691.10	\$ 1,105.25	\$ 1,900.70	0.3160%	4089.60	943 NOBLE VIEW DR	CA 92867	ORANGE	2338 N EATON OT	STEIN ROBYN L BW	310-32-210
100	5.	\$ 4,526.37		\$ 2,652.75	4	\$ 1,873.82	8 0,3115%	4041.18	934 MAX VIEW DR	AZ 85280	SCOTTSDALE	9019 E GRAY RD	POOLE RANDY R & LISA T HAW JT	310-32-209
6	S 4,884,50 S	\$ 6,226,27	\$ 1,800,35	\$ 2,707.58	65	\$ 1,912.34	1 0.3180%	4124.71	922 MAX VIEW DR	AZ 85344	PARKER	923 MAX VIEW DR	DAVIS EARL & ERNA HAV JT	310-32-208
大学 大学 はない からい からい	のない。	\$ 4,619.92	5	\$ 2,707.58		\$ 1,912.34	0.3180%	4124.71	912 MAX VIEW DR	H CA 92848	HUNTINGTON BCH	18922 FLAGSTAFF LANE	TRUSTEES	310-32-207
\$ 700.00 \$ 3435.00	\$ 6,735.00	\$ 4,616,62	5	\$ 2,707.58	5	\$ 1,812,34	0.3180%	4124.71	902 MAX VIEW DR	H CA 92848	HUNTINGTON BCH	18922 FLAGSTAFF LN		310-32-206
大学 大学 のできる できる	\$ 15.00	\$ 4,819,92	\$	\$ 2,707.58	5	\$ 1,812.34	0.3180%	4124.71	894 MAX VIEW DR	CA 91324	NORTHRIDGE	18729 LEMARSH	HEGLER MELVIN EDWARD S/8	310-32-205
4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		\$ 4,619,92	\$	\$ 2,707.54	-	\$ 1,812.34	0.3180%	4124.71	886 MAX VIEW DR	CA 91343	NORTH HILLS	15833 MALDEN ST		310-32-204
\$ 800.000 \$	\$ 5.388.00	\$ 5,610.43	\$ 990.51	\$ 2,707.56	57	\$ 1,912.34	0.3180%	4124.71	878 MAX VIEW DR	CA 92065	RAMONA	28045 MATLIN ROAD	TWARDOKS HOWARD A & HELEN F	310-92-203
\$ 600.00 \$ 6.65 50	\$ 5 6,051,50	\$ 5,624.84	\$ 1,004.82	\$ 2,707.58	\$	\$ 1,912.34	0.3180%	4124.71	866 MAX VIEW DR	CA 92627	COSTA MESA	TALL CON CUENCY WAT	ㅗ	
	200	*	\$ 1,084,03	\$ 4,079.26		5	1	8214.31	2		NVENDIUS	1944 AS ADSNAS WAY		310-32-202
9 10 10 10 10 10 10 10 10 10 10 10 10 10	3.017.00	2 14,552	1	\$ 0,103,07	6 1,210,10	ľ	T	0.00		?	5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	1975 M. I. INDEN ST	KINCAID ANNETTE M	310-32-201
		7		8 486 07		•		B491 83	2900	Ċ.	FOUNTAIN VALLEY	9700 LA CAPILLA AVE		310-32-200
S. C. S.	\$ 337.50	5	S	1		64		10157.28	2628	CA 91008	ARCADIA	250 E POREST AVE	WIGLEY PHILIP S & INA L HW JT	310-32-199
\$ 1700.00	\$ 1,700.00 \$	\$ 15,490.01	5 3,922.35	\$ 5,123.96	\$ 2,824,68	\$ 3,819,02	0.8017%	7805.81	937 MAX VIEW DR	CA 90712	LAKEWOOD	3802 FAIRMAN	STRONG ROBERT & BONNIE HW JT	310-32-198
Private Property Subdote Private Total Conversion - Transhing: 4785 Coat 11.2	Frivate Property P	Conversion	Cost Cost	Cost	Cost	APS Public Cost	% of 8q FI	PARCEL SIZE	SITUS ADDRESS	ST CODE	сту	ADDRESS	D Owner Namas	ARCEL ID

CUSI ESHMAIE

										- victorial	e haan dalatad from lhis :	ble parcel he	maricionis iharafora	arrive a hee dealload to voluntari	Percel 110,122,274 is numer had a Revenue who has declined to voluntative edictors. Horefore this parcel has been detailed from this spreadsheet.	
						anversion Service Area.	Ð	tuded from the Una	Traci C was exc	age for Tract B as	This spreadsheel Includes only aquare lootage for Tract B as Tract C was excluded from the Underground	ipreadsheel!		properly, properly record includes Traci B and Traci C.	Parsel 91312703 is centrally assessed pro	NOTES:
\$ 2,859,435.15	\$ 851,429.92	\$ 105,887.92	\$ 685,782.00	Total										stance	*Qualified for Financial Assistance	
\$ 3,317.50	3,317.50	\$ 14 mm	\$ 12,317.50	\$ 9,370.99	\$ 2,822.01	\$ 2,625.60	\$ 1,974,14	\$ 1,854,44	0.3083%	3999.82	2801 HILLCREST DR	85344	PARKER AZ	DRIVE	SWAN CHARLES JOSEPH S/S	*310-32-284
\$ 7,535.00	7,535.00	\$11.1.	\$ 6,735.00	\$ 7,788.88	\$ 1,183.16	\$ 3,877.28		\$ 2,738.50	0.4553%	DR 5908.64	BOI CRYSTAL VIEW DR	84157	SALT LAKE DITY UT	PO BOX 575745 H 9	"310-32-120/ERROR SHARON TRUSTEE	"310-32-120
\$ 1,100.00		\$ 3 17 77100.00	۳,	\$ 7,855.31	\$ 2,275.68	2,627,17	\$ 896,70 \$	\$ 1,855.55	0.3086%	R 4002.21	2874 MANOR VIEW DR	85344	PARKER AZ	2674 MANOR VIEW DRIVE P	"310-32-028 RICKWOOD	"310-32-028
\$ 2,071,367,65	5 863,382.42	\$ 100,467.02	\$ 696,914.60	\$ 1,000,005.23	\$ 383,808.28	861,547,20	\$ 161,108.46 \$	\$ 601,441.29	100,0000%			1				
\$ 0,330.14	* T.	\$	\$ 1000	\$ 6,330.14	\$	\$ 3,709.66		\$ 2,620.26	0.4357%	5651,60	2989 DUNLAP DR	95014	PHOENIX AZ	OME	HILLCREST WATER COMPANY: BARBARA DUNLAP	91312703
\$ 11,245,25	5		10 mg	\$ 11,245.25	\$	\$ 6,590,46		\$ 4,654.79	0.7736%	10039.86	2785 HILLOREST BAY	85344	PARKER AZ		HILLOREST BAY INC	310-32-273
\$ 4,729.47	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5	8	\$ 4,728.47		\$ 2,771.78		\$ 1,857.69	0.3255%	<u> </u>	2789 HILLCREST BAY	85344	PARKER AZ	924 BAY VIEW DRIVE P	HILLOREST BAY ING	310-32-272
\$ 10,901.70	3,017,50	500.00	\$ 3,317.50	\$ 7,084.20	\$ 1,308,70	\$ 3,364.24		\$ 2,380,28	0.3974%	5155.52	2773 HILLOREST BAY	91709	CHINO HILLS CA		WALSH GREGORY K & MICHELLE L	310-32-271A
\$ 12,014.28	\$ 16.4.17.50	800.00	\$ 2317.50	\$ 7,868.78	\$ 1,232,10	\$ 3,805.93		\$ 2,756.73	0.4587%	5950.27	2775 HILLCREST BAY	25344	PARKER AZ	2775 HILLCREST DRIVE P	SHAMNURG BETH S LW &; JOHNSON JEFFREY G UM AS JT	310-32-270A
\$ 15,643.06	\$ 488.00	\$ 1,100,00	5.368.00	\$ 9,175.08	\$ 1,138.31	\$ 4,711.24		\$ 3,327,51	0.5533% \$	7177.07	2779 HILLCREST BAY	92220	BANNING CA		310-32-289A DAGE WILLIAM H & SHARI D H/W JT	310-32-288A
\$ 19,823,47	7,266.00	\$ 1,900.00	\$ -5,368.00	\$ 12,555.47	\$ 1,474.21	\$ 6,494.35		\$ 4,588.91	0.7827% \$	8893,45	2785 HILLCREST DR	85344	PARKER AZ		310-33-267A THURMAN JIM UM	310-33-287A
\$ 13,320.58	7,268.00	\$ 1,900.00	\$ 3.5,360.00	\$ 6,052.58	\$ 1,572.54	\$ 2,625.60		5 1,854.44 3	0.3083% \$	3999.82	2793 HILLCREST DR	05344	PARKER AZ		STEWART MICHAEL & MELANIE A JT 2793 HILLOREST DR	
\$ 12,664,48	\$ 1.4.9,317.50		\$ 3,317.60	\$ 9,376.99	\$ 2,922.81	\$ 2,625.60	5 1,974.14 \$	1,854,44	0.3083% \$	3988.82	2801 HILLCREST DR	85344 2	PARKER AZ	2801 HILLCREST DRIVE P.	SWAN CHARLES JOSEPH S/8	310-32-264
\$ 6,775.36	\$ 447.50	1,100.00	\$ 3,317.50	\$ 6,357.00	\$ 677.62	\$ 2,625.60		1,854,44	0.3083% \$	3999,82	2808 HILLCREST OR	92553	MORENO VALLEY CA	23147 DONAHUE COURT M	M & LINDA E HW &;	
\$ 4,460,04			•	\$ 4,480.04	5	\$ 2,425.60		\$ 1,854.44 \$	0.3083% \$	3999,82	2815 HILLCREST OR	92851	AGUNA BEACH CA		BOLTON BRIAN	
\$ 4,480.04	-			\$ 4,480.04		\$ 2,625.60 \$		5 1,854.44 \$	0.3083% \$	3998.62	2823 HILLCREST DR	92851	LAGUNA BEACH CA	#2 VISTA DEL SOLE	BOLTON BRIAN	
\$ 9,212.00			\$ 1,000.00	\$ 8,212.00	\$ 864.59	3,838.40	627.35 \$	\$ 2,781.66 \$	0.4825% \$	5996.73	2835 HILLCREST DR	86301 21	PRESCOTT AZ	718 BLACK DRIVE PF	GRESETH LARRY & LAURA S HAW JT	310-32-280A
\$ 10,720.08		\$ -3,000.00 \$ 4,000.00	5 1,000.00	\$ 8,720.08	5	3,636.40		5 2,761,66 \$	0.4625% \$	5999,73	2837 HILLCREST DR	92382 26	RUNNING SPRINGSCA	P Q BOX 3812	310-32-258A BULTSMA TED & CARLA HW	310-32-259A
\$ 10,078.97	\$ 3,317.60	5	\$ 3,317.50	\$ 6,781.47	1,461.66	\$ 2,625.60 \$	819.75 \$	1,854.44 \$	0.3083% \$	3999.82	2851 HILLCREST OR	82230 26	CABAZON CA	P O BOX 80	JOHNSON GERALD & SHAWNA HAV	310-32-257
\$ 12,893.47		1,900,00	\$ 5,368,00	\$ 6,425.47	\$ 945.43	2,625.60		1,854.44 \$	0.3083% \$	3998,82	2855 HILLCREST DR	85344 26	PARKER AZ		RADVANSKY GEORGE & DEBBIE HAW	310-32-256
\$ 15,470.31	\$ 10,195,00	\$ 3,400.00	\$ 8,795,00	\$ 5,335.91	\$ 855.27	2,625,60		1,854.44 \$	0.3083% \$	3989.92	2863 HILLOREST DR	85344 25	PARKER AZ	BOTH LAKEVIEW DRIVE PA		1
\$ 4,487.70		S ATTENDED	を記れる	\$ 4,487.70		2,630.09 \$	1	1,857.81 \$	T	4008.88	2871 HILLCREST DR	86406 28	AKE HAVABU CTYAZ	RIVE		
\$ 15,288.45	\$ 1,100.00	5 S	\$ 100.00	\$ 14,188.45	1,712.37	6,737.61 \$	977.75 \$	4,758.72 \$	0.7912% \$	10284.02	2875 HILLOREST DR	85344 28	ARKER AZ	2875 HILLCREST OR PA	EE L HW	
\$ 18,458.80		3-6/-1-100.00		\$ 14,041.40	702.59	7,817.42 \$		5,521,39 \$	0.9180% \$	11909.00	BB HILLCREST DR	82399 2889	Yucispa CA			310-32-252
\$ 7,701.26			۳.			4,513.45 \$	-	3,187.61 \$	0.5300% \$	6875.75	2891 HILLCREST DR	85344 28	PARKER AZ	٤	5	310-32-251A
\$ 14,040.70	5 -3,317.50		ŝ	\$ 10,723,20	\$ 1,901,45	4,484.18 \$	L	3,153,02 \$	0.5242% \$	8800.70	2915 HILLOREST DR	81767 29	POMONA CA		MADRIGAL JOHN F & HELEN E:	310-32-249
\$ 33,367.26	\$ 8,051,50	; . ; :	\$ 6,051.50 \$	\$ 27,315.76	\$ 1,598.14	14,535.42 \$	l		1,7089% \$	22143.16	2925 HILLCREST DR	90630 29	CYPRESS CA	8884 VINAL HAVEN CT CY		310-32-248
5	8 3,317.50				1,493.65	9,057.37	819.75 \$	8,387.15 \$	\$.0838% \$	13797.93	2922 HILLCREST DR	85344 29	PARKER AZ	L	5	310-32-247A
\$ 18,593.47	F. 1			12,757.50	\$ 1,517.48 \$	5,881,50 \$	1,204.55 \$	4,154.08 \$	0.8807% \$	8859.84	2943 DUNLAP DR		LOS ALAMITOS CA	3152 WALKER LEE DRIVE LO	M LAURENCE	310-32-245A
Total Conversion	ub-total Private	Private Property Private Property Sub-local Private	Private Property	Cost	Verizon Savica Cost	Vertzen Publia V	APS Service V	APS Public Cost	% of Sq Ft AF	PARCEL SIZE	SITUS ADDRESS	ZIP SI	×	ADDRESS		PARCEL ID
-	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	المتناقبين الرام	1	_	_	_	_	_				1				

Parcel 310-32-274 is owned by La Pax County who has declined to voluniarily pericipate, therefore this percel has been deficied from his apreadance).

Apr-09

Total Squara Footaga 1287248.74

	ı	
LATION STALLITED	LLCREST BAY UC	TADES INC

310-32-037	310-32-036A	310-32-035A	310-32-034A	310-32-033	310-32-032	310-32-031 J	310-32-030 W	310-32-028 W	310-32-028	310-32-027 D	310-32-028	310-32-025	310-32-024	310-32-023	310-32-022	310-32-021	310-32-020	310-32-019	310-32-018 C	310-32-017	310-32-016	310-32-015	310-32-014A	310-32-012A	310-32-011	310-32-010	310-32-009	310-32-008	310-32-007	310-32-008	310-32-005A	310-32-003 FI	310-32-002	PARCEL IDON
THOMPSON EILEEN K TRUSTEE	LEOBETTER LINDA	DELIA HW JT	TRUSTEES	DALTON GALE M & EILEEN JT	JOGOLDIE JUNE SAV JT	JOGOLDIE JUNE SAW JT; 2888	WESTRA JOHN JACOB & WESTRA	VICALVIN NYLES AS CO-TRUSTEES	RICK WOOD	DES: DEUEL NANCY LEE TRUSTEES	STIREWALT CHARLES E SM	SHANNA S HAV	SLONE CLARK & PIPER HAV	SLONE CLARK & PIPER A HAV	FRAZIER MAC & JOYCE HW JT	HW TRUSTEES	HAW TRUSTERS	BUTUL	SHERRY SAV JT	<u>L</u>	D & ZELMA M	L	TRUSTEES		HW COUNTY C & ROBERTA A		CARTWRIGHT LARRY	PEDREGON VERONICA	1	PEDREGON VERONICA	JT	LJENNIFER C/O	FLETCHER JENNIFER D	Owner Names
762 BAY VIEW DR	2944 NOBLE VIEW DR	2948 NOBLE VIEW DR	2952 NOBLE VIEW DR	2910 MANOR VIEW DR	2904 MANOR VIEW DR	3898 MANOR VIEW DR	2882 MANOR VIEW DR	2882 MANOR VIEW DR	2874 MANOR VIEW DR	2858 MANOR VIEW DR	2880 MANOR VIEW DR	2852 MANOR VIEW DR	2844 MANOR VIEW DR	2834 MANOR VIEW DR	2828 MANOR VIEW DR	2814 MANOR VIEW DR	2800 MANOR VIEW DR	781 BAY VIEW OR	791 BAY VIEW DR	797 BAY VIEW DR	805 BAY VIEW OR	811 BAY VIEW DR	817 BAYVIEW DR	831 BAY VIEW DR	837 BAY VIEW DR	843 BAY VIEW DR	849 BAY VIEW DR	855 BAY VIEW DR	861 BAY VIEW DR	887 BAY VIEW DR	879 BAY VIEW DR	885 BAY VIEW DR.	897 BAY VIEW DR	SITUS ADDRESS
4230.81 0.3261%	7818.48 0.6027%	7818.48 0.5027%	9638.22 0.7490%	9045.17 0.6973%	5482.27 0.4211%	5008.88 0.3860%	4552.28 0.3509%	4174.08 0.3218%	4002.21 0.3085%	4002.21 0.3085%	4002.21 0.3085%	4002.21 0.3085%	4002.21 0,3085%	4002.21 0.3085%	4252.47 0.3278%	4629.81 0.3589%	4838,41 0.3578%	4303.32 0.3317%	4179.42 0.3222%	4107.84 0.3187%	0.3049%	4292,85 0,3309%	7108.56 0.5480%	0.5978%	5577.77 0.4300%	5888.85 0.4523%	5778.06 0.4453%	5356,75 0.4129%	5014,76 0.3866%	4872,78 0.3802%	8319.61 0.6413%	4542.54 0.3502%	7333.52 0.5853%	PARCEL SIZE % of Sq
\$. 2,157.71	\$ 3,987.41	3,987,42	<u> </u>	\$ 4,813,04	\$ 2,785.78	\$ 2,553.50	65	\$	\$ 2,041.13	-	\$ 2,041,13	<u> </u>	2.04113	-	\$ 2,158.76	5 2,361.20		\$2,194,69						_			\$ 2,945.79			\$ 2,383,12		_		Total Primary Extension Cost Entension Cost
\$ 1,078.86	\$ 1,993.71	\$ 1,983.71	\$ 2,457.75	\$ 2,308.52	\$ 1,392.68	\$ 1,276.75	\$ 1,180.83	\$ 1,084.38	\$ 1,020.58	\$ 1,020.66	\$ 1,020.56	\$ 1,020.56	\$ 1,020.56	\$ 1,020.58	\$ 1,084.38	\$ 1,180.60	\$ 1,183.05	\$ 1,097.35	\$ 1,065,75	\$ 1,047.52		\$ 1,094.63	\$ 1,812.68	\$ 1,977.38	\$ 1,422.33			\$ 1,385,67	\$ 1,278.76	\$ 1,181.56	\$ 2,121.50	\$ 1,158.35	\$ 1,870.05	APS Total Primary Extension Cost per Sq. FT
\$ 1,078.88	\$ 1,963.71		\$ 2,457,75	\$ 2,306.52	\$ 1,392.88	\$ 1,276.75	\$ 1,180.83	\$ 1,064.39	\$ 1,020.58	\$ 1,020.56	\$ 1,020.56	\$ 1,020.56	\$ 1,020.56	\$ 1,020.58	\$ 1,064.38	\$ 1,160.60	\$ 1,183.05	\$ 1,007,35	\$ 1,065.75	\$ 1,047.62			\$ 1,812.68	\$ 1,877.38	\$ 1,422.33	\$ 1,486.05			\$ 1,278.78	\$ 1,191.56	\$ 2,121.50		\$ 1,870.05	Varizon Total Primary Extension Cost per Sq. FT
\$ 807.44	\$ 1,492,13	\$ 1,492.14	\$ 1,838.43	\$ 1,726.25	\$ 1,042.46	\$ 855.55	\$ 888.79	\$ 796.61	ai î	\$ 763.81	\$ 763.61	\$ 769,61	\$ 763.61	\$ 783.81	\$ 811.57	\$ 883.50	\$ 885.42	\$ 821.28	797.63	763.66	5- 754.92	5 619:24	\$ 1,356.05	\$ 1,479.82	1,064.50	\$ 1,119.67	1,10235	1,022,32	957.05	\$	5 1,587.78	86,63	\$ 1,399.58	APS Total. Secondary
	\$ 17.48	\$ 17.48	6	6	\$	\$	es.	60 () 4 () 4 ()	\$	9	6.85	\$ 8.95	\$ 8.95	8 95	8.51	\$ 10.35	\$ 10.37	S 6.62 8	\$ 4.34 \$	\$ 918 5	9	9.60	\$ 75.88 \$	\$12 317.34	5 1247	271	\$ 12.81 5	\$ 11:98	\$ 1127	\$ 10.45	\$		\$ 16.39 \$	Verizon Total J Secondary V Secondary V Extension C
815,69	1 507 39	1:507.36	858.23	1,743.80	1,053.12	965.31	877.67	804.75	3771.62	771.02	771.62		2. 7.	\$ 774.62 \$		892.62 \$	894.47		805.78	792'00 5	762.04		1 970.52 3	1495.05		\$ 1 131 12 1		1,032.77	966.84	\$ 900:90	1,604.01	875.78	\$ 71,413.69	Vertzon Vertzon Public Service Cost Cost-labor & labor & material material
759.25	\$1 -1,403,08	\$ 1403.00	\$ 1,729.65 S	\$ 1,623.23 \$	1,053.12 \$ 980.25			748.07		\$ 718.23 \$	12. 718.23 S	5 718.23 S	718.23	718.23	5 783 14 \$	5.	832.58 \$		750.03 \$	737.20 \$	709.87			\$ 41,391.60		\$ 1,052,85 S	\$ 1,038.56 \$	961/31	899.64		_		8	erizon eryice Cost bor &
\$ 3,317.50	 -		\$ 6,735.00	3,317.50	3,317.50	\$ 500,00	,	\$ 2,634,00		4,001.00		1,700.00	\$ 2,034.00	\$ 4,684.50	2,634.00	3,317.50		4,001.00	850.00		880.00	3,317.50	700.00			3,317.50	2,834.00	\$ 2,634.00	\$ 1,950.50	\$ 850.00	\$ 2,634.00		.00	Secondary Private Property Electric
\$		5			800.00	\$		én ,	<u>د</u> م	\$ 2,000.00		én '	én '			S		\$ 1,400.00					\$	•	<u>د</u> م	en	\$		én ,		\$ 1,650.00	5	em	Secondary Private Property Trenching
\$ 3,317.60					\$ 4,117.50	\$	13.1		\$ 1,100,00	\$ 6,001,00		1,700,60	\$ 2,634.00	\$ 4,884.60	\$ 2,634.00				850.00	· Andrews	\$ 880.00	3,317,50	\$ 700.00	\$ 6,635.00		3,317.50	\$ 2,634,00	\$ 2,634,00	\$ 1,850.50	\$ - 850.00	\$ 4,484,00	\$	\$ 2,634.00	Saccindary Sub- total Private It
\$ 7,867.08	\$ 16,142.60	\$ 16,142.52	\$ 17,089.35	\$ 13,044.12	\$ 8,881.28	\$ 5,884,07	\$ 4,885.24	\$ 7,122.53	\$ 6,403.73	\$ 10,304,73	.1	\$ 6,003.73	\$ 6,637.73	\$ 8,688.23	\$ 7,206,65	\$ 8,286.12	\$ 4,888.04	\$ 10,028.53	5 5,144.28		1			\$ 14,973.86	\$ 8,631.99		të.	*	64	64	\$ 19,430.40		\$ 10,520.02	TOTAL Utility Con- version Cost

B. 117.14	4	6) (uu.uu	ē	9.18 - \$ 782.00	6	60 3 /84.04	0 \$ 1,047.60	19 \$ 1,047.60	\$ 4 72,085	4108.22 0.3167%	828 SWAN DR	SNR	310-32-088
•	•	•	-			e L				100	4 100:11	OZO OZONO	SIERRA HAW JT &; POOL EARLINE	310-32-085
\$ 10,618.73	6 0	\$ 2,400.00	\$ 4,001.00	8 5 737.25	€0	647		<u></u>	\$ 1.047	4		3	1/2; STEINER JOHN M & PEGGY J	
\$ 11,651.73	00 \$ 7,134.00	\$ 4,500.00	\$ 2,634.00	6 \$ 737,25	64	04 \$ 0.18	80 5 784.04	0 \$ 1,047,80	19 \$ 1,047.60		4108.22 0.3167%	10	WANDREA TR 1/3 INT: GLYNN DAVID	310-72-084
\$ 4,417.73	69	59	\$	6 \$ 737.25	64	04 \$ 8,18	50 \$ 784.04	0 \$ 1,047.60	1,047.80	7% \$ 2,095.19	4108.22 0.3187%	98	INT; WILKE RICHARD J & ANDREA WITR 1/3 INT; GLYNN DAVID M &	310-32-083 W
\$ 7,051.73	\$ 2,634.00	65	\$ 2,634.00	8 \$ 737.25	18 \$ 792.06	04 \$ 9.18	50 \$ 784.04	0 \$ 1,047.60	9 \$ 1,047.60		4108.22 0,3187%	8	LAMBROSE GEOFFREY WILLIAM	310-32-082
\$ 8,974.01	\$ 3,317.60	4	\$ 3,317.50	\$ 943,98	178 \$ 1,014.16	S	50	5 \$ 1,341.35	1 \$ 1,341.95	5% \$ 2,882.71	5280.21 0.4055%		LAMBROSE GEOFFREY WILLIAM	310-32-061
\$ 7,210.51	\$ 2,634,00		\$ 2,634.00	3 \$ 763.75	\$ 820.53	22 \$ 9.51	8 12.22	\$ 1,085.25	0' \$ 1,085,25	1% 5 2,170.50	4255.88 0.3281%		STEWART RANDY J & RACHAEL	310-32-080
\$ 8,401.14		\$	\$ 4,001.00	\$		92 \$ 0.15	780.92	\$ 1,043,42	5 \$ 1,043.42	4% 5 2,086.85	4091.88 0.3154%		BITRICH TERENCE W A UM	310-32-079
\$ 5,100.14	\$ 700:00		\$ 700.00	\$ 794.32	8.15 \$.4 .788.80	5	780.82	\$ 1,043.42	5 1,043,42	5	4091.88 0.3154%	797 SWAN DR	BITRICH TERENCE W A S/M	310-32-078
\$ 5,100.29			\$ 700.00	37 734.34	44	95 \$ 1 8.15	6 \$ 760.85	\$ 1,043,46	2 \$ 1,043,46	1% \$ 2,088.92	4092.00 0.3154%	807 SWAN DR	KUBICKA DOWELL A & KATHERINE S TRUSTEES	310-32-077
\$ 5,050.28	\$ 650.00		\$ 650.00	\$ 734.34	5 \$ 788.93	85 5 15	8 \$ 780.95	\$ 1,043.48	2 \$ 1,043.48	1% \$ 2,086.92	4092.00 0.3154%	815 SWAN DR	S TRUSTEES	310-32-076
\$ 7,034.14	\$ - 2,634.00	\$	\$ 2,634.00	\$734.52	6	92 \$. 8.15	2 \$ ~780.92	\$ 1,043.42	5 \$ 1,043.42	2,088.85	4091.86 0.3154%	821 SWAN DR	GATLIN GERALD W & MICHELLE C GAHWI; GATLIN JEFFREY W M/M 8	
\$ 4,400,14	5	\$	5	\$ 734,32	9.15 \$ 766.90	\$1	2 \$ 780.82	\$ 1,043.42	5 \$ 1,043.42	% \$	4091.88 0.3154%	827 SWAN DR	GATLIN GERALD W & MICHELLE C	310-32-074
\$ 4,400.14	\$		·	\$ 734.92	5 \$ 786.90	92 \$ 9.15		\$ 1,043.42	\$ 1,043.42	% \$ 2,088,85	4091,86 0.3154%	837 SWAN DR	GERVAIS RICHARD S/M	310-32-073
\$ 7,034.14	\$ 2,634.00		\$ 2,634.00	3 794,32	\$ 788.90	en.	2 \$ 780.82	\$ 1,043.42	5' \$ 1,043.42	% \$ 2,088.85	4091.86 0.3154%	845 SWAN DR	GERVAIS RICHARD R	310-32-072
\$ 12,117.77	\$ 3,317.50		\$ 3,317.50	\$ 1,488,63	8.29 \$ 11,577.81	\$9.71	5 \$ 1,561:841	\$ 2,086.85	\$ 2,086.85	% \$4,173,70	8183,72 0.6309%	859 SWAN DR	HAW JT	310-32-071A
\$ 4,400.14				\$ 1794.32	9-15 \$ 788.90	\$ 1.	2 \$ 780.92	\$ 1,043.42	\$ 1,043.42	% \$ 2,086.85	4091.86 0.3154%	1	DARLENE E TR	310-32-068
\$ 16,701.27	\$ 7,901.00	\$ 3,900.00	\$ 4,001.00	\$ - 1,468.63	8.29 \$ ~1,577,81	\$	5 \$ 1,561,84	\$ 2,086.85	\$ 2,088,85	% \$ 4 179.70	8163.72 0.6308%	873 SWAN DRIVE	BIBBY KAREN L & JAMES C WIH	310-32-088A
\$ 5,700,14	\$ 1,300.00	5	\$ 1,300.00	\$12734.32	5 \$ 786.90	92 \$1 8.15	2 \$ 780.92	\$ 1,043.42	\$ 1,043,42	% \$ 2,086.85	4091.86 0.3154%	889 SWANDR	DENVER LOUISE UW	310-32-086
\$ 9,585:30	\$ 4,517,50	\$ 1,200.00	\$ 3,317.50	\$ 842.40	0.49 \$ 805.02	\$ 1	895:87	\$ 1,197.01	\$ 1,197.01	% \$ 2,384,02	4894.15 0.3619%	895 SWANDR	JACQUELINE Y TR	310-32-065A
\$ 6,763,16			\$ 1,200.00	\$. 091.74	60 :	88 \$ 11.61	8 990,86	\$ 1,323.86	\$ 1,323.96	6	5192.00 0.4002%	913 SWAN DR	WILKINSON MICHAEL & TAMARA	310-32-084A
\$ 6,583.16	5	,		7,001:01 \$- 931.74	64	\$ 11	\$ 990,88	\$ 1,323.66	\$ 1,323.98	% \$ 2,647.92	5192.00 0.4002%	917 SWANDR	PEREZ JULIANA	310-32-083A
\$ 10,617.16	\$ 5,034,00	\$ 2,400.00	\$ 2,634.00	\$ 931.74	69	11.61	és .	\$ 1,323.86	\$ 1,323.98		5192.00 0.4002%	927 SWAN DR	ARTHUR MIM S/S	310-32-062/W
\$ 6,900.66	\$ 3,317.50	\$	\$ 3,317.50 \$	831.74	65	8 11.81	\$ 890.88	\$ 1,323.88	\$ 1,323.86	% 5 - 2,647.92	5192.00 0.4002%	933 SWAN DR		310-32-081A
\$ 12,366.47	\$ 2,850.50	\$ 900.00	\$ 1,850.50 \$	1,593.08	65	8 S 18.85	Bt 768 L	\$ 2,263.68	\$ 2,263,68		8877.17 0.6843%	951 SWAN DR	HOKENSON ROY M & MARGARET	310-32-080A
\$ 7,404.90	5			\$ 1235.77	\$ 1,927,63	0 \$ 15.39.	\$ 1,314.20	\$ 1,755.96	\$ 1,755.98	\$ 3,511,82	6886,11 0,5308%			310-32-057
\$ 12,734.77			\$ 4,001.00 \$	\$ 121,457.59	18 \$ 1,585.88	\$ 1.18	en:	\$ 2,071.08	\$ 2,071.08	5	8121.88 0.6261%		RRY W & SHEARL	310-32-056A
\$ - 8,566,78	\$ 4,112.50	\$ 795.00	\$ 3,317.50 \$	\$ 7/3.35	5 798.01	\$ 26	\$ 790,63	\$ 1,056.26	\$ 1,058.28	6 5 x 2 112.53	4142.21 0.3183%			310-32-054
\$ 7,635.84	\$ 3,184,00	\$ 550.00	\$ 2,634.00 \$	\$ 742.84	S" > 786.47	\$ 825	\$ 790.10	\$ 1,055,66	\$ 1,055.68	2,111.37	4139.84 0.3181%	994 BAY VIEW DR	BS TIMOTHY & JOLA NETTE	310-32-053
\$ 6,805.95			,	6	\$ 1,578,83	5 8 5 18.31	\$ 1,562,65	\$ 2,088.20	\$ 2,088.20	\$ 4,178.39	8189.00 0.8313%			310-32-052A
\$ 9,491,15	\$ 5,187.60 \$	1,850.00	\$ 3,317.50 \$	\$ 721.55 \$	60	5 5 8.99	\$ 767.35	\$ 1,025.29	\$ 1,025.28	\$ 2,050.57	4020.73 0.3099%	872 BAY VIEW DR		310-32-050
\$ 7,783.91	\$ 3,317.50 \$		\$ 3,317.50 \$	17	\$ 797.09	3 5 9.24	\$ 2 2 789.03	\$ 1,054.25	\$ 1,054.25	\$ 2,108.51	4134.33 0.3187%	886 BAY VIEW DR		310-32-049
\$ 12,659.64	\$ 5,634,00 \$	3,000.00	\$ 2,834.00 \$	\$ 1,155.78 \$	\$ 7241.70	4 \$1 74.40	\$	\$ 1,842.31	5 1,842.31	\$ 7 3,284,61	6440.42 0.4985%	856 BAY VIEW DR		310-32-048A
\$ 6,876.21				\$ 1/164.22 \$	\$ 1,250.77 \$	\$ 7.2.14	\$ 4 1 238 /11	\$ 1,654,30	\$ 1,654,30	\$ 1 3,308,60	8487.45 0.5001%	844 BAY VIEW DR		310-32-047A
\$ 15,809.88	\$ 6,900.00	3,000.00	\$ 3,900,00 \$	\$ 1,486,92 \$	100	18.52	\$ 1,561.30	\$ 2,112.84	\$ 2,112.84	\$ 4,225.66	8265.65 0.6387%	836 BAY VIEW DR	DONNA C S/W JT	310-32-045/M
\$ 15,461.40	\$ 6,901,00 \$	2,900.00	\$ 4,001.00 \$	\$3-1,428.60 \$	\$ 1,534,80	\$ 17.60	\$. 1,519.27	\$ 2,029.97	\$ 2,029.97	\$ 4,059,93	7980.85 0.6137%	816 BAY VIEW DR	٦	310-32-043A
7,280.77	\$ 2,934,00 \$		\$ 2,834.00 \$	en.	\$ 780.95	5 5 9.06	\$ 773.05	\$ 1,032,90	\$ 1,032.90	69	4050.80 0.3122%	810 BAY VIEW DR	1/2 INT; RIACH WILLIAM C & CONSTANCE F HAW &; RIACH JED 8	310-32-041 RI
6 4,418,51	55			\$ 797.38 \$	\$ 792.20	67	\$ 784.18	\$ 1,047.78	\$ 1,047.78		4108.85 0.3167%		NEVARES ALBERT & AMELIA HAVI	310-32-040
7,592.78	\$ 9,317.50 \$		\$ 3,317.50 \$	\$ 713.4B &	\$ 766.52	*	\$ 758.76	\$ 1,013,82	\$ 1,013,82	_				310-32-039
4,312.40				\$1.778.67 \$	\$ 779.17 \$ 4.718.67	7.27	765.35	23	\$ 1,022.62		-	790 BAYVIEW DR		
TOTAL Utility Con- version Cost	Secondary Substotal Private	Private Property Trenching	Private Property Electric	F	Verizon i otal Verizon Public Service Cost Secondary Verizon Public Service Cost Extension Cost-labor & labor & Cost Cost material material %	Verizon i otal	APS Total. Secondary Extension Cost	Verizon Total Primary Extension Cost per Sq. FT	Primary Extension Cost per Sq. FT	Total Primary Extension Cost Price per Sq. FT	PARCEL SIZE % of Sq	SITUS ADDRESS		PARCEL IFON
			-		The state of the	医多种性		_		The state of the state of				_

HILLOREST BAY LICSA	TADES, INC

	SITUS ADDRESS	
	PARCEL SIZE	
A	% of S	
	APS Total Primary Extension Cost per Sq. FT	
	Varizon Total Primary Extension Cost per Sq. FT	
では、「これでは、これでは、これでは、これできる。」 これでは、これでは、これでは、これでは、これでは、これでは、これでは、これでは、	Primary Verizon Total Verizon Total Verizon Total Verizon Total Verizon Total Primary Extension Cost Primary Extension Cost Property Extension Cost Cost Property Cost Property Cost Cost Property Cost Cost Cost Cost Cost Cost Cost Cost	
7000	Verizon Verizon Service Cost- ost-labor & labor & material	
	Secondary Private Property Electric	
,	Secondary Private Property Trenching	
	Secondary Subs TOTAL total Private Utility Con-Cost version Cost	:
\$ 4,417.73	TOTAL Utility Con- version Cost	_

PARCEL II	310-32-087
PARCEL ITON Owner Names LEE CLIFTON D & VIOLA J	TRUSTEES
100	836 SWAN DR
PARCEL % of Sc	4108.22 0.31674
Total Primary ARCEL Extension Cost SIZE % of Sq Price per Sq. FT	% \$ =5.2.2,085.19 \$
Primary Extension cost per Sq.	1,047.80 \$
5 J # -	1,047.60
Verizon Total Verizon Total Verizon Public Service Com- Secondary Verizon Public Service Com- Secondary Extension Cost-labor & labor & Extension Cost Cost Total Verification Material Services Cost Total Verification Cost Extension Cost Total Verification Cost Total Verification Cost Total Verification Cost Total Ve	60 \$ 10 784,04 \$ 10 00 00 18 \$
y Verizon Public S n Cost-labor & li material n	18 \$ 792.06
60	792 06 \$ 737.25 \$
Secondary Secondary Private Private Property Property Electric Trenching	60

-
()
\bigcirc
~
9
П
60
٠,
-4
inde

Color	•	-	777			ı			Ž.,	-	- 1	BOND WILL IAM & HARI ACKE HAN	01000
Company Comp	to.	\$ 5,368.00	67 (60	7. 5	69 ,3	6n	64	64		l	CALVIN MERLE D & JANET J H/W	200
Company Comp		\$ 4,684.50	67	69	F	65	64	65	0.3145%	4079.86		PETERS DAN & TER! H/W JT	310-32-130
Company Comp		\$ 4,001.00	8	60	¥.	69	65	50	0.3145%		1	RUTLEDGE CHARLES E & JUDY TRUSTEES	310-32-129
Column C	5	\$ 3,900.00		160	S.	6	50	60	69	-	Į.	INGRAM DENNIS A & PHYLLIS A	310-32-128
Company Comp	5			157	£.	s .	5	69	0.3145%	-		WAGNER LEAH C	310-32-127
		\$ 5,368.00	\$ 732.17	65	8	~	60	67	60		_	WAGNER LEAH C	310-32-126
Control Cont		\$ 6,735.00	\$ 706.16	80 \$ 758.64	97	50	\$	en.	es :	3934.90			
Control Cont	\$ 4,00	64	4	12 \$786.60	5	\$	5	64	€A .	4079.89	Ι.	HORTA VICTOR M & PRISCILLA M	310-32-124
Control Cont		6,051.50	\$ 818.02	1	5	8	67	60		4547,13	1	WILSON LOUIS M & LINDA D JT	310-32-123
Control Cont	\$ 1,80	•	\$ 1,056.31	\$ 1134.84	ė,	S	\$	60		5886.15	1	JORDAN MARVIN L & JOAN K HAW	310-32-122A
Control Cont	800	60	\$	\$ - 1,136.79		5	60	64	0.4553% \$	5906.64	l	ERROR SHARON TRUSTEE	310-32-120A
COLUMN C		5,368.00	\$ 1-706:66	*	\$	5	5	65		3937.76]	JOHNSON JACQUELINE J & SANDRA J UMV JT	310-32-119
Control Cont		6,051.50	\$ 1,413,32	81- \$ -1,518:39		60	5	6	69	7675,52	1	EASLEY RAYMOND D & PATRICIA	-
Control of a voca-a Statis Address Statis Address Statis		\$ 3,317.50	\$ 1 . 706.66	\$ 759.19	. J 🔻 🖰	•	*	60		3937.78	L	KUKURUDA VICTORIA	
Colombit Name		\$	6	30 5 759.18	\$1	65	és.	65	50	3937.76	_	O NEILL CHARLES T & ELLEN L S	310-32-115
COLORD Primary Color C		5	\$ 706.66	0 \$0 1-759.18	J. 2		50	65		3637.76	1.	1	310-32-114
Colonia Limita Colonia Chimata Colonia Chi		\$ 4,684.50	\$ 706.66	\$ - 759.19	: I = 1.		5	50	\$	3937.76	1		310-32-113
RODOWNE STATES ST		\$ 4,664.50	\$ 700.66	\$ 759.18	64	6	60	60	4	3937.78	١.	L	310-32-112
COLOMB C	[\$ 708.66	-759,19	65	60	50	64		3837.76	ı	<u> </u>	310-32-111
COLUMNO CALLO A MARY PHAY SHANNOR		4,684.60		\$ 147,167,71	Gn .	1	60	55	6		i		310-32-110A
		4,500.00		\$ 1,107.71	60	60	50	69	40	8058.85 0			
			\$1.706.66	\$9.11.759.10	65.7	4	60	4	en :	3937.760			
			\$ 1,273.07	\$ 1,387.71	69.4	1	50	60	65	7694,00 0	1		Ž
COLUMINIS INVESTIBLES MANUAL PR MANU		1,300.00	1693 16	\$ -2.959.58	66,	100.	60	65	69	4877.00 0	1	S; HOYT MARK A & ICATHY A HAW	_
		2,634.00	708.66	\$ 759.19		50	én.	60	3035% \$ 2,008.26	3637.76 0	1	SEIDENGLANZ LINDA SAV; CRANE	
				\$ 810.91	5	1.27	én	60	3242% \$ 2,145,05	4205,99 0.		SABCOCK SCOTT D & GRACE D	
COLDENCH COLDER COLDENCY COLDEN				\$1-2 810.49	\$	\$	\$ 1,071.89	64	64	4203.49 0.	1 1		
COLUMINIS INVESTMENTS STUS ADDRESS PARCEL TOSIPITIMON Entended Cost Secondary		4,001.00		792.06	40	8	\$ 1,047.60	69	69	4108.22 0.			
	1,100.0	\$ 3,317.50 \$	\$ 737.25 1	\$ 792.06	60		60	60	40	4108.22 0.	1 1	OHNSON SANDRA C TRUSTEE	
ICOLOMNON Names STUS ADDRESS PARCEL Total Primary Extension Cost Primary Pri	650.0	\$ 3,317.50 \$	U	\$ 792.06	65 1	41:	55	÷		4108.22 0.		TEVEN D M/M &; WOOD BRIAN D	
Primary Prim	900.00		737.25	\$ 792.06	Ġ	13	60	65	60	4108.22 0.		NDERSON FILMORE H S/M &; NDERSON VIRGINIA L S/W 9	
Columnar Names Cost	650.00	3,317.50 \$	737.26 \$	\$ 792.06	\$	\$ 1784.0	5	69	69	4108.22 0.3		CGREGOR THOMAS P &	
Continue Primary Pri			737.25 \$	\$ 792.06	8	\$ 784.0	\$ 1,047.80	5	6.5	4108.22 0.:			
	1,100.00		\$ 1,474:50 \$	\$ 1,584.12	en.	\$ 1,588.06	(A	50	67		l	DONALD & VIRGINIA HAV	
ICOLOMARY PHW JT 84 SWAN DR	2,900.00	4,001.00	_	792.06		130	64	60		4108.22 0.3			
	4,100.00			792,06	5 9,18	1 4	\$ 1,047.80	65	64	4108.22 0.3			
Primary Ventzon I cital Total Primary Ventzon I cital Primary Ventzon I cital Total Primary Vent	1,900.00	4,001.00 \$	737.25 \$	\$ 792.06	\$	\$ 784.04	\$ 1,047.60	69	69	4108.22 0.3			
Primary Verizon 1 total Verizo			737'25	\$ 792.08	8 1 9 18	\$ 784.04	_	60	6	4108.22 0.3	1		
Primary Verizon 1 otal Verizon 1 ota		1		\$ 792.06	8:42-2-8:18	\$ 784.04	\$ 1,047.60		167% \$ 2,095,19	4108.22 0.3	8 SWAN DR		8
Delinor Control Contro		-		Verizon Public S Cost-labor & la material - n	Secondary Extension Cost	APS Total 4	Primary Extension Cost per Sq. FT	Extension Cost per Sq.	Total Primary, Extension Cost of Sq. Price per Sq. FT	12	TUS ADDRESS		<u> </u>

\circ
Ö
្ន
m
(1)
County County
>

310-32-135	PARCEL
ECKER GLENN E & TANGES	II Ol Owner Names
880 CRYSTAL VIEW DR	SITUS ADDRESS
8159.78	PARCEL SIZE
0.6280%	% of Sq
8159.78 0.6280% \$ 4,161,49	APS Total Primary Primary Total Primary Extension Extension Cost Cost per Sq. Extension Cost Sq. Prica per Sq. FT Vo I Sq. Prica per Sq. FT
\$ 2,080,74	APS Yotal Primary Extension Cost per Sq. FT
\$ 2,080.74	Verizon Total Primary Extension Cost
\$ 2,080,74 \$ 2,080,74 \$	Vertzon Total Primary
7 \$7 18.24	Verizon Tota Secondary: Extension
\$ -1,573.19	Venzon Public Cost-labor & material*
\$ 1,464.34	Verizon Service Cost, Isbor &
\$ 6,735.00	Secondary Private Property Electric
\$ 1,400.00	Secondary Private Property Trenching
\$ 8,135,00	Secondary Sub-
\$ 16,609.5	TOTAL Utility Con- version Cost

TATOT BY STORAG	LLCREST BAY UCBA	TADES INC
-----------------	------------------	-----------

\$ 8,801.60	\$ 3,317.60		3,317.50	915.21 5	\$ 889.25	\$ 11	\$ 973.00	\$ 1,300.47	\$ 1,300.47	\$ 2,800.94	5099.88 0.3831%	5	840 LINGER DR	MCCURDY RICK J	310-32-181
\$ 16,762.70		\$ 1,100.00	4,684.50	\$ 1,830.43 \$	\$ 1,986.50	0 \$ 22.80	\$ 1,946.60	\$ 2,600.94	\$ 2,800.94	\$1-6201	10199.76 0.7883%	10	934 LINGER DR	POWERS JANICE	310-32-180A
\$ 10,385,10	\$ 4,901.00	\$ 900.00	4,001.00	\$ 915.21 \$	\$ 983.26	0 \$ 11.40	\$ 973,30	\$ 1,300.47	\$ 1,300.47	2,600.94	5099.88 0,3831%	50	820 LINGER DR	SVS	310-32-178
\$ 9,901.60	\$ 4,417.50	\$ 1,100,00	3,317,50	\$ 815.21 \$	\$ 983.26	0 \$ 11.40	\$ 973.30	\$ 1,300.47	\$ 1,300.47	2,600.94	5099.88 0.3831%	5	914 LINGER DR	BEAVERLY A HAW JT	310-32-177
\$ 12,252.10	\$1. 6,76A.00		5,368.00	\$ 915.21 \$	\$ 983.25	0 \$1-3 11:40	\$ 973.30	\$ 1,300,47	\$ 1,300,47	\$ 72,000.94	5089.88 0.3931%	56	904 LINGER DR	HW JT	310-32-178
\$ 13,435.60	\$ 7,951.50	\$ 1,900.00	6,051.50	\$ 915.21 \$	\$ 983.25	\$ 11.40	\$ 2973.30	\$ 1,300.47	\$ 1,300.47	<u>ب</u>	5099.88 0.3931%	Sí	896 LINGER DR	JT STORY DESCRIPTION OF THE PROPERTY OF THE PR	310-32-175
\$ 5,484,10	\$			\$ 915.21 \$	\$ 983.25	\$ 11.40	\$ 879.30	\$ 1,300.47	\$ 1,300.47	\$3 2,600.64	5099.88 0.3931%	55	890 LINGER DR	JT MARICAL THEODORE B & MARY I	310-32-174
\$ 11,272.63		\$ 1,100.00	3,317.50	\$ 1,144.02 \$	\$ 1,229.06	\$ 14.25	\$ 1,210.02	\$ 1,625,56	\$ 1,825.59	69	6374,85 0.4914%	63	882 LINGER DR	TRUSTEES	310-32-173A
\$ 12,065.13		-		\$ 1,144.02 \$	\$ -1,229.06	\$ 14.25	\$ 1,210.62	\$ 1,625.59	\$ 1,825.59	64	6374.85 0.4914%	83	864 874 LINGER		310-32-172C
\$ 10,086,13	\$ 3,234.00	\$ 600.00	2,634.00	\$ 1,144.02 \$	\$ 1,220.06	\$ 14	\$1 1,210,62	\$ 1,625.59	\$ 1,625.59	\$ 3,251:17	6374,85 0.4914%	63	852 LINGER DR	JOLICOBUR SHANE MIM	310-32-170A
\$ 6,855,19	•		,	\$ 1,144,02 \$	6.	2 \$ 14.25	4	\$ 1,625.59	\$ 1,625.59	\$ 3,251:17	6374.65 0.4914%	8	840 LINGER DR	THOMAS DAVID & SUSAN HAW JT	310-32-189A
\$ 12,001.60			3,317.50	\$ 1.915.21 \$	\$ 689.25	0 \$ 11.40	\$= 873.30	\$ 1,300.47	\$ 1,300.47	\$ 2,800.94	5099.88 0.3931%	56	830 LINGER DR	THOMAS DAVID & SUSAN HW JT	310-32-168
\$ 13,801.60		\$ 5,100.00	3,317.50	\$ 915.21 \$	\$ 983.25	07 FR. S. O	\$	\$ 1,300,47	\$ 1,300.47	\$ 2,800.94	5099.88 0.3931%	5.0	820 LINGER DR	11/1/2	310-32-167
\$ 9,984.10			4,500,00	\$ 915.27 \$	\$ 983.25	0 5: 11.40	\$ 973.30	\$ 1,300,47	\$ 1,300.47	2,500.84	5099.88 0.3931%	50	812 LINGER DR	SHIPLEY JUDITH B SAV	310-32-166
\$ 6,601,60			3,317.50	\$ 915.21 \$		0 \$ 11.40	S. 1 973.30	\$ 1,300,47	\$ 1,300.47	\$ 2,600.94	5098.88 0.3931%	50	804 LINGER DR	ᆚ_	310-32-165
\$ 10,701.60	\$ 5,217,50	\$ 1,800.00	3,317.50	\$ 915.21 \$	\$1 983:25	0.5	\$ 973.30	\$ 1,300.47	\$ 1,300,47	65	5099.88 0.3831%	55	794 LINGER DR	AYERS TOM W & KATHRYN A	310-32-184
,	\$ 4,884,00		4,684.00	\$ 851.76 \$	815.08	10.61	\$ 905.82	\$ 1,210.30	\$ 1,210.30	3 2 420.61	4746.29 0.3658%	47	791 LINGER DR	SMITH GARY W S/M ANDERSON THOMAS F: VANIER	310-32-162
4			2,634.00	\$ 790.40 \$	\$ 784.70	\$ 1.9.10	\$ 776.76	\$ 1,037.86	\$ 1,037.86	\$ 2,075.72	4070.03 0.3137%	4	801 LINGER DR	FLORES GERALD D	310-32-161
\$ 6,794,18	\$ 4.417.50	\$ 1,100.00	3,317.50	\$ 730.40 \$	\$-784.70	8:0.10	\$ 778.76	\$ 1,037.66	\$ 1,037,88	140	4070.03 0.3137%	4	B11 LINGER DR	┸	310-32-160
\$ 7,660,66		\$ 650,00	2,634.00	3 730.40 5	\$ 784.70	\$ 9.10	\$ 778.78	\$ 1,037.86	\$ 1,037.86	•	4070.03 0.3137%		818 LINGER DR	PUDEWA PAUL L & CAROL A HAW BULLARD RICKY & KAREN L HAW	310-32-159
\$ 10,594.16	\$ 6,217,50	\$ 2,900.00	3,317.60	5 730.40 \$	\$ 794.70	9.10	\$ 778.78	\$ 1,037.86	\$ 1,037.86	\$ - 2,075.72	4070.03 0.3137%	<u></u>	829 LINGER DR	CLARK DONALD & MELODY	310-32-158
\$ 7,010,66			2,634.00	\$ 730.40 \$	\$ 764.70	01.6	\$ 778.76	\$ 1,037.88	\$ 1,037.88	\$ 2075.72	4070,03 0,3137%		838 LINGER DR	EMARGARET HW; FERRALL	310-32-157
69		\$ 600,00	3,600.00	\$ 08.084,1	\$ 1,566.40	65	\$ 1,553.52	\$ 2,075.73	\$ 2,075,73	\$ 4,151.45	8140.10 0.8275%	9	853 LINGER DR	丄	310-32-156
\$ 8,894,16	_	\$ 1,200.00	3,317.50	790.40 \$	4	9.10	\$ 770.76	\$ 1,037.66	\$ 1,037.86	\$ 2,075.72	070.03 0.3137%	Â	887 LINGER DR	┸	310-32-154
en .		\$ 1,200,00	6,051.50	\$ 1,085.60 \$	\$ -1,177.04	3 13.65	\$ 1,185.13	\$ 1,558.78	\$ 1,556.79	-	8105.04 0.4708%	01	875 LINGER DR		310-32-1534
én.	7,018.00	\$ 1,650.00	5,388.00	\$ 1,095.60 \$	\$ 1.17704	3 5 13.65	\$ 1,165,13	\$ 1,550,76	\$ 1,558.79	122	6105.04 0.4708%		895 LINGER DR	┸	310-32-151/
\$ 10,659,92	\$ 1,800,00	\$ 800.00	1,100.00	\$1,460.80 \$	\$	18.20	\$ 1,553.51	\$ 2,075.72	\$ 2,075.72	\$ 4,151.43	8140.08 0.6275%	<u></u>	903 LINGER DR	CO-TR LEGGETT PAMELA A REVOCABLE	310-32-1504
\$ 4,376.66				\$ 750.40 \$	\$ 764.70	\$ 1 10	\$ 5:5778.78	\$ 1,037,66	\$ 1,037.88	\$ 2,075.72	4070.03 0.3137%	À	919 LINGER DR	VID EDWARD	310-32-148
\$	1,350,00		-	5 730.40 \$	\$ 784.70	8 3 9.10		\$ 1,037.66	\$ 1,037.66	\$ 2,075.72	4070.03 0.3137%	8	927 LINGER DR		310-32-147
to.	\$ 4,167.60	\$ 850.00	3,317.50	\$ 790.40 \$	\$ 784.70	\$ 9.70	\$ 778.78	\$ 1,037.86	\$ 1,037.88	\$ 2,075,72	1070.03 0.3137%	å	937 LINGER DR	NOBLE JUDI L UW	310-32-148
S	\$ 10 mm		—	\$ 730.40 \$	\$784.70	8	5 776.76	\$ 1,037.86	\$ 1,037.88	\$ 2,07572	4070.03 0.3137%		945 LINGER DR	GOOD DAN R & VIVIAN T TR	310-32-145
4A'		5	3,317.50	\$ 780 15 \$	\$ 848.80	5 2 9.84	\$ 840.30	\$ 1,122.76	\$ 1,122.78	2,245.52	1402.98 0.3394%	4	955 LINGER DR	L	310-32-144
\$	2,000.00	5	2,000.00	2.0	\$	96.8.11.2.5	\$ 766.64	\$ 1,024.20	\$ 1,024.20	2,048.41	4016.49 0,3096%	+	954 CRYSTAL VIEW DR	NELSON ROBERT & LORI HAW	310-32-143
				\$ -173217 \$	\$ 786.60		\$ 778.64	\$ 1,040.37	\$ 1,040.37	\$ 2,080,74	4079.89 0,3145%	-	948 CRYSTAL VIEW DR	4	310-32-142
\$ 7,387,27	3,000,00	in	3,000.00	\$1 73217 \$	786.60	8	\$ 778:64	\$ 1,040.37	\$ 1,040.37	\$ 2,080.74	4079.89 0.3145%	+	938 CRYSTAL VIEW DR	GOSSENBERGER LESLIE SAV JTS	310-32-141
\$ 4,387.27	5			\$ 792.17 \$	\$ ~ 786.60	67	\$ 778.64	\$ 1,040.37	\$ 1,040.37	\$ 1, 2,080.74	4079.89 0.3145%	\vdash	930 CRYSTAL VIEW DR	SHAS JT	310-32-140
\$ 4.387.27	Ĩ		$\overline{}$	\$ 732.17 \$	\$ 786.60	65	\$ 778.64	\$ 1,040.37	\$ 1,040.37	6	4079.89 0.3145%	\vdash	922 CRYSTAL VIEW DR	LAFRENIERE ALBERT O	310-32-139
_		1,000.00	5,368.00		\$ 786.60	8	\$ 776.64	\$ 1,040.37	\$ 1,040.37	\$ 2,080.74	4079.89 0.3145%	-	916 CRYSTAL VIEW DR	L	310-32-138
^	1 350 00	•	1,360.00	\$ 732.17 \$	\$ 786.60	8	\$ 778.64	\$ 1,040.37	\$ 1,040.37	\$ 2,080.74	4079.89 0.3145%	\vdash	906 CRYSTAL VIEW DR	MENATHAN J & WHITNEY HAW JT	310-32-137
	\$ 75,084.00		$=$ \perp	\$ 73247 \$	\$ 786.60	5	\$178.64	\$ 1,040.37	\$ 1,040.37	\$ 2,080.74	4079.89 0.3145%	-	896 CRYSTAL VIEW DR	HW JT	310-32-136
TOTAL Utility Con-	Secondary Sub- total Private:	Private Property Trenching	Private Property Etectric	Service Cost- labores	lary: Verizon Public Service Cost- ilon Cost-labor & labor &	Extens	Secondary Extension Cost	Extension Cost per Sq. FT	Cost per Sq.	Extension Cost Price per Sq. FT	PARCEL SIZE % of Sq	PAR	SITUS ADDRESS	ICOVOWNER Names	PARCEL II
- - -			Secondary	Verizon 3		Verlzon		藍	Primary						

COST ESTIMAT

BLLCRES	NO.
T BAY U	200
ASC	

-32-182	RCEL _
HORN WILLIAM E & JEANNETTE L	
954 LINGER DR	SITUS ADDRESS
4856.48 0.3	PARCEL SIZE %
744%	of Sq
4858.48 0.3744% \$ - 2,475.80 \$	APS Total Primary Primary Primary Primary Extansion Cost Cost per Sq. Extansion Cost Cost Cost Cost Cost Cost Cost Cost
1,238.40	APS Total Primary Extension ost Cost per Sq. 1
\$ 1,238.40	Verizon Total Primary Extension Cost per Sq. FT
928.85	APS Total Secondary Second
\$ 1,238.40 \$ 1,238.40	Arton Total Arton
92 \$ 871.53 \$	Verizon Pro-
4,001.00	Secondary Private Property Electric
	Secondary Private Proparty Tranching
\$ 4,001:00	Secondary Sub- total Private
8,223.36	TOTAL Utility Con- version Cost

	HILLCREST BAY UC	TADES, INC
•	COSA	n

310-32-226	310-32-225	310-32-224	310-32-223	310-32-222	310-32-221	310-32-220	310-32-219	310-32-218A	310-32-218A	310-32-215	310-32-214	310-32-213/	310-32-211	310-32-210	310-32-209	-			-	310-32-204		= 1		310-32-200	310-32-169	310-32-198	310-32-197	310-32-198	310-32-195A	310-32-193	310-32-192			310-32-189.HC	310-32-188B	310-32-186A	3	≥	€ 1	PARCEL IDOV
MANNING CHARLES S & BARBARA	POWELL RICHARD L & HELEN T		MARCHESI JOHN W & CATHERINE M TRUSTEES		RUNGE KEVIN R & CYNTHIA ANNE	MENDEZ MICHAEL S & MARIE B HAV JT	THERESE H/W JT; BERGSTROM BEWESLEY E JR S/S	LOWE BERNARD M & ELSIE M TRUSTEES	ROBLES FRANK I & JAN H/W JT	HAW; DALLSA NOC C/O; ATTN: BILL	-		1		IF MH			ELIAS-CALLES ANTONIO & ILEN		OKS HOWARD A & HELEN		JT 50 INT; MARTIN KEVIN D & BI		BACA WILLIAM A & GAYL CHW 25		STRONG ROBERT & BONNIE H/W 937			A V TR	//M S/S	POPLET KHANIM U/M	EVANS TIMOTHY G & ROBIN A H/W 863	EVANS TIMOTHY GORDON & 875	RESTER ROBERT S/M; HOFFMAN 867	BOWE JEROME P & KAREN M H/W 849	NELSON RONALD & SYLVIA H/W JT	LIVING TRUST; MARTIN CRAIG A & CINDY S TR C/0			Owner Names
1 1	NOBLE VIEW	1 1	1 I	1 1	1	L. 1	1	1 1	1		1	1	1 1	1 1	1	1 1	i l			1 1		1 1	1 1		*	1		1	l		1	_	1 1	, ,			1 1		3 NOBLE VIEW DRIVE	SITUS ADDRESS
0.3469% -\$1	0.3489% \$	0.3469%	0.3388% \$4-4	0.3519% \$	0.3469% \$	0.3469% \$	0.3469%	0.5203% \$	0.7509%	0.3977%	0.3469%	0.6668%	0.3334%	0.3160% \$	0.3115%	0.9180%	4124.71 0.3180% \$ 2,103.60	0.3180%	0.3180% \$	0.3180%	0.3180%	0.3180%	0.4790% \$	0.7240%	7.5. %0682°0	9	0.4163%	0.4169%	0.8325% \$	0.4163% \$	0.4163% \$	0.4163% \$	0.4255% \$	0.4718%	0.8048%	11038.74 0.8510% \$ 5,830.27	0.4020% \$	0.5908%		PARCEL Extension Cost SIZE % of Sq Price per Sq. FT
•	2,294,94 \$ 1,147,47 \$	₩.	\$ 1,124.01	5	55	8	69	42.50 \$ 1,721.25 \$	88.06 \$ 2,484.03 \$	64	94:84 \$ 1,147.47 \$	4411.60 \$ 2,205.80 \$	60	50	1,00 \$ 1,030.50 \$	3.60 \$ 1,051.80 \$	3.80 \$ 1,051.80 \$	659	45	60	40	66	\$	5	S	60	50	én.	\$ 2	65	45	50	6n	42 \$ 1,560.56 \$	27' \$ 2,662.14 \$	27 \$ 2,815.13 \$	64	65	\$ 2,223.97	APS Total Primary Extension Cost per Sq.
1,147.47	1	1,147.47	\$	\$		5	1,147.50 \$ 85	1,721.25 \$ 1,28	2,484.03 \$ 7,85	1,315.60 \$	*		1,102.90 \$ 625	1,045.40 \$ 782.40	1,030.50 \$771.25	1,051.60 \$ 787	1,051.80 \$ 1.787.19	1,051.80 \$ 787.18	\$	1,051,80 \$ 787,19	1,051.80 \$ 787:19	1,051.80 \$ % 787.19	6	5	•	S	8			1,376.67 \$ 1,030,55	1,376.97 \$ 1,030.55	1,376.97 \$ -11,11,030.55	1,407.57 \$50		2,662.14 \$ 1,862.40	2,815.13 \$ 2,108.81	67	1,854.34 \$ 4,462.87		Volzon Total Primary APS Total: Extension Cost Per Sq. FT Extension Cost
858.79 \$1 10.06 544	\$ 10.06 \$	858.76 \$ 70.06 \$	\$ 9.85	\$ 1	6	\$ 10	858.61 \$7 10.06 \$	288.22 \$ -15.09 \$	\$ 21.78 \$	984.55 \$ 71.53 \$	B	7	\$ 4 9.67	240 \$1 9.16 \$1.5	9.03 \$	\$.0.22	\$ 8.22 \$	\$ 8.22 \$	S" B.22 \$	\$ 8.22 \$	\$ 8.22 \$	8.22	\$ 13.89 \$	\$ 21.00 \$	\$ 22.71 \$	\$ 17.45 \$	\$ 12.07 \$	\$ 4 112.07	\$ 2414 5	\$ 12.07	\$ -12.07	\$ 12.07	\$ 12:34	19.68	\$	\$ 24.68 \$	\$ 11.86 \$	\$ 17.13	\$	Verizon Toti Secondary Extension
0.06 \$ 807.57 \$ × 807.54	65		849.84	880.17.	867.59	60	887:58 \$ 807.56	1,301,39: \$ 1,211,34	1,878.10 \$ 1,748.15		\$ 807.64.	5 1,552.94	\$ 776.17	2 - A- 1	779 13 \$ 725.22	795:24 \$ 740:21	60	\$ 740.21	785.24 \$5 740.21	67.	785.24 \$ 740.21	\$ 740.21	1,198.11 \$ 3.1,116.21	1,810:73 \$ 1,685,43	\$1,-1,822.60	\$ 1,400.81	4	\$ 1,041,09 \$ 969.05	2,082.17 5 1,936.10 1	8	4	\$4 1,041,09 \$ 4. 969,05	\$+~ 1,064,22 \$	5	01277 \$ 1973.48 \$		60	74 .		Vertzon Public Service Cost:
\$ 6,051.50 \$	\$ 6,735.00 \$	\$ 6,051.50 \$	60	\$ 1,500.00 \$	60	\$ 5,368,00 \$	\$ 5,368.00 \$	\$ 6,735.00 \$	\$ 6,735.00 \$	\$ 4,884.50 \$	\$ 6,051.50 \$	\$ 5,388.00 \$	\$ 1,550.00 \$	\$ 1,300,00 \$		\$ 4,684.50 \$		\$ 6,735.00 \$			\$ 5,368.00 \$	\$ 8,051.50 \$		\$ 3,317.50 \$	\$ 3,317.50 \$	\$ 1,700.00 \$	\$ 6,735.00 \$	\$ 1,300.00 \$	\$ 1,200.00 \$	\$ 4,001.00 \$	\$ 3,800,00 \$	en	\$ 4,001.00 \$	\$ 1,500.00 \$	1,500.00 \$		3,317.50 \$	3,317.50 \$	5	Secondary Si Private Property F
\$ 3,100.00 \$		2,800.00	3,200.00 \$	· ·	3,100.00 \$	3,200.00	800.00	3,100.00 \$		-	1,400.00 \$	1,300.00 \$	•		e	1,300.00 \$		1,700.00 \$	S	5.7	900.00	800.00 \$	en .	ėn :	en .	60,	1,900.00 \$	99	ės,		1,100.00	\$	1,400.00 :\$55	\$	100	5	6 25	3,000.00 \$	100	Secondary Secondary Private Property Jot
8,151,50' \$	6/735.00 \$	\$ 8,951.50 \$	S - 9,251,50 S	1,500,00	6,466.00 \$	8,566,00 \$	6,168.00 \$		6,735,00 \$	\$ 4,884.50 \$	\$ -7,451.50 \$	6,868.001 \$	1,550.00 \$	1,300.00 \$	5	12.	5	8,435,00 \$		8	6,266:00 \$	6,851.50 \$	5	3,317,50 \$	\$ 317.50 \$	-£1,700.00 \$	8. "1-B,635,00" \$	\$ 1,300.00 \$	1	4,001:00 \$	\$4,800.00 \$	\$ 1000	\$ 5,401.00 \$	\$ 1,600,00 \$	1,500.00 \$	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9,817.50 \$	8,317,50 \$	\$ 1:4- 9,317.50 \$	Secondary Sub- Total Private U
\$ 13,980.41	\$ 11,673.91	\$ 13,790.41	\$ 13,991.49	\$ 6,409.20	\$ 13,307.03	\$ 13,407.03	11,007.03	17,083,54	17,210.18	10,231.97	12,290,40	15,969,89	8,200.84	5,708.48	4,345.64	10,410.95	4,435.46	12,670.46	4,435,48	4,435.46	10,703.46	11,280.86	0,662.49	13,418.89	14,240.00	10,093.89	14,741.88	7,106.69	12,613.36	9,807.69	10,708.88	5,808.89	11,336.73	8,080.91	12,728.27	11,671.46	8,925.60	14,558.98	12,696.04	TOTAL Utility Con- version Cost

4	PARC	
337	EL 10	
SENOT LLC CE VE	Ol Owner Names	
JONES HAROLD ERIC & KATHIE JO	Names	
DERIC		
& KATH		
O 3	70	
803 N	SITUS ADDRESS	
NOSI S VISW DO	DDREA	
20	ั้ง เก	
2.00 BO 0 3.00 W 1 1 1 2 1 1 1 2 1 1 1 2 1 1 1 2 1 1 2 1 1 2 1 1 2	PARCEL Extension Cost Size % of Sq. Pricaryar St.Fer	
24804 0	% of Sp	
	Tota Exten	
3	Total Primary. Extension Cost	
•	C □ _ >	
1 447	APS Total Primary Extension Cost per Sq	
	m <	
.	erizon l Prima tension per Sq.	
47 47	Cost	
858.78	APS Total Primary Primary Primary Primary Extension Cost Extension Cost Primary Extension Cost Extension Cost Primary Extension Cost Extension Cost Primary Extension Cost Extension Co	
858.7	Total ndary	
9	Veni Sec	
) 0	on Tou	
	Veriz	
807	on Pub	
5 5		
807	r con	
5 6	THE RESE	
. <u>.</u>	Secondary Private Property Electric	
1,400.00	, s , s	
	Secondary Private Property Trenching	
, 60 j	2 2	
1,400.00	condar lotal Pri	
00.00	y Sub	
69	TOTAL Utility Co	
6,238	TOTAL Utility Conversion Con	

>	6 3 7,076.50	8 \$-: 1,916.06	\$ 805.86	8 983.92	\$ 1,135.59	1,369.73	\$ 1,888.14	1	\$ 763.36	\$ 763.36	\$ 763.36		\$ 1,145.03	\$ 1,145,03	\$ 763.36	\$ 763.36	\$ 763.36	\$ 764.66	\$ 1,958.86	\$ 2,272.80	\$ 1,312.22	\$ - 1,297,90	4,225.97	\$ 2,633,30	\$ 1,709.96	854:88	\$ 1,989.83.	\$ 1,098.03	\$ 1,250.85			13.	\$ 770.25	H1.	\$ 753.49	770,25	\$ 1,143,52	\$ 1,058.04	\$ 1,145.31	\$ 858.76	sion Cost	APS Total
	60	69	16 S - 1 9.44	2 \$ 11.53	9 \$ 13:30	3 \$ 16.04	6 7.	8 \$ 1.04	5	18	6 \$ 8.94	8.94	\$ + 13.41	3 41	8.84	\$ 804	\$ 8.94	9	\$ 22.95	\$ 26.62	\$ 15.37	\$ 15,20	\$1 49.50	\$ 30.85	\$ 20.03	\$.E. \10.01	\$ 23.49	\$12.80	\$ 14.72	\$ 15.87	11.23	9.02	\$ 9.02	\$	\$ - V 8.83	\$ 6.02	\$ 13.39	\$ 12.39	\$ 13.42	\$ = 10.06	Cost	Verizon Total
	69	60	\$ 814.00	\$ 983,98	\$1,147.20	65	4	5	en L	•	\$ 771718	\$ 4 771,16	\$ × 115674	8	10	5 771.16	90		\$ 1,978.89	\$ 2,296.04	\$ 1,325,63	\$ 7,311,46	8	5 2 660 22	\$ 1,727,44	\$ 803.72	\$	\$1,109.26	\$ 1,269,70	\$ 1,366.60	\$ 966.48	\$ " 778-13	\$ 778.18	762.07	\$ 761.13	5 778.13 5 724.29	\$ 1,165,21	\$ 1,068.85	\$ -1,157.02	\$ = 867.57	material.	Jenzon Public
	5 6	\$	\$ 757.78	\$. 925.20	\$ 1,087.82	69	\$ 1,775.46	60	8	\$ 717.80		4	\$ -1,076.70	\$ = "1,076.70	r F	\$ 717.80		\$ 719.03	\$ 1,641,96	\$ 2137.16	\$	\$ 1,220.44	9.,	\$ 2476.14	\$ -1.607.61	\$	\$ 171,880.67	1	\$1 -17181.65	\$ 1,274.17	69-	5.	# 1 E 1 1 e	\$ 709:34	\$ 708.46		\$ 1,075.27	\$ 994.90	\$ 1,076.98	\$ 807.54	material	erizon
	\$	55	•	\$ 3,317,50	\$ 3,317.50	\$ 5,368.00	\$ 5,368.00	\$ 5,388,00	65	\$ 3,317.50			\$ 1,000.00	\$ 1,000.00	\$ 3,317.50	\$ 5,366.00	\$ 6,735.00	•	\$ 1,100.00	\$ 3,317.50	•	\$ 3,317.50	\$ 6,051.50	\$ 3,317.50	\$ 4,400.00	\$ 1,500.00	\$	\$ 1,500.00		60	\$ 6,051.00	\$ 4,900.00	\$ 6,735.00	in.	55	\$ 6,051.50	\$ 6,051.50	\$ 6,735.00	\$	\$ 700.00	Electric	Secondary
	\$	65	\$	\$ 500.00	\$ 800.00	\$ 1,100.00	\$ 1,900.00	\$ 1,900.00	69	\$ 1,100.00	5		\$	\$ 3,000.00	45	\$ 1,900,00	\$ 3,400.00	£0	50	\$ 1,100.00	60		6 0	5	\$ 1,435.68			en ,		60	\$ 1,100.00	\$ 900.00	\$ 1,100.00	60	69	\$ 2,000.00	\$ 1,200.00	5	5	\$ 2,800.00	1	Secondary
COST		60 To 100	5.	00 \$ 3,817,50	0 \$ 4,117.50	69	65	60	€9	0 \$ 4,417.50	5	A.	\$ 1,000,00		\$ 3,317.50	40	0 \$10,135.00		\$ 1,100.00	3 4,417,50	(C) (C)	\$ 9,317,50	\$ 6,051.50		5,835,88	\$ 77 - 7,500.00	\$	\$ 1,500,00	\$	*	65	6	\$ 7,895,00	\$1.00	66	40	\$ 7,251.50	\$ 6,735.00	69	12	Cost	Sacondary Sub-
ST ESTIMATE	\$ 6,077,39	\$ 10,796.25	\$ 4,540.63	0 \$ 9,361,43	0 \$ 10,616.08	0 \$ 14,185.78	5 17,906.81	0: \$ 11,569,16	40	\$ 8,718.86	\$ 4,301.16	\$ 4,301.18	5. 7,451.74	\$ 10,451.74	5 7,618.66	\$ 11,589.16	\$ 14,436.16	\$ 4,308,62	\$ 12,197,30	\$ 17,229,71	\$ 7,993.76	\$ - 10,630.66	\$ 28,862.91	\$ 18,154.95	\$ 15,470.75	\$ 6,317.43	\$ 11,268.66	49	\$ 7,081.81	55	to.	és	\$ 12,175:04	\$ 4,250.48	\$ 4,245.22	\$ 12,391.54	\$ 13,884.72	\$ 12,696.57	\$ 6,459.30	\$ 6,336.61	version Cost	
MATE	<u> </u>] Est	<u> 16</u>	<u> </u>	J ^{CS}	<u> </u>	Γ	1 ⁵⁷	1	<u> </u>	J.T	1 	J**	Г.	15	<u></u>		s:	1		1.	<u> </u>	<u> </u>	<u> </u>				D	EC	CIS	iC	M	N) .		2.33×3.	# (4.50					

																																					~	٠	F	4
		310-32-272	310-32-271A	310-32-270.	310-32-266A	310-32-267A	310-32-265	310-32-264	310-32-263	310-32-262	310-32-261	310-32-260A	310-32-259A	310-32-257	310-32-256	310-32-255	310-32-254	910-32-253	310-32-252	310-32-251A	310-32-249	310-32-248	310-32-247A	310-32-245/L	310-92-243	-	2		310-32-238	310-32-237	310-32-238	310-32-235	310-32-234	310-32-233	310-32-232	310-32-231	310-32-230	310-32-228	310-32-228	PARCEL ICO
BABARBARA DUNLAP	HILLCREST BAY INC	HILLCREST BAY INC		SHAMNURG BETH S U/W &;		A THURMAN JIM U/M	STEWART MICHAELE & MELANIE	SWAN CHARLES JOSEPH S/8	&; LOVATO RUDY E & SIMONETTE	BOLTON BRIAN	BOLTON BRIAN		BULTSMA TED & CARLA HAV	HAW	RADVANSKY GEORGE & DEBBIE	GAULTEV	REPRESENTATIVE	IEE L H/W	BEVAN KATHI A M/W S/S	<u> </u>	MADRIGAL JOHN F & HELEN E;		GREER DOUGLAS & KAREN HAV	GARCIA PHILIP J &; LAURENCE ADEBORAH A HW		L	L	<u> </u>	TRUSTEES TEDDIE JO	DUMP NORMAN R & DIANNA L H/W		S			HEPLER KENNNETH R JR MM S/S 2	JT JT JUNE K HAW	L.	MALLIETT INVESTMENTS LLC 9	ELLE M S/W	ARCEL_I[OVOwner Names
D	2765 HILLCREST BAY	2769 HILLCREST BAY		2775	2779		2793 HILLCREST DR	2801 HILLCREST DR	2809 HILLCREST DR	2815 HILLCREST DR	1	2835 HILLCREST DR	2837 HILLCREST DR	2851 HILLCREST DR	2856 HILLCREST DR	2863 HILLCREST DR	2871 HILLCREST OR	2875 HILLCREST DR	2889 HILLOREST DR	2891 HILLCREST DR	2915 HILLCREST DR	2825 HILLCREST DR	1	i I		. !	2871 DUNILAP DR		1 1				2962 DUNLAP DR	2973 OTIS CT	2977 OTIS CT	2987 OTIS CT PARKER	918 NOBLE VIEW DR	910 NOBLE VIEW DR	902 NOBLE VIEW DR	SITUS_ADDRESS
5851.80 0.4357% \$ 3	10039,86 0.7739%	4222.51 0.3255%	5155.52 0.3974%	5950.27 0.4587%	7177.07 0.5533%	9893.45 0.7627%	3999.82 0.3083%	3899.82 0.3083%	3989.82 0,3083%	3999.82 0.3083%	3669.82 0.3083%	5989.73 0.4825%	5998.73 0.4625%	3999.82 0.3083%	3998.82 0.3083%	3999.82 0.3083%	4006,66 0.3088%	10264.02 0.7912%	11809.00 0.9180%	8875.75 0.5300%	6800,70 0.5242%	14	13797.93 1.0636%	8959.84 0.6907%	4479.92 0.3453%	10479.20 0.8078%	5753.48 0.4435%	6585.65 0.5077%	0.5473%	0.3872%	0.3111%	0.3111%	3652.69 0.3047%	3947.80 0.3043%	4035.97 0.3111%	5991.80 0.4818%	5543.90 0.4274%	6001.18 0.4626%	4499.89 0.3468%	PARCEL SIZE % of Sq
43.5	64		% \$ 2,829.32 S	69	60	٠.	5 2,039.91 5	\$ 2,039.91 \$	60	5 2,039.91 \$	60	60	5- 3,059.80 \$	\$ 2,039.91 \$	\$ 2,039,91 \$	90	\$ 2,043.40 \$	\$ 5,234,65 \$	\$ 6,073.59 \$	6	\$ 3,488,36 \$	60	*		\$ 2,284.76 \$	\$ 5,344.39 \$	\$ 2,934.26 \$	\$ 3,358.68 \$	\$ 3,821.07 \$	\$ 72,581,86 \$	\$ 2,058.34 \$	\$ 2,058,94 \$	\$ 2,015,87 \$	\$ 2,019.38 \$	\$ 2,056:34 \$	\$ 3,055.82 \$	\$ 2,827,38 \$	5 3,080.60 \$	\$ 2,294,94 \$	TotaliPrimary E Extension Cost Co Price per Sq. FT
1,441.18	2,560,16	1,078.74	1,314.66	1,517.32	1,830.15	2,522.83	1,019.95	1,019.85	1,019,95	1,019,95	1,019.95	1,529.93	1,529.83	1,019.95	1,018.95	1,019.85	1,021.70	2,617.33	3,036.80 \$	1,763,32	1,734,18	5,846,51	3,518.47	2,284,76	1,142,38	2,872.20 \$	1,467.13 \$	1,879.34 \$	1,810.54 \$	1,280.83 \$	1,029.17 \$	1,029.17 \$	1,007.94 \$	1,006.69 \$	1,028.17 \$	1,527.91 \$	1,413.89 \$	1,530.30 \$	1,147.47 \$	APS Total Primary Extension Cost per Sq. E.
\$ 1,441.18	\$ 2,560.16	\$ 1,076.74	\$ 1,314.66	\$ 1,517.32	\$ 1,830.15	\$ 2,522.83	\$ 1,019.95	\$ 1,010.05	\$ 1,019.95	\$ 1,019.65	\$ 1,019,95	\$ 1,529.93	\$ 1,529.93	\$ 1,019.65	1,019.85	1,018.95	1,021.70	2,617.33	3,036.80	1,753,32	1,734.18	5,848.51	3,518,47			1	1,467.13		1,810.54	1,260.93	1,029.17	1,029.17	1,007.94	1,006.69	1,029,17	1,527.91	1,413.69	1,530.30	1,147.47	Verizon Total Primary Extension Cost per Sq. FY
6 3 1,076,50	8 \$7: 3 7 1,916.08	805.88	8 8 883,92	65	8	6 0	\$ 769,36	\$ 763.36	\$ 763.36	65	5	\$ 1,145,03		6	60	\$ 763.36	\$ 764.66	\$ 1,958.86	\$ 2,272.80	\$ 1,312.22	\$ 1,297.90		2,633,30	1,709.96	5			\$ 1,258.85	\$ 1,355.04		\$ 770.25	5 770.25	\$ 754.38	\$ 753.43	\$ 770,25	\$ 1,143.52 \$	\$ 1,058.04 \$	\$ 1,145.31 \$	\$ 858.79 \$	APS Total Secondary Extension Cost
\$24. 12.69	\$ 22.44	\$ L 9.44	\$ 11.53	\$ 13.30	\$ 16:04	\$ 22.12	5 8.04	\$8.64	\$ 19.94	5 8.94		5 + 19.41	5 13.41 3	\$ 8.94 \$	894	8.94	8.96	\$ 22.95	26.62	15.37	15,20] ;	1.5	\$ 20.03 \$	£ 10.01	23.49	\$5 12.80 \$	\$1 14.72 \$	\$ 15.87	11.23	3	9.02		8.83	8 6.02 \$	1.2		13.42	10,06	Verizon Total Secondary Verizon Cost
\$ 1,089.62	\$ 1,935.67	\$ 814.00	\$ 983,96	\$ 1,147.20	\$ 1,383.73	\$ 1,907.44	771716	771116	771:16 \$	77176	\$ 4 - 771,16	* 115874	\$ 1,156.74	\$ 11.0 771.18	\$ 771.16	\$ 771.76		\$ 1,978.89	\$ 2,290.04	1 325.63	\$ 1,311,16.3	4,269 17	2,660,22	1,727,44	803.72	2,020.37	\$ 1,109.26 \$	\$ 1,269,70 \$	\$ 1,368.60 \$	\$ 988.48 \$	77843 5	778.49 \$	\$ 762.07	\$ 761.13 \$7.708.46	778.13 \$ 724.29	1,165,21	1,068.85 \$		\$ 867.57 \$	Verizon Public Service Costs Cost-labor & Jabor & Martin M
1,089.62 \$ 1,014.22 \$	\$ 1,801.73	\$ 757.76	\$ 925.20	\$ 1,067.82		\$ 1,775.46	\$717.80	717 BO	717.80	\$ 717.80	\$ 717.60	\$ 1,076.70	\$ = "1,076,70					\$ 1,641,96	1.16	\$ 1,233.01	\$ 1,220.44	5 3 973 76 \$	\$ 2.476.14	19.708	\$ 803.96 \$	\$ 171,880.67 \$	\$ 1,032.50 \$	\$1 17181.65 \$	\$ 1,274.17		724-29 \$	\$ 724.28 \$	\$ 700:34 \$	708.46 \$	724.29 \$	\$ 1,075.27 \$	\$ 994.90 \$	1,076.96 \$	\$ 807.54 \$	
	65	45	\$ 3,317,50	\$ 3,317.50	\$ 5,368.00	\$ 5,368.00	\$ 5,388,00	\$ 3,317.50	\$ 3,317.50			\$ 1,000.00	\$ 1,000.00	\$ 3,317.50	\$ 5,368.00	\$ 6,735.00		\$ 1,100.00	\$ 9,317.50		\$ 3,317.50		\$ 3,317.50	\$ 4,400,00	\$ 1,500.00		1,500.00		,	6,051.00 \$	4,900.00	6,735.00 \$	-		6,051.50 \$	6,051.50	6,735.00 \$		700.00 \$	Secondary Private Property Electric
\$	45	5	\$ 500.00	\$ 800.00	\$ 1,100.00	\$ 1,900.00	\$ 1,800.00	5	\$ 1,100.00	•		\$	\$ 3,000.00		\$ 1,900.00	\$ 3,400.00		5	\$ 1,100.00					\$ 1,435,68					,	1,100.00	\$ 900.00	1,100.00			\$ 2,000.00	\$ 1,200.00			2,800.00	Secondary Private Property Trenching
	\$ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 1	65	_	57	5	+-	\$ 3,317,50	0 \$ 4,417.50	5	\$	5 1,000.00	\$4,000.00	3,317,60	\$ 7,266,06	\$ 10,135.00	\$	_	3 4,417,50	10	\$ 9,317.50	\$ 6,057.50		5,895,88		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$ 1,500,00	5	4	69	69	\$ 7,895.00	10 A	60		\$ 7,251.50. \$	\$ 6,735.00 \$		8.	Secondary Sub- total Private?
\$ 6,077.39	\$ 10,796.25	\$ 4,540.63	\$ 9,361,43	\$ 10,516.06	\$ 14,185.78	\$ 17,906.81	\$ 11,589,16	\$ 7,618.66	\$. 8,718.86	\$ 4,301.16	\$ 4,301.16	\$. 7,451.74	\$ 10,451.74	\$ 7,618.68	\$ 11,589.16	\$ 14,438.18	\$ 4,308,62	\$ 12,197.30	\$ 17,229,71	\$ 7,393.76	\$ - 10,030.66	\$ 28,862.91	\$ 18,154.95	\$ 15,470.75	\$ 6,317.43	\$ 11,208.60	\$ 7,686.92	\$ 7,081.81	\$ 7,635.06	\$ 12,552.71	\$ 10,140.04	\$ 12,175:04	\$ 4,250.48	\$ 4,245.22	\$ 12,391.54	\$ 13,884.72	\$ 12,696.57	\$ 6,453.30	8 8,338.81	TOTAL Utility Con- version Cost

\circ
0
S
n
S
C-
7

		**310-32-264	*310-32-1	*310-32-028		PARCEL
Financial Assistance Program	*Qualified for	264 SWAN CHARLES JOSEPH S/S	1310-32-120A ERROR SHARON TRUSTEE	RICK WOOD		PARCEL III OVOwner Names
e Program	TOTAL	2801 HILLCREST DR	801 CRYSTAL VIEW DR	2874 MANOR VIEW DR	SUB-TOTAL	SITUS ADDRESS
		3999.82 0.3083% \$	5908.84 0.4553% \$	4002.21 0.3085% \$		PARCEL % of Sq
- - -	\$ 661,592,78 \$	- 1	\$ 3,012.39 \$	\$ 2,041.13 \$	\$ 861,592.78 \$ 330,796.39	Lotal Frimary: Extension Frimary: States Control of States Control
	330,798,39 \$		1,508.18 \$		E	84.
	320,796.39 \$	1,019.95	1,506.19	1,020.56	330,796.39	Extension Cost , Sis.
	246,175.56 \$	1,019.95 \$ 763.36, \$ 3.8	1,506.19 \$ 1,727.27 \$ 13	1,020.56 \$ 763.61 \$	330,796,38 \$ 246,175,56 \$ 2,883	condary Ext
	2,883.81 \$ 250,	94 \$	20 \$	8.85	2,883,61 \$.250,1	Extension Cost Secondary Cost Cost Constant Language Cost Cost Cost Cost Cost Cost Cost Cost
	105.91 \$ 232,781	3.43 \$ 3.65 \$	5.76 \$ -4:99	3.65. \$	1.61 \$.250,105,91 \$.232,799,82	ny veritabis uping laborate in a construction of the construction
	801,592,78 \$ 330,798,99 \$ 330,798.99 \$ 246,175.56 \$ 2,883.81 \$ 250,105.91 \$ 232,798.82 \$ 865,782.00 \$ 165,667.92 \$ 851,429.92 \$ 2,248,403.57	.65 \$ 3,317.50 \$	98 \$ 6,735.00	55 \$ 1,100.00	181 \$ 250 105 91 \$ 232799;82 \$ 686,914.50 \$ 188,487,92 \$ 863,362;42 \$ 2,256,356.07	Property Electric
	10 \$ 165,667.92	5	65	5	0 \$ 166,467.92	Property Trenching
	1 \$ 851,429.92	\$ 3,317.50 \$	800.00 \$ 7,535.00 \$	\$ 1,100.00 \$	\$ 863,382,42	total Private Utility Con-
	\$ 2,248,403.5	\$ 3,317.50	\$ 7,535.00	\$ 1,100.00	\$ 2,258,358.0	version Cost

Parcel 81312703 is centrally assessed property, property record includes Tract B and Tract C. This spreadsheet includes only square footage for Tract B as Tract C was excluded from the Underground Conversion Service Area.